

ANS. REC. BY:

REF:

CS/CTU8019107/Tlgbn2

Special Instruction:

Surveyor:

M. S. Men

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CT

Date/Time:

22.10.2018 2:00pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 3492A

Insured:

GR 7209S

at Workshop m/s

Hitachi Capital

Tel:

6833 6274

of

No. 8 Fourth Luk Yang Rd

Policy No:

DMCVGN0055491813

Claim No:

SNM180DUK75002.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17.10.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS. wpt

23.10.2018 @ morning

H.O.D. Endorsement:

Date/Time:

22.10.2018

2:15pm

Person Contacted:

Vohn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJS 3492A - x
	GR 7209S - CA/AG11002871/t
28/11/18	2.5m confirmed with Vohn vs \$6500, 11 days. cred to 6633.75, 51%

OUTSIDE

Surrender
Maiman

REF:

CTL

ASSIGNMENT

From:

Date:

23-10-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJS 3492A

at Workshop m/s

Hitachi Capital

of

No. 8 Fourth Lok King Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

morning

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

918K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

11 days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

5553492A

Yr Regn:

209 / my

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hilux

c.c.

1598

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

99882

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053EE/0615/692

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23/10/18 E5pm

Survey held at

Hitachi Capital

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair cost 97K.

RECEIVED 20 NOV 2018

Date/Time, File Pass to?

17/11/18



: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Report Format:

MIR-TP

Lump Sum / I.B.I.: (\$

6500

Days Of Repair:

11

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS. \$

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Oct 2018		22 Oct 2018 14:02 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS								[Created by insurer]	
Insured:		AGRI-CON AIR CONDITIONING SALES AND RENTAL, Co. Reg. No.: 29179900X							
Main Claimant:		CHAM KOK KIANG							
Vehicle Reg. No.:		SJS3492A		Date of Loss:		17/10/2018 19:00 - :59			
Claim Type:		TP / SNM18D04975C02		Policy/Cover Note No.:		DMCVSN0055491813 (Third Party Only)			
Vehicle Reg. No. (Insured):		GR7209S		Policy No. (Claimant):					
				Excess:		S\$0.00			
Repairer:		Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/10/2018]							
Adj Asg. Remarks:		EST \$14,053.11, CASE WITH SJE.							
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail	
There are no mail for this case.									
ALL ASSOCIATED TASKS									
						View All		Search Tasks	
						Create New Task		Complete	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Sent: Wednesday, 28 November 2018 2:51 PM
To: Shiau Chan (LKKAUTO); 'sur@lkkauto.com'
Cc: Jamilah, Binte MohdKassim; JiongHow, Ng
Subject: RE: SJS3492A DOA: 17/10/2018 FINALIZATION

Dear Shiau Chan,

Please ignore the previous email.

We accept LS, \$6500 before gst, 11 working days.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.siow@hcspl.com.sg
w: www.hitachi-capital.com.sg

From: Vonn, LM Siow
Sent: Wednesday, November 28, 2018 2:48 PM
To: 'Shiau Chan (LKKAUTO)' <siewsc@lkkauto.com>; 'sur@lkkauto.com'
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Subject: RE: SJS3492A DOA: 17/10/2018 FINALIZATION

Dear Shiau Chan,

We accept the COR at LS, \$6,520.00 (before gst), 11 working days.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.siow@hcspl.com.sg
w: www.hitachi-capital.com.sg

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 3563F

Vehicle Details

Vehicle No.: SJS3492A
Vehicle to be Exported: No
Intended Deregistration Date: 31 Oct 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: 3ZZ4920596
Chassis No.: MR053ZEE106151692
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$17,853.00
Original Registration Date: 13 Aug 2009
First Registration Date: 13 Aug 2009
Transfer Count: 0
Actual ARF Paid: \$17,853.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 12 Aug 2019
PARF Rebate Amount: \$8,926.00

Intended COE Rebate Details

COE Expiry Date: 12 Aug 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$14,310.00
COE Rebate Amount: \$1,119.00
Total Rebate Amount: \$10,045.00

The information contained herein is correct as at 18 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/10/2018 12:07
Date Of Accident	17/10/2018 19:00
Exact Location Of Accident	COMMONWEALTH AVE WEST NEAR CLEMENTI MALL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS3492A
Insured/Policyholder	
Name Of Registered Owner	CHAM KOK KIANG
NRIC No	S7603563F
Email Address	CKOKKIANG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97867935
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01013904
Cover Note Number	

Driver

Name of Driver	CHAM KOK KIANG
NRIC No	S7603563F
Date Of Birth	03/02/1976
Occupation	INDOOR
Date Of Driving Pass	09/05/1994
Driving Experience	24 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97867935
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	CKOKKIANG@GMAIL.COM

Address	BLK 268C BOON LAY DRIVE #16-550
Postcode	643268
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GR7209S
Vehicle Make/Model/Colour	NISSAN LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHUA KOK HAI
NRIC/Passport Number	S1512957C
Contact Number	96475758
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKX4690A
-----------------------------	----------

Vehicle Make/Model/Colour	PEUGEOT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ZHANG QINGJUN
NRIC/Passport Number	S6985232G
Contact Number	84448758
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.





 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/10/2018, about 7pm, I was driving my vehicle SJS3492A along Commonwealth Ave West. Due to heavy traffic ahead, the front vehicle slowed down and I followed. When my vehicle was stationary and suddenly I felt an impact from behind. As a result of the impact, the lorry GR7209S pushed my vehicle to hit the vehicle in front SKX4690A. No injury involved. we exchanged particulars then left the scene.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



No. 8 Fourth Lok Yang Road Singapore 629705

Tel : 64663022 Fax : 68966591

Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 18/10/2018

CHINA TAIPING

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 17/10/2018 @ 19:00

VRN : SJS3492A

MODEL : TOYOTA ALTIS 1.6

TP VRN : GR7209S

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 REAR BUMPER	1	\$ 515.00	\$ 515.00	de ✓
2 REAR BUMPER CLIPS	10	\$ 5.50	\$ 55.00	ne ✓
3 RR BUMPER SIDE RETAINER OUTER R/L	2	\$ 80.00	\$ 160.00	LH X, RH ne ✓
4 RR BUMPER SIDE RETAINER INNER R/L	2	\$ 80.00	\$ 160.00	LH X, RH ne ✓
5 RR BUMPER REFLECTOR LIGHT R/L	2	\$ 50.00	\$ 100.00	LH X, RH ne ✓
6 RR REINFORCEMENT SPONGE	1	\$ 125.00	\$ 125.00	ne ✓
7 RR REINFORCEMENT BRACKET R/L	2	\$ 87.00	\$ 174.00	LH-X, RH-bt ✓
8 TAILLAMP R/L	2	\$ 415.00	\$ 830.00	LH-X, RH ne ✓
9 REAR END PANEL	1	\$ 595.00	\$ 595.00	bt ✓
10 REAR END PANEL GARNISH	1	\$ 210.00	\$ 210.00	de ✓
11 SPARE TYRE COMPARTMENT	1	\$ 757.00	\$ 757.00	Ry ✓
12 SPARE TYRE COMPARTMENT BOARD	1	\$ 295.00	\$ 295.00	X ne ✓
13 BOOTLID	1	\$ 685.00	\$ 685.00	bt ✓
14 BOOTLID LOCK	1	\$ 110.00	\$ 110.00	bt ne ✓
15 BOOTLID HINGE R/L	2	\$ 65.00	\$ 130.00	LH X, RH-bt ✓
16 BOOTLID WEATHERSTRIP	1	\$ 190.00	\$ 190.00	ne ✓
17 BOOTLID REFLECTOR LIGHT R/L	2	\$ 195.00	\$ 390.00	LH-X, RH ne ✓
18 BOOTLID CENTER CHROME GARNISH	1	\$ 245.00	\$ 245.00	de ✓
19 BOOTLID TOYOTA LOGO	1	\$ 60.00	\$ 60.00	ne ✓
20 BOOTLID LOGO "1.6"	1	\$ 45.00	\$ 45.00	ne ✓
21 BOOTLID LOGO "CORROLLA"	1	\$ 48.00	\$ 48.00	ne ✓
22 BOOTLID LOGO "ALTIS"	1	\$ 48.00	\$ 48.00	ne ✓
23 REAR RH FENDER	1	\$ 925.00	\$ 925.00	buc ✓
24 REAR RH FENDER SHIELD	1	\$ 35.00	\$ 35.00	Ry ne ✓
25 REAR RH FENDER SHIELD CLIPS	4	\$ 5.50	\$ 22.00	X ne ✓
26 REAR RH TAILLAMP PANEL	1	\$ 85.00	\$ 85.00	bt ✓
27 REAR RH TAILLAMP WHITE CLIP	1	\$ 6.00	\$ 6.00	ne ✓
28 REAR WINDSCREEN MOULDING	1	\$ 90.00	\$ 90.00	ne ✓
29 REAR RH FENDER INNER TRIM	1	\$ 335.00	\$ 335.00	X ne ✓
30 BOOTLID CABLE	1	\$ 59.00	\$ 59.00	X ne ✓
31 FRONT BUMPER	1	\$ 436.00	\$ 436.00	ne ✓
32 FRONT BUMPER CLIPS	10	\$ 5.50	\$ 55.00	ne ✓
33 FRONT BUMPER RETAINER R/L	2	\$ 55.00	\$ 110.00	X ne ✓
			\$ 8,085.00	
Discount -25%			\$ 2,021.25	
			\$ 6,063.75	

Special Nett

59 REVERSE SENSOR	1	\$	200.00	\$	200.00	1W ✓
60 REAR LICENSE PLATE W CASING	1	\$	45.00	\$	45.00	x un ✓
61 REAR WINDSCREEN SEALANT	1	\$	40.00	\$	40.00	re ✓
62 FRONT LICENSE PLATE W CASING	1	\$	45.00	\$	45.00	pe ✓
				\$	330.00	285
63 REAR LH FENDER	Repair					
			PARTS TOTAL	\$	6,393.75	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area	250	\$	500.00
Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	1500	\$	2,000.00
Putty, Blend And Spray Paint on FRONT Affected Area	250	\$	500.00
Putty, Blend And Spray Paint on REAR Affected Area	1250	\$	2,000.00
Check Wiring, Re-align Headlamps & Taillamps, Ensure Proper Functioning	30	\$	80.00
Remove and Replace Rear Windscreen to Facilitate Repair	120	\$	180.00
Remove and Refit Rear End Panel Lining and Garnish to Facilitate Repair	60	\$	150.00
Remove and Reinstall Rear Trim Compartment to Facilitate Cutting and Repairing Work	60	\$	150.00
Dismantle and Transfer Bootlid Fittings & Mechanisms to New Bootlid	60	\$	200.00
Remove and Reinstall Reverse Sensors	30	\$	120.00
Re-align/Repair Chassis Member	250	\$	500.00
Cavity Treatment on New Parts	100	\$	240.00
Conduct Water Seepage Test	30	\$	120.00
LABOURS TOTAL	3740	\$	6,740.00

Grand Total : \$ 13,133.75
Add 7% GST : \$ 919.36
Nett Total : \$ 14,053.11

No. of repair days: 20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Tanpin 974957419
 23/10/18 E Spm
 Resurvey After repair.
 see @ lkkauto.com
 11 days.

25/10/18

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 18/10/2018

CHINA TAIPING

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 17/10/2018 @ 19:00
 VRN : SJS3492A
 MODEL : TOYOTA ALTIS 1.6
 TP VRN : GR7209S

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 REAR BUMPER	1	\$ 515.00	\$ 515.00 <i>de</i>	
2 REAR BUMPER CLIPS	10	\$ 5.50	\$ 55.00 <i>de</i>	
3 RR BUMPER SIDE RETAINER OUTER R/L	2	\$ 80.00	\$ 160.00 <i>LH x, RH ne</i>	
4 RR BUMPER SIDE RETAINER INNER R/L	2	\$ 80.00	\$ 160.00 <i>LH x, RH ne</i>	
5 RR BUMPER REFLECTOR LIGHT R/L	2	\$ 50.00	\$ 100.00 <i>LH x, RH ne</i>	
6 RR REINFORCEMENT SPONGE	1	\$ 125.00	\$ 125.00 <i>one</i>	
7 RR REINFORCEMENT BRACKET R/L	2	\$ 87.00	\$ 174.00 <i>LH-x, RH-bt</i>	
8 TAILLAMP R/L	2	\$ 415.00	\$ 830.00 <i>LH-x, RH ne</i>	
9 REAR END PANEL	1	\$ 595.00	\$ 595.00 <i>bt</i>	
10 REAR END PANEL GARNISH	1	\$ 210.00	\$ 210.00 <i>de</i>	
11 SPARE TYRE COMPARTMENT	1	\$ 757.00	\$ 757.00 <i>RY</i>	
12 SPARE TYRE COMPARTMENT BOARD	1	\$ 295.00	\$ 295.00 <i>x</i>	
13 BOOTLID	1	\$ 685.00	\$ 685.00 <i>bt</i>	
14 BOOTLID LOCK	1	\$ 110.00	\$ 110.00 <i>bt</i>	
15 BOOTLID HINGE R/L	2	\$ 65.00	\$ 130.00 <i>LH x, RH-bt</i>	
16 BOOTLID WEATHERSTRIP	1	\$ 190.00	\$ 190.00 <i>ne</i>	
17 BOOTLID REFLECTOR LIGHT R/L	2	\$ 195.00	\$ 390.00 <i>LH-x, RH ne</i>	
18 BOOTLID CENTER CHROME GARNISH	1	\$ 245.00	\$ 245.00 <i>de</i>	
19 BOOTLID TOYOTA LOGO	1	\$ 60.00	\$ 60.00 <i>ne</i>	
20 BOOTLID LOGO "1.6"	1	\$ 45.00	\$ 45.00 <i>ne</i>	
21 BOOTLID LOGO "COROLLA"	1	\$ 48.00	\$ 48.00 <i>ne</i>	
22 BOOTLID LOGO "ALTIS"	1	\$ 48.00	\$ 48.00 <i>ne</i>	
23 REAR RH FENDER	1	\$ 925.00	\$ 925.00 <i>buc</i>	
24 REAR RH FENDER SHIELD	1	\$ 35.00	\$ 35.00 <i>?</i>	
25 REAR RH FENDER SHIELD CLIPS	4	\$ 5.50	\$ 22.00 <i>x</i>	
26 REAR RH TAILLAMP PANEL	1	\$ 85.00	\$ 85.00 <i>bt</i>	
27 REAR RH TAILLAMP WHITE CLIP	1	\$ 6.00	\$ 6.00 <i>ne</i>	
28 REAR WINDSCREEN MOULDING	1	\$ 90.00	\$ 90.00 <i>ne</i>	
29 REAR RH FENDER INNER TRIM	1	\$ 335.00	\$ 335.00 <i>x</i>	
30 BOOTLID CABLE	1	\$ 59.00	\$ 59.00 <i>x</i>	
31 FRONT BUMPER	1	\$ 436.00	\$ 436.00 <i>one</i>	
32 FRONT BUMPER CLIPS	10	\$ 5.50	\$ 55.00 <i>ne</i>	
33 FRONT BUMPER RETAINER R/L	2	\$ 55.00	\$ 110.00 <i>x</i>	
			\$ 8,085.00	P: 5,500.00
			\$ 2,021.25	- 25%
			\$ 6,063.75	4,125.00
Discount -25%				

Special Nett

59 REVERSE SENSOR	1	\$	200.00	\$	200.00	✓
60 REAR LICENSE PLATE W CASING	1	\$	45.00	\$	45.00	x
61 REAR WINDSCREEN SEALANT	1	\$	40.00	\$	40.00	✓
62 FRONT LICENSE PLATE W CASING	1	\$	45.00	\$	45.00	✓ SN = 285-00
				\$	330.00	
63 REAR LH FENDER	Repair					

PARTS TOTAL \$ 6,393.75

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area		\$	500.00	250
Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	1500	\$	2,000.00	
Putty, Blend And Spray Paint on FRONT Affected Area	250	\$	500.00	
Putty, Blend And Spray Paint on REAR Affected Area	1250	\$	2,000.00	
Check Wiring, Re-align Headlamps & Taillamps, Ensure Proper Functioning	30	\$	80.00	
Remove and Replace Rear Windscreen to Facilitate Repair	120	\$	180.00	
Remove and Refit Rear End Panel Lining and Garnish to Facilitate Repair	60	\$	150.00	
Remove and Reinstall Rear Trim Compartment to Facilitate Cutting and Repairing Work	60	\$	150.00	
Dismantle and Transfer Bootlid Fittings & Mechanisms to New Bootlid	60	\$	200.00	
Remove and Reinstall Reverse Sensors	20	\$	120.00	
Re-align/Repair Chassis Member	L = 3,740-W plus 250?	\$	500.00	
Cavity Treatment on New Parts	100	\$	240.00	
Conduct Water Seepage Test	30	\$	120.00	

LABOURS TOTAL \$ 6,740.00

Grand Total : \$ 13,133.75

Add 7% GST : \$ 919.36

Nett Total : \$ 14,053.11

No. of repair days: 20

P: 4,125-W

SN: 285-W

L: 3,740-W

8,150-W

- 20% LS

6,520-W



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Tanpin 97495747

23/10/18 E Spm

Resony After repair.

see @ Internet.com

11 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019107/T1QBN2

Date: 03/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN0055491813
Claimant Vehicle No :	SJS3492A	Insured Vehicle No :	GR7209S
Date of Loss:	17/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D04975C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS3492A	Engine No:	3ZZ4920596
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106151692
Reg. Date:	13/08/2009 (Man. Year: 2009)	Odometer:	99882 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,393.75	4,410.00	1,983.75	31.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,740.00	3,740.00	3,000.00	44.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,133.75	8,150.00	4,983.75	37.95
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	13,133.75	6,500.00	6,633.75	50.51
+ GST 7.00/7.00% (S\$)	919.36	455.00	464.36	50.51
Nett Amount (S\$)	14,053.11	6,955.00	7,098.11	50.51

INSPECTION

Date of Assignment:	22/10/2018	
Date Inspected:	23/10/2018 Inspected At:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road Singapore 629705

Estimated Period of Repair: 11.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJS3492A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	515.00 FL	*515.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
3	2		*RR BUMPER SIDE RETAINER OUTER R/L	Os Necessary/Ns Not Necessary	160.00 FL	*80.00 FL
4	2		*RR BUMPER SIDE RETAINER INNER R/L	Os Necessary/Ns Not Necessary	160.00 FL	*80.00 FL
5	2		*RR BUMPER REFLECTOR LIGHT R/L	Os Cut/Ns Not Necessary	100.00 FL	*50.00 FL
6	1		*RR REINFORCEMENT SPONGE	Cracked	125.00 FL	*125.00 FL
7	2		*RR REINFORCEMENT BRACKET R/L	O/s Bent/N/s Not Necessary	174.00 FL	*87.00 FL
8	2		*TAILLAMP R/L	O/s Cracked/N/s Not Necessary	830.00 FL	*415.00 FL
9	1		*REAR END PANEL	Bent	595.00 FL	*595.00 FL
10	1		*REAR END PANEL GARNISH	Deformed	210.00 FL	*210.00 FL
11	1		*SPARE TYRE COMPARTMENT	Repair	757.00 FL	*- FL
12	1		*SPARE TYRE COMPARTMENT BOARD	Not Necessary	295.00 FL	*- FL
13	1		*BOOTLID	Bent	685.00 FL	*685.00 FL
14	1		*BOOTLID LOCK	Bent	110.00 FL	*110.00 FL
15	2		*BOOTLID HINGE R/L	O/s Bent/N/s Not Necessary	130.00 FL	*65.00 FL
16	1		*BOOTLID WEATHERSTRIP	Twisted	190.00 FL	*190.00 FL
17	2		*BOOTLID REFLECTOR LIGHT R/L	O/s Cracked/N/s Not Necessary	390.00 FL	*195.00 FL
18	1		*BOOTLID CENTER CHROME GARNISH	Deformed	245.00 FL	*245.00 FL
19	1		*BOOTLID TOYOTA LOGO	Necessary	60.00 FL	*60.00 FL
20	1		*BOOTLID LOGO 1.6	Necessary	45.00 FL	*45.00 FL
21	1		*BOOTLID LOGO COROLLA	Necessary	48.00 FL	*48.00 FL
22	1		*BOOTLID LOGO ALTIS	Necessary	48.00 FL	*48.00 FL
23	1		*REAR RH FENDER	Buckled	925.00 FL	*925.00 FL
24	1		*REAR RH FENDER SHIELD	Not Necessary	35.00 FL	*- FL
25	4		*REAR RH FENDER SHIELD CLIPS	Not Necessary	22.00 FL	*- FL
26	1		*REAR RH TAILLAMP PANEL	Bent	85.00 FL	*85.00 FL
27	1		*REAR RH TAILLAMP WHITE CLIP	Necessary	6.00 FL	*6.00 FL
28	1		*REAR WINDSCREEN MOULDING	Necessary	90.00 FL	*90.00 FL
29	1		*REAR RH FENDER INNER TRIM	Not Necessary	335.00 FL	*- FL
30	1		*BOOTLID CABLE	Not Necessary	59.00 FL	*- FL
31	1		*FRONT BUMPER	Cracked	436.00 FL	*436.00 FL
32	10		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
33	2		*FRONT BUMPER RETAINER R/L	Not Necessary	110.00 FL	*- FL
34	1		*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
35	1		*REAR LICENSE PLATE W CASING	Not Necessary	45.00 FS	*- FS
36	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
37	1		*FRONT LICENSE PLATE W CASING	Bent	45.00 FS	*45.00 FS
38	1		*REAR LH FENDER (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 8,415.00 5,785.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					2,021.25	1,375.00
Total Parts (S\$)					6,393.75	4,410.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT, CUT, WELD, RE-ALIGN & REPLACE DAMAGED PARTS OF FRONT AFFECTED AREA.	New	500.00	250.00
2	PANEL BEAT, CUT, WELD, RE-ALIGN & REPLACE DAMAGED PARTS OF REAR AFFECTED AREA.	New	2,000.00	1,500.00
3	PUTTY, BLEND AND SPRAY PAINT ON FRONT AFFECTED AREA.	New	500.00	250.00
4	PUTTY, BLEND AND SPRAY PAINT ON REAR AFFECTED AREA.	New	2,000.00	1,250.00
5	CHECK WIRING, RE-ALIGN HEADLAMPS & TAILLAMPS, ENSURE PROPER FUNCTIONING.	New	80.00	30.00
6	REMOVE AND REPLACE REAR WINDSCREEN TO FACILITATE REPAIR.	New	180.00	120.00
7	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR.	New	150.00	60.00
8	REMOVE AND REINSTALL REAR TRIM COMPARTMENT TO FACILITATE CUTTING AND REPAIRING WORK.	New	150.00	60.00
9	DISMANTLE AND TRANSFER BOOTLID FITTINGS & MECHANISMS TO NEW BOOTLID.	New	200.00	60.00
10	REMOVE AND REINSTALL REVERSE SENSORS.	New	120.00	30.00
11	RE-ALIGN / REPAIR CHASSIS MEMBER	New	500.00	0.00
12	CAVITY TREATMENT ON NEW PARTS.	New	240.00	100.00
13	CONDUCT WATER SEEPAGE TEST.	New	120.00	30.00
Gross Labour Cost (S\$)			6,740.00	3,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >