



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

2 October 2018

HHTPClaims18-105

India International Insurance Pte Ltd
64 Cecil Street, IOB Building
#04-00 / #05-00
Singapore 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SFY 2848 E & SHA 4161 S ON 28/9/2018 ALONG COMMONWEALTH AVE WEST AT ABOUT 0835 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No : SFY 2848 E
Vehicle Make : HONDA
Vehicle Model : HONDA CIVIC 1.8L 5AT
Vehicle Chassis No : JHMFD16309S200925
Policy No : 5087272209-01
Date of Accident : 28/9/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper		\$ 420.00 <i>CRA</i>
2	10	Front Bumper Clip	\$ 2.00	\$ 20.00 <i>NEC</i>
3	1	Front Bumper Retainer (RH)		\$ 45.00 ?
4	1	Front Headlamp (RH)		\$ 480.00 <i>SCR</i>
5	1	Front Headlamp Bracket (RH)		\$ 28.00 ?
6	1	Front Fender (RH)		\$ 250.00 <i>DEF</i>
7	1	Front Inner Shield (RH)		\$ 95.00 <i>TN</i>
8	10	Front Inner Shield Clip (RH)	\$ 2.00	\$ 20.00 <i>NEC</i>
				\$ 1,358.00
				Less 20% \$ (135.80)
				\$ 1,222.20

To dismantle & change front bumper, front RH fender, front RH headlamp, knocking & pull straight front RH wheel house panel & front RH door

\$ 800.00 *400*

To perform wire checking

\$ 20.00 *NEC*

To spray front bumper, front RH fender and touch up front RH door

\$ 600.00 *400 300*

\$ 2,642.20

\$ 184.95

7% GST
Total

\$ 2,827.15



Authorised by Claims Dept
Mrs Tan @ 9639 9195

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Authorised by Repairer

Signature: _____
Date: _____

NAZ LKK
22/8/18 1000
L/S
4 days
- CHECK ITEMS PHOTO
- AFTER REPAIR PHOTO