

15/07/10

INS. CASE OWNER:

CC 6 / AIG1801 9110, G. Khb 52

LKK:

IDAC:

Surveyor:

XGD

DOI:

ASSIGNMENT

18/10/18

Date / Time:

18/10/18

Registered in Merimen:

18/10/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUF 9012M

Name of Insured:

LAR LOVE LENSUNG PUL

Insured Tel No.:

HP:

Claim No.:

10 81299 81214

Policy No.:

01000000000000000000

Make / Model:

TOYOTA

Excess Sec II :SS

D.O.A.:

15/10/18

Place of Accident:

KIPPIKT SUNGURUP

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MUHAMMAD SHAHRIFAL BIN AMMAD

TP GIA REPORT: YES / NO

TP GIA REPORT (YES / NO)

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final? Yes / No

SUF 9012M

SFB 7765P

SMC 1068Y



INSRS: WSP: Tel: Liability: RMKS: 01



INSRS: WSP: Tel: Liability: RMKS: TP



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time	STAGE	DATE/ PIC
24/10/18	SFB 7765P - X	SUF 9012M - X
	TP LOD IN BY EMAIL	
	AIG INSTRUCTIONS CAN DO BS	
12/11/19 @ 2.25 pm	Spoke to OI (Co. rep: Mr. Edwin). He confirmed the mva. 3 veh c.c. OI last vehicle. Informed OI on TP claim, agreed to settle and aware of ACD will be withheld - time being.	
15/7/19	FILE PASS TO TYPE MANDATE	
8/9/19	File pass to shu kei to close	

**PRELIMINARY ADVICE** Date/Time: Sent By: Confirm by:

**FINALIZATION** Date/Time: Confirm with: Confirm by:

Repair Cost: 45 SS 9,550 ( 7 days) Reduction: 5% Email  Call

**FINAL SETTLEMENT** Date/Time: 6/9/19 Confirm with sharon Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28 If NO or B 28. Ass. Lia: 100% (3 veh c.c. OI last case)

Repair Cost: (w/ GST) SS 10,218.50

Loss of Rental (LOR): SS - ( - days)

Loss of Use (LOU): SS 900 ( 15 x 9 days)

Loss of Income (LOI): SS - ( S x - days)

LOR only  LOU only  LOR + LOU  LOR + LO  [Tick only one]

GIA/LTA Search SS 7.45

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost SS -

**Total:** SS 11,125.95 **Global Sum SS:**

**FINAL PAYMENT** Date/Time: Confirm with: Email  Call

Payee 1: SS 11,125.95 Name 1: OPTIMA WERKZ PTE LTD

Payee 2: (Strike if N.A.) SS - Name 2:

Payee 3: (Strike if N.A.) SS - Name 3:





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18019110/Ghb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 22-10-2018	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLE 9012M	Veh. Inspected	SKB 7765P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/10/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	15/10/2018	Inspection Date	18/10/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# OPTIMA WERKZ PTE LTD

Ena. G. L.  
22/10/18

Vic

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500

Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 17 OCTOBER 2018

Third Party Insurer: AIG

Vehicle No: SKB7765P

Third Party Veh No: SLE9012M

Model: MERCEDES BENZ E200C GI

Date of Accident: 15 OCTOBER 2018

Chassis: WDD2120482A398872 - 2011

## ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID / <i>Free</i>		✓ \$2,497.50
1	REAR BOOTLID EMBLEM LOGO /		✓ \$55.50
1	REAR BOOTLID EMBLEM E200 / <i>Y.M.C.</i>		✓ \$83.25
1	REAR BOOTLID EMBLEM CGI /		✓ \$83.25
1	REAR BOOTLID CHROME MOULDING / <i>BT</i>		✓ \$129.50
1	REAR BOOTLID MECHANISM LOCK /		✓ \$277.50
1	REAR BOOTLID MECHANISM LOCK STRIKER / <i>X Repair</i>		X \$425.50
1	REAR BOOTLID WEATHER STRIP / <i>Free</i>		✓ \$181.30
2	REAR BOOTLID HINGE RH/LH / <i>X</i>	\$166.50	X \$333.00
2	REAR BOOTLID HINGE GARNISH RH/LH / <i>X Repair</i>	\$27.75	X \$55.50
1	REAR BOOTLID REFLECTOR RH / <i>Set</i>		✓ \$444.00
1	REAR TAILLAMP RH / <i>Set</i>		✓ \$582.75
3	REAR TAILLAMP CLIPS / <i>MC</i>	\$9.00	✓ \$27.00
1	REAR BUMPER / <i>RL</i>		✓ \$1,609.50
10	REAR BUMPER CLIPS / <i>MC</i>	\$5.50	✓ \$55.00
6	REAR BUMPER RIVET / <i>MC</i>	\$6.00	✓ \$36.00
1	REAR BUMPER CENTRE CHROME MOULDING / <i>Y.M.C.</i>		✓ \$175.75
2	REAR BUMPER CHROME MOULDING RH/LH /	\$101.75	✓ \$203.50
1	REAR BUMPER TOW HOOK COVER / <i>Cut</i>		✓ \$64.75
1	REAR BUMPER LOWER LIP / <i>RL</i>		✓ \$499.50
3	REAR BUMPER REVERSE SENSOR / <i>DM Tape</i>	\$203.50	✓ \$610.50
3	REAR BUMPER REVERSE SENSOR RUBBER SEAL / <i>MC</i>	\$9.25	✓ \$27.75
2	REAR BUMPER SIDE RETAINER RH/LH / <i>MC</i>	\$46.25	✓ \$92.50
1	REAR BUMPER LOWER BRACKET RH / <i>X</i>		✓ \$18.50
1	REAR BUMPER REINFORCEMENT / <i>X</i>		✓ \$666.00
1	REAR END PANEL / <i>X Repair</i>		X \$1,239.50
1	REAR END PANEL INNER TOP GARNISH / <i>RL</i>		✓ \$150.00
1	FRONT DRIVER SEAT HEAD REST RH / <i>Repair X</i>		X \$925.00
1	FRONT DRIVER SEAT BELT RH / <i>X</i>		X \$1,250.00
1	FRONT PASSENGER SEAT HEAD REST LH / <i>X Repair</i>		X \$925.00
1	FRONT PASSENGER SEAT BELT LH / <i>X</i>		X \$1,250.00
1	FRONT BONNET / <i>X Repair</i>		X \$2,220.00
1	FRONT HEADLAMP LH / <i>X NN</i>		X \$878.75
1	FRONT GRILLE WITH LOGO / <i>MC</i>		✓ \$1,110.00
1	FRONT BUMPER / <i>X Repair</i>		X \$1,267.25
10	FRONT BUMPER CLIPS / <i>MC</i>	\$5.50	✓ \$55.00
2	FRONT BUMPER PARKING SENSOR / <i>Q / NW</i>	\$203.50	✓ \$407.00
2	FRONT BUMPER PARKING SENSOR RUBBER SEAL / <i>MC</i>	\$9.25	✓ \$18.50
1	FRONT BUMPER NUMBER PLATE GARNISH / <i>RL</i>		✓ \$194.25
1	FRONT BUMPER LOWER CENTRE GRILLE / <i>Q / Cut</i>		✓ \$92.50

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143 Tel : +65 6472 1313 Fax : +65 6472 2112  
 Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011  
 Co. Reg. No. 201212455W

Date: 17 OCTOBER 2018 Third Party Insurer: AIG  
 Vehicle No: SKB7765P Third Party Veh No: SLE9012M  
 Model: MERCEDES BENZ E200C GI Date of Accident: 15 OCTOBER 2018  
 Chassis: WDD2120482A398872 - 2011

## ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
2	FRONT BUMPER CHROME MOULDING RH/LH / <i>MC</i>	\$88.80	/ \$177.60
1	RADIATOR TOP GARNISH / <i>CAH</i>		/ \$138.75
SUB TOTAL			\$21,533.90
Less 10%			-\$2,153.39
PARTS TOTAL			\$19,380.51

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	FRONT NUMBER PLATE WITH CASING / <i>cut</i>		/ \$70.00
S/N TOTAL			\$70.00

### LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION / <i>800-700</i>	\$1,200.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION / <i>1200</i>	\$1,300.00
TO TUFF KOTE / ANTI-RUST / <i>/</i>	\$60.00
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR / <i>80</i>	\$180.00
TO CHECK WIRING WITH WATER LEAKAGE TEST / <i>40</i>	\$60.00
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR / <i>40</i>	\$60.00
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD / <i>150</i>	\$220.00
<b>LABOUR TOTAL</b>	<b>\$3,080.00</b>

PEI TING **TOTAL \$22,530.51**

*7 Days -  
 Unpism repair.  
 After repair photos.  
 Gmo Qian - 82880282  
 18/10/18*

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 17 OCTOBER 2018

Third Party Insurer: AIG

Vehicle No: SKB7765P

Third Party Veh No: SLE9012M

Model: MERCEDES BENZ E200C GI

Date of Accident: 15 OCTOBER 2018

Chassis: WDD2120482A398872 - 2011

## ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID / <i>free</i>		\$2,497.50
1	REAR BOOTLID EMBLEM LOGO /		\$55.50
1	REAR BOOTLID EMBLEM E200 / <i>gmc.</i>		\$83.25
1	REAR BOOTLID EMBLEM CGI /		\$83.25
1	REAR BOOTLID CHROME MOULDING / ?		\$129.50
1	REAR BOOTLID MECHANISM LOCK / <i>BT</i>		\$277.50
1	REAR BOOTLID MECHANISM LOCK STRIKER X <i>Repair</i>		\$425.50
1	REAR BOOTLID WEATHER STRIP / ?		\$181.30
2	REAR BOOTLID HINGE RH/LH X	\$166.50	\$333.00
2	REAR BOOTLID HINGE GARNISH RH/LH X <i>Repair</i>	\$27.75	\$55.50
1	REAR BOOTLID REFLECTOR RH / <i>set</i>		\$444.00
1	REAR TAILLAMP RH / <i>set</i>		\$582.75
3	REAR TAILLAMP CLIPS / <i>set</i>	\$9.00	\$27.00
1	REAR BUMPER / <i>re</i>		\$1,609.50
10	REAR BUMPER CLIPS / <i>mc</i>	\$5.50	\$55.00
6	REAR BUMPER RIVET / <i>mc</i>	\$6.00	\$36.00
1	REAR BUMPER CENTRE CHROME MOULDING / <i>gmc</i>		\$175.75
2	REAR BUMPER CHROME MOULDING RH/LH / <i>gmc</i>	\$101.75	\$203.50
1	REAR BUMPER TOW HOOK COVER / <i>set</i>		\$64.75
1	REAR BUMPER LOWER LIP / <i>re</i>		\$499.50
3	REAR BUMPER REVERSE SENSOR / <i>pm 2pc</i>	\$203.50	\$610.50
3	REAR BUMPER REVERSE SENSOR RUBBER SEAL / <i>mc</i>	\$9.25	\$27.75
2	REAR BUMPER SIDE RETAINER RH/LH / <i>mc</i>	\$46.25	\$92.50
1	REAR BUMPER LOWER BRACKET RH / <i>BT</i>		\$18.50
1	REAR BUMPER REINFORCEMENT / <i>BT</i>		\$666.00
1	REAR END PANEL / ?		\$1,239.50
1	REAR END PANEL INNER TOP GARNISH / ?		\$150.00
1	FRONT DRIVER SEAT HEAD REST RH <i>Repair</i> X		\$925.00
1	FRONT DRIVER SEAT BELT RH X		\$1,250.00
1	FRONT PASSENGER SEAT HEAD REST LH X <i>Repair</i>		\$925.00
1	FRONT PASSENGER SEAT BELT LH X		\$1,250.00
1	FRONT BONNET X <i>Repair</i>		\$2,220.00
1	FRONT HEADLAMP LH / ?		\$878.75
1	FRONT GRILLE WITH LOGO / <i>mc</i>		\$1,110.00
1	FRONT BUMPER X <i>Repair</i>		\$1,267.25
10	FRONT BUMPER CLIPS / <i>mc</i>	\$5.50	\$55.00
2	FRONT BUMPER PARKING SENSOR / ?	\$203.50	\$407.00
2	FRONT BUMPER PARKING SENSOR RUBBER SEAL /	\$9.25	\$18.50
1	FRONT BUMPER NUMBER PLATE GARNISH / ?		\$194.25
1	FRONT BUMPER LOWER CENTRE GRILLE / ?		\$92.50

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Branch office : 9A Serangoon North Ave 5 Singapore 554500

Co. Reg. No. 201212455W

Date: 17 OCTOBER 2018

Vehicle No: SKB7765P

Model: MERCEDES BENZ E200C GI

Chassis: WDD2120482A398872 - 2011

**LKK Auto Consultants** hence notify  
 • Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to cost of materials  
 • Any survey is on a "Without Prejudice" basis  
 • Supplementary item(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Third Party Insurer: AIG**  
**Third Party Veh No: SLE9012M**  
**Date of Accident: 15 OCTOBER 2018**

## ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
2	FRONT BUMPER CHROME MOULDING RH/LH / <i>MC</i>	\$88.80	\$177.60
1	RADIATOR TOP GARNISH / <i>ORA</i>		\$138.75
		SUB TOTAL	\$21,533.90
		Less 10%	-\$2,153.39
		PARTS TOTAL	\$19,380.51

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	FRONT NUMBER PLATE WITH CASING / <i>Cut</i>		\$70.00
		S/N TOTAL	\$70.00

### LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	<i>700</i>	\$1,200.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	<i>1200</i>	\$1,300.00
TO TUFF KOTE / ANTI-RUST	<i>/</i>	\$60.00
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	<i>80</i>	\$180.00
TO CHECK WIRING WITH WATER LEAKAGE TEST	<i>40</i>	\$60.00
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	<i>40</i>	\$60.00
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	<i>150</i>	\$220.00
	LABOUR TOTAL	\$3,080.00

PEI TING **TOTAL \$22,530.51**

*7 Days -  
 Unpssm repair.  
 After repair PHOTOS.  
 Eric Qiang - 82880282  
 18/10/18*

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3711H
Vehicle Details	
Vehicle No.:	SKB7765P
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Oct 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 200CGI
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	27186030200244
Chassis No.:	WDD2120482A398872
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$51,151.00
Original Registration Date:	28 Jun 2011
First Registration Date:	28 Jun 2011
Transfer Count:	0
Actual ARF Paid:	\$51,151.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2021
PARF Rebate Amount:	\$30,690.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$62,000.00
COE Rebate Amount:	\$16,671.00
<b>Total Rebate Amount:</b>	<b>\$47,361.00</b>

The information contained herein is correct as at 19 Oct 2018

OK

> Back to OneMotoring

**Enquire Transfer Fee**

Vehicle Details	
Vehicle No.:	SKB7765P
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 200CGI
Chassis No.:	WDD2120482A398872
Propellant:	Petrol
Engine No.:	27186030200244
Engine Capacity:	1796 cc
Maximum Power Output:	135.0 kW ( 181 bhp)
Maximum Laden Weight:	2150 kg
Unladen Weight:	1615 kg
Year Of Manufacture:	2011
Original Registration Date:	28 Jun 2011
Lifespan Expiry Date:	-
COE Category:	E - Open Category
Quota Premium:	\$62,000.00
COE Expiry Date:	27 Jun 2021
Road Tax Expiry Date:	27 Jun 2019
PARF Eligibility Expiry Date:	27 Jun 2021
Inspection Due Date:	27 Jun 2020
Intended Transfer Date:	19 Mar 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

You may print this page for reference.

OK      Print

## **Khanchna (LKK Auto)**

---

**From:** Khanchna (LKK Auto)  
**Sent:** Tuesday, 3 September 2019 12:10 PM  
**To:** Lily.loi@ow.sg; Vic (LKKAuto)  
**Cc:** 'Sharon'; 'angela.tan'; 'Adeline Lim'  
**Subject:** RE: FW: LOD - SKB7765P CLAIMING AGAINST SLE9012M DOA: 15/10/2018 YOUR REF: CC6/AIG18019110/Gkb3 (AIG)

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows:

1. Cost of Repair (w/GST)	\$ 10,218.50
2. Loss of Rental (9 days x \$100)	\$ 900.00
3.LTA Search Fee	\$ 7.45
<b>Total</b>	<b>\$ 11,125.95</b>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Khanchna** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: **6841 2360** | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Lily.loi@ow.sg <Lily.loi@ow.sg>

**Sent:** Saturday, 17 August 2019 2:09 PM

**To:** Vic (LKKAuto) <vicalpeh@lkkauto.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>

**Cc:** 'Sharon' <sharon@ow.sg>; 'angela.tan' <angela.tan@ow.sg>; 'Adeline Lim' <adeline@ow.sg>

**Subject:** RE: FW: LOD - SKB7765P CLAIMING AGAINST SLE9012M DOA: 15/10/2018 YOUR REF: CC6/AIG18019110/Gkb3 (AIG)

Dear Khanchna,

Up-to-date, we still have not yet received any response from you.

## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Monday, 19 August 2019 8:55 AM  
**To:** Chan, Kian-Meng  
**Cc:** Admin A  
**Subject:** SEEK MANDATE - AIG REF: TP / 1081809812SG [ACCIDENT INVOLVING SLE9012M (OI) & SKB7765P ON 15/10/2018 ]

<b>Tracking:</b>	<b>Recipient</b>	<b>Delivery</b>
	Chan, Kian-Meng	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 19/8/2019 8:55 AM
	olivialau@lkkauto.com	Delivered: 19/8/2019 8:55 AM

AIG Ref: TP / 1081809812SG  
LKK Ref: CC6/AIG18019110/Gkb3

Dear Sir/Madam,

### **ACCIDENT INVOLVING SLE9012M (OI) & SKB7765P(TP) ON 15/10/2018**

We refer to the above matter.

This is a 3 vehicle chain collision, our Insured vehicle is last. The liability is not in our Insured's favour.

We seek your approval to offer to Third Party repairer, "**OPTIMA WERKZ PTE LTD**" as follows: -

	<b>Claimed Amount</b>	<b>Revised Amount</b>
1. Cost of Repair (w/GST)	\$ 24,107.65	\$ 10,218.50
2. Loss of Rental (13days x \$100.00)	\$ 1,300.00	\$ 900.00 (9 days x \$100)
LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
<b>total</b>	<b>\$ 25,415.10</b>	<b>\$ 11,125.95</b>

\*\*7 days recommendation for repair +1 Sundays +1 PRS = 9 days

All the relevant documents had been uploaded in Merimen.

**Kindly let us have your mandate in Merimen.**

Best Regards,  
Khanchna | Case Handler

# Print Received Message

This mail is associated with :

**\*SKB7765P (1081809812SG)  
[SLE9012M]**

TP

ROYAL LIMOUSINE PTE LTD  
Oct 15 2018 11:00PM  
[CAR COVE LEASING PTE LTD]  
Optima Werkz Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 19/08/2019 10:34 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$11125.95) - SKB7765P - Claim Handler: Chan, Kian-Meng

Approved:11125.95.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Oct 2018 <a href="#">Edit Reg</a>		18 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$9,550.00</b> <a href="#">Edit Estimates</a>	<b>S\$9,550.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>CAR COVE LEASING PTE LTD</b> , Co. Reg. No.: 201602573M								
Main Claimant:	<b>ROYAL LIMOUSINE PTE LTD</b> , Co. Reg. No.: 199303711H								
Vehicle Reg. No.:	<b>SKB7765P</b>	Date of Loss:	15/10/2018 23:00 - :59 [87 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 1081809812SG</b>	Policy/Cover Note No.:	0999994802 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLE9012M</b>	Policy No. (Claimant):	SD18V00524/VPL/R03						
		Excess:							
Repairer:	<b>Optima Werkz Pte Ltd (HQ)</b> 9A Serangoon North Ave 5, 554500 Serangoon - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Kian-Meng</b> ] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	<b>Liberty Insurance Pte Ltd (HQ)</b> - Tel: (65) 6221 8611								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 31/10/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>• AIG_SG_EXPRESS (19/08/2019): <b>Alert - Adj Mandate Approved (S\$11125.95) - SKB7765P - Claim Handler: Chan, Kian...</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# Claim Documents

**\*SKB7765P (1081809812SG)**  
**[SLE9012M]**  
 TP  
**ROYAL LIMOUSINE PTE LTD**  
**Oct 15 2018 11:00PM**  
**[CAR COVE LEASING PTE LTD]**  
**Optima Werkz Pte Ltd**

View  ▾

Letters/Correspondences			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	<b>Third Party Express Settlement – Payment Breakdown</b>	 Edit	

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
32	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
33	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
34	19/08/19 08:36	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
35	19/08/19 08:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
36	19/08/19 08:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
37	19/08/19 08:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
48	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
49	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
50	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
51	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
52	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
53	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
54	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
55	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
56	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
57	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
58	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
59	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
60	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
61	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
62	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
63	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
64	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
65	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
66	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
67	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
68	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
69	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
70	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
71	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
72	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
73	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
74	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
75	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
76	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
77	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
78	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
79	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
80	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
81	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
82	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
83	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
84	19/08/19 08:36	General View	 Load JPG	<input checked="" type="checkbox"/>
85	19/08/19 08:36	General View	Load JPG	<input checked="" type="checkbox"/>
86	19/08/19 08:36	General View	Load JPG	<input checked="" type="checkbox"/>
87	19/08/19 08:36	General View	Load JPG	<input checked="" type="checkbox"/>
88	19/08/19 08:36	General View	Load JPG	<input checked="" type="checkbox"/>
89	19/08/19 08:36	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
90	19/08/19 08:36	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	19/08/19 08:36	General View		Load JPG <input checked="" type="checkbox"/>
92	19/08/19 08:36	General View		Load JPG <input checked="" type="checkbox"/>
93	19/08/19 08:36	General View		Load JPG <input checked="" type="checkbox"/>
94	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
95	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
96	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
97	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
98	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
99	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
100	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
101	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
102	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
103	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
104	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
105	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
106	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
107	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
108	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
109	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
110	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
111	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
112	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
113	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
114	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
115	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
116	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
117	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
118	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
119	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
120	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
121	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
122	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
123	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
124	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
125	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
126	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
127	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
128	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
129	19/08/19 08:37	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
130	19/08/19 08:38	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
131	19/08/19 08:38	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
132	19/08/19 08:38	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
133	19/08/19 08:38	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
134	19/08/19 08:38	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
135	19/08/19 08:38	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/10/18 17:18	TP ESTIMATE- MARKED		Load PDF <input type="checkbox"/>
2	22/10/18 17:18	TP GIA REPORT		Load PDF <input type="checkbox"/>
3	30/04/19 10:02	LETTER TO OI		Load PDF <input type="checkbox"/>
4	16/08/19 16:57	LTA SEARCH		Load PDF <input type="checkbox"/>
5	16/09/19 13:17	LOD		Load PDF <input type="checkbox"/>
6	16/09/19 13:17	AUTHORISATION TO ACT		Load PDF <input type="checkbox"/>
7	16/09/19 13:17	RELEASE VOUCHER		Load PDF <input type="checkbox"/>



NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLE9012M (Insd veh)	Model:	MERCEDES-BENZ 200E 2.0 (A)
	SKB7765P (TP veh)		
Date of Accident:	15/10/2018		

Global Sum Settlement	:	[ ] Yes	[ X ] No	
Repair Estimate	:		<input checked="" type="checkbox"/>	\$ 24,107.65
Final Repair Cost	:		<input checked="" type="checkbox"/>	\$ 10,218.50
Loss of Use	:		<input checked="" type="checkbox"/>	\$ 900.00      9.00 days at \$100.00 per day
Rental (if any)	:		<input checked="" type="checkbox"/>	\$                      days
LTA / GIA Search Fee	:		<input checked="" type="checkbox"/>	\$ 7.45
Others:	:		<input checked="" type="checkbox"/>	\$
	:		<input checked="" type="checkbox"/>	\$
Final Settlement Sum	:		<input checked="" type="checkbox"/>	\$ 11,125.95
<b>Is Third Party Workshop GIA Registered?</b> [ ] YES    [ X ] NO    (Kindly indicate below)				
<b>A) For Non GIA Registered Workshop:</b>		Agreed Liability ____ 100 ____ (%)		
<b>B) For GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No    BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown				
1)	Optima Werkz Pte Ltd	:	\$	11,125.95
2)		:	\$	
3)		:	\$	
4)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

16 Sep  
2019

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/  
Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18019110/GKB3S2  
Date: 16/09/2019

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994802
Claimant Vehicle No :	SKB7765P	Insured Vehicle No :	SLE9012M
Date of Loss:	15/10/2018	Nature of Claim:	TP
		Claim No:	1081809812SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SKB7765P</b>	Engine No:	27186030200244
Make & Model:	MERCEDES-BENZ 200E, 2.0 (A)	Chassis No:	WDD2120482A398872
Reg. Date:	28/06/2011 (Man. Year: 2011)	Odometer:	364345 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,450.51	9,757.96	9,692.55	49.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	2,370.00	710.00	23.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,530.51</b>	<b>12,127.96</b>	<b>10,402.55</b>	<b>46.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,550.00</b>		
(S\$)	22,530.51	9,550.00	12,980.51	57.61
<b>+ GST 7.00/7.00% (S\$)</b>	1,577.14	668.50	908.64	57.61
<b>Nett Amount (S\$)</b>	<b>24,107.65</b>	<b>10,218.50</b>	<b>13,889.15</b>	<b>57.61</b>
<b>+ Loss of Use (9.0 x S\$100.00/day) (S\$)</b>		900.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>11,125.95</b>		

## INSPECTION

Date of Assignment:	18/10/2018		
Date Inspected:	18/10/2018	Inspected At:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500
Estimated Period of Repair:	7.0 days		

Adjuster: XING GUO QIANG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

*ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	2,497.50 FL	*2,497.50 FL
2	1		*REAR BOOTLID EMBLEM LOGO	Necessary	55.50 FL	*55.50 FL
3	1		*REAR BOOTLID EMBLEM E200	Necessary	83.25 FL	*83.25 FL
4	1		*REAR BOOTLID EMBLEM CGI	Necessary	83.25 FL	*83.25 FL
5	1		*REAR BOOTLID CHROME MOULDING	Broken	129.50 FL	*129.50 FL
6	1		*REAR BOOTLID MECHANISM LOCK	Bent	277.50 FL	*277.50 FL
7	1		*REAR BOOTLID MECHANISM LOCK STRIKER	Repair	425.50 FL	*- FL
8	1		*REAR BOOTLID WEATHER STRIP	Twisted	181.30 FL	*181.30 FL
9	2		*REAR BOOTLID HINGE RH/LH	Repair	333.00 FL	*- FL
10	2		*REAR BOOTLID HINGE GARNISH RH/LH	Repair	55.50 FL	*- FL
11	1		*REAR BOOTLID REFLECTOR RH	Scratched	444.00 FL	*444.00 FL
12	1		*REAR TAILLAMP RH	Scratched	582.75 FL	*582.75 FL
13	3		*REAR TAILLAMP CLIPS	Necessary	27.00 FL	*27.00 FL
14	1		*REAR BUMPER	Deformed	1,609.50 FL	*1,609.50 FL
15	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
16	6		*REAR BUMPER RIVET	Necessary	36.00 FL	*36.00 FL
17	1		*REAR BUMPER CENTRE CHROME MOULDING	Necessary	175.75 FL	*175.75 FL
18	2		*REAR BUMPER CHROME MOULDING RH/LH	Necessary	203.50 FL	*203.50 FL
19	1		*REAR BUMPER TOW HOOK COVER	Cut	64.75 FL	*64.75 FL
20	1		*REAR BUMPER LOWER LIP	Deformed	499.50 FL	*499.50 FL
21	3		*REAR BUMPER REVERSE SENSOR	Damaged	610.50 FL	*610.50 FL
22	3		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	27.75 FL	*27.75 FL
23	2		*REAR BUMPER SIDE RETAINER RH/LH	Necessary	92.50 FL	*92.50 FL
24	1		*REAR BUMPER LOWER BRACKET RH	Bent	18.50 FL	*18.50 FL
25	1		*REAR BUMPER REINFORCEMENT	Bent	666.00 FL	*666.00 FL
26	1		*REAR END PANEL	Repair	1,239.50 FL	*- FL
27	1		*REAR END PANEL INNER TOP GARNISH	Deformed	150.00 FL	*150.00 FL
28	1		*FRONT DRIVER SEAT HEAD REST RH	Repair	925.00 FL	*- FL
29	1		*FRONT DRIVER SEAT BELT RH	Repair	1,250.00 FL	*- FL
30	1		*FRONT PASSENGER SEAT HEAD REST LH	Repair	925.00 FL	*- FL
31	1		*FRONT PASSENGER SEAT BELT LH	Repair	1,250.00 FL	*- FL
32	1		*FRONT BONNET	Repair	2,220.00 FL	*- FL
33	1		*FRONT HEADLAMP LH	Not Necessary	878.75 FL	*- FL
34	1		*FRONT GRILLE WITH LOGO	Necessary	1,110.00 FL	*1,110.00 FL
35	1		*FRONT BUMPER	Repair	1,267.25 FL	*- FL
36	10		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
37	2		*FRONT BUMPER PARKING SENSOR	Not Working	407.00 FL	*407.00 FL
38	2		*FRONT BUMPER PARKING SENSOR RUBBER SEAL	Necessary	18.50 FL	*18.50 FL
39	1		*FRONT BUMPER NUMBER PLATE GARNISH	Deformed	194.25 FL	*194.25 FL
40	1		*FRONT BUMPER LOWER CENTRE GRILLE	Cut	92.50 FL	*92.50 FL
41	2		*FRONT BUMPER CHROME MOULDING RH/LH	Necessary	177.60 FL	*177.60 FL
42	1		*RADIATOR TOP GARNISH	Cracked	138.75 FL	*138.75 FL
43	1		*FRONT NUMBER PLATE WITH CASING	Cut	70.00 FS	*70.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>21,603.90</b>	<b>10,834.40</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>2,153.39</b>	<b>1,076.44</b>
<b>Total Parts (\$\$)</b>	<b>19,450.51</b>	<b>9,757.96</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION.	New	1,200.00	800.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION.	New	1,300.00	1,200.00
3	TO TUFF KOTE / ANTI-RUST.	New	60.00	60.00
4	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.	New	180.00	80.00
5	TO CHECK WIRING WITH WATER LEAKAGE TEST.	New	60.00	40.00
6	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR.	New	60.00	40.00
7	TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD.	New	220.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,080.00</b>	<b>2,370.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >