

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 17 OCTOBER 2018

Third Party Insurer: AIG

Vehicle No: SKB7765P

Third Party Veh No: SLE9012M

Model: MERCEDES BENZ E200C GI

Date of Accident: 15 OCTOBER 2018

Chassis: WDD2120482A398872 - 2011

## ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID / <i>mc</i>		\$2,497.50
1	REAR BOOTLID EMBLEM LOGO /		\$55.50
1	REAR BOOTLID EMBLEM E200 / <i>mc</i>		\$83.25
1	REAR BOOTLID EMBLEM CGI /		\$83.25
1	REAR BOOTLID CHROME MOULDING / ?		\$129.50
1	REAR BOOTLID MECHANISM LOCK / <i>BT</i>		\$277.50
1	REAR BOOTLID MECHANISM LOCK STRIKER X <i>Repair</i>		\$425.50
1	REAR BOOTLID WEATHER STRIP / ?		\$181.30
2	REAR BOOTLID HINGE RH/LH X <i>Repair</i>	\$166.50	\$333.00
2	REAR BOOTLID HINGE GARNISH RH/LH X <i>Repair</i>	\$27.75	\$55.50
1	REAR BOOTLID REFLECTOR RH / <i>scr</i>		\$444.00
1	REAR TAILLAMP RH / <i>scr</i>		\$582.75
3	REAR TAILLAMP CLIPS / <i>mc</i>	\$9.00	\$27.00
1	REAR BUMPER / <i>re</i>		\$1,609.50
10	REAR BUMPER CLIPS / <i>mc</i>	\$5.50	\$55.00
6	REAR BUMPER RIVET / <i>mc</i>	\$6.00	\$36.00
1	REAR BUMPER CENTRE CHROME MOULDING / <i>mc</i>		\$175.75
2	REAR BUMPER CHROME MOULDING RH/LH / <i>mc</i>	\$101.75	\$203.50
1	REAR BUMPER TOW HOOK COVER / <i>scr</i>		\$64.75
1	REAR BUMPER LOWER LIP / <i>re</i>		\$499.50
3	REAR BUMPER REVERSE SENSOR / <i>RM 2PC</i>	\$203.50	\$610.50
3	REAR BUMPER REVERSE SENSOR RUBBER SEAL / <i>mc</i>	\$9.25	\$27.75
2	REAR BUMPER SIDE RETAINER RH/LH / <i>mc</i>	\$46.25	\$92.50
1	REAR BUMPER LOWER BRACKET RH / <i>BT</i>		\$18.50
1	REAR BUMPER REINFORCEMENT / <i>BT</i>		\$666.00
1	REAR END PANEL / ?		\$1,239.50
1	REAR END PANEL INNER TOP GARNISH / ?		\$150.00
1	FRONT DRIVER SEAT HEAD REST RH <i>Repair</i> X		\$925.00
1	FRONT DRIVER SEAT BELT RH X		\$1,250.00
1	FRONT PASSENGER SEAT HEAD REST LH X <i>Repair</i>		\$925.00
1	FRONT PASSENGER SEAT BELT LH X		\$1,250.00
1	FRONT BONNET X <i>Repair</i>		\$2,220.00
1	FRONT HEADLAMP LH / ?		\$878.75
1	FRONT GRILLE WITH LOGO / <i>mc</i>		\$1,110.00
1	FRONT BUMPER X <i>Repair</i>		\$1,267.25
10	FRONT BUMPER CLIPS / <i>mc</i>	\$5.50	\$55.00
2	FRONT BUMPER PARKING SENSOR / ?	\$203.50	\$407.00
2	FRONT BUMPER PARKING SENSOR RUBBER SEAL /	\$9.25	\$18.50
1	FRONT BUMPER NUMBER PLATE GARNISH / ?		\$194.25
1	FRONT BUMPER LOWER CENTRE GRILLE / ?		\$92.50

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Branch office : 9A Serangoon North Ave 5 Singapore 554500

Co. Reg. No. 201212455W

Date: 17 OCTOBER 2018

Vehicle No: SKB7765P

Model: MERCEDES BENZ E200C GI

Chassis: WDD2120482A398872 - 2011

**LKK Auto Consultants** hence notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to change without notice  
 • Supplementary item(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Third Party Insurer: **AIG**  
 Third Party Veh No: **SLE9012M**  
 Date of Accident: **15 OCTOBER 2018**

## ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
2	FRONT BUMPER CHROME MOULDING RH/LH / <i>del</i>	\$88.80	\$177.60
1	RADIATOR TOP GARNISH / <i>ORH -</i>		\$138.75
SUB TOTAL			\$21,533.90
Less 10%			-\$2,153.39
PARTS TOTAL			\$19,380.51

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	FRONT NUMBER PLATE WITH CASING / <i>cut</i>		\$70.00
S/N TOTAL			\$70.00

### LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	<i>700</i>	\$1,200.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	<i>1200</i>	\$1,300.00
TO TUFF KOTE / ANTI-RUST	<i>/</i>	\$60.00
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	<i>80</i>	\$180.00
TO CHECK WIRING WITH WATER LEAKAGE TEST	<i>40</i>	\$60.00
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	<i>40</i>	\$60.00
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	<i>150</i>	\$220.00
LABOUR TOTAL		\$3,080.00

PEI TING **TOTAL \$22,530.51**

*7 Days -  
 Unpssm repair.  
 After repair photos.  
 Gino Qiang - 82880282  
 18/10/18*