

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
 LKK
 L/S # 9200/-
 2/10/18
 9 day.
 (LKK)

Qty Particular SSS 4225Z Amount S\$

List Item :

1 pc Front bonnet	638.90	\$ Buc	1,123.20 ✓
1 pc Front bonnet lock	105.60	\$ Trl	197.80 ✓
2 pc Front bonnet hinge @ 76.00		\$ n1	152.00 X
1 pc Front bonnet insulator		\$ re	199.50 ✓
1 pc Front bonnet seal		\$ ne	37.20 ✓
1 pc Front support panel	466.20	\$ Buc/Buc	765.20 ✓
1 pc Front support panel top garnish		\$ B/Born	210.30 ✓
1 pc Front grille	285.40	\$ cr	351.60 ✓
1 pc Front grille emblem		\$ ne	28.40 ✓
1 pc Front grille moulding		\$ cr	291.30 ✓
1 pc Front horn @ 76.30		\$ cr	152.60 lpc
2 pc Front head lamp @ 982.90	765.20 x 2 = 1530.40	\$ cr	1,965.80 ✓
2 pc Front head lamp lower bracket @ 76.80		n/s \$ cr	153.60 lpc
1 pc Front bumper	635.60	\$ n2	1,082.70 ✓
1 pc Front bumper reinforcement	285.40	\$ n2	541.30 ✓
2 pc Front bumper side retainer @ 32.50		\$ Buc	65.00 ✓
1 pc Front bumper top beam		\$ n5	101.20 X
1 pc Front bumper lower grille		\$ n1	123.50 X
2 pc Front bumper fog lamp @ 452.30		\$ n2	904.60 X
2 pc Front bumper fog lamp cover @ 195.60		\$ n1	391.20 X
1 pc Radiator	1485	Buc/ \$ cr	1,284.20 ✓
1 pc Radiator fan motor		\$ n1	656.30 X
1 pc Radiator fan coving		\$ n1	165.20 X
1 pc Radiator fan blade		\$ n1	99.20 X
1 pc Aircond condenser	826.60	Buc/ \$ pu1	1,195.20 ✓
1 pc Aircond fan motor		\$ n1	569.50 X
1 pc Aircond fan coving		\$ n1	164.20 X
1 pc Aircond fan blade		\$ n1	95.20 X
2 pc Front fender @ 685.20		n/s \$ Buc	1,370.40 lpc
2 pc Front fender cowling @ 185.20		\$ n1	370.40 X

11428

9142.4

Continue =

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Not Authorised
 ✓
 L/S # 9220/1
 22/10/18
 9 dy.

Unit Price

Qty Particular Amount S\$

List Item :

1 pc	Rear boot	903.00	body	\$	1,284.70	✓
1 pc	Rear boot lock	145.00	twl	\$	295.40	✓
1 pc	Rear boot lock catch			\$	11	95.20 X
1 pc	Rear boot centre garnish			\$	11	235.90 X
1 pc	Rear boot rubber	166.80		\$	twl	215.30 ✓
2 pc	Rear boot absorber @ 168.10			\$	11	336.20 X
2 pc	Rear boot hinge @ 92.00			\$	11	184.00 X
1 pc	Rear boot emblem (stream)	35.00		\$	ru	55.60 ✓
1 pc	Rear boot inner board	225.30	re/s	\$	cnq	352.60 ✓
1 pc	Rear boot inner pull cable garnish			\$	11	165.20 X
1 pc	Rear boot centre emblem			\$	11	65.02 X
1 pc	Rear boot wiper motor			\$	11	756.80 X
2 pc	Rear fender inner garnish @ 414.00			\$	11	828.00 X
2 pc	Rear tail lamp @ 889.80	338.30 x 2 = 676.60		\$	one	1,779.60 ✓
2 pc	Rear tail lamp panel @ 161.20			\$	2	322.40 X
1 pc	Rear floor panel			\$	2	1,102.30 X
1 pc	Rear floor panel top cover board			\$	2	351.20 X
1 pc	Rear end panel	306.40	body	\$	00	725.30 ✓
1 pc	Rear end panel (lower)	184.50	body	\$	00	365.20 ✓
1 pc	Rear end panel top garnish			\$	twl	170.30 ✓
1 pc	Rear bumper	665.40		\$	00	951.50 ✓
1 pc	Rear bumper top beam			\$	NS	215.20 X
2 pc	Rear bumper side retainer @ 31.70			\$	sel	63.40 ✓
2 pc	Rear bumper lower bracket @ 65.00			\$	sel	130.00 ✓
1 pc	Rear bumper towing cover	28.00		\$	twl	64.40 ✓
2 pc	Rear number plate lamp @ 48.00			\$	11	96.00 X
1 pc	Rear exhaust silencer			\$	11	984.50 X
2 pc	Rear exhaust rubber @ 38.00			\$	11	76.00 X
List Item Total :				\$	27,075.02	
Discount 20 % :				\$	5,415.00	
				\$	21,660.01	

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Qty	Particular	Amount S\$
-----	------------	------------

B / F \$ 21,660.01

Special Nett Item :

1 pc	Front number plate	\$ <i>sent</i>	45.00	<i>40</i>
3 pc	Front grille clips @ 5.00	\$ <i>11</i>	15.00	<i>X</i>
12pc	Front bonnet insulator clips @ 5.00	\$ <i>rec</i>	60.00	<i>40</i>
8 pc	Front bumper lower clips @ 5.00	\$ <i>rec</i>	40.00	<i>✓</i>
10pc	Rear boot inner board clips @ 5.00	\$ <i>rec</i>	50.00	<i>40</i>
1 pc	Rear boot windscreen sealant	\$ <i>rec</i>	100.00	<i>40</i>
4 pc	Rear end panel top garnish clips @ 5.00	\$ <i>11</i>	20.00	<i>X</i>
1 pc	Rear end panel sealant	\$ <i>rec</i>	80.00	<i>50</i>
12pc	Rear fender inner garnish clips @ 5.00	\$ <i>11</i>	60.00	<i>X</i>
1 pc	Rear number plate	\$ <i>11</i>	45.00	<i>X</i>
1 pc	Rear reverse camera	\$ <i>11</i>	850.00	<i>X</i>
Special Nett Item :		\$	1,365.00	

Labour Charge :

To check wiring	\$	200.00	<i>30</i>
Tuffkote	\$	200.00	<i>120</i>
Towing	\$ <i>11</i>	120.00	<i>X</i>
Remove and replace aircond condenser and refill gas	\$	160.00	<i>100</i>
Remove and replace radiator	\$ <i>11</i>	100.00	<i>X</i>
Remove and refix rear boot windscreen	\$	160.00	<i>120</i>
Remove and refix rear boot garnish item	\$	200.00	<i>60</i>
Remove and replace rear exhaust pipe	\$ <i>11</i>	160.00	<i>X</i>
Remove and refix upholstery and cushion seat	\$	160.00	<i>80</i>
Remove and replace reverse camera	\$ <i>11</i>	160.00	<i>X</i>
Remove and replace spare part and panel beating	\$	3,000.00	<i>1200</i>
To spray painting and etc	\$	3,000.00	<i>1800</i>
Labour Charge Total :	\$	7,620.00	

Singdollars :Thirty Thousand Six Hundred Fourty Five And Cents Ten Only .

E & O .E

Total Amount :

\$ 30,645.01

129024
1034