

ASS. REC. BY:

REF:

CS/FCI/8019123/Ktd3e2

Special Instruction:

Surveyor:

Kenneth

CWS

ASSIGNMENT (Office)

From (Person):

Lurene Jw

of

FCI

Date/Time:

19/10/18 7:54pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 910D

Insured:

SHD 8830C

at Workshop m/s

Btt Auto Services

Tel:

6559 8944

of

BKI, Bin Ming Ind. Est sec C # 01-115

Policy No:

Claim No:

D1800 75 84 MPST

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

9:49am @ 22/10/18

Person Contacted:

jarelyn

Vehicle:

IN (UT)

Date/Time	Action/Instruction (✓) Estimate
	SLJ 910D - x
	SHD 8830C - x
23/10@ 3:56pm	Revised preli advise via email
	Part by Part \$36571- (Red: 596760; 62%)

ASS. REC. BY:

REF: 1021

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

WP 1-B.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

23/10

File pass to Catherine

RECEIVED 11 DEC 2018

Date/Time, File Pass to?

1) 10/12 Typist

Date/Time, File Return to?

2)

☐ : Prell. Report  
☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trlp:

Add Fee:

- ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech Invs (\$)  
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

170
50
50+50
19
339

Report Format :

Lump Sum / I.B. (\$) :

TP  
3657

Veh No:

SLJ910D

Yr Regn:

02, 10

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

M. C180

Hamp C.C.

1796

Colour:

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

107879

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W00 2040 452A 358877

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

16/10/18

D.O.I.

22/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	18-10-2018	<b>Our Ref No.</b> D18007584MFSH
<b>Accident Date</b>	16-10-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD8830C	<b>Third Party Vehicle.</b> SLJ910D
<b>Survey Location</b>	BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115	
<b>Contact Person.</b>	JACELYN LOH	
<b>Contact No.</b>	65598944/ 0	<b>Fax No.</b> 62692404
<b>Survey Type</b>	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	BH AUTO SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	LURENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Tuesday, 23 October 2018 3:56 PM  
**To:** Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments  
**Cc:** 'Lurene Jaw'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18007584MFSH/1  
**Attachments:** PRELI ADVISED SLJ 910D.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLJ 910D**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Monday, 22 October 2018 9:51 AM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Lurene Jaw' <[LureneJaw@msfirstcapital.com.sg](mailto:LureneJaw@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18007584MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 19 October 2018 7:54 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Lurene Jaw <[LureneJaw@msfirstcapital.com.sg](mailto:LureneJaw@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D18007584MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007584MFSH

Date: 23/10/2018

Our Ref: CS/FCI18019123/Ktd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 910D

Please be informed that we had conducted the inspection of the abovementioned vehicle 18/10/2018 at the premises of M/s BH Auto Services and have the following to report: -

Workshop Estimate Amount	: S\$ 10,234.12
Revised Estimate Amount	: S\$ 2,406.00
"Check" Items Amount	: S\$ 571.50
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Owner ID:

### Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

### Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

### Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

**Total Rebate Amount:**

Singapore NRIC

0399F

SLJ910D

No

18 Oct 2018

MERCEDES BENZ

C180K

Grey

2009

27191031302617

WDD2040452A358877

115.0 kW (154 bhp)

\$36,976.00

01 Feb 2010

01 Feb 2010

3

\$36,976.00

Yes

31 Jan 2020

\$20,336.00

31 Jan 2020

A - Car (1600cc & below)

10

\$20,501.00

\$2,634.00

**\$22,970.00**

The information contained herein is correct as at 18 Oct 2018

OK

## Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Jun 2017 Mercedes Benz C180 Avantgarde Offer \$150800



In House Finance & Low  
Downpayment \$15,800! C&C  
Warranty! High ARF, 1 Owner  
Only  
**Speedo Motoring** StarAd



click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

[Post an Ad](#)

Advertiser Login

## Ways of Selling

Browse by Category ▼

Sort by Date Posted ▼

20 results/page

13 vehicles

Mercedes-Benz C180

Advanced Search 

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>Mercedes-Benz C180</b>	Any	Any	<b>2010</b>	Any	Any	Any	<b>Available</b>
	<b>Mercedes-Benz C-Class C180 CGI</b>	<b>\$45,000</b>	<b>\$13,240 /yr</b>	<b>22-Sep-2010</b>	<b>1,796 cc</b>	<b>140,159 km</b>	<b>Luxury</b>	<b>Available</b>
<p>No Dealers/Consignment Agents Allowed. Just Change Tyres, Headlights And More With Receipts To Proof. Sleek And Well Maintained C180 Up To Date. Hurry, Call Me Now.</p> <p>Posted: 18-Oct-2018    Tags: 2010 Mercedes-Benz C180, 2010 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz</p>								
	<b>Mercedes-Benz C-Class C180 CGI</b>	<b>\$40,800</b>	<b>\$12,540 /yr</b>	<b>01-Jul-2010</b>	<b>1,796 cc</b>	<b>-</b>	<b>Luxury</b>	<b>Available</b>
<p>Cheapest In The Market! CGI Facelifted Model! Very Well Maintained By Previous Owner! Excellent Condition! Warranty Provided! STA Evaluation Welcome! View To Believe! High Trade In For Your Used Car! ...</p> <p>ST Carz Pte Ltd</p> <p>Posted: 18-Oct-2018    Tags: 2010 Mercedes-Benz C180, 2010 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz</p>								
	<b>Mercedes-Benz C-Class C180 CGI</b>	<b>\$45,000</b>	<b>\$13,070 /yr</b>	<b>01-Oct-2010</b>	<b>1,796 cc</b>	<b>118,081 km</b>	<b>Luxury</b>	<b>Available</b>
<p>Great Deal In Town. Best Selling C180 CGI Model. Buy And Drive With Class. Smooth Driving And Well Kept Interior. No Further Repairs Needed. View To Believe. High Trade In Available. Up To 80% Bank Lo...</p> <p>Posted: 17-Oct-2018    Tags: 2010 Mercedes-Benz C180, 2010 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz</p>								
	<b>Mercedes-Benz C-Class C180 CGI</b>	<b>\$43,500</b>	<b>\$12,100 /yr</b>	<b>13-Oct-2010</b>	<b>1,796 cc</b>	<b>-</b>	<b>Luxury</b>	<b>Available</b>
<p>Rare CGI Engine That Makes The Car Drive Much Smoother Than Kompressor. Very Well Maintained Wear And Tear Replaced With Receipt To Prove. Cash Back \$19458. Flexible Loan Packages. Come View It And Ju...</p> <p>Posted: 13-Oct-2018    Tags: 2010 Mercedes-Benz C180, 2010 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz</p>								
<p><b>GET YOUR COE RENEWAL LOAN</b></p> <p><b>Is your COE expiring? Let us help you renew it!</b></p> <p>Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.</p>								
	<b>Mercedes-Benz C-Class C180K</b>	<b>\$37,500</b>	<b>\$13,120 /yr</b>	<b>31-Mar-2010</b>	<b>1,597 cc</b>	<b>-</b>	<b>Luxury</b>	<b>Available</b>
<p>Sporty Mercedes Benz C180 Black On Black. Well Maintained. 100% Accident Free. Owner Upgraded To New CLA180. Arrange For Test Drive Now. 3K To 5K Drive Away!</p> <p>Posted: 13-Oct-2018    Tags: 2010 Mercedes-Benz C180K, 2010 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz</p>								
	<b>Mercedes-Benz CLC-Class CLC180K</b>	<b>\$31,800</b>	<b>\$9,800 /yr</b>	<b>01-Apr-2010</b>	<b>1,796 cc</b>	<b>167,000 km</b>	<b>Sports</b>	<b>Available</b>
<p>Flexible Repayment In-House Financing! Come With Nice Number Plate 5755. C&amp;C Unit. Extremely Fuel Friendly For A Luxury Car. Spacious, Quiet And Comfortable Cabin For 4 Passengers To Travel In Top Not...</p> <p>Quality Motor Trading Enterprise</p> <p>Posted: 13-Oct-2018    Tags: 2010 Mercedes-Benz CLC180K, 2010 mercedes-benz clc180k, Mercedes-Benz CLC180K, mercedes-benz clc180k, Mercedes-Benz, CLC180K, clc180k, Used Mercedes-Benz</p>								

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/10/2018 19:11
Date Of Accident	16/10/2018 20:40
Exact Location Of Accident	ANSON ROAD - SPRINGLEAF MCDONALD DRIVETHRU
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ910D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	POH BUAY HOON
NRIC No	S1590399F
Email Address	CLIM0126@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90081188
Alternative Phone No	OFFICE-90081188

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180K-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA362277/1
Cover Note Number	

### Driver

Name of Driver	POH BUAY HOON
NRIC No	S1590399F
Date Of Birth	26/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	24/07/1987
Driving Experience	31 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90081188
Fax Number	
Contact Number	OFFICE-90081188
EMail Address	CLIM0126@GMAIL.COM



Address	68 JALAN GELENGGANG SINGAPORE 578242
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD8830C
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	FRONT PORTION
Vehicle Category	TAXI
Name of Driver	CHUA YONG TIAN JUSTIN
NRIC/Passport Number	S7516628A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**



Springleaf Mac Donald at  
Anson Road - Drive Thru  
Vehicle A - SLJ 910D  
Vehicle B - SHD 8830C


**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**


My car SLJ 910D was station in front of the window of Macdonald (Springleaf Tower at Anson Road) Drive Thru' on 16 OCT 18 at 2040 waiting for my order to be dispense to me. Suddenly, I felt a "Bang" on the rear of my car. I was shocked & alighted from my car & realised vehical B collided onto the rear of my car.


Vehicle A - SLJ 910D  
Vehicle B - SHD 8830C

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: Ngai Kar Kit  
NRIC/FIN No.: G2743331L

17 / 10 / 2018 @ 1815 HRS

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636  
Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT  
FIRST CAPITAL INSURANCE LTD  
30 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877  
TEL : 6507 3848 FAX : 6507 3849

DATE : 19/10/2018  
PAGE : 1 OF 2

*Not Authorised*  
*I.B.I*  
*Refusing B4 paint*

ACCIDENT REPAIR ON : SLJ910D  
MODEL : MERCEDES BENZ C180K  
POLICY NO : GA362277/1  
CHASSIS NO : WDD2040452A358877  
YEAR OF MANUFACTURE : 2009  
DATE / TIME OF ACCIDENT : 16/10/2018@20:40HRS  
LOCATION : ALONG ANSON ROAD- SPRINGLEAF MACDONALD DRIVE THRU  
THIRD PARTY VEHICLE NO : SHD8830C

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT	
1	REAR BOOTLID	1	<i>7K</i>	\$ 1,520.00	X
2	REAR BOOTLID "LOGO" EMBLEM	1	<i>22</i>	\$ 46.00	X
3	REAR BOOTLID "C180" EMBLEM	1	<i>22</i>	\$ 78.00	X
4	REAR BOOTLID "C&C" EMBLEM	1	<i>22</i>	\$ 48.00	X
5	REAR BOOTLID "KOMPRESSOR" EMBLEM	1	<i>22</i>	\$ 100.00	X
6	REAR BOOTLID OUTER CHROME MOULDING	1	<i>52</i>	\$ 190.00	X
7	REAR BOOTLID MECHANISM LOCK	1	<i>7K</i>	\$ 270.00	X
8	REAR TAILLAMP LH	1	<i>52</i>	\$ 545.00	X
9	REAR TAILLAMP RH	1	<i>52</i>	\$ 545.00	X
10	REAR TAILLAMP LOWER BRACKET LH	1	<i>CM / 52</i>	\$ 65.00	X
11	REAR TAILLAMP LOWER BRACKET RH	1	<i>CM / 52</i>	\$ 65.00	X
12	REAR BUMPER	1	<i>CM / 1400</i>	\$ 1,460.00	X
13	REAR BUMPER SIDE RETAINER LH	1	<i>0.1</i>	\$ 35.00	X
14	REAR BUMPER SIDE RETAINER RH	1	<i>0.1</i>	\$ 35.00	X
15	REAR BUMPER REVERSE SENSOR	<i>Not</i> 4	\$ 185.00	\$ 740.00	X
16	REAR BUMPER OUTER CHROME MOULDING CENTER	1		\$ 105.00	X
17	REAR BUMPER OUTER CHROME MOULDING LH	1	<i>22</i>	\$ 95.00	X
18	REAR BUMPER OUTER CHROME MOULDING RH	1	<i>22</i>	\$ 95.00	X
19	REAR BUMPER TOW HOOK COVER	1		\$ 42.00	X
20	REAR BUMPER REINFORCEMENT	1	<i>12</i>	\$ 635.00	X
21	REAR END PANEL	1	<i>7K</i>	\$ 1,170.00	X
22	REAR END PANEL INNER TOP GARNISH	1	<i>52</i>	\$ 110.00	X
		SUB TOTAL		\$ 7,994.00	
		LESS 10%		\$ (799.40)	
		PARTS TOTAL		\$ 7,194.60	

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT	
1	REAR BOOTLID OUTER CHROME MOULDING CLIPS	<i>22</i> 4	\$ 5.00	\$ 20.00	X
2	REAR BUMPER CLIPS	<i>22</i> 10	\$ 5.00	\$ 50.00	X
3	REAR BUMPER RIVET	<i>22</i> 10	\$ 5.00	\$ 50.00	X
4	REAR END PANEL INNER TOP GARNISH CLIPS	<i>22</i> 4	\$ 5.00	\$ 20.00	X
		PARTS TOTAL		\$ 140.00	

*Supplementary*  
1) ~~Rear Bumper Inner Bracket~~ - *CM* \$ 130.00 ✓

ACCIDENT REPAIR ON : SLJ910D

MODEL : MERCEDES BENZ C180K

POLICY NO : GA362277/1

CHASSIS NO : WDD2040452A358877

YEAR OF MANUFACTURE : 2009

DATE / TIME OF ACCIDENT : 16/10/2018@20:40HRS

LOCATION : ALONG ANSON ROAD- SPRINGLEAF MACDONALD DRIVE THRU

THIRD PARTY VEHICLE NO : SHD8830C

DATE : 19/10/2018

PAGE : 2 OF 2

LABOUR CHARGES FOR REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 1,000.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 700.00
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.	\$ 80.00
4	REMOVE AND REFIX REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS.	\$ 120.00
5	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00
6	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 250.00
LABOUR TOTAL		\$ 2,230.00

2501

2501

601

X

X

TOTAL PARTS & LABOUR	\$ 9,564.60
GST 7%	\$ 669.52
GRAND TOTAL	\$ 10,234.12
ESTIMATE REPAIR DURATION	6 DAYS

YOURS SINCERELY,

ESTIMATOR : KIT

TEL : 8405 4058

FAX : 6269 2404

EMAIL : karkit.ngai@bhauto.com.sg

Parts : \$3300.00 - 1070 2 day 2997.00

8/next : \$100.00

LB : \$560.00

\$3657.00 ✓ ok

SURVEY ATTENDED BY :

NAME	Kenneth
COMPANY	UKK
DATE	22/10/18
TIME	1-20pm
TEL	96910663
EMAIL	

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT

FIRST CAPITAL INSURANCE LTD

30 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL : 6507 3848 FAX : 6507 3849

DATE : 19/10/2018

PAGE : 1 OF 2

*Not Authorized  
I.B.I  
Recovery B4 paint*

ACCIDENT REPAIR ON : SLJ910D

MODEL : MERCEDES BENZ C180K

POLICY NO : GA362277/1

CHASSIS NO : WDD2040452A358877

YEAR OF MANUFACTURE : 2009

DATE / TIME OF ACCIDENT : 16/10/2018@20:40HRS

LOCATION : ALONG ANSON ROAD- SPRINGLEAF MACDONALD DRIVE THRU

THIRD PARTY VEHICLE NO : SHD8830C

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT	
1	REAR BOOTLID	1	<i>fl</i>	\$ 1,520.00	X
2	REAR BOOTLID "LOGO" EMBLEM	1	<i>na</i>	\$ 46.00	X
3	REAR BOOTLID "C180" EMBLEM	1	<i>na</i>	\$ 78.00	X
4	REAR BOOTLID "C&C" EMBLEM	1	<i>na</i>	\$ 48.00	X
5	REAR BOOTLID "KOMPRESSOR" EMBLEM	1	<i>na</i>	\$ 100.00	X
6	REAR BOOTLID OUTER CHROME MOULDING	1	<i>ln</i>	\$ 190.00	X
7	REAR BOOTLID MECHANISM LOCK	1	<i>fl</i>	\$ 270.00	X
8	REAR TAILLAMP LH	1	<i>ln</i>	\$ 545.00	X
9	REAR TAILLAMP RH	1	<i>ln</i>	\$ 545.00	X
10	REAR TAILLAMP LOWER BRACKET LH	1	<i>ln</i>	\$ 65.00	X
11	REAR TAILLAMP LOWER BRACKET RH	1	<i>ln</i>	\$ 65.00	X
12	REAR BUMPER	1	<i>CM / Bn</i>	\$ 1,460.00	✓
13	REAR BUMPER SIDE RETAINER LH	1		\$ 35.00	X
14	REAR BUMPER SIDE RETAINER RH	1		\$ 35.00	X
15	REAR BUMPER REVERSE SENSOR	<i>Not</i> 4	\$ 185.00	\$ 740.00	4+
16	REAR BUMPER OUTER CHROME MOULDING CENTER	1		\$ 105.00	✓
17	REAR BUMPER OUTER CHROME MOULDING LH	1	<i>na</i>	\$ 95.00	✓
18	REAR BUMPER OUTER CHROME MOULDING RH	1	<i>na</i>	\$ 95.00	✓
19	REAR BUMPER TOW HOOK COVER	1		\$ 42.00	X
20	REAR BUMPER REINFORCEMENT	1		\$ 635.00	7
21	REAR END PANEL	1	<i>fl</i>	\$ 1,170.00	X
22	REAR END PANEL INNER TOP GARNISH	1	<i>ln</i>	\$ 110.00	X
SUB TOTAL				\$ 7,994.00	
LESS 10%				\$ (799.40)	
PARTS TOTAL				\$ 7,194.60	

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT	
1	REAR BOOTLID OUTER CHROME MOULDING CLIPS	<i>na</i> 4	\$ 5.00	\$ 20.00	X
2	REAR BUMPER CLIPS	<i>na</i> 10	\$ 5.00	\$ 50.00	✓
3	REAR BUMPER RIVET	<i>na</i> 10	\$ 5.00	\$ 50.00	✓
4	REAR END PANEL INNER TOP GARNISH CLIPS	<i>na</i> 4	\$ 5.00	\$ 20.00	X
PARTS TOTAL				\$ 140.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**ACCIDENT REPAIR ON : SLJ910D**  
**MODEL : MERCEDES BENZ C180K**  
**POLICY NO : GA362277/1**  
**CHASSIS NO : WDD2040452A358877**  
**YEAR OF MANUFACTURE : 2009**  
**DATE / TIME OF ACCIDENT : 16/10/2018@20:40HRS**  
**LOCATION : ALONG ANSON ROAD- SPRINGLEAF MACDONALD DRIVE THRU**  
**THIRD PARTY VEHICLE NO : SHD8830C**

**DATE : 19/10/2018**  
**PAGE : 2 OF 2**

LABOUR CHARGES FOR REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 1,000.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 700.00
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.	\$ 80.00
4	REMOVE AND REFIX REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS.	\$ 120.00
5	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00
6	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 250.00
LABOUR TOTAL		\$ 2,230.00

250/  
 250/  
 60/  
 X  
 X  
 X

TOTAL PARTS & LABOUR	\$ 9,564.60
GST 7%	\$ 669.52
<b>GRAND TOTAL</b>	<b>\$ 10,234.12</b>
<b>ESTIMATE REPAIR DURATION</b>	<b><del>6</del> DAYS</b>

2 day,

YOURS SINCERELY,



ESTIMATOR : KIT  
 TEL : 8405 4058  
 FAX : 6269 2404  
 EMAIL : karkit.ngai@bhauto.com.sg

**SURVEY ATTENDED BY :**

NAME	Kenneth
COMPANY	KKK
DATE	22/10/18
TIME	1-20pm
TEL	96910663
EMAIL	




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18019123/Ktd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-12-2018		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 8830C	Veh. Inspected	SLJ 910D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007584MFSH	Excess (\$)	0.00	
Assign From	LURENE JAW	Assign Date	19/10/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ C180K (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WDD2040452A358877	Colour	METALLIC GREY	
Odometer	107819	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45Z R17	MICHELIN	7 mm	
L/H Front Tyre	225/45Z R17	MICHELIN	7 mm	
R/H Rear Tyre	225/45Z R17	MICHELIN	7 mm	
L/H Rear Tyre	225/45Z R17	MICHELIN	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/10/2018	Inspection Date	22/10/2018	
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 910D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOTLID	TO REPAIR SEE LABOUR	1,520.00	-
1	REAR BOOTLID "LOGO" EMBLEM	NOT NECESSARY	46.00	-
1	REAR BOOTLID "C180" EMBLEM	NOT NECESSARY	78.00	-
1	REAR BOOTLID "C&C" EMBLEM	NOT NECESSARY	48.00	-
1	REAR BOOTLID "KOMPRESSOR" EMBLEM	NOT NECESSARY	100.00	-
1	REAR BOOTLID OUTER CHROME MOULDING	SERVICEABLE	190.00	-
1	REAR BOOTLID MECHANISM LOCK	TO REPAIR SEE LABOUR	270.00	-
1	REAR TAILLAMP LH	SERVICEABLE	545.00	-
1	REAR TAILLAMP RH	SERVICEABLE	545.00	-
1	REAR TAIL LAMP LOWER BRACKET LH	CRACKED	65.00	65.00
1	REAR TAIL LAMP LOWER BRACKET RH	CRACKED	65.00	65.00
1	REAR BUMPER	CRACKED / BUCKLED	1,460.00	1,460.00
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	35.00	35.00
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	35.00	35.00
4	REAR BUMPER REVERSE SENSOR @\$185.00	DENTED	740.00	740.00
1	REAR BUMPER OUTER CHROME MOULDING CENTER	NECESSARY	105.00	105.00
1	REAR BUMPER OUTER CHROME MOULDING LH	NECESSARY	95.00	95.00
1	REAR BUMPER OUTER CHROME MOULDING RH	NECESSARY	95.00	95.00
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	42.00	-
1	REAR BUMPER REINFORCEMENT	BENT	635.00	635.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,170.00	-
1	REAR END PANEL INNER TOP GARNISH	SERVICEABLE	110.00	-
	LESS 10% DISCOUNT		-799.40	-333.00
			7,194.60	2,997.00
<b><u>SPECIAL NETT ITEMS</u></b>				
4	REAR BOOTLID OUTER CHROME MOULDING CLIPS @\$5.00 (SN)	NOT NECESSARY	20.00	-
10	REAR BUMPER CLIPS @\$5.00 (SN)	NECESSARY	50.00	50.00

Report Ref No. CS/FCI18019123/Ktd3e2



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	REAR BUMPER RIVET @\$5.00 (SN)	NECESSARY	50.00	50.00
4	REAR END PANEL INNER TOP GARNISH CLIPS @\$5.00 (SN)	NOT NECESSARY	20.00	-
			140.00	100.00
	<b>LABOUR</b>			
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR BOOTLID MECHANISM LOCK AND REAR END PANEL.		1,000.00	250.00
	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.		700.00	250.00
	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.		80.00	60.00
	REMOVE AND REFIX REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS.	NOT NECESSARY	120.00	-
	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	NOT NECESSARY	80.00	-
	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	NOT NECESSARY	250.00	-
			2,230.00	560.00
<b>GRAND TOTAL</b>			<b>9,564.60</b>	<b>3,657.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,657.00</b>

Report Ref No. CS/FCI18019123/Ktd3e2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.