From (Person): DUTH or of FCI Date/Time: 19/10/180/402 Estimated Cost: DOM: TP: WS: TP RES: OD RES: EVA / INV / MV / CS To Inspect Vehicle No: SJM 88332 Insured: SHC 23979 at Workshop m/s Promium Automobiles Tel: G768 99 11 of 55 Ubi Pacadl Policy No: Claim No: D18007502 MFS+1 Sum Insured: Excess: Make of Veh: D.O.A. 13/10/18 CA / REV / REP. / REV 24 HRS (DS) Date/Time: 10:11cm 22/10/18 Person Contacted: JUMES Vehicle IN/10/11 Date/Time: Action/Instruction (Estimate SJM 88337 - CC3/A/G/180/18850 / As D. 23/10/18 23/10/18 0 17:34 p.m. revised PA to Jame Yong Via enal.	From (Person): fourth or of FCI Date/Time: 19110/1868 Estimated Cost: Bill to: OD/TP+)WS+TP RES/OD RES/EVA/INV/MV7CS To Inspect Vehicle No: SJM 8833Z Insured: SHC 239 at Workshop m/s Promium Automobiles Tel: 6768 9911 of 55 Ubi Rocal Policy No: Claim No: D18007502 MFS+1 Sum Insured: Excess: Make of Veh:	
Estimated Cost: ODE TP / WS/TP RES / OD RES / EVA / INV / MV / CS To Inspect Vehicle No: SIM 8833Z Insured: SHC 23979 at Workshop m/s Pomium Automobiles Tel: 6768 99 11 of 55 Ubi Pocod Policy No: Claim No: D18007502 MFS+† Sum Insured: Excess: Make of Veh: (Client's Record) CA / REV / REP. / REV 24 HRS (DS) Date/Time: 10-11000 20 1018 Person Contacted: Date/Time: Action/Instruction () Estimate SIM 88337 - CC3 Alg 8018850 / Als b Date/13 Out	Estimated Cost: OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS To Inspect Vehicle No: SJM 8833Z Insured: SHC 239 at Workshop m/s Policy No: Solid Poccol Policy No: Sum Insured: Excess: Make of Veh: Bill to: SHC 239 Claim No: D18007502MFSH DOA 1310118	179
To Inspect Vehicle No: SIM 88332 Insured: SHC 23979 at Workshop m/s Promium Automobiles Tel: 6768 9911 of	To Inspect Vehicle No: SJM 8833Z Insured: SHC 239 at Workshop m/s Promium Automobiles Tel: 6768 99 11 of 55 ubi Rocal Policy No: Claim No: D18007502 MFSH Sum Insured: Excess: Make of Veh: DOA 1310118	79
at Workshop m/s Promium Automobiles Tel: 6768 9911 of	at Workshop m/s Premium Automobiles Tel: 6768 99 11 of	79
Policy No: Claim No: D.18007502MFSH Sum Insured: Excess: D.O.A. 131(0)18 CA / REV / REP. / REV 24 HRS (DS) Date/Time: 10:11cm(0) => 16/18 Person Contacted: JUMLS Vehicle INJOUT Date/Time: Action/Instruction () Estimate SIM 88337 - CC3/A/G/8018850/ASD DATE/Time Action/Instruction () Estimate	of	
Policy No: Claim No: D.18007502MFSH Sum Insured: Excess: D.O.A. 131(0)18 CA / REV / REP. / REV 24 HRS (DS) Date/Time: 10-11cm(2) 201618 Person Contacted: UMLS Vehicle-IN/OUT Date/Time: Action/Instruction () Estimate SIM 88337 - CC3/A1G18018850/ASD D18007502MFSH H.O.D. Endorsement: Vehicle-IN/OUT Date/Time: Action/Instruction () Estimate	of	
Policy No: D18007502MFSH Sum Insured: Excess: D.O.A. 131018 Make of Veh: D.O.A. 131018 Chient's Record: D.O.A. 131018 CA / REV / REP. / REV 24 HRS (DS) H.O.D. Endorsement: Date/Time: 10.11cm@ 201618 Person Contacted: Jumes Vehicle INJOUT Date/Time Action/Instruction () Estimate SIM 88337 - CC3/A1G18018850/ASD Data/1310/20	Policy No: Claim No: D18007502 MFS+1 Sum Insured: Excess: D0A 1310118	
Make of Veh: Client's Record) CA / REV / REP. / REV 24 HRS CDS Date/Time: 10-11cm@ 20/10/18 Person Contacted: Jumes Vehicle-IN/OUT Date/Time: Action/Instruction () Estimate SIM 88337 - CC3/A/G/80/8850/ASD DOO: 13/10/18 Date/Time Action/Instruction () Estimate	Sum Insured: Excess: Make of Veh: DOA 13 10 18	
CA / REV / REP. / REV 24 HRS (DS) Date/Time: 10:11cm@ 20 10 18 Person Contacted: Jumes Vehicle INJOUT Date/Time Action/Instruction () Estimate SIM 88337 - CC3/A/G/80/8850/ASD Date/Time Action/Instruction () Estimate	Make of Veh: D.O.A. 13/0/18	
CA / REV / REP. / REV 24 HRS (DS) Date/Time: 10.11cm@ 2010/18 Person Contacted: 10.11cm Date/Time: Action/Instruction () Estimate SIM 88 337 - CC3/A/G/80/8850/ASD Date/Time Sim 88 337 - CC3/A/G/80/8850/ASD		
Date/Time Action/Instruction () Estimate SIM 88337 - CC3/A/G/8018850/ASD Daz:13/10/20	CA / REV / REP. / REV 24 HRS CDS	
SIM 8833Z-CC3/AIGI8018850/ASB 32A:13/10/20	Date/Time: 10.11cm@ 20/10/18 Person Contacted: Yumes Vehicle_IN_10UT	
SIM 88337-CC3/AIGI8018850/ASD 2002/3/10/20	Date/Time Action/Instruction () Estimate	
23/10/18 & 17:37 pm revised PA to Jame Yong via enal.		0/206
	23/10/18 & 17:37 pm revised PA to Jame Yong via en	10/.
-		

ASSIGNMENT Vi Eagn 208 Inc. SIM 88332 Type: Mcol M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or OD / TP / WS / TP RES / OD RES / EVA / INV / MV Audi AS SB 1984. Make: To inspect Vehicle No. Insured / Std / NI / NA Bleval . A/C: Colour at Workshop m/s T/Radio_Insured / Std / NI / NA 6148. Sp.Reading Eng/No: WAUZZZF58JA09832Z C/No: Palicy No. Gen. Cond. Good / Fair / Poor / Burnt Claims No. Steering: Ingrafer / Jammed / Leaked / Burnt or Sum Insured Brake: Incoder / Jammed / Leaked / Burnt or (Client's Record) Modi Nil / S/Rim / STD A/Rim or Make of Veb: 245/40R18. Tyre Size 245/40818. (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FR / SUMI / M/S Remark: The veh had commenced its repair at the time of inspection. TOYO / YOKO or Rear Front Bal, or Market Value: HOY . R/Bal. R/Bal. Consistent?: Yes or No IDAC Accident Rport: L/Bal 06 L/Bal. mm Consistent?: Yes or No GIA / PR Seen: D.O.A. Res. Yes or No Premium, Survey held at 3 Val : Yes or No Lum Sum: Des. of Damages : Frt Regr-/ O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision Person Contacted Date: Action / Instruction Date / Time 19/12/18 Confirmed P/P \$7,692.70 @ 3 days with Advisor (\$2,679.30 Red - 26%) RECEIVED 2 0 DEG 2018 Days Of Repair: Preli. Report Survey Fee 170 Resurvey No. of Trip: Final Report 50 Transportation 50 Site Insp (\$

Add Fee: 22 Inforcioso (\$ Tech Invs (\$ Report Format: Lump Sum / LB & (\$ 7.692.70

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18007502MFSH

Date: 23 October 2018

Our Ref: CS/FCI18019125/Asd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJM 8833Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/10/2018 at the premises of M/s Premium Automobiles Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	10,222.00	
Revised Estimate Amount	: SS	5,055.00	
"Check" Items Amount	: SS	3,351.00	
Market Value	: S\$		
LTA Reimbursement Value	: <u>SS</u>		
Nett Value	: <u>S\$</u>		

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent. Repair days: 3 Days

Yours faithfully, Adrian Ling Automotive Assessor



MS First Capital Insurance Limited to Reg. No. 1950001050 051 Reg. No. Mc-0001070-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims 8 Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

16-10-2018

Our Ref No. D18007502MFSH

Accident Date

13-10-2018

Claim Type. Third Party

Insured Vehicle

SHC2397G

Third Party Vehicle. SJM8833Z

Survey Location

55 UBI ROAD 1

Contact Person.

JEFFERY TAN

Contact No.

63882323/67689911

Fax No. 68411183

Survey Type

DIRECT SETTLEMENT:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

PREMIUM

AUTOMOBILES PTE LTD

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

JOANNEY

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Thursday, 20 December 2018 10:11 AM

To:

'Carrine Leong'

Cc:

jiayee.yap@premiumauto.com.sg; 'Claims Dept'; Adrian Ling (LKKAuto); SUR

Subject:

RE: FINAL REVISION - SJM8833Z - TP FIRSTCAP - SURVEYED 17 OCT 18

Dear Carrine,

Confirmed final fig of \$ 7,692.70 (part by part) @ 3 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong < carrine.leong@premiumauto.com.sg>

Sent: Friday, 14 December 2018 3:20 PM

a@lkkauto.com>

Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>

Subject: RE: FINAL REVISION - SJM8833Z - TP FIRSTCAP - SURVEYED 17 OCT 18

Hi Adrian and all,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle. Revised estimate was mailed to you on 29 Nov 2018.

We sincerely appreciate your early closure.

Thanks & Best Regard Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

[x]	

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Thursday, 29 November, 2018 4:15 PM

To: Adrian Ling <adrianling@lkkauto.com>; cs-a@lkkauto.com; admin-a@lkkauto.com; Carrine Leong

<carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing

<claims@premiumauto.com.sg>

Subject: FINAL REVISION - SJM8833Z - TP FIRSTCAP - SURVEYED 17 OCT 18

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$7692.70 @ 3 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Tuesday, 23 October 2018 5:37 PM

To:

'Joanne Yong Lai fong'; 'CWS Motor Claims'

Cc:

SUR; assignments; Admin-D (LKKAuto)
RE: SURVEY ASSESSMENT - D18007502MFSH/1

Subject: Attachments:

SJM 8833Z - Preli Advise .pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SJM 8833Z.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Monday, 22 October 2018 10:33 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18007502MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Friday, 19 October 2018 4:22 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong

<Joanneyong@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18007502MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

This email has been checked for viruses by AVG antivirus software.
www.avg.com



IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

		ADDE	NDUM	
(A)	PARTICULARS OF PE	RSON MAKING THE AMENDM	RENTS:	
	Original Report No	MPA 118133411	Vehicle Registration No.	SJM 6033 Z
		Diana Ow Chay Chee	NRIC/FIN/Passport No :	
		hicle Owner) (*) Please delete		
		186 Hill view Avenu		Singapore(669598
	Address	190 1-11111	Mobile No : 98182	
	Contact (Tei)		Mobile No. : 4 5103	
	Email Address	Diana. OW @ Premiumaut	o-com-og	
	Date of Accident	18/10/2018	Time of Accident :	14:10
	Place of Accident	Jalan Bulid Merch		
		MC		
	Insurance Company			
	I would like	to amond from class	ming Own policy to	third party
	Policyholder / Davrei	's Signature	Reporting Centre Per	sonnei's Signature
	Date: 18/10/18	50 <u>8</u>	Name: Ton Frys	4poppes

SICC|9|81:3160

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/TP/1173/2018/JT

Date : 18-Oct-18

Vehicle not IN workshop. Kindly assist to arrange for survey.

First Capital Insurance Ltd

36 Robinson Road # 16-01 City House Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Ms. Diana Ow Choy Chee

Address : 136 Hillview Avenue

#05-09

Singapore 669598

 Telephone
 : HP +65 98182428

 Type of Claim
 : Third party Claims

 Policy No.
 : 1800056429

 Vehicle No
 : SJM 8833 Z

Model Code : Audi A5 SB 2.0 TFSI
Model / Year : Jun-18

Model / Year : Jun-18
Engine No : CVK 061459

Chassis No : WAUZZZF58JA098322

Mileage :

Date In : Liability :

Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 13-Oct-18

Place of Accident : Jalan Bukit Merah

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJM 8833 Z

S/I	N Nature of Jobs			Estimated Charges
1	To remove and transfer rear parking aid and rear lid kick sensor . Check function.	S/N	\$	360.00 / `
2	To dismantle and renew rear bumper. Re-organize rear crash management components. Inspect for further damages. Reinstall all parts removed.		\$	1,050.00 600 700
3	To respray rear bumper.		S	900,00
4	To remove and renew rhs exhaust silencer and centre silencer align to position.	S/N	\$	480.00 ?
5	To carry out diagnostic check.	5/N	\$	192.00
	TOTAL LABOUR CHARGES	:	\$	2,982.00

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJM 8833 Z.

S/N	Parts Description			Damage Parts & Prices S/NETT REMARKS
1	REAR BUMPER Del_d		\$	2,190.00 -
2	REAR BUMPER FIXING PARTS 2		S	142.00 *
3	REAR BUMPER SECURING STRIP Songd.		\$	191.00 *
4	REAR BUMPER CHROME TRIM 64		\$	878.00 - 877-50
5	REAR BUMPER CLIP ME W	11	\$	
6	REAR LIGHT REFELCTOR-LH/RH RH wt	2	\$	20.00 35 34.70
7	REAR BUMPER CARRIER The New		\$	786.00 7 X
8	REAR BUMPER SEAL NEW NEW	2	\$	24.00 ? <
9	REAR BUMPER GUIDE SECTION-RH		\$	37.00 🗸
10	REAR BUMPER UPPER GUIDE SECTION-RH ~~~~		5	19.00
11	REAR SENSOR KHE ME	2	5	421.00 +
12	REAR SENSOR SEAL RING Me New	4	\$	ع 14.00
13	REAR SILENCER Bent		\$	789.00 ? /
14	REAR SILENCER DUAL CLIP No.	3	\$	128.007 127.50
15	REAR SILENCER-CENTRE 300.		\$	801.00 ?
16	REAR SILENCER DUAL CLIP HERE		s	43.00 1 X
17	SUNDRIES HE NEW		\$	300.00 '×
	TOTAL SPARE PARTS	1.5	\$	7,240.00
	TOTAL LABOUR CHARGES		\$	2,982.00
	GRAND TOTAL		\$	10,222.00
	Legend : Remarks (OK) = Approved, Remarks (X) = Not approved	d		

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

Authorised Repris, 03 ays.

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting

 To display damaged part(s) during resurvey · Parts prices are subject to confirmation

No illegal modification(s) is allowed.

Acknowledged by Repairer

Signature:

Date:

Third party survey is on a "Without Prejudice" basis

is subject to final approval from Insurance Company

Supplementary item(s) must be resurveyed and

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd Date 78 Shenton Way #07-16 AIG Building Pages Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

PA/TP/1173/2018/JT Estimate No.

1-Nov-18 Jeffery Tan Service Advisor

51M 8833 Z Regn No

Audi A5 SB 2.0 TFSI Model No

Quantity	escription	Ur	nit Price	Amount
<u>Labour</u>				,
1	To carry out paint protection (Supplied by owner)	\$	150.00	
	TOTAL	\$	150.00	

For Premium Automobiles Pte Ltd

Authorised Signature

LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/TP/1173/2018/JT

Date : 18-Oct-18

Vehicle not IN workshop. Kindly assist to arrange for survey.

Hi Adrian

3 days - ok - jb - 29 Nov 18

First Capital Insurance Ltd

36 Robinson Road # 16-01 City House Singapore 068877

Attn: Motor Claims Dept Tel:6854 3909 Fax: 6507 3849

Owner's Name : Ms. Diana Ow Choy Chee

Address : 136 Hillview Avenue

#05-09

Vehicle No : SJM 8833 Z Model Code : Audi A5 SB 2.0 TFSI

Model / Year : Jun-18
Engine No : CVK 061459

Chassis No : WAUZZZF58JA098322

Mileage

Date In : Liability :

Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 13-Oct-18

Place of Accident : Jalan Bukit Merah

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJM 8833 Z

			Estimated		
S/N	Nature of Jobs		Charges	_	
1	To remove and transfer rear parking aid and rear lid kick sensor . Check function.	S/N	\$ 360.00	\$	360.00
2	To dismantle and renew rear bumper. Re-organize rear crash management components. Inspect for further damages. Reinstall all parts removed. (\$700.00 per day for new A5)		\$ 1,050.00	\$	700.00
3	To respray rear bumper.		\$ 900.00	\$	800.00
4	To remove and renew rhs exhaust silencer and centre silencer align to position.	S/N	\$ 480.00	\$	480.00
5	Added labour charges - see attached (Owner)		\$ 150.00	\$	150.00
6	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 3,132.00	\$	2,682.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJM 8833 Z.

		Damage Pa	rts	& Prices		
S/N	Parts Description			S/NETT	_	REMARKS
	Secretary and the control of the con		•	2,190.00	\$	2,190.00
1	REAR BUMPER		\$		Þ	2,730.00
2	REAR BUMPER FIXING PARTS		\$	142.00		
3	REAR BUMPER SECURING STRIP		\$	191.00	\$	191.00
4	REAR BUMPER CHROME TRIM		\$	878.00	\$	877.50
5	REAR BUMPER CLIP	11	\$	407.00		
6	REAR LIGHT REFELCTOR-LH/RH	2	\$	70.00	\$	34.70
7	REAR BUMPER CARRIER		\$	786.00		
8	REAR BUMPER SEAL	2	\$	24.00		
9	REAR BUMPER GUIDE SECTION-RH		\$	37.00		
10	REAR BUMPER UPPER GUIDE SECTION-RH		\$	19.00		
11	REAR SENSOR	2	\$	421.00		
12	REAR SENSOR SEAL RING	4	\$	14.00		
13	REAR SILENCER		\$	789.00	\$	789.00
14	REAR SILENCER DUAL CLIP	3	\$	128.00	\$	127.50
15	REAR SILENCER-CENTRE		\$	801.00	\$	801.00
16	REAR SILENCER DUAL CLIP		\$	43.00		
17	SUNDRIES		\$	300.00	i _	
	TOTAL SPARE PARTS		\$	7,240.00	\$	5,010.70
	TOTAL LABOUR CHARGES	3	\$	3,132.00	\$	2,682.00
	GRAND TOTAL	29 28	\$	10,372.00	\$	7,692.70
		7650 1657 1657 126	-			

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No Model No PA/TP/1173/2018/JT

1-Nov-18 Jeffery Tan

1

SJM 8833 Z

Audi A5 SB 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labour			
1	To carry out paint protection (Supplied by owner)	\$ 150.00	\$ 150.00
	TOTAL	\$ 150.00	\$ 150.00

For Premium Automobiles Pte Ltd

A)

Authorised Signature

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant



OPTI-SHINE PTE. LTD.

25 Kaki Bukit Road 4 #06-47 Synergy & KB Singapore 417809 M: 9661 8747 | 1 9605 9666 | P. 6605 4646 | www.cpt-shrini.com Blog: No: 201227466Q

01 Nov 2018

Ms Diana Ow

Dear Ms Ow,

Quotation for Audi A5 (SJM8833M)

Please refer below for pricing on the following items:

- Polishing and Recoating Rear Bumper after Repair
- Please note that we need one(1) working day for the above works.

All items mention above is chargeable at \$150.

Thank you.

Best regards.

John Year



OPTI-SHINE PTE. LTD. Reg No. 201227486G

25 Kaki Bukit Road 4 #06-47 Synergy®KB Singapore 417800 Tel: +65 6635 5656 Fax: +65 6635 4646 Mobile: +65 8661 8747 Email: sales@opti-shine.com Website: www.opti-shine.com

Invoice / Cash Sale NO.: OS-13720

/ehicle	No.	Model Audi AS SI	_ Email	Remarks		
	1		7 8 P. S.		Amou	unt
S. No		Description			\$	CTS
	Signature Protect				400	00
	Tramin Pockage	ChubeRond				
	Done on 19/06/	2013				
1	5 Fears Warranty					
1	1				E STREET	
-						
1						
1						
12	id by cach					
				TOTAL	400	00
			DEPO	SIT PAID	1.00	1
			BALANCE	DAVABLE	1	

ct number on this form, you give us permission to call you in response to this request and other marketing activities via nd phone even if your contact number is listed in the Do Not Call Registry. Your privacy is important to us. We will never sell, trade or share ersonal information with any third party organization.

ove agreeement is not refundable or transferable.

otherwise stated, the expiry date of package shall be for a period of 24 months from date of agreement.

s should be crossed and made payble to OPTI-SHINE PTE. LTD.

ansfer should be made to DBS Current Account No. 0093463537 and proof of transfer to be emailed to sales@opti-shine.com for our e.

y is subject to Quick Maintenance done at least once every 6 months.

ents are due upon receipt of this invoice.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

4		Affiliated to Federation Intern	nationale Des Experts En Autom	nobile		
MS	FIRST CAPITAL IN	ISURANCE LTD	Ref : CS/FCI18019125/Asd3n2			
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 24-12-2018 Code: FCI2			
1.		Policy Particula	ars :- THIRD PARTY CLAI	M		
	Insured Veh.	SHC 2397G	Veh. Inspected	SJM 8833Z		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	D18007502MFSH	Excess (\$)	0.00		
	Assign From	JOANNE YONG	Assign Date	19/10/2018		
2.		Vehicle Pa	articulars & Condition			
	Make & Model	AUDI A5 SB	c.c	1984		
	Engine No.	HIDDEN	Year of Reg.	2018		
	Chassis No.	WAUZZZF58JA098322	Colour	BLACK		
	Odometer	6148	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.		Con	ditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	245/40 R18	PIRELLI	6 mm		
	L/H Front Tyre	245/40 R18	PIRELLI	6 mm		
	R/H Rear Tyre	245/40 R18	PIRELLI	6 mm		
	L/H Rear Tyre	245/40 R18	PIRELLI	6 mm		
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	13/10/2018	Inspection Date	17/10/2018		
	Survey held at	PREMIUM AUTOMOBILES	PTE LTD			
	100	55 UBI ROAD 1 . SINGAPORE 408699				
5a.			Remarks			
	B)THE INSPECTION	ISISTENT TO ACCIDENT RE ON WAS CONDUCTED ON A' CE TO YOUR INSTRUCTION:	'WITHOUT PREJUDICE" BAS	SIS. SED REPAIRS.		
5b.		Estim	ate Days of Repair			
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Day	rs .		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 8833Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (SN)	DEFORMED	2,190.00	2,190.00
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	142.00	84
1	REAR BUMPER SECURING STRIP (SN)	DAMAGED	191.00	191.00
1	REAR BUMPER CHROME TRIM (SN)	CUT	878.00	877.50
11	REAR BUMPER CLIP (SN)	NOT NECESSARY	407.00	
2	REAR LIGHT REFLECTOR-LH/RH (SN)	O/S CUT	70.00	34.70
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	786.00	
2	REAR BUMPER SEAL (SN)	NOT NECESSARY	24.00	33+
1	REAR BUMPER GUIDE SECTION-RH (SN)	NOT NECESSARY	37.00	72
1	REAR BUMPER UPPER GUIDE SECTION-RH (SN)	NOT NECESSARY	19.00	
2	REAR SENSOR (SN)	NOT NECESSARY	421.00	
4	REAR SENSOR SEAL RING (SN)	NOT NECESSARY	14.00	
1	REAR SILENCER (SN)	BENT	789.00	789.00
3	REAR SILENCER DUAL CLIP (SN)	NECESSARY	128.00	127.50
1	REAR SILENCER-CENTRE (SN)	BENT	801.00	801.00
-1	REAR SILENCER DUAL CLIP (SN)	NOT NECESSARY	43.00	
1	SUNDRIES (SN)	NOT NECESSARY	300.00	(6
	152000-5-171000-1-184-0-001		7,240.00	5,010.70
	LABOUR			
	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR CHECK FUNCTION.		360.00	360.00
	TO DISMANTLE AND RENEW REAR BUMPER.RE- ORGANIZE REAR CRASH MANAGEMENT COMPONENTS.INSPECT FOR FUTHER DAMAGES.REINSTALL ALL PARTS REMOVED.	*	1,050.00	700.00
	TO RESPRAY REAR BUMPER.		900.00	800.00
	TO REMOVE AND RENEW RHS EXHAUST SILENCER AND CENTRE SILENCER ALIGN TO POSITION.		480.00	480.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
	TO CARRY OUT PAINT PROTECTION (SUPPLIED BY OWNER)(ADDITIONAL).		150.00	150.00
	4 Control of Control o		3,132.00	2,682.00

Report Ref No. CS/FCI18019125/Asd3n2



Page No.:2 of 2

GRAND TOTAL	10,372.00	7,692.70
RECOMMENDED COST OF REPAIRS		7,692.70

Report Ref No. CS/FCI18019125/Asd3n2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.