



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBB2503T181018

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Date: 19-10-18

Address Motor Claims Department

Vehicle No: GBB2503T

8 Shenton Way #27-01

Model/Make: Toyota Dyna 150

AXA Tower

Singapore 068811

Manual 3 Seater

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper	\$ 481.60	
2	Bumper Clips 1 set	\$ 65.00	
3	Head Lamp	\$ 705.00	
4	Grille	\$ 588.00	
4	Grille Clips 1 set	\$ 48.00	
	To check all wiring & electrical component for proper function	\$ 50.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	
	To putty & spray painting & including touch up paint on accident affected	\$ 400.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 2,837.60

Total amount in Lump Sum Basis for repaired vehicle



SDLS:

M/s Liu's Brother Auto Engrg Wks

not allowed here
 L/S #1200
 22/10/18
 take shd. After repair.
 3dy.

P-1257.6
 less 500
 625.80
 labor 590
 1215.80

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: