

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

22-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6416 J

1 pc	Rear bumper <i>X repair</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>X</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>X</i>	\$	607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00 <i>X</i>	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X</i>	\$	36.00
		\$	1,859.00
		Less 10%	\$ 185.90
		\$	1,673.10

S/NETT

1 set	Rear bumper clips <i>X</i>	\$	48.00
1 set	Reverse sensor <i>X</i>	\$	280.00
Sundry		\$	50.00 <i>X</i>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 <i>X</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 <i>X</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc		\$	650.00 <i>100</i>
To putty and spray painting on rear bumper, end panel		\$	550.00 <i>180</i>
To apply rustproofing on the repaired and replaced panels.		\$	120.00 <i>X</i>
		\$	3,671.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

LKK Auto Consultants hence notify the Repairer **THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

- To resurvey by the following:
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company.

Acknowledged by: *paper*
Signature:
Date:

Kalvillay
23/10/18 1035 hrs
2 Reps
4/5
After Repair photo