

COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.10.2018

REPAIR ESTIMATE

Time: 09:26:21

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305227682
 REGN NO : SHA8277R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 25.08.2016
 DATE/TIME IN : 18.10.2018 14:55
 ACCIDENT DATE : 18.10.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0573-A FRONT FENDER RH 1 566.30 20.00 453.04

SUB-TOTAL : 453.04

JOB NATURE

0000 20-05 Frt Fender Adv.Sticker RH 100.00
 0001 L PANEL BEATING 220.00
 0002 23-502 SPRAYPAINT-Frt Bumper/W.Mirror RH 600.00
 0003 17-01 WIRING CHECK 40.00
 0004 20-00 TUFF COAT ON AFFECTED PARTS. 40.00

SUB-TOTAL : 1,000.00

TOTAL : 1,453.04

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin / OK / 14
 19/10/18 1020h.
 2 Pys.
 PIP
 Before Part pld