



CYCLE & CARRIAGE  
Exceptional Journeys

CYCLE & CARRIAGE KIA PTE LTD

Body & Paint Centre  
209 Pandan Gardens, Singapore 609339  
Tel +65 6568 4501 · Fax +65 6565 1240  
Company No. 199405410K

21st May 2019

LKK Ref: CC4/III18019166/R1pa3

Mr Carlor Chan Jia Le  
LKK Auto Consultants Pte Ltd  
Blk 51 Paya Ubi Industrial Park  
#02-25 Ubi Avenue 1  
Singapore 408933

Dear Sir,

Amended Invoice for Accident Involving Vehicles SDZ926U and SHB6705E on  
25/09/2018

Attached is the amended invoice name to India Insurance as per your request.

Kindly process for payment to, Cycle & Carriage Kia Pte Ltd, the soonest possible.

Appreciate your assistance.

Yours Sincerely,

---

Loi Ai Ting  
Customer Service Advisor



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**TAX INVOICE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
India International Insurance Pte Ltd Motor Claims Department 64 Cecil Street #04/05 IOB Building Singapore 049711	Cust No/Name LCV05922/LIM TECK LENG (LIN DILONG) Reg No/Reg Date SDZ926U / 21/06/2018 Date In/Mileage 20/10/2018/ 5322 Chassis/Package KNAPH81BMJ5465347 /KC17P(F) Engine No D4HBJH374089 Make/Model KIA/SORENTO 2.2 A D SX SR GDS7 Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No		
CTP00080	Cash	22/03/2019/ 13:51	TLT	260 / AiTing	36455	81395929		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								550.00
REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								
E PNT98000								420.00
RESPRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME								
E PNT88000								80.00
TRANSFER FRONT PARKING SENSOR TO NEW PANEL								
A 54900099								30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 10028901								200.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								
M SUNDRY								20.00
SUNDRIES								
X	COVER-FR BUMPER UPR				1.00	561.00	00.00	561.00
X	GRILLE-FRONT BUMPER FOG LAMP,L				1.00	81.00	00.00	81.00
X	MOULDING-FRONT BUMPER LWR,LH				1.00	89.00	00.00	89.00
					</			

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.