

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LIM TECK LENG (LIN DILONG) BLK 20 ANG MO KIO AVENUE 2 #07-36 SINGAPORE 567701 Contact No	Cust No/Name	LCV05922/LIM TECK LENG (LIN DILONG)
	Reg No/Reg Date	SDZ926U / 21/06/201
	Date In/Mileage	/ 0
	Chassis No	KNAPH81BMJ5465347
	Engine No	D4HBJH374089
	Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV05922	CRDVCH	01/10/2018/ 14:21		465 / Tay Jian Ye	36455		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							550 1100.00
TO RENEW FRT BUMPER							420 840.00
E PNT98000							80.00
PAINT WORK SPRAY FRT BUMPER							30.00
E PNT88000							200.00
TO TRANSFER FRT PARKING SENSOR TO NEW PARTS							20.00
A 54900099							
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							
SUNDRIES							
M COVER-FR BUMPER UPR				1.00	561.00	00.00	repair 561.00
M GRILLE-FRONT BUMPER FOG LAMP,L				1.00	81.00	00.00	chk 81.00
M MOULDING-FRONT BUMPER LWR,LH				1.00	89.00	00.00	scr 89.00

SURVEYOR NAME: Rahul - 499000568

SURVEYOR SIGNATURE: [Signature]

DATE: 19/10/18 @ 1650

REMARKS: 3 days

Repay after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

7% GST on	Nett	3,001.00
	3001.00	210.07
	Total Payable	3,211.07

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.