



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TPA A
Vic.

18/10/2018

Accident date: 12/10/2018

Estimated repair cost for vehicle no: SGS5522U HONDA VEZEL 1.5 X A '16

S/n	Qty	Items	U/price	Amount
1	1	Front L/H Door <i>Repair</i>		\$1,180.60 <i>+</i>
2	2	Front L/H Door Frame Sticker <i>new</i>	\$30.00	\$60.00 <i>+</i>
3	1	Rear L/H Door <i>Replaced</i>		\$1,280.50 <i>✓</i>
4	2	Rear L/H Door Frame Sticker <i>new</i>	\$30.00	\$60.00 <i>✓</i>
5	1	Rear L/H Door Inner Rubber <i>new</i>		\$221.60 <i>+</i>
6	1	Rear L/H Door Inner Trim Board <i>new</i>		\$821.70 <i>479</i>
7	1	Rear L/H Door Side Lower Sticker <i>new</i>		\$175.00 <i>✓</i>
8	1	Rear L/H Door Gear Motor Assy <i>new</i>		\$401.30 <i>+</i>
9	1	Rear L/H Fender <i>Repair</i>		\$950.10 <i>+</i>
10	1	Rear L/H Fender Protector <i>cut</i>		\$175.20 <i>✓</i>
11	1	Rear L/H Fender Cowling <i>Replaced</i>		\$105.30 <i>✓</i>
12	1	Rear Bumper <i>cut</i>		\$863.50 <i>✓</i>
13	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 <i>30</i>
14	1	Rear L/H Bumper Side <i>Replaced</i>		\$198.70 <i>✓</i>
15	1	Rear L/H Rim <i>cut</i>		\$850.00 <i>500 (SW)</i>
16	1	Rear L/H Tyre <i>cut</i>		\$380.00 <i>200 (SW)</i>
17	1	Rear Axle Bearing <i>Replaced</i>		\$270.70 <i>✓</i>
18	1	Rear Axle Shock Absorber <i>new</i>		\$401.70 <i>+</i>
19	1	Rear Axle <i>Replaced</i>		<i>1513</i> \$1,613.20 <i>✓</i>
20	1	L/H Rocker Panel <i>Replaced</i>		\$660.60 <i>✓</i>
21	1	L/H Rocker Panel Skirt <i>cut</i>		\$477.50 <i>✓</i>
22	10	L/H Rocker Panel Skirt Clip <i>new</i>	\$6.50	\$65.00 <i>30</i>

Subtotal :- \$11,264.20

6027.5 S.N. 700

4822

Labour charges

To remove & refit rear L/H door, gear motor, glass, rubber & trim board	\$180.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit petrol tank	\$280.00 x.
To remove & refit roof lining	\$380.00 x.
To remove & refit rear axle	\$380.00 280
To check wheel alignment	\$150.00 80
To check wiring	2470 \$100.00 30
Tuff kote	\$150.00 750
Panel beating	\$1,400.00 1000
Spray painting	\$1,400.00 900
Side Bumper	
Door x 2.	
Fender	
Sill Panel.	
Subtotal :-	\$4,520.00
Total:-	\$15,784.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian King
4/3 22/10/18.

07 days.

total: 7952

4/3: 6.4k

6.4k