

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1203/2018/GW
Date : 23-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Tel: 6829 9199

Owner's Name : Mr. Shawhney Sameer
Address : 5 Saber Grove
Singapore 129220
Telephone : HP +65 81805834
Type of Claim : Third party Claims
Policy No. : PNPV2018-00010462
Vehicle No : **SFL 6868 P**
Model Code : Audi Q5 2.0 TFSI Quattro AT D
Model / Year : Dec-09
Engine No : CDN074232
Chassis No : WAUZZZ8R1AA038561
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Oct-18
Place of Accident : PIE Slip Road Towards Lornie RD

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFL 6868 P .

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid . Check function.	S/N	\$ 280.00	✓
2	To dismantle and renew rear bumper. Re-organize rear crash management components. Reinstall all parts removed.		\$ 1,050.00 600	
3	To respray rear bumper and rear lower spoiler.		\$ 1,400.00 1000	
4	To remove and renew both rear exhaust silencer and centre silencer. To align to position.	S/N	\$ 480.00	?
5	To carry out diagnostic checks.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	\$ 3,402.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SFL 6868 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Rehd</i>	\$ 1,430.00	✓
2	REAR BUMPER FIXING PARTS <i>Rehd</i>	\$ 143.00	X
3	REAR BUMPER SPOILER <i>Rehd</i>	\$ 749.00	✓
4	REAR BUMPER UPPER GUIDE SECTION-LH	\$ 46.00	X
4	REAR BUMPER GUID SECTION-LH/RH	2 \$ 92.00	X
6	REAR BUMPER CARRIER	\$ 571.00	X
7	REAR BUMPER HOLDER BRACKET-LH/RH	2 \$ 368.00	X
8	REAR PARKING DISTANCE SENSOR	2 \$ 421.00	X
9	REAR PARKING AID <i>Rehd</i>	2 \$ 392.00	✓
10	TAILRIGHT-LH/RH <i>Rehd</i>	2 \$ 526.00	✓
11	REAR SILENCER-LH/RH ?	2 \$ 1,766.00	?
12	REAR SILENCER DUAL CLIP <i>Rehd</i>	\$ 47.00	X
13	REAR SILENCER BRACKET-LH/RH <i>Rehd</i>	2 \$ 100.00	X
14	REAR SILENCER CENTRE <i>Rehd</i>	\$ 875.00	X
15	REAR SILENCER CENTRE DUALCLIP ?	\$ 52.00	X
16	REAR SILENCER CLAMP -LH/RH	2 \$ 93.00	X
17	REAR SILENCER HANGER-LH/RH	2 \$ 78.00	X
17	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS :		\$ 8,049.00	
TOTAL LABOUR CHARGES		\$ 3,402.00	
GRAND TOTAL		\$ 11,451.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim .
Surveyed Date : 23/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : We Authorised , 03 days
Please allow for before paint photo.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant