

cc 4, Asm, 19177, U 8232

LKK:

EDAC:

76157

Surveyor:

Marins

DOI:

ASSIGNMENT

22/10/2018

Date / Time:

19.10.18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 237 T

Name of Insured:

T/C SRS P/L

Insured Tel No.:

HP:

Excess Sec II : S\$

5,000.00

D.O.A.:

18/10/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

88m00225

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

JPR 608 J

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Yew Tee



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

3/10/18

JPR 608 J-X;

RCM

SHD 237 T - 16/10/18 220088 / KUBA7 ; D.O.A. 15/10/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

22/10/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: Shawn

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 10.

If NO or B 28, Ass. Lia.:

Repair Cost:

w/651

S\$

6033.00

Loss of Rental (LOR):

S\$

days)

Loss of Use (LOU):

S\$

3w-w (\$60 x 5

days)

Loss of Income (LOI):

S\$

(\$ x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

29.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

6362.00

Global Sum S\$: 6300.00

1) Claim status: Not Rejected/Private Settle

2) Report Format:

3) Survey fee:

#250.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

6300.00

Name 1:

Yew Tee Automobile Tech Pte Ltd

GIA

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Surrogate **Marius**

REF: **Asm (AXH)**

ASSIGNMENT

From: _____ Date: **22.10.2018**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SJR 608J**
at Workshop m/s: **Yew Tee Automobile**

of **Blk 6 Woodlands Rd 399F**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **62**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **5** days Res.: Yes or No

Lum Sum: **183** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 41392

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SJR 608J** Yr Regn: **4 / 16**

Type: **Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or **CA**

Make: **Honda** C.C. **1496**

Colour: **White** A/C: Insured / Std / NI / NA

Sp. Reading: **039183** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **RU111-3772**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **In order** / Jammed / Leaked / Burnt or

Brake: **In order** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: **F: 215 / 60 R16**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. **6** mm

L/Bal. **6** mm

D.O.A. **18/10/18**

Survey held at _____

Rear

R/Bal. **6** mm

L/Bal. **6** mm

D.O.A. **22/10/18**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIV \$ 5638.40 Cred \$ 1199.90 / 18/11

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) \$ + RS. \$

) Photos: _____

) Others: _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1810/012
Policy No:	5079106090-02	Date of Loss:	18/10/2018
Vehicle Reg. No.:	SJR608J	Driveable?	yes
Driver Age:	1976-10-28	Third Party Vehicle No.:	SHD237T
Any Injuries?	no	Contact No:	98440167
Insured/Claimant:	LEE HWAN CHER, JOYCE	Driver:	LEE HWAN CHER, JOYCE

Make/Model:	Honda, Vezel - RU1	Vehicle Reg. Date:	06/04/2016
Vehicle Colour:	WHITE	Engine Number:	L15B4033777
Chassis No:	RU11113772	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: **COLLISION - MAJOR/MINOR**
 Remarks:
 Present Location: **Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ**

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	4,568.30
Labour	270.00
Paintwork Labour	1,080.00
Towing	920.00
	0.00
Gross Total(S\$):	6,838.30
GST 7.00%(S\$):	478.68
Nett Amount(S\$):	7,316.98

This claim is handled by: Sky Toh T C

KH Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Authorized**WKK merus**2/10/18**Take photo before painting**Sky**5638.40*

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER Dis	154.00	154.00	+10.00	169.40
2	1	FRONT BUMPER SIDE RETAINERS Bel	12.00	12.00	+10.00	13.20
3	1	FRONT BUMPER FOG LAMP COVER LH Twi	18.00	18.00	+10.00	19.80
4	1	FRONT BUMPER FOG LAMP LH Re	164.00	164.00	+10.00	180.40
5	1	FRONT BUMPER LOWER GUARD Cut/Re	158.00	158.00	+10.00	173.80
6	1	FRONT BUMPER REINFORCEMENT Sy	198.00	198.00	+10.00	217.80
7	1	FRONT BUMPER LOWER RUBBER Re	48.00	48.00	+10.00	52.80
8	1	FRONT BUMPER LOWER GRILLE Rix	48.00	48.00	+10.00	52.80
9	1	FRONT HORN LH Re	33.00	33.00	+10.00	36.30
10	1	FRONT GRILLE BASE Cne	187.00	187.00	+10.00	205.70
11	1	FRONT GRILLE OUTER Complete	154.00	154.00	+10.00	169.40
12	2	FRONT GRILLE CHROME MOULDING	25.00	50.00	+10.00	55.00
13	1	FRONT GRILLE LOGO	18.00	18.00	+10.00	19.80
14	1	FRONT GRILLE TOP BRACKET	55.00	55.00	+10.00	60.50
15	1	FRONT HEADLAMP LH Historic Cne	880.00	880.00	+10.00	968.00
16	1	FRONT HEADLAMP LOWER BRACKET LH CRe	30.00	30.00	+10.00	33.00
17	1	BONNET Suc	418.00	418.00	+10.00	459.80
18	1	BONNET HINGES LH Bel	34.00	34.00	+10.00	37.40
19	1	BONNET HINGES RH Bel	34.00	34.00	+10.00	37.40
20	1	BONNET LOCK Twi	73.00	73.00	+10.00	80.30
21	1	BONNET RUBBER Re	19.00	19.00	+10.00	20.90
22	1	FRONT SUPPORT PANEL P.D./Bel	352.00	352.00	+10.00	387.20
23	1	FRONT SUPPORT PANEL TOP GARNISH Def/Re	46.00	46.00	+10.00	50.60
24	1	FRONT AIR INTAKE DUCT Twi/Cne	45.00	45.00	+10.00	49.50
25	1	FRONT AIR INTAKE JOINT PIPE R1	48.00	48.00	+10.00	52.80
26	1	AIR CON CONDENSER Bel/Re	308.00	308.00	+10.00	338.80
27	1	AIR CON CONDENSER AIR GUIDE LH Re	25.00	25.00	+10.00	27.50
28	1	RADIATOR Bel/Twi	310.00	310.00	+10.00	341.00
29	1	RADIATOR FAN COWLING R1 X	80.00	80.00	+10.00	88.00
30	1	FRONT FENDER LH R1 X	0.00	0.00	+10.00	0.00
31	1	FRONT FENDER INNER SHIELD LH To Re	80.00	80.00	+10.00	88.00
32	1	FRONT FENDER WHEEL ARCH GARNISH LH To Re	55.00	55.00	+10.00	60.50
33	1	BATTERY +VE COVER R1	19.00	19.00	+10.00	20.90

Total Parts (\$\$) 4,568.30

5036.9

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS Re	35.00	35.00	0.00	35.00
2	1	FRONT NUMBER PLATE Bel	35.00	35.00	0.00	35.00
3	1	FRONT SUPPORT PANEL TOP GARNISH CLIPS R1	35.00	35.00	0.00	35.00
4	1	FRONT FENDER INNER SHIELD CLIPS R1	35.00	35.00	0.00	35.00
5	1	BATTERY	130.00	130.00	0.00	130.00

Sub Total (\$\$) 270.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical	30.00	30.00	0.00	30.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
2	1	wiring Harness Wire, Sockets, Replace Damaged Parts. To Pressure Test Air Con Condenser and Radiator For Leakage.	11 120.00	120.00	X 0.00	120.00
3	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	100 0.00	180.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	750.00	750.00	520 0.00	750.00

Gross Labour Cost (\$\$) 1,080.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	30 0.00	60.00
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	11 60.00	X 0.00	60.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	800.00	700 0.00	800.00

Gross Labour Cost (\$\$) 920.00

< END OF ESTIMATES >

7366.90

P - 3744
+ 104
4118.40
S.N + 150
labour + 1370
\$ 5638.40



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9030

Arrange By

Driver

PCH



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 64

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

YEW TEE AUTOMOBILE TECH PTE LTD*
BLK 6 #01-399F WOODLAND ROAD
YEW TEE IND. EST

SINGAPORE 677953
TEL : 67653373 FAX : 67604895
ATTN :

TAX INVOICE : AR201810-128
DATE : 24/10/20
CUSTOMER ID : YEW0
VEH REG. NO. : SJR60
TERMS : 30 da
PO NO. :
PAGE NO. : Page 1 of
CURR : SC

SQ STOCKID	DESCRIPTION	StkLoo	QTY	U/PRICE	AMOUNT
1 H71101-T7J-H00ZZ	FR BUMPER	PA PL4-A1-01	1	180.00	180.
2 H71106-T7J-H00	FOG GARNISH LH	PA PL1-C1-08C	1	15.00	15.
3 H33950-SLE-J51(H) RU1	FOGLAMP LH	PA PL1-L1-10A	1	140.00	140.
4 H71102-T7W-A00 RU1	FR BUMPER LOWER	PA PL4-B1-23	1	120.00	120.
5 H71130-T7A-000/010ZZ RU1	REINFORCEMENT FR(T7A-010)	PA PL1-A1-05B	1	180.00	180.
6 H71110-T7A-000 RU1	FR UNDER SPOILER RUBBER	PA PL1-M1-11A	1	40.00	40
7 H38150-T7A-J01 RU1	HORN ASSY,HIGH	PA PL1-L1-10A	1	28.00	28.

CONTINUE NEXT PAGE

[P] 24/10/2018 11:22:40AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 24/10/2018 11:11:00A



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 64

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

YEW TEE AUTOMOBILE TECH PTE LTD*
BLK 6 #01-399F WOODLAND ROAD
YEW TEE INDUST

SINGAPORE 677953
TEL : 67653373 FAX : 67604895
ATTN :

TAX INVOICE : AR201810-128
DATE : 24/10/20
CUSTOMER ID : YEW0
VEH REG. NO. : SJR60
TERMS : 30 da
PO NO. :
PAGE NO. : Page 2 of
CURR : SC

SO STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
8 H71151-T7A-000 RU1	UP BEAM RH FRT GRIL	PA PL1-L1-11H	1	10.00	10.
9 H71152-T7A-000 RU1	UP BEAM LH FRT GRIL	PA PL1-L1-11Q	1	10.00	10.
10 H33150-T7S-E11 HRV-RU1	HEAD LAMP LH	PA PL1-J1-110	1	790.00	790.
11 H71190-T7A-000 RU1	BRACKET, L. FR BUMPER	PA PL1-L1-08L	1	20.00	20.
12 H60100-T8N-T00ZZ HRV	BONNET	PA PL1-E1-FRT	1	380.00	380
13 H60120-T8N-T00/01ZZ RU1	BONNET HINGE RH	PA PL1-L1-07P	1	28.00	28
14 H60170-T8N-T00/01ZZ	BONNET HINGE LH	PA PL1-L1-03G	1	28.00	28

CONTINUE NEXT PAGE

[P] 24/10/2018 11:22:40AM

[E] 24/10/2018 11:11:00A

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

Arrange By _____ Driver _____



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

YEW TEE AUTOMOBILE TECH PTE LTD*
BLK 6 #01-399F WOODLAND ROAD
YEW TEE IND. EST

SINGAPORE 677953
TEL : 67653373 FAX : 67604895
ATTN :

TAX INVOICE : AR201810-128
DATE : 24/10/20
CUSTOMER ID : YEW0
VEH REG. NO. : SJR60
TERMS : 30 da
PO NO. :
PAGE NO. : Page 3 of
CURR : SC

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
15	H74120-T7A-003 RU1	LOCK ASSY HOOD	PA PL1-L1-11S	1	65.00	65.
16	H74192-T7A-000	RUBBER L HOOD SEAL	PA PL1-A1-12G	1	15.00	15.
17	H60400-T7A-300/310/901ZZ RU1	SUPPORT PANEL(T7A-310/901ZZ)	PA PL1-A1-09B	1	295.00	295.
18	H71129-T7J-H00 HRV-RU1	COVER, FR GRILLE	PA PL1-M1-10K	1	40.00	40.
19	H17252-50T-000 RU1 RU3	DUCT ASSY AIR INTAKE	PA PL1-M1-09C	1	40.00	40
20	H80110-T7A-J01 RU1	CONDENSER COMP	PA PL1-B1-050	1	310.00	310
21	H71116-T8N-T50 HRV	AIR GUIDE LH FR BUMPER	PA PL1-M1-09G	1	20.00	20

CONTINUE NEXT PAGE

[P] 24/10/2018 11:22:40AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 24/10/2018 11:11:00A

AP



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9751 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9752



Dept Direct: 6417 9754

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 64

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

YEW TEE AUTOMOBILE TECH PTE LTD*
BLK 6 #01-399F WOODLAND ROAD
YEW TEE INDUST

SINGAPORE 677953

TEL : 67653373 FAX : 67604895

ATTN :

TAX INVOICE : AR201810-128
DATE : 24/10/2018
CUSTOMER ID : YEW0
VEH REG. NO. : SJR60
TERMS : 30 da
PO NO. :
PAGE NO. : Page 4 of
CURR : SC

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
22	H19010-50T-901/02 RUI	RADIATOR MS	PA PL1-A1-03A	1	700.00	700.
23	H74150-T7A-000 RUI	FENDER SHIELD LH	PA PL1-H1-09S	1	70.00	70.
24	H74157-T7M-H01 RUI	WHEEL ARCH FR LH	PA PL1-B1-08A	1	50.00	50.

SUB-TOTAL : 3,574
ADD GST 7.00 % 250

E. & O.E

TOTAL AMOUNT SGD : 3,824

[P] 24/10/2018 11:22:40AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 24/10/2018 11:11:00A

JAE Auto Pte. Ltd.

Sales Executive: EDMUND



Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date

This is computer generated document.
No signature is required.

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

YEW TEE AUTOMOBILE TECH PTE LTD*
BLK 6 #01-399F WOODLAND ROAD
YEW TEE INDUST

SINGAPORE 677953

TEL : 67653373 FAX : 67604895

ATTN :

TAX INVOICE : AR201810-1670
DATE : 31/10/2018
CUSTOMER ID : YEW01
VEH REG. NO. : SJR60
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H71121-T7A-000 RU1	FR GRILLE	PA PL1-R1-010	1	170.00	170.00

SUB-TOTAL : 170.00
ADD GST 7.00 % 11.00

E. & O.E TOTAL AMOUNT SGD : 181.00

[P] 31/10/2018 2:55:22PM

[E] 31/10/2018 2:53:30PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: EDMUND

This is computer generated document.

No signature is required.



* AR201810-16766 *

ORIGINAL

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	4084F

Vehicle Details

Vehicle No.:	SJR608J
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT ABS D/AIRBAG 2WD
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4033777
Chassis No.:	RU11113772
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,977.00
Original Registration Date:	07 Apr 2016
First Registration Date:	07 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$9,977.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Apr 2026
PARF Rebate Amount:	\$7,482.00

Intended COE Rebate Details

COE Expiry Date:	06 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,504.00
COE Rebate Amount:	\$33,910.00
Total Rebate Amount:	\$41,392.00

The information contained herein is correct as at 24 Oct 2018


OK

500+ dealers
competed to
buy my car!



Sell ur Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

(New 10 Years COE) Honda City 1.5A LX



100% Guarantee Cash Price
Sincere Motoring



Browse by Category

« Back (1 2 3 4 5 6 7 8) Next »

Sort by Date Posted 20 results/page

155 vehicles

Honda Vezel

Search Selection

Honda Vezel

Any

Any

2016

Any

Any

Any

Available



Honda Vezel 1.5A X

\$66,000

\$8,040 /yr

31-May-2016

1,496 cc

38,000 km

SUV

Available

\$0 Down. 100% Loan Amount And 100% Accident Free. No Guarantor Needed, High Trade In, Overloan Up To \$4000. Call Now.
\$0 Down. 100% Loan No Guarantor Overloan \$4000 To Cover Yr Loss. Last Unit To Go

Posted: 24-Oct-2018 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X

\$69,000

\$8,090 /yr

21-Sep-2016

1,496 cc

25,000 km

SUV

Available

\$0 Down. 100% Loan Amount And 100% Accident Free. No Guarantors Needed, High Trade In, Overloan Up To \$4000. Call Now.
\$0 Down. 100% Loan No Guarantor Overloan \$4000 To Cover Yr Loss. Last Unit To Go

Posted: 24-Oct-2018 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X

\$64,500

\$7,580 /yr

31-Aug-2016

1,496 cc

40,000 km

SUV

Available

10% Down Payment. Low Interest Rate From 2.78%! Very Well Maintained With Low Mileage Done, 2 Years Warranty/Service By Platinum Motoring
In House Workshop. New \$2k Metallic Paint Color Of Your Choice...

10% Down Payment, Low Interest Rate @2.78%! Very Well Maintained & Low Mileage!

Posted: 24-Oct-2018 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X

\$69,800

\$8,430 /yr

02-Jun-2016

1,496 cc

26,666 km

SUV

Available

\$3,000 Drive Away. \$1,057 /mth. Good Condition. Flexible Loan Package. Instant Approval. Ex Bankrupt Welcome. High Trade In.

Posted: 24-Oct-2018 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Used 7" Motorised Screen Pioneer DVD

AVH-P6850DVD 2-Din 7 inch Motorized LCD 6-Disc (DVD, VCD, CD) Receiver warranty 3 mth if installation done at AutoImage

More info about this product



Honda Vezel 1.5A X

\$69,800

\$8,470 /yr

01-Jun-2016

1,496 cc

-

SUV

Available

3 Months Warranty From Our In-house Workshop. Excellent Condition, Accident Free, No Repair Needed. Bank Loan In-house Loan Available. Trade In Welcome.

Posted: 23-Oct-2018 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X

\$70,900

\$8,190 /yr

13-Oct-2016

1,496 cc

-

SUV

Available

Elegant White SUV, One Owner Only, Low Maintenance Cost, Comes With Warranty, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 23-Oct-2018 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Honda Vezel 1.5A X Honda Sensing

\$65,800

\$7,910 /yr

14-Jun-2016

1,496 cc

68,021 km

SUV

Available

Loan Available, Viewing Till 9pm Possible, No Need To Compare, Absolute The Best Value, 100% Accident Free. Drives And Smell Like A New
1 On Fuel Efficiency, Very Well Maintained By Only Own...

Service Request Details

Claim

S8M00ZQS

Reference

None 

Loss Date

October 18, 2018

Request Date

October 19, 2018

Due Date

October 26, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

[Decline Work](#)[Accept Work](#)

Vehicle Information

Incident Vehicle Registration

SJR608J

Make

TPVD HONDA

19.10.2018 @ 1.47 pm
Vinnie veh in but estimate not ready
arrange survey at Yew Tee on 22/10/2018

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1810/012
Policy No:	5079106090-02	Date of Loss:	18/10/2018
Vehicle Reg. No.:	SJR608J	Driveable?	yes
Driver Age:	1976-10-28	Third Party Vehicle No.:	SHD237T
Any Injuries?	no	Contact No:	98440167
Insured/Claimant:	LEE HWAN CHER, JOYCE	Driver:	LEE HWAN CHER, JOYCE

Make/Model:	Honda, Vezel - RU1	Vehicle Reg. Date:	06/04/2016
Vehicle Colour:	WHITE	Engine Number:	L15B4033777
Chassis No:	RU11113772	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION - MAJOR/MINOR
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	4,568.30
Miscellaneous Items	270.00
Labour	1,080.00
Paintwork Labour	920.00
Towing	0.00
Gross Total(S\$):	6,838.30
GST 7.00%(S\$):	478.68
Nett Amount(S\$):	7,316.98

This claim is handled by: Sky Toh T C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
WKK merlus
20/10/18
Take photo before painting
4 day - 5 day

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>Dis</i>	154.00	154.00	+10.00	169.40
2	1	FRONT BUMPER SIDE RETAINER LH <i>Reat</i>	12.00	12.00	+10.00	13.20
3	1	FRONT BUMPER FOG LAMP COVER LH <i>?</i>	18.00	18.00	+10.00	19.80
4	1	FRONT BUMPER FOG LAMP LH <i>?</i>	164.00	164.00	+10.00	180.40
5	1	FRONT BUMPER LOWER GUARD <i>cut/zone</i>	158.00	158.00	+10.00	173.80
6	1	FRONT BUMPER REINFORCEMENT <i>34</i>	198.00	198.00	+10.00	217.80
7	1	FRONT BUMPER LOWER RUBBER <i>?</i>	48.00	48.00	+10.00	52.80
8	1	FRONT BUMPER LOWER GRILLE <i>?</i>	48.00	48.00	+10.00	52.80
9	1	FRONT HORN LH <i>?</i>	33.00	33.00	+10.00	36.30
10	1	FRONT GRILLE BASE <i>one</i>	187.00	187.00	+10.00	205.70
11	1	FRONT GRILLE OUTER <i>one</i>	154.00	154.00	+10.00	169.40
12	2	FRONT GRILLE CHROME MOULDING <i>Misson</i>	25.00	50.00	+10.00	55.00 <i>1pc</i>
13	1	FRONT GRILLE LOGO <i>new</i>	18.00	18.00	+10.00	19.80
14	1	FRONT GRILLE TOP BRACKET <i>one</i>	55.00	55.00	+10.00	60.50
15	1	FRONT HEADLAMP LH <i>holder one</i>	880.00	880.00	+10.00	968.00
16	1	FRONT HEADLAMP LOWER BRACKET LH <i>?</i>	30.00	30.00	+10.00	33.00
17	1	BONNET <i>3uc</i>	418.00	418.00	+10.00	459.80
18	1	BONNET HINGES LH <i>?</i>	34.00	34.00	+10.00	37.40
19	1	BONNET HINGES RH <i>?</i>	34.00	34.00	+10.00	37.40
20	1	BONNET LOCK <i>two</i>	73.00	73.00	+10.00	80.30
21	1	BONNET RUBBER <i>new</i>	19.00	19.00	+10.00	20.90
22	1	FRONT SUPPORT PANEL <i>?</i>	352.00	352.00	+10.00	387.20
23	1	FRONT SUPPORT PANEL TOP GARNISH <i>?</i>	46.00	46.00	+10.00	50.60
24	1	FRONT AIR INTAKE DUCT <i>?</i>	45.00	45.00	+10.00	49.50
25	1	FRONT AIR INTAKE JOINT PIPE <i>?</i>	48.00	48.00	+10.00	52.80
26	1	AIR CON CONDENSER <i>?</i>	308.00	308.00	+10.00	338.80
27	1	AIR CON CONDENSER AIR GUIDE LH <i>?</i>	25.00	25.00	+10.00	27.50
28	1	RADIATOR <i>?</i>	310.00	310.00	+10.00	341.00
29	1	RADIATOR FAN COWLING <i>nx</i>	80.00	80.00	+10.00	88.00
30	1	FRONT FENDER LH <i>nx</i>	0.00	0.00	+10.00	0.00
31	1	FRONT FENDER INNER SHIELD LH <i>70.00</i>	80.00	80.00	+10.00	88.00
32	1	FRONT FENDER WHEEL ARCH GARNISH LH <i>70.00</i>	55.00	55.00	+10.00	60.50
33	1	BATTERY +VE COVER <i>?</i>	19.00	19.00	+10.00	20.90

Total Parts (\$\$) 4,568.30

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS <i>new</i>	35.00	35.00	0.00	35.00
2	1	FRONT NUMBER PLATE <i>35.00</i>	35.00	35.00	0.00	35.00
3	1	FRONT SUPPORT PANEL TOP GARNISH CLIPS	35.00	35.00	0.00	35.00
4	1	FRONT FENDER INNER SHIELD CLIPS <i>70.00</i>	35.00	35.00	0.00	35.00
5	1	BATTERY	130.00	130.00	0.00	130.00

Sub Total (\$\$) 270.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical	30.00	30.00 <i>20</i>	0.00	30.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
2	1	wiring Harness Wire, Sockets, Replace Damaged Parts. To Pressure Test Air Con Condenser and Radiator For Leakage.	11 120.00	120.00	X 0.00	120.00
3	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	? 0.00	180.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	750.00	520 750.00	0.00	750.00

Gross Labour Cost (S\$) 1,080.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	50 0.00	60.00
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	11 60.00	X 0.00	60.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	800.00	700 0.00	800.00

Gross Labour Cost (S\$) 920.00

< END OF ESTIMATES >

R- 2804.60
 ? 1883.20
 2063.70
 L- 1270

Hsiao Tong (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Wednesday, 28 August 2019 8:43 AM
To: Hsiao Tong (LKKAuto)
Subject: FW: New message for service request 76157, vehicle number SJR608J

27/8/19 9:53 PM *** Status of claim *** Pls advise. - KHOR Saw Theng

-----Original Message-----

From: sawtheng.khor@axa.com.sg <sawtheng.khor@axa.com.sg>
Sent: Tuesday, 27 August, 2019 9:54 PM
To: admin-d@lkkauto.com
Subject: New message for service request 76157, vehicle number SJR608J

AXA Insurance has sent you a message for claim number S8M00ZQS.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: YT(HQ) <info@yewteegroup.com>
Sent: Thursday, 6 December 2018 3:54 PM
To: Asher Sng (LKKAuto)
Cc: Admin A; YT(HQ)
Subject: RE: Accident involving SJR608J & SHD237T on 18-10-2018 *** LKK REF: CC4/ASM18019177/ea3
Attachments: SJR608J LOD.pdf; SJR608J_18102018.pdf

Hi Asher,

Attached the LOD for your kind perusal.

Appreciate your quick response.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Yew Tee (HQ) [mailto:utauto@singnet.com.sg]
Sent: Monday, 22 October, 2018 6:35 PM
To: Mei Kwan (LKKAUTO)
Cc: YT(HQ); Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: Re: Accident involving SJR608J & SHD237T on 18-10-2018 *** LKK REF: CC4/ASM18019177/ea3

Hi

Based on bola sceno I believe that liability should be clear for direct settlement we are not talking on the merit of the case

Best Regards
Shaun Toh L M

9743 2262 / 8100 7999
Website: www.yewteegroup.com
Like Us On Facebook

Director of
-**YEW TEE AUTOMOBILE TECH PTE LTD**
-**ULTIMAX LEASING PTE LTD**
-**SKT TYRES & BATTERY SERVICES PTE LTD**
-**YEW TEE (CAMBODIA) AUTOMOBILE CO. LTD**



HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road 4
Unit No #01-60/61
Singapore 417800
DID: 6702 3113 (3 Lines) Fax: 6702 3773
Email: utauto2@singnet.com.sg

Please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person

On 22 Oct 2018, at 18:32, Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com> wrote:

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Please be informed that we are currently **pending verification for direct settlement**.

Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.

<image002.png>

<image003.png>

Please provide us the following.

- ***evidence i.e. video and scene photo***
- ***estimated cost of repair***

Please note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) <info@yewteegroup.com>

Sent: Friday, 19 October, 2018 11:18 AM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Cc: YT(HQ) <info@yewteegroup.com>

Subject: Accident involving SJR608J & SHD237T on 18-10-2018

Dear Sir/Madam,

Attached the GIA report for your kind perusal.

Kindly arrange survey before repair at Yew Tee HQ.

Please let us have the surveyor list to choose for and the officer in charge too.

Thank you

Best Regards

Vinnie Lim

<image004.png>

Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 31/8/2019

Survey Details:

Date of loss	18-Oct-18
Date of appointment	19-Oct-18
Date of survey	22-Oct-18
Location of survey	YEW TEE AUTOMOBILE TECH PL

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJR608J
Make and Model	HONDA VEZEL 1.5X CVT - 1.80Cee
Date of registration	7-Apr-16
Excess	
Market Value	\$ 62,000.00
Parf Rebate	\$ 41,416.00
Nett Loss	\$ 20,584.00

Repair details:

Initial Estimate	6,838.30
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 4,268.40
Check items (estimate)	NIL
Labour	\$ 1,370.00
Total	\$ 5,638.40
Lump Sum(if applicable)	\$ -

Number of days for repair	\$ 5.00
---------------------------	---------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	6,033.09
Loss of use	\$	300.00 (5days x \$60.00)
Loss of rental		NIL no. of days
Loss of income		NIL no. of days
LTA search fees	\$	29.00
Others		NIL
Proposed Total	\$	6,362.09

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Monday, 9 September 2019 2:10 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 76157, vehicle number SJR608J

7/9/19 12:32 PM

*** Pls proceed with your proposed mandate. - KHOR Saw Theng

-----Original Message-----

From: sawtheng.khor@axa.com.sg <sawtheng.khor@axa.com.sg>
Sent: Saturday, 7 September, 2019 12:33 PM
To: admin-d@lkkauto.com
Subject: New message for service request 76157, vehicle number SJR608J

AXA Insurance has sent you a message for claim number S8M00ZQS.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: YT(HQ) <utauto@singnet.com.sg>
Sent: Tuesday, 10 September 2019 11:31 AM
To: Hsiao Tong (LKKAuto); 'YT(HQ)'
Cc: Admin A
Subject: RE: Accident involving SJR608J & SHD237T on 18-10-2018 *** LKK REF: CC4/ASM18019177/Upa3

Hi

ok accept

Best Regards

Shaun Teh LM

9743 2262

www.yewteegroup.com

info@yewteegroup.com

Like Us On Facebook

Managing Director of

-YEW TEE AUTOMOBILE TECH PTE LTD

-YEW TEE (CAMBODIA) AUTOMOBILE CO. LTD



WEST HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081

Fax: 6760 4895

Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4

Unit No #01-60/61

Singapore 417800

DID: 6702 3113 (3 Lines)

Fax: 6702 3773

Email: utauto2@singnet.com.sg

NORTH Branch:

Mega@Woodlands

39 Woodlands Close #01-12

Singapore 737856

DID: 6256 2081 (3 Lines)

Fax: 6256 2533

Email: info@yewteegroup.com

please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Hsiao Tong (LKKAuto)

Sent: Tuesday, 10 September, 2019 11:29 AM

To: YT(HQ) <info@yewteegroup.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Accident involving SJR608J & SHD237T on 18-10-2018 *** LKK REF: CC4/ASM18019177/Upa3

Without Prejudice

Dear Sirs/Mdm,

Thank you for your patience.

We propose settlement at a global sum of **\$6,300.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) <info@yewteegroup.com>

Sent: Thursday, 6 December 2018 3:54 PM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; YT(HQ) <info@yewteegroup.com>

Subject: RE: Accident involving SJR608J & SHD237T on 18-10-2018 *** LKK REF: CC4/ASM18019177/ea3

Hi Asher,

Attached the LOD for your kind perusal.

Appreciate your quick response.

Thank you

Best Regards

Vinnie Lim



Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DD: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: yt@auto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID:62562081
Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Yew Tee (HQ) [<mailto:utauto@singnet.com.sg>]
Sent: Monday, 22 October, 2018 6:35 PM
To: Mei Kwan (LKKAuto)
Cc: YT(HQ); Asher Sng (LKKAuto); Joy Irene (LKKAuto); Admin A
Subject: Re: Accident involving SJR608J & SHD237T on 18-10-2018 *** LKK REF: CC4/ASM18019177/ea3

Hi

Based on bola sceno I believe that liability should be clear for direct settlement we are not talking on the merit of the case

Best Regards
Shaun Toh L M

9743 2262 / 8100 7999
Website: www.yewteegroup.com
Like Us On Facebook

Director of
-YEW TEE AUTOMOBILE TECH PTE LTD
-ULTIMAX LEASING PTE LTD
-SKT TYRES & BATTERY SERVICES PTE LTD
-YEW TEE (CAMBODIA) AUTOMOBILE CO. LTD



HQ:
[Blk 6 Woodlands Road 399F](#)
Yew Tee Ind. Est

Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road 4
Unit No #01-60/61
Singapore 417800
DID: 6702 3113 (3 Lines) Fax: 6702 3773
Email: utauto2@singnet.com.sg

Please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person

On 22 Oct 2018, at 18:32, Mei Kwan (LKKAuto) <Meikwan@lkkauto.com> wrote:

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Please be informed that we are currently **pending verification for direct settlement**.

Eyi, OI has reported. Please refer to the below OI's sketch plan and statement.

<image002.png>

<image003.png>

Please provide us the following.

- *evidence i.e. video and scene photo*
- *estimated cost of repair*

Please note that for liability, claim negotiation and settlement, please contact Asher at 6841 0051.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) <info@yewteegroup.com>

Sent: Friday, 19 October, 2018 11:18 AM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Cc: YT(HQ) <info@yewteegroup.com>

Subject: Accident involving SJR608J & SHD237T on 18-10-2018

Dear Sir/Madam,

Attached the GIA report for your kind perusal.

Kindly arrange survey before repair at Yew Tee HQ.

Please let us have the surveyor list to choose for and the officer in charge too.

Thank you

Best Regards

Vinnie Lim

<image004.png>

Yew Tee Automobile Tech Pte Ltd

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: utauto2@singnet.com.sg

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID: 62562081

Email: info@yewteegroup.com

 please consider the environment before printing this email

Notice: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Yew Tee Automobile Tech Pte Ltd

Blk 6 Woodlands Road 399F Yew Tee Ind. Est.

Singapore 678006

Tel: 67653373 Fax: 67604895

06.12.18

AXA Insurance Singapore
143 Cecil Street
#01-01 GB Building
Singapore 069542

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING VEHICLE: SJR608J & SHD237T on 18/10/2018

We are the authorized repair workshop for the owner of motor vehicle no: SJR608J which was involved in the captioned accident with your insured vehicle: SHD237T. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Cost of repair	\$	5,638.40
02)	TP search fee	\$	27.10
		\$	5,665.50
	7% GST	\$	396.59
	Sub Total	\$	6,062.09
03)	Loss of Use 5 days@ \$60 per day	\$	300.00
	Grand Total	\$	<u>6,362.09</u>

We enclosed herewith the following documents to support the claims:-

- a) Tax Invoice/ Letter of authorisation
- b) GIA report

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours faithfully


Sham Toh - 97432262

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18019177/Upa3s2	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: STACEY NG			Date : 30-09-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 237T	Veh. Inspected	SJR 608J	
Policy No.	VPX/P1680520	Coverage (\$)	0.00	
Claim No.	S8M00ZQS	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	19/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11113772	Colour	WHITE	
Odometer	039183	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/10/2018	Inspection Date	22/10/2018	
Survey held at	BLK 6 WOODLANDS RD 399F			
Repairer	YEW TEE AUTOMOBILE TECH PL			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 608J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (WCP) (CONSISTENT)	DISTORTED	180.00	180.00
2	FRONT BUMPER SIDE RETAINERS (WCP) (CONSISTENT)	BENT	20.00	20.00
1	FRONT BUMPER FOG LAMP COVER LH (WCP) (CONSISTENT)	TWISTED	18.00	15.00
1	FRONT BUMPER FOG LAMP LH (WCP) (CONSISTENT)	CRACKED	164.00	140.00
1	FRONT BUMPER LOWER GUARD (WCP) (CONSISTENT)	CUT / TORN	158.00	120.00
1	FRONT BUMPER REINFORCEMENT (WCP) (CONSISTENT)	BENT	198.00	180.00
1	FRONT BUMPER LOWER RUBBER (WCP) (CONSISTENT)	DEFORMED	48.00	40.00
1	FRONT BUMPER LOWER GRILLE (WCP) (CONSISTENT)	NOT NECESSARY	48.00	-
1	FRONT HORN (WCP) (CONSISTENT)	CRACKED	33.00	28.00
1	FRONT GRILLE BASE (WCP) (CONSISTENT) }	CRACKED	187.00	170.00
1	FRONT GRILLE OUTER (WCP) (CONSISTENT) }		154.00	-
2	FRONT GRILLE CHROME MOULDING @ \$25.00 (WCP) (CONSISTENT) }		50.00	-
1	FRONT GRILLE LOGO (WCP) (CONSISTENT) }		18.00	-
1	FRONT GRILLE TOP BRACKET (WCP) (CONSISTENT)	NOT NECESSARY	55.00	-
1	FRONT HEADLAMP LH (WCP) (CONSISTENT)	HOLDER CRACKED	880.00	790.00
1	FRONT HEADLAMP LOWER BRACKET LH (WCP) (CONSISTENT)	CRACKED	30.00	20.00
1	BONNET (WCP) (CONSISTENT)	BUCKLED	418.00	380.00
1	BONNET HINGES LH (WCP) (CONSISTENT)	BENT	34.00	28.00
1	BONNET HINGES RH (WCP) (CONSISTENT)	BENT	34.00	28.00
1	BONNET LOCK (WCP) (CONSISTENT)	TWISTED	73.00	65.00
1	BONNET RUBBER (WCP) (CONSISTENT)	NECESSARY	19.00	15.00
1	FRONT SUPPORT PANEL (WCP) (CONSISTENT)	DENTED / BENT	352.00	295.00
1	FRONT SUPPORT PANEL TOP GARNISH (WCP) (CONSISTENT)	DEFORMED / TWISTED	46.00	40.00
1	FRONT AIR INTAKE DUCT (WCP) (CONSISTENT)	TWISTED / CRACKED	45.00	40.00
1	FRONT AIR INTAKE JOINT PIPE (WCP) (CONSISTENT)	NOT NECESSARY	48.00	-
1	AIR CON CONDENSER (WCP) (CONSISTENT)	BENT / PUNCTURE	310.00	310.00

Report Ref No. CC4/ASM18019177/Upa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON CONDENSER AIR GUIDE LH (WCP) (CONSISTENT)	DEFORMED	25.00	20.00
1	RADIATOR (WCP) (CONSISTENT)	BENT / TWISTED	700.00	700.00
1	RADIATOR FAN COWLING (WCP) (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT FENDER LH (NPA) (WCP) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER INNER SHIELD LH (WCP) (CONSISTENT)	TORN	80.00	70.00
1	FRONT FENDER WHEEL ARCH GARNISH LH (WCP) (CONSISTENT)	TORN	55.00	50.00
1	BATTERY + VE COVER (WCP) (CONSISTENT)	NOT NECESSARY	19.00	-
	COST PLUS 10%		457.90	374.40
			5,036.90	4,118.40
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	BENT	35.00	35.00
1	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	FRONT FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	BATTERY (SN) (CONSISTENT)	DENTED	130.00	80.00
			270.00	150.00
	LABOUR			
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		30.00	20.00
	TO PRESSURE TEST AIR CON CONDENSER AND RADIATOR FOR LEAKAGE.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT AIR-CON COMPRESSOR, AIR-CON MOTOR, CONDENSER, PIPES & VACUUM, INCLUDING REFILLING OF GAS.		180.00	100.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		750.00	520.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		60.00	30.00

Report Ref No. CC4/ASM18019177/Upa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PARTS FOR RUST PROTECTION.	NOT NECESSARY	60.00	-
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLAENING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		800.00	700.00
			2,000.00	1,370.00
GRAND TOTAL			7,306.90	5,638.40
RECOMMENDED COST OF REPAIRS				5,638.40

Report Ref No. CC4/ASM18019177/Upa3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.