

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>Dis</i>	154.00 <i>180</i>	154.00	+10.00	169.40
2	<i>2</i>	FRONT BUMPER SIDE RETAINERS <i>Bel</i>	12.00 <i>20</i>	12.00	+10.00	13.20
3	1	FRONT BUMPER FOG LAMP COVER LH <i>Tw</i>	18.00 <i>15</i>	18.00	+10.00	19.80
4	1	FRONT BUMPER FOG LAMP LH <i>Cne</i>	164.00 <i>140</i>	164.00	+10.00	180.40
5	1	FRONT BUMPER LOWER GUARD <i>Cut/To</i>	158.00 <i>120</i>	158.00	+10.00	173.80
6	1	FRONT BUMPER REINFORCEMENT <i>Sc</i>	198.00 <i>180</i>	198.00	+10.00	217.80
7	1	FRONT BUMPER LOWER RUBBER <i>De</i>	48.00 <i>40</i>	48.00	+10.00	52.80
8	1	FRONT BUMPER LOWER GRILLE <i>21X</i>	48.00	48.00 <i>X</i>	+10.00	52.80
9	1	FRONT HORN LH <i>Cne</i>	33.00 <i>28</i>	33.00	+10.00	36.30
10	1	FRONT GRILLE BASE <i>Cne</i>	187.00 <i>170</i>	187.00	+10.00	205.70
11	1 <i>Complete</i>	FRONT GRILLE OUTER <i>c</i>	154.00	154.00 <i>X</i>	+10.00	169.40
12	2	FRONT GRILLE CHROME MOULDING <i>X</i>	25.00	50.00 <i>X</i>	+10.00	55.00 <i>12</i>
13	1	FRONT GRILLE LOGO	18.00	18.00 <i>X</i>	+10.00	19.80
14	1	FRONT GRILLE TOP BRACKET <i>11 X</i>	55.00	55.00 <i>X</i>	+10.00	60.50
15	1	FRONT HEADLAMP LH <i>holder Cne</i>	880.00 <i>790</i>	880.00	+10.00	968.00
16	1	FRONT HEADLAMP LOWER BRACKET LH <i>CPR</i>	30.00 <i>20</i>	30.00	+10.00	33.00
17	1	BONNET <i>Sc</i>	418.00 <i>380</i>	418.00	+10.00	459.80
18	1	BONNET HINGES LH <i>Bel</i>	34.00 <i>28</i>	34.00	+10.00	37.40
19	1	BONNET HINGES RH <i>Bel</i>	34.00 <i>28</i>	34.00	+10.00	37.40
20	1	BONNET LOCK <i>Tw</i>	73.00 <i>65</i>	73.00	+10.00	80.30
21	1	BONNET RUBBER <i>Bel</i>	19.00 <i>15</i>	19.00	+10.00	20.90
22	1	FRONT SUPPORT PANEL <i>700/Bel</i>	352.00 <i>295</i>	352.00	+10.00	387.20
23	1	FRONT SUPPORT PANEL TOP GARNISH <i>Del/Tw</i>	46.00 <i>40</i>	46.00	+10.00	50.60
24	1	FRONT AIR INTAKE DUCT <i>Tw/Cne</i>	45.00 <i>40</i>	45.00	+10.00	49.50
25	1	FRONT AIR INTAKE JOINT PIPE <i>11</i>	48.00	48.00 <i>X</i>	+10.00	52.80
26	1	AIR CON CONDENSER <i>Bel/2m</i>	308.00 <i>310</i>	308.00	+10.00	338.80
27	1	AIR CON CONDENSER AIR GUIDE LH <i>De</i>	25.00 <i>20</i>	25.00	+10.00	27.50
28	1	RADIATOR <i>Bel/Tw</i>	310.00 <i>700</i>	310.00	+10.00	341.00
29	1	RADIATOR FAN COWLING <i>11 X</i>	80.00	80.00 <i>X</i>	+10.00	88.00
30	1	FRONT FENDER LH <i>11 X</i>	0.00	0.00 <i>X</i>	+10.00	0.00
31	1	FRONT FENDER INNER SHIELD LH <i>To</i>	80.00 <i>70</i>	80.00	+10.00	88.00
32	1	FRONT FENDER WHEEL ARCH GARNISH LH <i>To</i>	55.00 <i>50</i>	55.00	+10.00	60.50
33	1	BATTERY +VE COVER <i>11</i>	19.00	19.00 <i>X</i>	+10.00	20.90
Total Parts (\$\$)						4,568.30

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS <i>11</i>	35.00	35.00	0.00	35.00
2	1	FRONT NUMBER PLATE <i>Bel</i>	35.00	35.00	0.00	35.00
3	1	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>11</i>	35.00	35.00 <i>X</i>	0.00	35.00
4	1	FRONT FENDER INNER SHIELD CLIPS <i>11</i>	35.00	35.00 <i>X</i>	0.00	35.00
5	1	BATTERY <i>D</i>	130.00	130.00 <i>80.5</i>	0.00	130.00
Sub Total (\$\$)						270.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical	30.00	30.00 <i>20</i>	0.00	30.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
2	1	wiring Harness Wire, Sockets, Replace Damaged Parts.				
		To Pressure Test Air Con Condenser and Radiator For Leakage.	11 120.00	120.00	X 0.00	120.00
3	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	100 0.00	180.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	750.00	750.00	520 0.00	750.00

Gross Labour Cost (\$\$) 1,080.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	30 0.00	60.00
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	11 60.00	X 0.00	60.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	800.00	700 0.00	800.00

Gross Labour Cost (\$\$) 920.00

< END OF ESTIMATES >

P - 3744
 + 102
 4118.40
 S.N + 150
 labour + 1370
\$ 5638.40