

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1810/012
Policy No:	5079106090-02	Date of Loss:	18/10/2018
Vehicle Reg. No.:	SJR608J	Driveable?	yes
Driver Age:	1976-10-28	Third Party Vehicle No.:	SHD237T
Any Injuries?	no	Contact No:	98440167
Insured/Claimant:	LEE HWAN CHER, JOYCE	Driver:	LEE HWAN CHER, JOYCE

Make/Model:	Honda, Vezel - RU1	Vehicle Reg. Date:	06/04/2016
Vehicle Colour:	WHITE	Engine Number:	L15B4033777
Chassis No:	RU11113772	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION - MAJOR/MINOR
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	4,568.30
Labour	270.00
Paintwork Labour	1,080.00
Towing	920.00
	0.00
Gross Total(S\$):	6,838.30
GST 7.00%(S\$):	478.68
Nett Amount(S\$):	7,316.98

This claim is handled by: Sky Toh T C

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorised
with merits
22/10/18
take photo before painting
4 day - 5 day.

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>Dis</i>	154.00	154.00	+10.00	169.40
2	1	FRONT BUMPER SIDE RETAINER LH <i>Ref</i>	12.00	12.00	+10.00	13.20
3	1	FRONT BUMPER FOG LAMP COVER LH ?	18.00	18.00	+10.00	19.80
4	1	FRONT BUMPER FOG LAMP LH ?	164.00	164.00	+10.00	180.40
5	1	FRONT BUMPER LOWER GUARD <i>cut/zone</i>	158.00	158.00	+10.00	173.80
6	1	FRONT BUMPER REINFORCEMENT <i>SH</i>	198.00	198.00	+10.00	217.80
7	1	FRONT BUMPER LOWER RUBBER ?	48.00	48.00	+10.00	52.80
8	1	FRONT BUMPER LOWER GRILLE ?	48.00	48.00	+10.00	52.80
9	1	FRONT HORN LH ?	33.00	33.00	+10.00	36.30
10	1	FRONT GRILLE BASE <i>one</i>	187.00	187.00	+10.00	205.70
11	1	FRONT GRILLE OUTER <i>one</i>	154.00	154.00	+10.00	169.40
12	2	FRONT GRILLE CHROME MOULDING <i>misson</i>	25.00	50.00	+10.00	55.00 <i>IPC</i>
13	1	FRONT GRILLE LOGO <i>new</i>	18.00	18.00	+10.00	19.80
14	1	FRONT GRILLE TOP BRACKET <i>one</i>	55.00	55.00	+10.00	60.50
15	1	FRONT HEADLAMP LH <i>holder one</i>	880.00	880.00	+10.00	968.00
16	1	FRONT HEADLAMP LOWER BRACKET LH ?	30.00	30.00	+10.00	33.00
17	1	BONNET <i>one</i>	418.00	418.00	+10.00	459.80
18	1	BONNET HINGES LH ?	34.00	34.00	+10.00	37.40
19	1	BONNET HINGES RH ?	34.00	34.00	+10.00	37.40
20	1	BONNET LOCK <i>two</i>	73.00	73.00	+10.00	80.30
21	1	BONNET RUBBER <i>new</i>	19.00	19.00	+10.00	20.90
22	1	FRONT SUPPORT PANEL ?	352.00	352.00	+10.00	387.20
23	1	FRONT SUPPORT PANEL TOP GARNISH ?	46.00	46.00	+10.00	50.60
24	1	FRONT AIR INTAKE DUCT ?	45.00	45.00	+10.00	49.50
25	1	FRONT AIR INTAKE JOINT PIPE ?	48.00	48.00	+10.00	52.80
26	1	AIR CON CONDENSER ?	308.00	308.00	+10.00	338.80
27	1	AIR CON CONDENSER AIR GUIDE LH ?	25.00	25.00	+10.00	27.50
28	1	RADIATOR ?	310.00	310.00	+10.00	341.00
29	1	RADIATOR FAN COWLING <i>new</i>	80.00	80.00	+10.00	88.00
30	1	FRONT FENDER LH <i>new</i>	0.00	0.00	+10.00	0.00
31	1	FRONT FENDER INNER SHIELD LH <i>new</i>	80.00	80.00	+10.00	88.00
32	1	FRONT FENDER WHEEL ARCH GARNISH LH <i>new</i>	55.00	55.00	+10.00	60.50
33	1	BATTERY +VE COVER ?	19.00	19.00	+10.00	20.90

Total Parts (\$\$) 4,568.30

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS <i>new</i>	35.00	35.00	0.00	35.00
2	1	FRONT NUMBER PLATE <i>Ref</i>	35.00	35.00	0.00	35.00
3	1	FRONT SUPPORT PANEL TOP GARNISH CLIPS	35.00	35.00	0.00	35.00
4	1	FRONT FENDER INNER SHIELD CLIPS <i>new</i>	35.00	35.00	0.00	35.00
5	1	BATTERY	130.00	130.00	0.00	130.00

Sub Total (\$\$) 270.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical	30.00	30.00 <i>20</i>	0.00	30.00

Estimates On Labour			Rate	Amount	%Disc	After Disc
No.	Qty	Particulars				
2	1	wiring Harness Wire, Sockets, Replace Damaged Parts. To Pressure Test Air Con Condenser and Radiator For Leakage.	11 120.00	120.00	X 0.00	120.00
3	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	180.00	180.00	? 0.00	180.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	750.00	750.00	520 0.00	750.00
Gross Labour Cost (\$\$)						1,080.00

Estimates On Paint Work Labour			Rate	Amount	%Disc	After Disc
No.	Qty	Particulars				
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	30 0.00	60.00
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00 11	60.00	X 0.00	60.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	800.00	700 0.00	800.00
Gross Labour Cost (\$\$)						920.00

< END OF ESTIMATES >