

ASS. REC. BY:

REF: CS/FCI18019220/K1td3n2

Special Instruction:

Surveyor:

KALVIN

ASSIGNMENT (Office)

From (Person):

Sithera

of

FCI

Date/Time:

23/10/18 @ 12.01pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6770K

Insured:

SHC 7991H

at Workshop m/s

Premier Automotive

Tel:

6544 6689

of

23 Cheng south Ave 2 #03-02

Policy No:

Claim No:

D18007641MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/10/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

12.39pm @ 23/10/18

Person Contacted:

Vincent

Vehicle

☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC6770K - NS/INC18019167/K1tb DOR: 19/10/18
	SHC7991H - NS/INC18019167/K1tb DOR: 19/10/18
24/10 @ 2:51pm	revised preli advise via email.

MOTOR SURVEY ASSIGNMENT

Date	22-10-2018	Our Ref No. D18007641MFSH
Accident Date	19-10-2018	Claim Type. Third Party
Insured Vehicle	SHC7991H	Third Party Vehicle. SHC6770K
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 24 October 2018 2:51 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007641MFSH/1
Attachments: PRELI ADVISED SHC 6770K.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 6770K**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 23 October 2018 1:12 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007641MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 23 October, 2018 12:01 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007641MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007641MFSH

Date: 24/10/2018

Our Ref: CS/FCI18019220/K1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKV 7790K

Please be informed that we had conducted the inspection of the abovementioned vehicle
18/10/2018 at the premises of M/s Premier have the following to report: -

Workshop Estimate Amount	: S\$ 2,740.30
Revised Estimate Amount	: S\$ 1,935.50
"Check" Items Amount	: S\$ 14.40
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
n/s front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kalvin

Automotive Assessor

[Text size +](#)**Enquire Transaction History****Transaction History Details**

Log Date/Time:	30 Apr 2015 / 09:22:50	Receipt No.:	AACCK001-AX239-150430-000006
Asset Type:	Vehicle	Transaction Amount:	\$64,849.00
Asset ID:	SHC6770K	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150430092250029620		
Vehicle No.:	SHC6770K		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	30 Apr 2015		
Original Registration Date:	30 Apr 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5593467		
Engine No.:	D4FDEH313373		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$21,451.00		
Minimum PARF Benefit:	\$8,719.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	30 Apr 2015 09:22:50		
COE No.:	2015043001002318C		
COE Expiry Date:	29 Apr 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$50,177.00		
Lifespan Expiry Date:	29 Apr 2023		

CASH SALE/WORK ORDER

No:AD 4583



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 19/10/18

寶號

Messrs:

車號

Vehicle No:

由

From:

到

To:

其他

Remark:

時間

Time:

22:13:22:53:23:35

AMOUNT: \$

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

收貨人

Received by:

No Video

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6770 K

1 pc	Front bumper	531.00	\$	531.00
1 pc	Front bumper emblem @ \$44.00	44.00	\$	44.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	32.00	\$	32.00
1 pc	Front n/s wheel cover @ \$116.00	116.00	\$	116.00
1 pc	Front n/s fender @ \$384.00	384.00	\$	384.00
1 pc	Front n/s fender inner shield @ \$120.00	120.00	\$	120.00
		1,227.00	\$	1,227.00
	Less 10%	122.70	\$	122.70
		1,104.30	\$	1,104.30

S/NETT

1 set	Front bumper clips	48.00	\$	48.00
1 pc	Front n/s fender sticker	30.00	\$	30.00
1 set	Front n/s fender inner shield clips	28.00	\$	28.00
	Sundry	50.00	\$	50.00
	Towing Fee	50.00	\$	50.00
	To check front n/s wheel alignment	80.00	\$	80.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	180.00	\$	180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	650.00	\$	650.00
	To putty and spray painting on front bumper, front n/s fender	400.00	\$	400.00
	To apply rustproofing on the repaired and replaced panels.	120.00	\$	120.00
		2,740.30	\$	2,740.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalir (UKK)
23/10/18/Book
3 R,
4s
Alta Rep photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18019220/K1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7991H	Veh. Inspected	SHC 6770K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007641MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	23/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5593467	Colour	SILVER	
Odometer	348298	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/10/2018	Inspection Date	23/10/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6770K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
2	FRONT BUMPER N/S & O/S SIDE RETAINER @\$16.00	SERVICEABLE	32.00	-
1	FRONT N/S WHEEL COVER	GRAZED	116.00	116.00
1	FRONT N/S FENDER	DENTED	384.00	384.00
1	FRONT N/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
	LESS 10% DISCOUNT		-122.70	-107.50
			1,104.30	967.50
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			156.00	68.00
LABOUR				
	TOWING FEE.		50.00	50.00
	TO CHECK FRONT N/S WHEEL ALIGNMENT.		80.00	60.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING TO KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE OF THE END PANEL, ETC.		650.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT N/S FENDER.		400.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	30.00
			1,480.00	900.00
GRAND TOTAL			2,740.30	1,935.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,550.00

Report Ref No. CS/FCI18019220/K1td3n2



Report Ref No. CS/FCI18019220/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.