

REPAIR ESTIMATE

22/10/2018 11:20

VEHICLE NO : SHC 2194A

MAKE :

MODEL : TOYOTA PRIUS

Chiang

AGA

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
BONNET ✓			\$ 950.50
INSULATOR, HOOD ✓			\$ 398.10
INSULATOR CLIPS ✓			\$ 3.60
BONNET RUBBER ✓			\$ 35.50
BONNET HINGE (RH) ✓			\$ 57.70
BONNET HINGE (LH) ✓			\$ 57.70
BONNET LOCK ✓			\$ 132.60
CATCH, HOOD AUXILIARY HOOK ✓			\$ 8.60
RADIATOR GRILLE ✓			\$ 438.00
RADIATOR GRILLE EMBLEM ✓			\$ 88.00
LAMP SET, STOP CENTER ?			\$ 231.30
LAMP ASSY, FOG, RH ✓			\$ 920.00
LAMP ASSY, FOG, LH ✓			\$ 920.00
BULB, FOG LAMP, LH ✓			\$ 34.00
FRONT BUMPER COVER ✓			\$ 499.90
FRONT BUMPER REINFORCEMENT ✓			\$ 696.40
FRONT BUMPER REINFORCEMENT ABSORBER ✓			\$ 115.70
FRONT BUMPER SPONGE ✓			\$ 78.80
FRONT BUMPER CENTRE GRILLE ✓			\$ 301.90
FRONT BUMPER LOWER GRILLE ✓			\$ 166.90
FRONT BUMPER CLIPS ✓			\$ 22.00
FRONT BUMPER SIDE RETAINER ✓		\$ 77.00	\$ 154.00
FRONT LOWER CROSSMEMBER x repl			\$ 357.70
FRONT UNDER COVER x			\$ 180.80
SUPPORT FR BUMPER, RH ✓			\$ 81.70
SUPPORT FR BUMPER, LH ✓			\$ 81.70
FRONT BUMPER CENTRE FRAME ✓			\$ 236.90
BRACKET, FRONT BUMPER MOUNTING ✓			\$ 29.60
BRACKET, FRONT BUMPER MOUNTING, NO.2 ✓			\$ 97.80
UNIT ASSY, HEADLAMP, RH (LED) ✓			\$ 3,455.00
UNIT ASSY, HEADLAMP, LH (LED) ✓			\$ 3,455.00
HEAD LAMP PANEL (RH) ✓			\$ 240.10
HEAD LAMP PANEL (LH) ✓			\$ 240.10
TOP PANEL CENTRE ✓			\$ 364.90
TOP PANEL SIDE ✓			\$ 69.20
TOP PANEL SIDE ✓			\$ 69.20
BRACE PANEL			\$ 75.20
BRACKET, HEADLAMP MOUNTING, RH x			\$ 25.50
BRACKET, HEADLAMP MOUNTING, LH x			\$ 25.50
RADIATOR ASSY x			\$ 1,841.80
RADIATOR BOTTOM MOUNTING x			\$ 27.50
HORN WIRE x			\$ 6,079.70
HORN (1 PC) x			\$ 112.71
CLEANER ASSY, AIR ✓			\$ 970.30
AIR DUCT ✓			\$ 129.40
CONDENSER ASSY, W/RECEIVER ✓			\$ 1,336.60

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
FENDER SUB-ASSY, FRONT LH ✓			\$ 945.30	
FRONT FENDER SHIELD, LH ✓			\$ 196.60	
FRONT FENDER SHIELD CLIP ✓			\$ 3.80	
FRONT FENDER HYBRID EMBLEM, LH ✓			\$ 53.50	
BRACKET, FRONT SIDE PANEL, LH ✓			\$ 44.50	
EXTENSION, FRONT FENDER, LH ✓			\$ 47.20	
PROTECTOR, FRONT FENDER, UPPER, LH ?			\$ 46.10	
TRAY, BATTERY ✕			\$ 42.80	
CLAMP, BATTERY ✕			\$ 16.10	
FRONT DOOR SAFETY BELT (LH/RH) ✓		\$ 846.10	\$ 1,692.20	
REAR DOOR SAFETY BELT (LH/RH) ✓		\$ 838.00	\$ 1,676.00	
FRONT WINDSCREEN GLASS ✓			\$ 1,627.30	
FRONT WINDSCREEN GLASS MOULDING ✓			\$ 208.60	
FRONT WINDSCREEN GLASS PILLAR ✕ <i>reper</i>			\$ 343.10	
FRONT CHASSIS MEMBER (LH) ✕ <i>reper</i>			\$ 2,035.10	
COMPUTER ASSY, AIR BAG ECU (STEERING AIR BAG) ✓			\$ 2,402.20	
SIDE AIRBAG, LH ✓			\$ 1,479.00	
SIDE AIRBAG, RH ✓			\$ 1,479.00	
AIR BAG ASSY, DRIVER SIDE LOWER, RH ✓			\$ 1,615.00	
AIR BAG ASSY, FRONT SEAT, RH ✓			\$ 857.90	
AIR BAG ASSY, FRONT SEAT, LH ✓			\$ 857.90	
AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR, LH ✓			\$ 3,277.50	
SENSOR ASSY, SIDE AIR BAG, RH ✓			\$ 709.30	
SENSOR, AIR BAG, REAR RH ✓			\$ 567.80	
SUB TOTAL			\$ 48,118.91	
LESS 20%			\$ 9,623.78	
DISCOUNTED TOTAL			\$ 38,495.13	
FRONT NO. PLATE ✓			\$ 25.00	NETT
FRONT NO PLATE TRIM COVER ✓			\$ 30.00	NETT
FRONT NO.PLATE GARNISH ✓			\$ 99.00	NETT
FRONT BUMPER LOGO ✓			\$ 87.10	NETT
FRONT WINSCREEN SEALANT ✓			\$ 46.00	NETT
			\$ 287.10	

SHC 2194A

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
LABOUR CHARGE			1400
Panel Beating		\$	2,000.00
Spray Painting Charge		\$	1,500.00 1000
Wiring Charge		\$	50.00 20
Tuff Kote		\$	50.00 20
Towing Charge		\$	60.00
Front Chassis Alignment Charge		\$	400.00 100
Remove/Refix Radiator		\$	280.00 50
Remove/Refix Aircon & Refill Gas		\$	150.00 60
Remove/Refix Engine		\$	450.00 X
Remove/Refix Dashboard		\$	400.00 100
Remove/Refix Fuse Box		\$	120.00 X
Remove/Refix Front Windscreen Glass		\$	90.00 90
Remove/Refix Cushion & Upholstery Front		\$	150.00 50
R/Refix Air Bag/Steering Wheel/Dashboard/Seat		\$	550.00 200
TOTAL LABOUR		\$	6,250.00
ESTIMATE TOTAL		\$	45,032.23

Kahr 16004

22/10/18 1630 L.

14 Days

PIP

Before Part photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be insured and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.