

INSURANCE

INS. CASE OWNER

CC 3/AIG1801

AMY, K. J. 6/6/18

LKK

IDAC

Surveyor:

Fennell

DOI:

ASSIGNMENT

21/10/18

Date / Time:

21/10/18

Registered in Merimen:

21/10/18

Pre-assign / CCU / FTE



Insured Vehicle No.

SGS 1306D

Name of Insured

YAP POO LAM

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

18/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MIOWS YAP YI LAM

Driver Tel No.:

(VA / YES / NO)

Claim No.

21016056456

Policy No.

20007224-11

Make / Model:

MISS AM

Place of Accident:

1105 STAMFORD RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SHD 81A



INSRS:
WSP:
Tel:
Liability:
RMKS:

Trans
Cab



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

21/10/18

21/10/18

STAGE

DATE / PIC

Non-Reporting 1st

Non-Reporting 2nd

Non-Reporting 3rd

Notification 1st (if non-pickup)

Call Of:

After call 1st to OI

204 18-10-18

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

X

After call 1st to OI

X

Authorisation To Act

X

Release Voucher

X

Final Repair Bill

X

Car Rental Invoice

X

Towing Invoice

X

LTA / GIA

X

Medical Bill

X

PIR

X

Mandate/Reject Instruction

X

LOD

X

Payment Breakdown Form

X

Post-Repair Photos

X

Others

X

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

24-1-19

Confirm with

RMKS

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia

Repair Cost:

SS

4,024.32

Loss of Rental (LOR):

SS

211.48

2 days

105.74

Loss of Use (LOU):

SS

100

(5 x 2 days)

Loss of Income (LOI):

SS

100

(50 x 2 days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

SS

7.45

Medical:

SS

=

Disbursement:

SS

=

Legal Cost:

SS

=

(e.g. Turf / Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

4,343.25

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4,343.25

Name 1:

TRANS-CAB AUTO SERVICES PRE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18019224/K1jb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 23-10-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGS 1306D	Veh. Inspected	SHD 81A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/10/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/10/2018	Inspection Date	22/10/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 81A**AAD1810-215**

Not Authorised
Resurvey B4 painting **83761.05**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 81A

VF1ABL15AUC283395

RENAULT

LATITUDE

18.10.2018

AIG**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Per</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Per</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMPR RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>RL</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>RL</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>RL</i> 225.95	✓
13	1 OUTER PANEL REAR (End Panel)	\$	<i>RL</i> 1,471.77	✓
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i> 404.56	✓
15	1 TAILLAMP RH	\$	<i>SL</i> 552.55	✓
16	1 TAILLAMP PANEL RH	\$	<i>RL</i> 986.70	✓
17	1 TAILLAMP LH	\$	<i>SL</i> 552.55	✓
18	1 TAILLAMP PANEL LH	\$	<i>RL</i> 986.70	✓
19	1 BOOT REAR	\$	<i>RL</i> 2,872.68	✓
20	1 BOOT FINISHER	\$	<i>SL</i> 470.06	✓
21	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	✓
22	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	✓
23	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	✓
24	1 BOOT BADGE 'RENAULT'	\$	<i>RL</i> 225.36	✓
25	1 BOOT BADGE	\$	<i>RL</i> 225.36	✓
26	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	✓
27	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	✓
28	1 BOOT HINGE LH	\$	<i>RL</i> 367.84	✓
29	1 BOOT HINGE RH	\$	<i>RL</i> 367.84	✓

Trans-cab Auto Services Pte Ltd

AAD1810-215

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 81A

30	1 BOOT INNER TRIM	\$	Sm 586.45 X
31	1 BOOT SWITCH	\$	Sm 168.13 X
32	1 BOOT LOCK	\$	R 202.67 X
33	1 BOOT LOCK CATCH	\$	R 74.40 X
		\$	16,046.87
	10%	\$	7.44
		\$	16,039.43

Special Nett

1	1SET PARKING AID	\$	Sm 700.00 X
2	1SET REAR BUMPER CLIP	\$	nn 66.00
3	1SET BUMPER BRACKET CTR CLIP	\$	nn 33.00
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00 X
5	1SET BUMPR RETAINER RH CLIP RR	\$	nn 20.00 X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	nn 10.00 X
7	1SET BUMPR RETAINER CLIP LH RR	\$	nn 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	nn 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	nn 66.00
10	1 EXHAUST MOUNTING REAR	\$	Sm 17.82 X
11	2 REAR WINDSCREEN SELANT	\$	nn 80.00 X
12	1 WINDSCREEN MOULDING	\$	Sm 100.00 X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	Sm 100.00 X

TOTAL \$ 1,244.82**TOTAL PARTS \$ 17,284.25****LABOUR**

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 2,200.00

Trans-cab Auto Services Pte Ltd

AAD1810-215

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 81A

To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X

TOTAL \$ 6,610.00**Over All Total \$ 39,933.69****(PART-BY-PART)****Repair Days****10-DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD81A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003114
Chassis No.:	VF1ABL15AUC283395
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	24 Jul 2017
First Registration Date:	24 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jul 2025
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	23 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$30,848.00
Total Rebate Amount:	\$45,846.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Oct 2018

OK

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1810-215

Your Ref : SGS1306D

Date : 31 January 2019

AIG ASIA PACIFIC INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SHD0081A AND SGS1306D ON 18/10/18 03:45 PM ALONG HILL STREET

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	4,024.32
2.	Loss of Rental for <u>2</u> days @ \$ <u>105.74</u> per day	\$	211.48
3.	Loss of Income for <u>2</u> days @ \$ <u>50</u> per day	\$	100.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	4,343.29

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

Joy Irene (LKKAuto)

From: Jackson Yap <jack.yap51@gmail.com>
Sent: Wednesday, 28 November 2018 3:15 PM
To: Joy Irene (LKKAuto)
Subject: Re: ACCIDENT INVOLVING SGS 1306D AND SHD 81A ON 18/10/2018

Thank you Joy for the update .
This is reasonable and I have no issues with this claim .

On Wed, 28 Nov 2018 at 11:53 AM, Joy Irene (LKKAuto) <JoyIrene@lkkauto.com> wrote:

Our ref: CC3/AIG18019224/Kjb3

Dear Mr. Yap,

Thank you for your e-mail and call.

Our technical expert have reviewed the matter and have adjusted the claimed repair cost accordingly.

We attach our surveyor's inspection, re-inspection photos and estimate with markings for your reference.

As spoken, the estimated repair cost claimed is at \$ 39,933.69 (before GST) and this was lowered down and adjusted to \$3,761.05 in accordance to our inspection done and damages observed. We are of the opinion that the amount is already fair and reasonable.

Given that the merits of the case is not in our favour, we will proceed to resolve the Third Party claim against your motor policy amicably, to prevent further escalation of cost.

Do note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Should you have further clarifications, please call us.

Thank you.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Jackson Yap [mailto:jack.yap51@gmail.com]

Sent: Thursday, 22 November 2018 5:34 PM

To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: ACCIDENT INVOLVING SGS 1306D AND SHD 81A ON 18/10/2018

Thank you for your assistance.

On Thu, 22 Nov 2018 at 10:46 AM, Joy Irene (LKKAuto) <JoyIrene@lkkauto.com> wrote:

Dear Mr. Yap,

We take note on the damage issue.

Our surveyor will look into the matter.

We will revert to you for an update.

Thank you.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Jackson Yap [mailto:jack.yap51@gmail.com]

Sent: Thursday, 22 November 2018 10:43 AM

To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: ACCIDENT INVOLVING SGS 1306D AND SHD 81A ON 18/10/2018

Thank you Joy for your email.

Per our telephone conversation this morning , I am disputing this claim of about S\$39,000 .

This is absurd as my car barely touch his taxi

You can see the photos taken after the accident and there was not event an damage . Furthermore , my car front is so low and barely reach his boot .

I am available for your mechanic verify this .

Thank you

Jackson Yap

On Wed, 21 Nov 2018 at 7:09 PM, Joy Irene (LKKAuto) <JoyIrene@lkkauto.com> wrote:

OUR REF: LKK: CC3/AIG18019224/Kjb3

YAP FOOK CHIN

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING SGS 1306D AND SHD 81A ON 18/10/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHD0081A and SGS1306D along HILL STREET on 18/10/18 03:45 PM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 20 (day) of January 2019

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, TRANS-CAB AUTO SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 4,024.32 (Repair Cost), S\$ 311.48 (Loss of rental/^{30(1)(d)}use), S\$ 7.45 (Disbursement), for vehicle no. SHD 81A that was damaged pursuant to the accident which occurred on 18.10.2018 (date) along HILL STREET (location) involving vehicle no/s SGS 1306D. This is pursuant to the inspection conducted on 22.10.2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TRANS-CAB SERVICES PTE LTD ("the third party claimant") of vehicle no. SHD 81A make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHD 81A (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 24 (day) of 1 (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO: AIG ASIA PACIFIC INSURANCE PTE LTD 78 Shenton Way #07-16 CHARTIS Building 079120 Singapore ATTENTION:	INVOICE NO. : INV1811-274 DATE : 30. November 2018 REFERENCE NO : AAD1810-215 TERMS : Net 30 Days DUE DATE : 30. December 2018 PAGE : 1
--	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHD0081A;DOA 18.10.18(PART-BY-PART-18)	1	4,024.32	4,024.32

Total SGD Excl. GST :	3,761.05
7% GST :	263.27
Total SGD Incl. GST :	4,024.32

****** FOUR THOUSAND TWENTY FOUR AND THIRTY TWO SGD ONLY ******

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.**THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE**

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

31 January, 2019

To Whom It May Concern

Dear Sir / Madam,

Accident on 18/10/18 03:45 PM at HILL STREET

1. We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the registered owner of the taxi bearing vehicle registration no. SHD0081A. The taxi was hired to SIM BEE CHYE a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$105.74 per day (inclusive of GST).
2. Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan
General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

18-10-2018

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.
Accident No.	AAD1810-215	Accident Date 18-10-2018
22/10/2018 09:10	23/10/2018 16:00	SHD0081A

Yours Faithfully,

Trans-Cab Services Pte Ltd**Jasmine Tan****General Manager**

[➤ Back to OneMotoring](#)

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
YM6675Z	17 Oct 2018 / 13:15:00	AXA INSURANCE PTE LTD
SLJ9174C	17 Oct 2018 / 18:45:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.
GBA1777G	18 Oct 2018 / 07:25:00	NTUC INCOME INS CO-OP LTD
SLT2932A	18 Oct 2018 / 13:55:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.
SGS1306D	18 Oct 2018 / 15:45:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Print

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Oct 2018 Edit Reg		22 Oct 2018 00:00 Edit Adj Rpt	S\$3,761.05 Edit Estimates	S\$3,761.05 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: YAP FOOK CHIN , ID: S0078871F									
Main Claimant: TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K									
Vehicle Reg. No.: SHD81A		Date of Loss: 18/10/2018 15:00 - :59 [14 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2301605628SG		Policy/Cover Note No.: 2100007327 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): SGS1306D		Policy No. (Claimant): VPX/P1680520							
		Excess:							
Repairer: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, S69111 Ang Mo Kio - Tel: 62876666									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/11/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD81A (2301605628SG)
[SGS1306D]
TP
TRANS-CAB SERVICES PTE LTD
Oct 18 2018 3:00PM
[YAP FOOK CHIN]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
2	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
3	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
4	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
5	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
6	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
7	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
8	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
9	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
10	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
11	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
12	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
13	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
14	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
15	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
16	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
17	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
18	19/02/19 18:48	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 19:17	TP ESTIMATE- MARKED	Load PDF	
2	23/10/18 19:17	TP GIA REPORT	Load PDF	
3	21/02/19 13:49	WORKSHOP INVOICE	Load PDF	
4	21/02/19 13:49	AUTHORISATION TO ACT FORM	Load PDF	
5	21/02/19 13:49	Release Voucher	Load PDF	
6	21/02/19 13:49	RENTAL RECEIPT	Load PDF	
7	21/02/19 13:49	RENTAL MILEAGE	Load PDF	
8	21/02/19 13:49	LTA SEARCH	Load PDF	
9	21/02/19 13:49	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/10/18 10:43	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) | [Save](#) | [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGS1306D (Insd veh)	Model:	RENAULT LATITUDE 2.0 L
	SHD81A (TP veh)		(A)
Date of Accident:	18/10/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	23,857.78	
Final Repair Cost	: \$	4,024.32	
Loss of Use	: \$	100.00	2.00 days at \$50.00 per day
Rental (if any)	: \$	211.48	2 days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	4,343.25	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Trans-cab Auto Services Pte Ltd	: \$	4,343.25
2)		: \$	
3)		: \$	
4)		: \$	
5)		: \$	

JOANNE LEE KHANG MIN

21 Feb
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18019224/KJB3Q2

Date: 21/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100007327
Claimant Vehicle No : SHD81A **Insured Vehicle No :** SGS1306D
 Date of Loss: 18/10/2018 Nature of Claim: TP Claim No: 2301605628SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD81A**
 Make & Model: RENAULT LATITUDE, 2.0 L (A) Engine No: M9R8839C003114
 Reg. Date: 24/07/2017 (Man. Year: 2016) Chassis No: VF1ABL15AUC283395
 Colour: Metallic White/Red Odometer: 135125 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Giti 8 mm Rear Left Side: Giti 8 mm
 Front Right Side: Giti 8 mm Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,686.99	2,961.05	12,725.94	81.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,610.00	800.00	5,810.00	87.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,296.99	3,761.05	18,535.94	83.13
+ GST 7.00/7.00% (S\$)	1,560.79	263.27	1,297.52	83.13
Nett Amount (S\$)	23,857.78	4,024.32	19,833.46	83.13
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$105.74/day) (S\$)		211.48		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,343.25		

INSPECTION

Date of Assignment: 22/10/2018
 Date Inspected: 22/10/2018 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
 2, Ang Mo Kio Street 63
 Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	225.95 FL	*225.95 FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
19	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
20	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
24	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
25	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
26	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
28	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
29	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
30	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
31	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
32	1		*BOOT LOCK	Repair	202.67 FL	*- FL
33	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
34	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
35	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
36	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
39	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
40	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
41	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
42	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
43	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
44	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
45	1		*WINDSCREEN MOULDING	Serviceable	100.00 FS	*- FS
46	1		*REAR WINDSCREEN INNER SPONGE SEAL	Serviceable	100.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) 17,291.68 3,271.72

- List Item Discount on L Items 10.00/10.00% (\$\$) 1,604.69 310.67

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					15,686.99	2,961.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.Q	New	2,200.00	300.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (\$\$)			6,610.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >