

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 81A****AAD1810-215**

*Not Authorised*  
*Resurvey B4 pricing* **83761.05**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHD 81A**

VF1ABL15AUC283395

RENAULT

LATITUDE

18.10.2018

**AIG****PART****LIST**

|    |                                    |    |                     |   |
|----|------------------------------------|----|---------------------|---|
| 1  | 1 BUMPER COVER REAR                | \$ | <i>Per</i> 1,108.46 | ✓ |
| 2  | 1 BUMPER LOWER REAR                | \$ | <i>Per</i> 768.84   | ✓ |
| 3  | 1 BUMPER BRACKET CTR REAR          | \$ | <i>SL</i> 113.47    | X |
| 4  | 1 BUMEP R BRACKET SIDE RH REAR     | \$ | <i>SL</i> 135.97    | X |
| 5  | 1 BUMEP R RETAINER RH REAR         | \$ | <i>SL</i> 44.99     | X |
| 6  | 1 BUMPER REFLECTOR RH              | \$ | <i>SL</i> 43.61     | X |
| 7  | 1 BUMEP R BRACKET SIDE LH REAR     | \$ | <i>SL</i> 135.97    | X |
| 8  | 1 BUMPER RETAINER LH REAR          | \$ | <i>SL</i> 44.99     | X |
| 9  | 1 BUMPER REFLECTOR LH              | \$ | <i>SL</i> 43.61     | X |
| 10 | 1 BUMPER BEAM REAR                 | \$ | <i>R</i> 777.52     | ✓ |
| 11 | 1 BUMPER BEAM BRACKET LH REAR      | \$ | <i>R</i> 225.95     | ✓ |
| 12 | 1 BUMPER BEAM BRACKET RH REAR      | \$ | <i>R</i> 225.95     | ✓ |
| 13 | 1 OUTER PANEL REAR (End Panel)     | \$ | <i>R</i> 1,471.77   | ✓ |
| 14 | 1 OUTER PANEL REAR (End Panel)TRIM | \$ | <i>SL</i> 404.56    | ✓ |
| 15 | 1 TAILLAMP RH                      | \$ | <i>SL</i> 552.55    | ✓ |
| 16 | 1 TAILLAMP PANEL RH                | \$ | <i>R</i> 986.70     | ✓ |
| 17 | 1 TAILLAMP LH                      | \$ | <i>SL</i> 552.55    | ✓ |
| 18 | 1 TAILLAMP PANEL LH                | \$ | <i>R</i> 986.70     | ✓ |
| 19 | 1 BOOT REAR                        | \$ | <i>R</i> 2,872.68   | ✓ |
| 20 | 1 BOOT FINISHER                    | \$ | <i>SL</i> 470.06    | ✓ |
| 21 | 1 BOOT WHEATERSTRIP                | \$ | <i>SL</i> 323.05    | ✓ |
| 22 | 1 BOOT REFLECTOR LAMP LH           | \$ | <i>SL</i> 493.35    | ✓ |
| 23 | 1 BOOT REFLECTOR LAMP RH           | \$ | <i>SL</i> 493.35    | ✓ |
| 24 | 1 BOOT BADGE 'RENAULT'             | \$ | <i>SL</i> 225.36    | ✓ |
| 25 | 1 BOOT BADGE                       | \$ | <i>SL</i> 225.36    | ✓ |
| 26 | 1 BOOT STRUT LH                    | \$ | <i>SL</i> 276.08    | ✓ |
| 27 | 1 BOOT STRUT RH                    | \$ | <i>SL</i> 276.08    | ✓ |
| 28 | 1 BOOT HINGE LH                    | \$ | <i>R</i> 367.84     | ✓ |
| 29 | 1 BOOT HINGE RH                    | \$ | <i>R</i> 367.84     | ✓ |

**Trans-cab Auto Services Pte Ltd**

AAD1810-215

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 81A**

|    |                   |        |    |                  |   |
|----|-------------------|--------|----|------------------|---|
| 30 | 1 BOOT INNER TRIM | \$     | Sm | 586.45           | X |
| 31 | 1 BOOT SWITCH     | \$     | Sm | 168.13           | X |
| 32 | 1 BOOT LOCK       | \$     | R  | 202.67           | X |
| 33 | 1 BOOT LOCK CATCH | \$     | R  | 74.40            | X |
|    |                   | \$     |    | <b>16,046.87</b> |   |
|    |                   | 10% \$ |    | <b>7.44</b>      |   |
|    |                   | \$     |    | <b>16,039.43</b> |   |

**Specical Nett**

|    |                                     |    |    |                 |   |
|----|-------------------------------------|----|----|-----------------|---|
| 1  | 1SET PARKING AID                    | \$ | Sm | 700.00          | X |
| 2  | 1SET REAR BUMPER CLIP               | \$ | nn | 66.00           | ✓ |
| 3  | 1SET BUMPER BRACKET CTR CLIP        | \$ | nn | 33.00           | ✓ |
| 4  | 1SET BUMPER BRACKET SIDE CLIP RH RR | \$ | nn | 10.00           | X |
| 5  | 1SET BUMPR RETAINER RH CLIP RR      | \$ | nn | 20.00           | X |
| 6  | 1SET BUMPR BRACKET SIDE CLIP LH RR  | \$ | nn | 10.00           | X |
| 7  | 1SET BUMPR RETAINER CLIP LH RR      | \$ | nn | 20.00           | X |
| 8  | 1SET BUMPER LOWER REAR RIVET        | \$ | nn | 22.00           | X |
| 9  | 1SET BUMPER LOWER REAR CLIP         | \$ | nn | 66.00           | ✓ |
| 10 | 1 EXHAUST MOUNTING REAR             | \$ | Sm | 17.82           | X |
| 11 | 2 REAR WINDSCREEN SELANT            | \$ | nn | 80.00           | X |
| 12 | 1 WINDSCREEN MOULDING               | \$ | Sm | 100.00          | X |
| 13 | 1 REAR WINDSCREEN INNER SPONGE SEAL | \$ | Sm | 100.00          | X |
|    | <b>TOTAL</b>                        | \$ |    | <b>1,244.82</b> |   |

|                    |    |                  |
|--------------------|----|------------------|
| <b>TOTAL PARTS</b> | \$ | <b>17,284.25</b> |
|--------------------|----|------------------|

**LABOUR**

|                                                                                                                                 |    |              |
|---------------------------------------------------------------------------------------------------------------------------------|----|--------------|
| Putty And Spray Painting Of The Affected Portion.                                                                               | \$ | 44d 3,000.00 |
| Panel Beating, Knocking And Straightening The<br>Necessary Portion, Remove And Renewal Of Parts,<br>Adjust And Realign The Same | \$ | 30d 2,200.00 |

**Trans-cab Auto Services Pte Ltd****AAD1810-215**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 81A**

|                                                                                      |    |        |          |
|--------------------------------------------------------------------------------------|----|--------|----------|
| To Rust-Proofing Of The Affected Areas.                                              | \$ | 170.00 | X        |
| To reinstall rear bumper parking sensor.                                             | \$ | 170.00 | 601      |
| To transfer of bootlid fittings, attachments and perform water seepage test.         | \$ | 170.00 | 170.00 X |
| To repair and realign rear exhaust pipe.                                             | \$ | 170.00 | 170.00 X |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. | \$ | 170.00 | 170.00 X |
| To transfer of rear end panel fittings, attachment and perform water seepage test.   | \$ | 170.00 | 170.00 X |
| To transfer of rear windscreen fittings and conduct water seepage test.              | \$ | 170.00 | 170.00 X |
| To check steering geometry and computer wheel alignment                              | \$ | 220.00 | 220.00 X |

**TOTAL \$ 6,610.00****Over All Total \$ 39,933.69****(PART-BY-PART)****Repair Days****10 DAYS****2 day,**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: