

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Oct-18

ESTIMATE REPAIR BILL FOR MERCEDES W212 REGN NO: SHB 9000 K

1 pc	Bonnet <i>X/R</i>	\$	2,151.09
1 pc	Front bumper	\$	1,184.55
1 pc	Front bumper o/s side bracket	\$	98.07
1 pc	o/s headlamp	\$	1,011.30
1 pc	o/s fog lamp chrome ?	\$	44.82
1 pc	o/s fog lamp ?	\$	223.34
1 pc	Front o/s fender	\$	937.80
1 pc	Front o/s fender inner shield ?	\$	142.00
1 pc	Front o/s rim	\$	427.31
1 pc	Bonnet actuator- o/s	\$	318.60
1 pc	Front o/s shock absorber ?	\$	694.00
1 pc	Front o/s tie rod ?	\$	161.00
1 pc	Front o/s trust arm ?	\$	98.73
1 pc	Front o/s lower strut ?	\$	177.60
1 pc	Front o/s upper strut ?	\$	177.66

Less 10%

S/nett

1 set	Front bumper clips	\$	52.00
1 set	Front o/s fender inner shield clips	\$	30.00

Sundry

To check wheel alignment

To dismantle and replace front o/s undercarriage

To check system check light, wiring & computer reset

To labour charge for dismantle and renew the accident damaged parts. To panel beat, knock out, straighten and adjust on the same etc

To putty and spray painting on front bumper, front o/s fender, bonnet

To apply rustproofing on repair/replace panel

Towry fee

\$50

LKK Auto Consultants hence notify

Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Any item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

\$ 120.00 *50*

\$ 9,275.08

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kalve (K/K)
23/10/18 1020h
4 days
After Repair photo.

CASH SALE/WORK ORDER No:AL 0091



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 20/10/2018

賣號

Messrs: P. Ramanathan

車號

Vehicle No:

SUB9000K

車型

Model No:

B200

由

From:

River Valley (SAC)

到

To:

OMEGA

其他

Remark:

OK

時間

Time:

02:28:03:00:03:45

AMOUNT:

\$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

收貨人

Received by: