

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05869

Vehicle Insured : SGC2002H

Accident Date : 20-Oct-2018

Date : 22-Oct-2018

Our Ref : 218174 (AIG) / CHAN

PAGE : 1

ERIC LIM SOON MENG(ERIC LIN SHUNMING)

BLK 412 SERANGOON CENTRAL

#05-329

Singapore 550412

*Not Authorized
Resurvey 1-B.1
Blepping*

ESTIMATED COST OF REPAIR FOR TOYOTA WISH 1.8 CVT SLF8163L

1 pc	Tail gate			<i>By</i>	1,175.90	—
1 pc	Tail gate glass moulding			<i>na</i>	125.30	—
1 pc	Tail gate inner lock			<i>na</i>	361.60	—
1 pc	Tail gate rubber			<i>na</i>	302.60	?
1 pc	Tail gate "ELEGANCE" plate			<i>na</i>	55.00	—
1 pc	Tail gate logo			<i>na</i>	49.70	—
1 pc	Tail gate "VALVEMATIC" plate			<i>na</i>	70.00	—
1 pc	Rear end panel -inner				99.60	?
1 pc	Rear end panel -outer			<i>By</i>	453.90	—
1 pc	Rear bumper fascia			<i>Philips</i>	491.90	—
2 pcs	Rear bumper side retainer (L)	@ S\$ 89.90		<i>na</i>	179.80	—
2 pcs	Rear bumper side retainer (S)	@ S\$ 54.70		<i>na</i>	109.40	—
2 pcs	Rear bumper bracket	@ S\$ 48.50			97.00	?
4 pcs	Rear bumper clip	@ S\$ 3.50		<i>na</i>	14.00	—
2 pcs	Rear bumper reflector	@ S\$ 52.40			104.80	?

3,690.50

Less 25% : 922.63

1 pc Rear w/s glass sealant

1 pc Rear bumper reverse sensor

To remove & refix rear windscreen glass and conduct water leak test.

To remove roof lining, front and rear seats, trim board and carpet

na 2,767.87
na 400.00 sn
Shari 300.00 sn
200.00

150.00 *120/*

60/
120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Page : 2

Vehicle Insured : SGC2002H

To apply undersealing

601
80.00

To putty and spray replaced parts

800.00 7201

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

900.00 7001

Total :

S\$ 5,177.87
=====

Singapore Dollars Five Thousand One Hundred and
Seventy Seven and Cents Eighty Seven Only