

ASS. REC. BY:

REF:

C8/CT118019229/ Gr d3

Special Instructions:

Surveyor
Meimen

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

23/10/18 11:04am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 7844B

Insured:

SJT 9368G

at Workshop m/s

(WTS) Woodlands Automotive

Tel:

87489825

of

17 Kaki Bukit Rd 4 # 01-58

Policy No:

DMPCSN3080841700

Claim No:

SNM18D04973C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/10/2018

CA / REV / REP. / REV 24 HRS

lup

24/10/18 11am-11:30am

H.O.D. Endorsement:

Date/Time:

12:14pm 23/10/18

Person Contacted:

Idram

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GX 7844B - X
	SJT 9368G - X

Signature

Xml.

REF: CRI

C3427K

ASSIGNMENT

(-2019)

From:

Date:

24/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GX7844B

at Workshop m/s

Woodlands Automotive (WTS)

of

17 kaki Blt Rd 4 # 01-58

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

11am-11:30am owner waiting

Make of Veh:

Idrum @ 8748 9825

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{10p}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GX7844B

Yr Regn:

16 Sep 2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Liteace

C.C

2184

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

251734

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

CR425010531

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Good / Jammed / Leaked / Burnt or

Brake: In Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

165 R13

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kenda

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

24-10-18

Survey held at

W/S

11:30AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S RA

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/10

\$976 realized with Aidi

Red: \$ 2924.00, 75%.

25/10/2018

RECEIVED 20 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

220

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

7p

Lump Sum / I.B.I: (\$ 976.00)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Oct 2018		23 Oct 2018 11:04 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	VALUE ADD SYSTEM & TECHNOLOGY PTE LTD		
Vehicle Reg. No.:	GX7844B	Date of Loss:	13/10/2018 00:00 - :59
Claim Type:	TP / SNM18D04973C02	Policy/Cover Note No.:	DMPCSN3080841700
Vehicle Reg. No. (Insured):	SJT9368G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Woodlands Automotive Service Pte Ltd (HQ) 17 KAKI BUKIT ROAD 4, #01-58 BARTLEY BIZ CENTRE, 417809 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Muham'mad Idram Bin Abdul Rahman <muhammad.idram@pitstop.com.sg>
Sent: Friday, 19 October, 2018 12:55 PM
To: Claims Dept of CTI
Cc: roslee.puasa@pitstop.com.sg; 'eddy ramli'; suraimi.farid@pitstop.com.sg
Subject: LIABILITY CHECK : GX7844B claim against SJT9368G - D.O.A : 13/10/2018 - BLK 443 BUKIT BATOK WEST AVENUE 8 DECK 2
Attachments: SAS2490944.PDF; IMG-20181017-WA0006.jpg; TP damage 1.jpg

To : China Taiping Insurance (Singapore) Pte. Ltd.

Attention : Motor Claim Department

Dear Officer-In-Charge,

LIABILITY CHECK : GX7844B claim against SJT9368G - D.O.A : 13/10/2018 – BLK 443 BUKIT BATOK WEST AVENUE 8 DECK 2

Our Client Vehicle : GX7844B

Your insured Vehicle: SJT9368G

Kindly advise and confirm the liability at soonest as our insured GX7844B is claiming against your insured SJT9368G.

Location : : PITSTOP@Bartley 17 Kaki Bukit Road 4 Bartley Biz Centre #01-58 Singapore 417809

P.I.C: Idram - 87489825

Enclosed Photo and GIA Report for your reference.

Thank you and look forward to your favourable reply.

Best Regards

Muhammad Idram

Service Advisor, Pitstop@Bartley



Woodlands Automotive Service Pte Ltd

17 Kaki Bukit Road 4 Bartley Biz Centre #01-58, Singapore 417809

Main Line : +65 6844 9449 Fax : +65 6844 9463

Direct Line : +65 6844 9457

www.woodlandstransport.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3427K
Vehicle Details	
Vehicle No.:	GX7844B
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACE 5DR
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	3C4002080
Chassis No.:	CR425010531
Maximum Power Output:	-
Open Market Value:	\$18,689.00
Original Registration Date:	16 Sep 2004
First Registration Date:	16 Sep 2004
Transfer Count:	1
Actual ARF Paid:	\$935.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$20,383.00
COE Rebate Amount:	\$3,123.00
Total Rebate Amount:	\$3,123.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 25 Oct 2018

OK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

REPAIR ESTIMATE

Client: China Taiping Insurance (Singapore) Pte. Ltd.
Address: 3 Anson Road #16-00 Springleaf Tower Singapore 079909
Attention: Motor Claim Department
Contact No: 6389 6181
Fax No:
Email:

• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplier/Veh No: GX78448
• is subject to final approval from Insurance Company
Mileage:
Acknowledged by Repairer
Signature:
Date:

Service Advisor		Payment Terms	Quotation Validity
Name:	Muhammad Idram	Due Upon Receipt	
Contact No:	87489825		
Email:	muhammad_idram@pitstop.com.sg		
Fax No:			

S/No	Description	Price	Actions		Remarks
1	LHS FRONT SIDE FENDER <i>Repair X</i>	\$570.00	Accept	Reject	
2	LHS FRONT PASSENGER DOOR COMPLETE ASSY <i>Repair X</i>	\$700.00	Accept	Reject	
3	LHS FRONT UNDERSHIELD <i>1 pc</i>	\$300.00	Accept	Reject	1827 168
4	LHS FRONT UNDERSHIELD CLIP (10 PIECES) <i>1 pc</i>	\$80.00	Accept	Reject	40
5	LHS FRONT RIM <i>COVER - AT</i>	\$340.00	Accept	Reject	50 (SN)
6	ROC STICKER (12.63 22) <i>1 pc</i>	\$80.00	Accept	Reject	20 (SN)
7	BODYWORKS: TO PUTTY AND SPRAY LHS SIDE PANEL AND PASSENGER DOOR <i>400</i>	\$500.00	Accept	Reject	
8	BODYWORKS: TO PUTTY AND SPRAY LHS FRONT RIM <i>X NN</i>	\$280.00	Accept	Reject	
9	LABOUR: TO DISMANTLE AND REFIX THE ABOVE MENTIONED PARTS INCLUDING REALIGN BODY <i>450</i>	\$650.00	Accept	Reject	
10	LABOUR: TO PUTTY AND SPRAY THE AFFECTED AREA <i>X NN</i>	\$400.00	Accept	Reject	
Remark	*We will advise if further supplementary items are necessary*				
Estimated Days of Repair:	4 Working Day	Sub-Total			\$3,900.00
		Gst			\$273.00
		Total			\$4,173.00

The above is based on initial assessment. We will advise further if there is supplementary repair.

Customer Signature / Date
(To accept this quotation, please sign & return)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Company Stamp

STV 170
Labour: 750

3 Days.

part by part.

After repair photos.

Eno Q'ap - 82880282.

24/10/18.

105.976

Subject parts prices correct

25/10/2018

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019229/GRD3N2
Date: 29/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3080841700
Claimant Vehicle No :	GX7844B	Insured Vehicle No :	SJT9368G
Date of Loss:	13/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D04973C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX7844B	Engine No:	3C4002080
Make & Model:	TOYOTA LITEACE, 2.2 5 DR (A)	Chassis No:	CR425010531
Reg. Date:	16/09/2004 (Man. Year: 2004)	Odometer:	251734 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165R13	Rear Tyre Size:	165R13
Front Left Side:	Kenda 6 mm	Rear Left Side:	Kenda 6 mm
Front Right Side:	Kenda 6 mm	Rear Right Side:	Kenda 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,070.00	226.00	1,844.00	89.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	750.00	1,080.00	59.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,900.00	976.00	2,924.00	74.97
+ GST 7.00/7.00% (S\$)	273.00	68.32	204.68	74.97
Nett Amount (S\$)	4,173.00	1,044.32	3,128.68	74.97

INSPECTION

Date of Assignment:	23/10/2018	
Date Inspected:	24/10/2018	Inspected At:
		Woodlands Automotive Service Pte Ltd (HQ) 17 KAKI BUKIT ROAD 4, #01-58 BARTLEY BIZ CENTRE Singapore 417809

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Oct 2018)
Parts:	N/A TOYOTA LITEACE 2.2 5 DR (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX7844B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHS FRONT SIDE FENDER	Repair	570.00 F	*- FL
2	1		*LHS FRONT PASSENGER DOOR COMPLETE ASSY	Repair	700.00 F	*- FL
3	1		*LHS FRONT UNDERSHIELD	Deformed	300.00 F	*168.00 FL
4	10		*LHS FRONT UNDERSHIELD CLIP	Necessary	80.00 F	*40.00 FL
5	1		*LHS FRONT RIM COVER	Cut	340.00 FS	*50.00 FS
6	1		*ROC STICKER	Necessary	80.00 FS	*20.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					2,070.00	278.00
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	52.00
Total Parts (\$\$)					2,070.00	226.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODYWORKS TO PUTTY AND SPRAY LHS SIDE PANEL AND PASSENGER DOOR	New	500.00	400.00
2	BODYWORKS TO PUTTY AND SPRAY LHS FRONT RIM	New	280.00	-
3	LABOUR TO DISMANTLE AND REFIX THE ABOVE MENTIONED PARTS INCLUDING REALIGN BODY	New	650.00	350.00
4	LABOUR TO PUTTY AND SPRAY THE AFFECTED AREA	New	400.00	-
Gross Labour Cost (S\$)			1,830.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >