



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
 64 CECIL STREET
 #04-00 & #05-00 IOB BUILDING
 SINGAPORE 049711

Registration No : SLS2925B
 Chassis No : MRHGM6660JT000140
 Model : CITY 1.5SV CVT 2018 (EURO 6)
 Owner's Name : YEO PUAY BOON
 Ins Policy No. :
 Date of Accident : 20/10/2018

Document No. : SQT18004548 Page 1
 Date : 23. Oct 2018
 Customer No. : WZ1007
 Svc Advisor :
 Engine No : L15Z15202940
 Date | Time : 23. Oct 2018 5:17:45 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: YEO PUAY BOON OWNER INSURER: TOKIO MARINE ACC DATE: 20/10/2018 SURVEYED BY: DATE: REF NO: TP INSURER: III TP VEH: SH 6144 L						
71501-T9A-T20ZZ	FACE, RR. BUMPER	1 de	463.70	25	347.77	24.34	372.11
33505-T9A-K01	REFLECTOR ASSY, R. RR.	1	14.80	25	11.10	0.78	11.88
33555-T9A-K01	REFLECTOR ASSY, L. RR.	1	14.80	25	11.10	0.78	11.88
71593-T9A-J00	SPACER R.RR.BUMPER SIDE	1 ne	11.50	25	8.62	0.60	9.22
71598-T9A-J00	SPACER L.RR.BUMPER SIDE	1 ne	11.50	25	8.62	0.60	9.22
71504-T9D-K00	GARNISH, R. RR. BUMPER SIDE	1 ?	42.70	25	32.02	2.24	34.26
71509-T9D-K00	GARNISH, L. RR. BUMPER SIDE	1 ?	42.70	25	32.02	2.24	34.26
71505-T9D-K00	GARNISH, RR. BUMPER CENTER	1 ?	24.30	25	18.22	1.28	19.50
91505-TM8-003	CLIP, BUMPER	4 ne	2.00	25	6.00	0.42	6.42
66100-T9A-T50ZZ	PANEL COMPRR. - photo	1 ht	323.90	25	242.92	17.00	259.92
04655-T9A-T00ZZ	PANEL SETRR.FLOOR	1 ?	408.80	25	306.60	21.46	328.06
04636-T9A-T00ZZ	PANEL SETR.RR.OUTSIDE	1 buc	1134.80	25	851.10	59.58	910.68
68500-T9A-T30ZZ	LID COMPTRUNK	1 bt	444.50	25	333.37	23.34	356.71
74865-T9A-T01	WEATHERSTRIPTRUNK LID	1 ?	71.60	25	53.70	3.76	57.46
75722-T9A-T10	EMBLEM, RR. CITY	1 ne	11.30	25	8.47	0.59	9.06
75701-T9C-000	EMBLEM H	1 ne	11.00	25	8.25	0.58	8.83
75725-T9A-T00	EMBLEMRR.I-VTEC	1 ne	11.90	25	8.92	0.62	9.54
33500-T9A-T01	TAILLIGHT ASSYR.	1 cno	205.70	25	154.27	10.80	165.07
34150-T9A-T01	LIGHT ASSY, R.LID	1 out	77.80	25	58.35	4.08	62.43
73127-TY0-000	RUBBER C WINDSHIELD DAMPER	3 ne	11.20	25	25.20	1.76	26.96
73227-T9A-T00	RUBBER C WINDSHIELD DAMPER	1 ne	17.30	25	12.97	0.91	13.88

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLS2925B

Chassis No : MRHGM6660JT000140

Model : CITY 1.5SV CVT 2018 (EURO 6)

Owner's Name : YEO PUAY BOON

Ins Policy No. :

Date of Accident : 20/10/2018

Document No. : SQT18004548 Page 2

Date : 23. Oct 2018

Customer No. : WZI007

Svc Advisor :

Engine No : L15Z15202940

Date | Time : 23. Oct 2018 5:17:45 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2 <i>2</i>	60.00		120.00	8.40	128.40
74940-SZW-003	BUZZER ASSYSMART	1 <i>?</i>	60.10	25	45.07	3.15	48.22
NMRS-4P	4 PCS REAR SENSOR	1 <i>?</i>	149.20	10	134.28	9.40	143.68
Sum Item					2838.94	198.71	3,037.65
BOSUN	SUNDRIES	1 <i>30</i>	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1 <i>✓</i>	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT RHS REAR FENDER	1 <i>✓</i>	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1 <i>✓</i>	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1 <i>?</i>	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1 <i>✓</i>	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1 <i>✓</i>	280.00		280.00	19.60	299.60
BODAMKIT	WINDSCREEN DAM KIT.	1 <i>120</i>	150.00		150.00	10.50	160.50
BG02R	REPLACE RR. WINDSCREEN.(N)	1 <i>✓</i>	280.00		280.00	19.60	299.60
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA(N)	1 <i>✓</i>	380.00		380.00	26.60	406.60
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM(N)	1 <i>✓</i>	380.00		380.00	26.60	406.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1 <i>✓</i>	560.00		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1 <i>✓</i>	560.00		560.00	39.20	599.20
BKFE22R	CUT OFF & RENEW RR R FENDER.RENEW ALL DAMAGE PARTS	1 <i>4480</i>	5000.00		5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1 <i>2700</i>	3600.00		3600.00	252.00	3852.00
Sum Labor					11870.00	830.90	12,700.90

Survey By *Tan Jm 97495719.*

Date & Time *24/10/18 e Han.*

Excess *WP'*

Status *Resing before paint*

Total Amount 14,708.94 1,029.61 15,738.55

Total (Inclusive of GST) **15,738.55**

Printed on 23/10/2018 5:38:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

*sur @ khandpwm.**8 days*