

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : LONPAC INSURANCE BHD

PARTICULARS OF CLAIM

| | | | |
|-------------------|--------------------|--------------------------|---------------------|
| Claim Type: | TP | Ref. No: | YTKB/TP/1810/010 |
| Policy No: | VCA/P2067845 | Date of Loss: | 18/10/2018 |
| Vehicle Reg. No.: | GBF6870K | Driveable? | yes |
| Driver Age: | | Third Party Vehicle No.: | GBG3956L |
| Any Injuries? | no | Contact No: | |
| Insured/Claimant: | JOCIA FOOD TRADING | Driver: | HENG YAO MIN JOSEPH |

| | | | |
|-----------------|---------------------|------------------------------|--------------|
| Make/Model: | Nissan, NV350 - E26 | Vehicle Reg. Date: | 17 Feb 2017 |
| Vehicle Colour: | GREY | Engine Number: | YD254116674A |
| Chassis No: | JN1MC2E26Z0007598 | Odometer: | |
| Total Loss? | NO | Est. Duration of Repair(Day) | |

Description of Accident/loss HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

| | Amount |
|--------------------------|-----------------|
| Parts | 2,811.91 |
| Miscellaneous Items | 261.00 |
| Labour | 1,140.00 |
| Paintwork Labour | 630.00 |
| Towing | 0.00 |
| Gross Total(S\$): | 4,842.91 |
| GST 7.00%(S\$): | 339.00 |
| Nett Amount(S\$): | 5,181.91 |

This claim is handled by: may chai

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not authorized
24/10/18
take photo before painting
Harry
plp

REPAIR DETAILS**Estimates On Parts**

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|--|----------|----------|--------|------------|
| 1 | 1 | REAR TAILGATE / <i>badly dented</i> | 2,101.40 | 2,101.40 | -30.00 | 1,470.98 |
| 2 | 1 | REAR TAILGATE NISSAN EMBLEM / <i>NEC</i> | 75.50 | 75.50 | -10.00 | 67.95 |
| 3 | 1 | REAR TAILGATE LOCK / <i>jam</i> | 323.70 | 323.70 | -10.00 | 291.33 |
| 4 | 1 | REAR TAILGATE RUBBER X <i>WN</i> | 131.90 | 131.90 | -10.00 | 118.71 |
| 5 | 1 | REAR BUMPER / <i>De</i> | 690.60 | 690.60 | -30.00 | 483.42 |
| 6 | 1 | REAR TAILGATE NV350 EMBLEM / <i>NEC</i> | 87.00 | 87.00 | -10.00 | 78.30 |
| 7 | 1 | REAR TAILGATE URVAN EMBLEM / <i>NEC</i> | 87.00 | 87.00 | -10.00 | 78.30 |
| 8 | 1 | REAR BUMPER SIDE RETAINER LH X | 18.10 | 18.10 | -10.00 | 16.29 |
| 9 | 1 | REAR BUMPER SIDE RETAINER RH X | 18.10 | 18.10 | -10.00 | 16.29 |
| 10 | 1 | REAR BUMPER STEP GARNISH? <i>XX</i> | 20.00 | 20.00 | -10.00 | 18.00 |
| 11 | 1 | REAR END PANEL? | 246.20 | 246.20 | -30.00 | 172.34 |

Total Parts (\$\$) 2,811.91

Estimates of Miscellaneous Items

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|--------------|--|--------|--------|-------|------------|
| 1 | 1 | REAR TAILGATE 70KM/H <i>rec</i> | 8.00 | 8.00 | 0.00 | 8.00 |
| 2 | 1 | REAR TAILGATE 8 PAX <i>rec</i> | 8.00 | 8.00 | 0.00 | 8.00 |
| 3 | 1 <i>set</i> | REAR REVERSE SENSOR <i>short</i> | 200.00 | 200.00 | 0.00 | 200.00 |
| 4 | 1 | REAR WINDSCREEN GLASS SEALANT <i>rec</i> | 45.00 | 45.00 | 0.00 | 45.00 |

Sub Total (\$\$) 261.00

Estimates On Labour

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|---|--------|--------|-------|-------------|
| 1 | 1 | To Dismantle and Refit Rear Windscreen Glass. | 100.00 | 100.00 | 0.00 | 100.00 ✓ |
| 2 | 1 | To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings. | 180.00 | 180.00 | 0.00 | 180.00 X |
| 3 | 1 | To Transfer Rear Tailgate. | 80.00 | 80.00 | 0.00 | 80.00 60 |
| 4 | 1 | To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts. | 30.00 | 30.00 | 0.00 | 30.00 20 |
| 5 | 1 | To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools. | 650.00 | 650.00 | 0.00 | 650.00 500? |
| 6 | 1 | To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section. | 100.00 | 100.00 | 0.00 | 100.00 11 X |

Gross Labour Cost (\$\$) 1,140.00

Estimates On Paint Work Labour

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|--|-------|--------|-------|------------|
| 1 | 1 | To Carry-Out Body Cavity Preservation. | 20.00 | 20.00 | 0.00 | 20.00 ? |
| 2 | 1 | To Supply Spray Terostat Sealant On The Cutting Areas. | 30.00 | 30.00 | 0.00 | 30.00 ? |

Estimates On Paint Work Labour

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|--|--------|--------|-------|------------|
| 3 | 1 | To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available. | 580.00 | 580.00 | 0.00 | 580.00 |

560

| | |
|--------------------------|--------|
| Gross Labour Cost (\$\$) | 630.00 |
|--------------------------|--------|

< END OF ESTIMATES >