



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN : MOTOR CLAIMS FAX :		NAME : MR ISAAC FOO YONG WEI ADDRESS : 84 FLORA ROAD #07-14 EDELWEISS PARK CONDOMINIUM SINGAPORE 507001 TEL : 98430308		WIP : 23086 EXCESS : DATE: 22-Oct-18	
VEH NO :	SJL7123B	DATE IN :		CONTACT PERSON :	JOB THOMAS 6331 0682
CHASSIS NO :	WMWSV320X0T151884	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MINI COOPER R56	DATE REG.:	23-Jul-12	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
		QTY			
1	REAR BUMPER <i>cut</i>	1	M51.12.7.264.358		\$ 862.38
2	REAR BUMPER GRILLE <i>DE</i>	1	M51.12.7.260.590		\$ 202.88
3	REAR BUMPER SPOILER <i>DE</i>	1	M51.12.7.265.088		\$ 213.69
4	REAR BUMPER FOGLAMP CHROME LH ?	1	M51.12.7.260.595		\$ 76.63
5	REAR BUMPER FOGLAMP CHROME RH ?	1	M51.12.7.260.596		\$ 76.19
6	REAR BUMPER CENTRE GUIDE <i>DE</i>	1	M51.12.7.127.744		\$ 33.38
7	REAR BUMPER CENTRE BRACKET <i>DE</i>	1	M51.12.7.126.172		\$ 24.50
8	REAR BUMPER SUPPORT LH ?	1	M51.12.2.751.303		\$ 22.25
9	REAR BUMPER SUPPORT RH ?	1	M51.12.2.751.304		\$ 22.25
10	REAR BUMPER EXPANDING RIVET <i>DE</i>	2	M51.48.1.915.964		\$ 2.94
11	REAR BUMPER GROMMET <i>DE</i>	2	M07.13.0.702.966		\$ 2.76
12	REAR BUMPER FASTENER <i>DE</i>	6	M63.25.2.758.031		\$ 11.64
13	REAR BUMPER CLIP <i>DE</i>	2	M51.47.2.754.477		\$ 4.62
14	ULTRASONIC SENSOR GASKET <i>DE</i>	4	M66.20.6.923.000		\$ 25.24
15	ULTRASONIC SENSOR ?	2	M66.20.9.196.705		\$ 592.12
TOTAL PARTS					\$ 2,173.47
					\$ -
TOTAL PARTS COST					\$ 2,173.47
Labour Description					
1	TO REPLACE REAR BUMPER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			840	\$ 1,000.00
2	TO RESPRAY REAR BUMPER.			800	\$ 1,000.00
3	TO TRANSFER THE REVERSE SENSORS.			420	\$ 500.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150	\$ 250.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			250	\$ 350.00
6	SUNDRIES.			NETT	\$ 50 100.00

	TOTAL LABOUR	\$ -	\$ 3,200.00
	TOTAL PARTS	\$ -	\$ 2,173.47
	TOTAL	\$ -	\$ 5,373.47
	LESS EXCESS	\$ -	\$ -
	TOTAL AFTER EXCESS	\$ -	
	GST 7%	\$ -	\$ -
	GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Rasul
Hp 90010068
3 days
25/10/18 @ 1500hrs
Ready bk part