

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1207/2018/GW
Date : 23-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. **SKM 6236 Z**

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Khoo Kah Bee
Address : Blk 267A Compassvale Link
#16-77
Singapore 541267
Telephone : HP +65 96990609
Type of Claim : Third Party Claim
Policy No. : 2100507276-01
Vehicle No : **SKB 9903 U**
Model Code : Audi A5 COUPE 2.0 TFSI
Model / Year : Apr-17
Engine No : CVK 029003
Chassis No : WAUZZZF56HA021524
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Oct-18
Place of Accident : Left Lane Merging onto CTE; About 8KM & 7 1/2 KM

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 9903 U.

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓
2	To dismantle and renew rear bumper.re-organize rear crash management components. Reinstall all parts removed.	\$ 1,050.00 600
3	To respray rear bumper.	\$ 900.00 ¹⁰⁰⁰ 600
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
SUB-TOTAL LABOUR CHARGES -		: \$ 2,502.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKB 9903 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER / R	\$ 2,190.00	
2	REAR BUMPER FIXNING PARTS ? / MC	\$ 142.00	
2	REAR KICK SENSOR SECURING STRIP ?	\$ 191.00	
3	REAR BUMPER CHROME TRIM / R	\$ 878.00	
4	REAR BUMPER CLIP / MC	11 \$ 407.00	
4	REAR BUMPER OUTER CLIP / MC	4 \$ 148.00	
5	REAR LIGHT REFLECTOR-LH/RH ?	2 \$ 70.00	
6	REAR BUMPER CARRIER ?	\$ 786.00	
7	REAR BUMPER GUIDE SECTION-LH/RH ?	2 \$ 74.00	
8	REAR BUMPER UPPER GUIDE SECTION-LH/RH ?	2 \$ 38.00	
9	REAR SENSOR ?	2 \$ 421.00	
10	REAR SENSOR SEAL RING / MC	4 \$ 14.00	
11	SUNDRIES ?	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 5,659.00	
TOTAL LAOUR CHARGES		: \$ 2,502.00	
GRAND TOTAL		: \$ 8,161.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Lim Kai ng.*
Surveyed Date : *24/10/18*
Authorised Date :
Excess Cost : *before paint photos.*
Liability :
Remarks : *3 Days.*

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant