

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKB 9903 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER PR	\$ 2,190.00	\$ 2,190.00
	REAR BUMPER FIXNING PARTS X NN	\$ 142.00	X
2	REAR KICK SENSOR SECURING STRIP NN	\$ 191.00	\$ 191.00
3	REAR BUMPER CHROME TRIM BR	\$ 878.00	\$ 877.50
	REAR BUMPER CLIP X	11 \$ 407.00	X
4	REAR BUMPER OUTER CLIP X	4 \$ 148.00	X
5	REAR LIGHT REFLECTOR-LH/RH X	2 \$ 70.00	X
6	REAR BUMPER CARRIER X	\$ 786.00	X
7	REAR BUMPER GUIDE SECTION-LH/RH X	2 \$ 74.00	X
8	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$ 38.00	\$ ① 18.60
9	REAR SENSOR X	2 \$ 421.00	X
10	REAR SENSOR SEAL RING X	4 \$ 14.00	X
11	SUNDRIES NEC	\$ 300.00	\$ 2.00
TOTAL SPARE PARTS CHARGES		\$ 5,659.00	\$ 3,279.10
TOTAL LAOUR CHARGES		\$ 2,502.00	\$ 1,952.00
GRAND TOTAL		\$ 8,161.00	\$ 5,231.10

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 9903 U.

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00	\$ 360.00 ✓
2	To dismantle and renew rear bumper.re-organize rear crash management components. Reinstall all parts removed. <i>(New model A5 @ \$700/- per day)</i>	\$ 1,050.00	\$ 700.00 ✓
3	To respray rear bumper. <i>New model A5 @ \$700/- per piece)</i>	\$ 900.00	\$ 700.00 ✓
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00 ✓
SUB-TOTAL LABOUR CHARGES -		: \$ 2,502.00	\$ 1,952.00

surveyor ✓