

ASS. REC. BY:

REF:

CS/CT#18019240/Tlvd3ⁿ² Special Instruction:

Surveyor

Meinmen

From (Person):

Taufik
Elaine Cheong

ASSIGNMENT (Office)

of CT1

Date/Time: 23/10/18 @ 11:58am

Estimated Cost:

Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S12 9999L

Insured:

PC 1530A

at Workshop n/s:

Wearnes Automotive

Tel:

8126 1237

of

28 Jeng Kee Road

Policy No:

DMBISN1825911800

Claim No:

SNM18065000C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/10/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

12:35pm @ 23/10/18

Person Contacted:

paul

Vehicle IN

OUT

Date/Time

Action/Instruction (✓) Estimate

S12 9999L - NBA/CT#18019119/y

D.O.A: 22/10/18

PC 1530A - NBA/CT#18019119/y

D.O.A: 22/10/18

12/11/18

@ 240pm Paul will email us finalised

22/11/18

Final fig \$ 8550.93 confirmed by email (Red 4343.57, 3490)

Signature

Taylor

REF:

CT

ASSIGNMENT

SC79999L

Yr Regn. 2017, Mach

From Date

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. 1-24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Segner XE 2.0

c.c 1999.

Colour

white

A/C Insured / Std / NI / NA

Sp. Reading

61066

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SAJAB4ANX HCPO6260

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/35R9

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

C

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

29/10/18 E 320pm

Survey held at

Weeming

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 22 NOV 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

22/11 - typist

Report Format :

Merimen

Lump Sum / I.B.I: (\$

8550.93

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

: S + RS. \$

: Photos

: Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2018		23 Oct 2018 11:58 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S LONGLIM PTE LTD, Co. Reg. No.: 201109995N		
Main Claimant:	LEE ENG LIN		
Vehicle Reg. No.:	SLZ9999L	Date of Loss:	22/10/2018 09:00 - :59
Claim Type:	TP / SNM18D05000C02	Policy/Cover Note No.:	DMB1SN1825911800 (Comprehensive)
Vehicle Reg. No. (Insured):	PC1530A	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2018]		
Adj Asg. Remarks:	EST \$13,733.55 , CASE WITH SJE.		

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Paul Ong Qing Yong <paul.ong@wearnes.com>
Sent: Monday, 22 October, 2018 5:14 PM
To: DL-CLAIMS
Subject: TP Claim - Our Client SCZ9999L; TP Vehicle PC1530A
Attachments: 0676_001.pdf; SCZ9999L 22.10.2018.pdf; WhatsApp Video 2018-10-22 at 17.01.06.mp4

Sensitivity: Confidential

Attached TP Claim,

Please advise if can settle direct.

Best Regards,

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 22 November 2018 10:16 AM
To: 'Paul Ong Qing Yong'; SUR; Denise Tay (LKKAuto)
Subject: RE: SCZ9999L Finalise
Sensitivity: Confidential

Dear Paul,

WITHOUT PREJUDICE

Confirmed amount \$8550.93 before GST @ 4 working days.

Kindly send Final invoice and all supporting documents to CHINA TAIPING.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Paul Ong Qing Yong <paul.ong@wearnes.com>
Sent: Wednesday, 21 November 2018 2:22 PM
To: SUR <sur@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: SCZ9999L Finalise
Sensitivity: Confidential

Attached.

Best Regards,

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/10/2018 14:23
Date Of Accident 22/10/2018 09:00
Exact Location Of Accident COLLYER QUAY
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCZ9999L
Insured/Policyholder
Name Of Registered Owner LEE ENG LIN
NRIC No S8039997I
Email Address YINGRENLI@GMAIL.COM
Mobile Phone No (LOCAL) +65-86689900
Alternative Phone No OTHERS-86689900

Vehicle Particulars

Manufacturer JAGUAR
Model XE-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? YES
If No, Please state action to be taken
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company HL ASSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number MP307095
Cover Note Number 31.03.2018 TO 30.03.2019

Driver

Name of Driver LEE ENG LIN
NRIC No S8039997I
Date Of Birth 22/12/1980
Occupation OUTDOOR
Date Of Driving Pass 04/01/2000
Driving Experience 18 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-86689900
Fax Number
Contact Number OTHERS-86689900
Email Address YINGRENLI@GMAIL.COM

Address	55 PASIR RIS DRIVE 1 #11-01
Postcode	519530
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DIANA TAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 22/10/2018 at about 0900hrs, I was driving my vehicle (A: SCZ9999L) on the centre lane along Collyer Quay towards NTUC building. I already complete change lane into second lane from left, slowed down and stop due to vehicle in front stopped. Suddenly I felt an impact from my vehicle's left portion and realised that a vehicle (B: PC1530A) which was travelling along the extreme left lane (Bus Lane), change lane and hit onto my vehicle's left portion. Nobody was injured in this accident. Vehicle A (SCZ9999L) - 1 female adult passenger on board. Vehicle B (PC1530A) - unaware number of passenger on board.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC1530A
Vehicle Make/Model/Colour	SCANIA
Details Of Properties	BUS
Vehicle Category	BUS
Name of Driver	QIAO ZIKUI
NRIC/Passport Number	G2391849N
Contact Number	9380 6180
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

RIGHT FRONT PORTION

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

22/10/18
C 1440w

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Can WPI SM
06864052R

SKETCH PLAN

Refer to Scene photo

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to C/A report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

77/10/18
91440h

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Cam Wai Shun
NRIC/FIN NO: 68646328

SERVICE ESTIMATE

89133 - C00001

SL: SERVICE SALES - PC

Mr Lee Eng Lin Jason

55 Pasir Ris Drive 1

#11-01

Singapore 519530

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 22/10/2018

WIP No. : 34219

Veh.In/Out:

*Tel.No. : Mobile: 86689900

Reg.No. : SCZ9999L

Reg.date : 31/03/2017

Mileage : 0

Chassis No: SAJAB4ANXHCP06260

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Lee Eng Lin Jason

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	B
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT LH FENDER, 900	0	3600.00	0		3,600.00 S	1800. ✓
FRT LH DOOR, FRT LH WING MIRROR, ETC							
800	TO PUTTY SPRAYPAINT ON	0	3200.00	0		3,200.00 S	1600. ✓
FRT LH FENDER, FRT LH DOOR,	800						
BONNET, LH WING MIRROR, ETC							
302	TO TRANSFER LH DOOR PART	0	500.00	0		500.00 S	✓ ✓
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00 S	✓ ✓
RESETTING OF ALL ELECTRICAL							
MODULES							
1	PANEL FENDER FRT LH	1.0 EA	670.60			670.60 S	bt - 603.54
2	MOUNTING-BRACKET	1.0 EA	27.70			27.70 S	7 X 111
3	BAFFLE-FENDER	1.0 EA	66.90			66.90 S	cut - 60.21
4	DOOR PANEL LHF XE	1.0 EA	1492.30			1,492.30 S	bt - 1343.07
5	SOUND DEADENING PAD	2.0 EA	250.00			500.00 S	ne - 450
6	FINISHER-VENT	1.0 EA	259.50			259.50 S	cut - 233.55
7	SEAL-DOOR	1.0 EA	232.30			232.30 S	ne - 209.07
8	DOOR MIRROR LH XE	1.0 EA	791.00			791.00 S	di dis - 711.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Signature Taufiq 97495749.
 2/11/18
 up
 29/10/18 @ 330
 04 days
 Resurvey before paint
 sur @ lkkauto.com

SERVICE ESTIMATE

89133 - C00001 SL: SERVICE SALES - PC

Mr Lee Eng Lin Jason

55 Pasir Ris Drive 1

#11-01

Singapore 519530

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date: : 22/10/2018

WIP No. : 34219

Veh.In/Out:

*Tel.No. : Mobile: 86689900

Reg.No. : SCZ9999L

Reg.date: : 31/03/2017

Mileage : 0

Chassis No: SAJAB4ANXHCP06260

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Lee Eng Lin Jason

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
9	MIRROR COVER LH XF R	1.0 EA	166.90			166.90	S R
10	DOOR MIRROR LAMP LH	1.0 EA	40.30			40.30	S ? X n n
11	MIRROR MOTOR LH XJ	1.0 EA	252.50			252.50	S ? X n n
12	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	S n e 494.19

12,894.50

		Gross Total	12,835.10
Labour Total	7,786.00	Net.....	12,835.10
Parts Total	5,049.10	GST @ 7.0%	898.46
Package Total	0.00	Total.....	13,733.55
		Paid.....	0.00
		Please Pay..	13,733.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 21/11/2018
 SINGAPORE 079909 WIP No. : 34219
 Veh.In/Out: 29/10/2018 05/11/2018

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Lee Eng Lin Jason

*Tel.No. : 63896111
 Reg.No. : SCZ9999L
 Reg.date : 31/03/2017
 Mileage : 69,066
 Chassis No: SAJAB4ANXHCP06260

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT LH FENDER, FRT LH DOOR, FRT LH WING MIRROR, ETC	0	1800.00	0		1,800.00	S
800	TO PUTTY SPRAYPAINT ON FRT LH FENDER, FRT LH DOOR, LH WING MIRROR, ETC	0	1600.00	0		1,600.00	S
802	TO TRANSFER LH DOOR PART	0	500.00	0		500.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
①	PANEL FENDER FRT LH	1.0 EA	670.60	10		603.54	S
②	BAFFLE-FENDER	1.0 EA	66.90	10		60.21	S
④	DOOR PANEL LHF XE	1.0 EA	1492.30	10		1,343.07	S
⑤	SOUND DEADENING PAD	2.0 EA	250.00	10		450.00	S
⑥	FINISHER-VENT	1.0 EA	259.50	10		233.55	S
⑦	SEAL-DOOR	1.0 EA	232.30	10		209.07	S
⑧	DOOR MIRROR LH XE	1.0 EA	791.00	10		711.90	S
⑨	ADHESIVE SEALER FL2	1.0 EA	549.10	10		494.19	S

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 2
 #16-00, SPRINGLEAF TOWER Inv.date. : 21/11/2018
 SINGAPORE 079909 WIP No. . : 34219
 Veh.In/Out: 29/10/2018 05/11/2018

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Lee Eng Lin Jason

*Tel.No. . : 63896111
 Reg.No. . : SCZ9999L
 Reg.date. : 31/03/2017
 Mileage . : 69,066
 Chassis No: SAJAB4ANXHCP06260

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	<i>SR</i> BUMPER NUT XF <i>vec.</i>	15.0 EA	4.40	10		59.40	S

Labour Total 4,386.00
 Parts Total 4,164.93
 Package Total 0.00

Gross Total. 8,550.93
 Net..... 8,550.93
 GST @ 7.0% 598.57
 Total..... 9,149.50
 Paid..... 0.00
 Please Pay.. 9,149.50

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

supp.

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 21/11/2018
 SINGAPORE 079909 WIP No. . : 34219
 Veh.In/Out: 29/10/2018 05/11/2018

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Lee Eng Lin Jason

*Tel.No. . : 63896111
 Reg.No. . : SCZ9999L
 Reg.date . : 31/03/2017
 Mileage .. : 69,066
 Chassis No: SAJAB4ANXHCP06260

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER NUT XF	15.0 EA	4.40	10		59.40	S <i>acc</i>

Labour Total 0.00
 Parts Total 59.40
 Package Total 0.00

Gross Total. 59.40
 Net..... 59.40
 GST @ 7.0% 4.16
 Total..... 63.56
 Paid..... 0.00
 Please Pay.. 63.56

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118019240/T1VD3N2

Date: 29/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN1825911800
Claimant Vehicle No :	SCZ9999L	Insured Vehicle No :	PC1530A
Date of Loss:	22/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05000C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCZ9999L	Engine No:	161020W0330204DTD
Make & Model:	JAGUAR XE, 2.0 (A)	Chassis No:	SAJAB4ANXHCP06260
Reg. Date:	31/03/2017 (Man. Year: 2016)	Odometer:	69066 km
Colour:	White		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,108.50	4,164.93	943.57	18.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,786.00	4,386.00	3,400.00	43.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,894.50	8,550.93	4,343.57	33.69
+ GST 7.00/7.00% (\$\$)	902.62	598.57	304.05	33.69
Nett Amount (\$\$)	13,797.12	9,149.50	4,647.62	33.69

INSPECTION

Date of Assignment:	23/10/2018	
Date Inspected:	29/10/2018 Inspected At:	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road Singapore 159105

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2018)
Parts:	143	JAGUAR XE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCZ9999L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL FENDER FRT LH	Bent	670.60 FS	*603.54 FS
2	1		*MOUNTING-BRACKET	Not Necessary	27.70 FS	*- FS
3	1		*BAFFLE-FENDER	Cut	66.90 FS	*60.21 FS
4	1		*DOOR PANEL LHF XE	Bent	1,492.30 FS	*1,343.07 FS
5	2		*SOUND DEADENING PAD	Necessary	500.00 FS	*450.00 FS
6	1		*FINISHER-VENT	Cut	259.50 FS	*233.55 FS
7	1		*SEAL-DOOR	Necessary	232.30 FS	*209.07 FS
8	1		*DOOR MIRROR LH XE	Distorted	791.00 FS	*711.90 FS
9	1		*MIRROR COVER LH XF R	Repair	166.90 FS	*- FS
10	1		*DOOR MIRROR LAMP LH	Not Necessary	40.30 FS	*- FS
11	1		*MIRROR MOTOR LH XJ	Not Necessary	252.50 FS	*- FS
12	1		*ADHESIVE SEALER FL2	Necessary	549.10 FS	*494.19 FS
13	15		*BUMPER NUT XF	Necessary	59.40 FS	*59.40 FS
Total Parts (S\$)					5,108.50	4,164.93

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT LH FENDER,FRT LH DOOR,FRT LH WING MIRROR,ETC	New	3,600.00	1,800.00
2	TO PUTTY SPRAYPAINT ON FRT LH FENDER,FRT LH DOOR,BONNET,LH WING MIRROR,ETC	New	3,200.00	1,600.00
3	TO TRANSFER LH DOOR PART	New	500.00	500.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	486.00	486.00
Gross Labour Cost (S\$)			7,786.00	4,386.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >