

Adrian LK - AXA



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

TPAXA

Vic

22/10/2018

KDY2318030732

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

Accident date: 21/10/2018

Estimated repair cost for vehicle no: GBG7733L TOYOTA DYNA 3.0 MANUAL '17

CHASSIS: KDY2318030732

S/n	Qty	Items	U/price	Amount
1	1	Front Grille <i>crushed</i>		\$581.45 ✓
2	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 20
3	1	Front Grille Emblem Logo <i>new</i>		\$122.25 ✓
4	1	Front Bumper <i>Bent</i>		\$720.25 ✓
5	1	Front Bumper Reinforcement <i>new</i>		\$374.75 ✓
6	1	Front R/H Bumper Fog Lamp <i>3 new</i>		\$381.90 ×
7	1	Front R/H Bumper Fog Lamp Bracket <i>new</i>		\$172.45 ×
8	1	Front R/H Head Lamp <i>crushed</i>		\$1,217.45 978
9	1	Front R/H Head Lamp Panel <i>2 new</i>		\$374.25 +
10	1	Front R/H Head Lamp Lower Rubber <i>new</i>		\$121.45 +
11	4	Front R/H Head Lamp Lower Rubber Clip	\$6.50	\$26.00 +
12	1	Front R/H Side Panel <i>crushed</i>		\$287.75 ✓
13	1	Front R/H Door <i>Dented</i>		\$1,712.45 ✓
14	2	Front R/H Door Hinge <i>Lower Bent</i>	\$122.25	\$244.50 122.25
15	1	Front R/H Door Pillar <i>Bent</i>		\$631.35 ✓
16	1	Front R/H Door Signal Lamp <i>crushed</i>		\$122.10 ✓
17	1	Front R/H Door Sticker <i>new</i>		\$50.00 30.00
18	1	Front R/H Door Inner Lock <i>new</i>		\$581.90 ×
19	1	Front R/H Door Inner Rubber <i>new</i>		\$374.45 ✓
20	1	Front R/H Door Inner Lower Rubber <i>new</i>		\$182.10 ✓
21	1	Front R/H Door Inner Trim Board <i>crushed</i>		\$781.45 485.10
22	1	Front R/H Door Gear Motor Assy <i>new</i>		\$581.10 ×
23	1	Front R/H Door Side Mirror Assy <i>new</i>		\$975.45 ×
24	1	Front R/H Step Panel <i>crushed</i>		\$274.10 ✓
25	1	Front R/H Arch Panel <i>Repis</i>		\$281.90 ×
26	1	Front R/H Arch Panel Garnish <i>crushed</i>		\$274.25 ✓
27	1	Front Windscreen Rubber <i>new</i>		\$371.75 ✓

7259.60

5444.70

Subtotal :-

\$11,870.80

SW: 30

Labour charges

To remove & refit front R/H door, gear motor, glass, lock, rubber & trim board

~~\$180.00~~ 80

To remove & refit front dashboard

~~\$180.00~~ ✓

To remove & refit front windscreen

~~\$120.00~~ ✓

Gum

~~\$50.00~~ +

To check wiring

~~\$100.00~~ 30

Tuff kote

3150

~~\$150.00~~ 40

Panel beating

~~\$1,600.00~~ 1400.

Spray painting

~~\$1,600.00~~ 1300

Subtotal :- \$3,980.00

Total:- \$15,850.80

total: 862470.

4/5: 69K

009 Pays

6.9K

009 Pays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: