



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8493Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER RUBBER MAT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN) (CONSISTENT)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00 (SN) (CONSISTENT)	NECESSARY	200.00	200.00
			300.00	250.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		400.00	100.00
	SPRAY PAINTING CHARGE.		300.00	200.00
			700.00	300.00
<b>GRAND TOTAL</b>			<b>1,000.00</b>	<b>550.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>550.00</b>

Report Ref No. CC4/ASM18019244/K1pb3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.