

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8493Y

DATE 22/10/2018 14:27

MAKE :

MODEL : HYUNDAI i40

PbyP

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00	Nett
	Rear Bumper Advertisement Logo <i>/</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) <i>/</i>		\$ 100.00	\$ 200.00	Nett
				\$ 300.00	
	Labour Charge				
	Panel Beating			\$ 400.00	
	Spray Painting Charge			\$ 300.00	
				200	
	TOTAL LABOUR			\$ 700.00	
	ESTIMATE TOTAL			\$ 1,000.00	
<p><i>Ka/ha 11/11/14</i></p> <p><i>23/10/18 1100h</i></p> <p><i>20/11/18</i></p> <p><i>PIP</i></p> <p><i>After Rep's photo</i></p>					
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					