

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0463/2018
DATE : 20-OCT-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : CHEW TEE YONG
ADDRESS : BLK 25 TECK WHYE LANE
#06-164
S(680025)
TELEPHONE NO : 97629895

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

22/10/2018

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-FBM2295K
VEHICLE NO : SLD8911E
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2300643A
CHASSIS NO : SJNFEAJ11U1705734
MILEAGE : 1 KM
DATE IN : 20/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 09/10/2018

Tanpin 97495749
9/11/18 @ 5pm
03 days
sure@tchando.com
Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary term(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLD8911E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
2	RSI	R/INSTALL OR RENEW REAR SENSOR, NECESSARY ADJUSTMENT FUNCTION TEST	110.00	✓
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4	ZZ/001	REPAIR REAR END PANEL & RENEW REAR BUMPER	750.00	250.
5	ZZ/002	S/PAINT REAR END PANEL & REAR BUMPER(2TONE)	600.00	300.
TOTAL LABOUR CHARGES			1680.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLD8911E

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 ORNAMENT ASSY R	26560-JJ90A	55.00 X		
2 SUNDRIES	NPN			50.00 20.
3 BRACKET-BUMPER	85221-4EA0A	35.90 ?		
4 CANOE RIVET(6.5X2)	76882-0M000	13.00 nec ✓		
5 RETAINER-BUMPER	79185-4EA0A	23.80 nec ✓		
6 CLIP(7.4X3)	85284-JD00A	22.20 nec ✓		
7 FASCIA-RR BUMP	85022-4EA0H	717.00 db		
8 CLIP(10X1.2)	01553-05933	12.00 nec		
9 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			180.00 nw ✓
SUB TOTAL		878.90	0.00	230.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		175.78	0.00	0.00
GRAND TOTAL		703.12	0.00	230.00
OVERALL TOTAL		933.12		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLD8911E

TOTAL LABOUR CHARGES 1680.00
TOTAL SPARE PARTS CHARGES 933.12

GRAND TOTAL 2613.12 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.