

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #24-01 AXA TOWER
 SINGAPORE 068811

Xiao Tony

Estimate No: EST1800327
 Date: 20 Oct 2018

ATTN: Motor Claim Department

Veh Reg No: SGX7437T
 Make/Model: TOYOTA COROLLA
 ALTIS 1.6 AUTO
 Chasis No: MR053ZEC107153938
 Reg. Date: 05/09/2007
 Your Ref No: SLF7289P

Claim Type: Third Party
 Accident Date: 18/10/2018
 TP Veh Reg No: SLF7289P

Estimate Repair Cost to Vehicle No :SGX7437T

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1	1 PC REAR BUMPER <i>Dented</i>	511 484.90 ✓	
2	1 PC REAR BUMPER BRACKET RH <i>New</i>	383.25 48.50 ✗	
3	1 PC REAR BUMPER RETAINER RH <i>New</i>	26.10 ✓	
4	1 PC TAIL LAMP - RH <i>New</i>	271.70 ✗	
		831.20	
	Less 25%	207.80	623.42
Special Net			
5	1 SET REAR BUMPER CLIPS <i>New</i>	40.00 30.	
6	1 PC REAR BUMPER LOWER SPOILER <i>Dented</i>	530 850.00 300.	
7	1 SET REAR BUMPER LOWER SPOILER CLIPS <i>New</i>	40.00 ✗	
8	1 SET REVERSE SENSORS <i>Dented</i>	250.00 200.	
		1.180.00	1.180.00
Labour			
9	1 TO CHECK WIRING	50.00 30	
10	1 TO REMOVE AND REFIT REVERSE SENSOR	880 80.00 50	
11	1 TO SPRAY UNDERSEAL	80.00 ✗	
12	1 (REAR) TO SPRAY PAINTING	600.00 400	
13	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	600.00 400.	
		1.410.00	1.410.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 18/10/2018
TP Veh Reg No: SLF7289P

Estimate No: EST1800327
Date: 20 Oct 2018

Veh Reg No: SGX7437T
Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO
Chasis No: MR053ZEC107153938
Reg. Date: 05/09/2007
Your Ref No: SLF7289P


Estimate Repair Cost to Vehicle No :SGX7437T

Quantity	Description	List Price	Amount
		SS	SS
		Total	SS 3,213.42
		Add GST @ 7%	224.94
		Total Amount Payable	SS 3,438.36

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FOUR HUNDRED THIRTY EIGHT AND CENTS THIRTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

Adrian Lij
L/S 26/10/18
03 Days

total: 1793.25
L/S: 164K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: