

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 613E**AAD1810-156***Munday
22/10/18**Not Authorised
11 Sep 2020*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHF 613E
VF1ABL15AUC278452
RENAULT
LATITUDE
12.10.2018
CHINA TAIPING

PART**LIST**

- 1 FENDER PANEL REAR RH
- 1 FENDER PANEL INNER TRIM REAR
- 1 WHEELARCH REAR RH
- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR

\$	<i>B1</i> 3,299.13 ✓
\$	<i>S2</i> 671.45 X
\$	<i>S2</i> 543.47 X
\$	<i>Bu</i> 1,108.46 ✓
\$	<i>S2</i> 768.84 X
\$	<i>S2</i> 113.47 X
\$	<i>010</i> 135.97 ✓
\$	<i>S2</i> 44.99 X

\$	6,685.78
----	-----------------

10% \$	668.58
--------	---------------

\$	6,017.20
----	-----------------

Specical Nett

- 1SET WHEELARCH CLIP REAR LH

\$	<i>nn</i> 30.50 X
----	-------------------

TOTAL \$	30.50
-----------------	--------------

TOTAL PARTS \$	6,047.70
-----------------------	-----------------

LABOUR

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts, adjust
and realign the same

\$	<i>6001</i> 3,000.00
----	-------------------------

Putty and spray painting of the affected portion.

\$	3,000.00 <i>4401</i>
----	----------------------

Trans-cab Auto Services Pte Ltd**AAD1810-156**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 613E

To rust-proofing of the affected areas.	\$	170.00	30d
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	10d
To check steering geometry and computer wheel alignment	\$	220.00	~ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ X
To Check Electrical Lighting Concerned.	\$	170.00	20d
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	~ X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00	~ X

TOTAL \$ 7,870.00**Over All Total \$ 13,917.70****LUMP SUM (REPAIR DAY)****10 DAYS****4 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: