

4/2/03/2002

ASS. REC. BY:

REF:

CS3/AG18019270/Gcd3e2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

chin lee Ying

of

AIG

Date/Time:

23/10/18 @ 12:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLL1887X

Insured:

SLA 5494C

at Workshop m/s

Gee Seng Motor

Tel:

6747 2429

of

1 kaki Bkt Ave 6 # 01-69 Autobay

Policy No:

2100455233

Claim No:

3820588673SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/10/2018

CA / REV / REP. / REV 24 HRS

up

21/10/18 @ Morning

H.O.D. Endorsement:

Date/Time:

4:40pm @ 23/10/18

Person Contacted:

Ah Seng

Vehicle

IN/OUT

Date/Time

Action/Instruction (x) Estimate

SLL1887X - NBA / LP18018779/Y

DOA: 15/10/18

SLA 5494C - NBA / LP18018779/Y

DOA: 15/10/18

Dismantle: 25/10/2018

After repair: 29/10/2018

Signature

REF: AIG

8816E

ASSIGNMENT

From: Date: 24/10/2018

Estimated Cost:

OD/TP WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLL1887X
at Workshop m/s Ghee Seng Motor
of 11kaki Bkt Ave 6 # 01-69

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLL1887X Yr Regn: 16 Feb 2017

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1597

Colour: Red A/C: Insured / Std / NI / NA

Sp.Reading: 28349 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHF C 56506T 001133

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/85 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 24-10-18

Survey held at w/s 3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$1500 / \$2500

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format: DAR

Lump Sum / I.B.I: (\$)

180

20

200

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 23/10/2018 12:27:14 PM
Attachments:  tmp8DE1.tif

Hi LKK,

Kindly assist to survey, vehicle is in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: juseq@singnet.com.sg [mailto:juseq@singnet.com.sg]
Sent: Tuesday, October 23, 2018 10:39 AM
To: Azlan, Syazairdina
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; juseq@singnet.com.sg
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLA5494C AND SLL1887X ON 15/10/2018

Dear Sir,,

We refer to your letter / email.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

- 1) PAR Automotive Consultancy,
- 2) SK Auto Consultants,
- 3) Chartered Auto Assessors,
- 4) LCW APPRAISER PTE LTD
- 5) Sincere Appraisal Services,
- 6) Pal's Appraisal Pte Ltd,
- 7) Mc-Coy Appraiser Pte Ltd,
- 8) CM Automotive Consultancy,

Please be informed that if the above is not agreeable by you, our client's motor vehicle is available for pre-repair inspection at the under-stated workshop:-

Gee Seng Motor Service

Blk 1 Kaki Bukit Avenue 3

#01-69

Singapore 417883

Tel : 6747-2429 (Seng)

* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11.

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation

171 Chin Swee Road #02-06, CES Centre

Singapore 169877

Tel: 6506 6065 / 6536 9339

Fax: 6536 5368

E-mail: tk_sim@juseq.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-06, CES Centre, Singapore 169877

Telephone (65) 6536 9339,

Fax : (65) 6536 5368 (Litigation & Conveyancing)

Email : juseq@singnet.com.sg

website : www.juseq.com.sg

Our Ref: JEQ/180819/1018/GS (zl)

Your Ref: SLA5494C

22 October 2018

KANTAYYA SUNITHA RAZU
265B Sixth Avenue
Singapore 276559

By Post Only

AIG ASIA PACIFIC INSURANCE PTE LTD
Singapore

By Fax: 6835 7416 Only

Dear Sir

ACCIDENT INVOLVING SLL1887X & SLA5494C ON 15.10.2018

We act for the owner of vehicle no. SLL1887X.

We hereby notify you of a road traffic accident on **15 October 2018** at about **1750 hrs**, at Commonwealth Avenue involving our client's vehicle and vehicle registration no. **SLA5494C** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8816E
Vehicle Details	
Vehicle No.:	SLL1887X
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	R16B21601436
Chassis No.:	MRHFC5650GT001133
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,818.00
Original Registration Date:	16 Feb 2017
First Registration Date:	16 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$21,146.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Feb 2027
PARF Rebate Amount:	\$15,859.00
Intended COE Rebate Details	
COE Expiry Date:	15 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$42,344.00
Total Rebate Amount:	\$58,203.00

The information contained herein is correct as at 25 Oct 2018

OK

MNA116134560-01 / National Assessment Centre Services - Uol
 ENTRY DATE & TIME: 18/10/2018 16:57
 SUBMITTED BY: ROSLI BIN ABDUL WAHAB

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2018 16:57
Date Of Accident	15/10/2018 17:50
Exact Location Of Accident	ALONG COMMONWEALTH AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL1867X
Insured/Policyholder	
Name Of Registered Owner	LEONG QINHAO, CALVIN (LIANG QINHAO, CALVIN)
NRIC No	S8438616E
Email Address	CALVIN_LEONG2001@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96521437
Alternative Phone No	OTHERS-91826327

Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	DRIVING BACK HOME FROM WORK

Are you claiming under your own insurance policy for repair to your vehicle? **NO**

If No, Please state action to be taken **THIRD PARTY**

Vehicle Category **PRIVATE CAR**

Insurance Company **LIBERTY INSURANCE PTE LTD**

Name of Insurance Company **LIBERTY INSURANCE PTE LTD**

Type Of Coverage **COMPREHENSIVE**

Fleet Policy **NO**

Policy Number **SD17V02333/VPC2/R00**

Cover Note Number

Driver	
Name of Driver	LIM CHEE YENG
NRIC No	S8279811J
Date Of Birth	25/10/1982
Occupation	INDOOR
Date Of Driving Pass	30/11/2010
Driving Experience	7 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91826327
Fax Number	
Contact Number	OTHERS-96521437
Email Address	CALVIN_LEONG2001@YAHOO.COM.SG

Address BLK 18C HOLLAND DRIVE
 #08-441
 Postcode 274018
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : COLLEAGUE
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLA5494C
 Vehicle Make/Model/Colour NISSAN
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver KANTAYYA SUNITHA RAZU
 NRIC/Passport Number S2572861J
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

G88 SENG-MOTOR SVR

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At around 1750hrs, I was travelling along Commonwealth Ave on extreme right lane. Stopping at the traffic light and was being from behind by a car.

DECLARATION

I/we declare the foregoing particulars accurate in every respect.

Policyholder's Signature

Date & Time

16/10/18 1620

Driver's Signature

(If driver is not the policyholder)

Date & Time

16/10/18 1620

Reporting Centre Person's Signature

Name

NRIC/PUE No.

Valuebold

Rafiq Umar

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair (X) (3)Check (F)
(4)Not Consistent (C)

Rear Portion

NAC	INC	Item	CON	AC	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	DIS	✓	
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler	CRA	✓	
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	DD R	✓	
1160	993339	Rear End Panel Top Garnish	CRA	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	SCR R	✓	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SLL1887X

NAC	INC	Item	CON	AC	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items:

Assessor:

31/10/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2018 Edit Reg		23 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:

KANTAYYA SUNITHA RAZU, ID: S2572861J

Main Claimant:

LEONG QINHAO, CALVIN (LIANG QINHAO, CALVIN), ID: S8438816E

Vehicle Reg. No.:

SLL1887X

Date of Loss:

15/10/2018 17:00 - :59
[19 Months and 29 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 3820588673SG

Policy/Cover Note No.:

2100455233 (Comprehensive)

Vehicle Reg. No. (Insured):

SLA5494C

Policy No. (Claimant):

Excess:

Repairer:

Gee Seng Motor Service (HQ) Blk 1 Kaki Bukit Ave 6, #01-69 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/11/2018]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (24/10/2018): No OI GIA Report
- AIG_SG (24/10/2018): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLL1887X (3820588673SG)**
[SLA5494C]

TP





































LEONG QINHAO, CALVIN (LIANG QINHAO, CALVIN)

Oct 15 2018 5:00PM

[KANTAYYA SUNITHA RAZU]

Gee Seng Motor Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print				
1	30/10/18 11:00	Video - Accident from claimant													Load MOV					
2	02/11/18 10:12	Video - Accident from insured													Load MP4					
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
2	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
3	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
4	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
5	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
6	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
7	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
8	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
9	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
10	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
11	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
12	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
13	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
14	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
15	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
16	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
17	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
18	27/10/18 14:30	General View													Load JPG	<input checked="" type="checkbox"/>				
19	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
20	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
21	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
22	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
23	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
24	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
25	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
26	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
27	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
28	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
29	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
30	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
31	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
32	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
33	27/10/18 14:30	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	27/10/18 14:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	31/10/18 12:07	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/10/18 11:00	E-filed GIA report	 Load PDF	
2	02/11/18 09:25	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18019270/GCD3E2

Date: 13/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100455233
Claimant Vehicle No : SLL1887X **Insured Vehicle No :** SLA5494C
 Date of Loss: 15/10/2018 Nature of Claim: TP Claim No: 3820588673SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL1887X**
 Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B21601436
 Reg. Date: 16/02/2017 (Man. Year: 2016) Chassis No: MRHFC5650GT001133
 Colour: Red Odometer: 28349 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/10/2018
 Date Inspected: 24/10/2018 Inspected At: Gee Seng Motor Service (HQ)
 Blk 1 Kaki Bukit Ave 6, #01-69 Autobay @
 Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
4	1		*REAR BUMPER MOULDING	Distorted	0.00 F	*- F
5	1		*REAR BUMPER LOWER SPOILER	Cracked	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
8	1		*BOOTLID	Repair	0.00 F	*- F
9	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >