

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0468/2018
DATE : 22-OCT-2018

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MRS KOW THONG JEN @ KOW CHONG JIN
ADDRESS : 1 JALAN JAMBU BATU
S(588720)
TELEPHONE NO : 64666391/96740981

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHD3045K
VEHICLE NO : SKV5742M
MODEL CODE : BDRAREZL33EYA---F-
MODEL/YEAR : NISSAN TEANA 2.0
ENGINE NO : MR20041395R
CHASSIS NO : MNTBBAL33Z0005029
MILEAGE : 1 KM
DATE IN : 22/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 19/10/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT ~~WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

18/11 - LIA Ben

17/10/18

22/10/18

14/11

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKV5742M

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	120
2	RRMLB	TO RENEW REAR MULTI LINK BEAM	240.00	?
3	RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE RH REAR	480.00	?
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 02	200.00	X
5	WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	/
6	ZZ/001	REPAIR RH REAR FENDER AND RENEW REAR BUMPER	1000.00	780
7	ZZ/002	S/PAINT REAR BUMPER AND RH REAR FENDER	900.00	500
8	ZZ/003	RENEW AND CONDUCT WHEEL BALANCING S/RIM RH REAR	15.00	/
9	ZZ/004	SUPPLY AND RENEW RH REAR TYRE 215/55R17		
10	ZZ/005	R/I REVERSE SENSOR TO ASSIST REPAIR OR RENEW	110.00	/
TOTAL LABOUR CHARGES			3288.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKV5742M

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	GROMET C/LAMP X	26557-2U001	4.40		
2	GROMET C/LAMP X	26557-2U000	4.40		
3	CLIP C/LAMP X	26398-9N00A			6.00
4	LAMP COMB RR,RH X	26550-3TS0B	401.70		
5	GROMET BUMPER \$5.30 EA X 02 <i>new</i> ✓	85099-3TS0A			10.60
6	BRACKET-BUMPER RH <i>new</i> ?	85221-3TS0A	105.20		
7	GROMMET BUMPER \$2.50 EA X 02 <i>new</i> ✓	63846-5V000	5.00		
8	SPACER RR BMRP RH SIDE <i>new</i> ✓	85094-3TU0A	29.90		
9	BRACKET-BUMPER RH ?	85220-3TS0A	52.60		
10	CLIP BUMPER \$2.50 EA X 08 <i>new</i> ✓	01553-09241	20.00		
11	FASCIA RR BUMPER <i>scd</i> ✓	85022-3TD4H	907.10		
12	ORNAMENT S/RIM <i>new</i> ✓	40343-2LR0A			34.90
13	WHEEL-ROAD AL RH REAR <i>scd</i> ✓	D0300-3TU2B			1461.10
14	SEAT SPRING RR ?	55050-3TS0A			47.70
15	SEAT-RUBBER SPRING ?	55036-3TA0A			48.60
16	BKT ASSY-MOUNTING, SHOCK ABS ?	55322-3TS0A	47.10		
17	BUMPER-SUSPENSION ?	55240-3TS0A			86.40
18	SHOCK ABSORBER RH REAR ?	E6210-3TU0B			204.40
19	MEMBER COMPL ?	55400-3TS0C			1123.00
20	STAY ASSY-REAR RH X	55451-JN01B			81.90
21	STAY ASSY-REAR RH X	55451-3TS0A			203.70
22	HUB A RR AXLE ?	43202-3TU0A			438.60
23	HOUSING ASSY-REAR RH ?	43018-3TS0A			465.60
24	SUNDRIES ?	NPN			100.00
25	215/55R17 MICHELIN PRIMACY LC RH REAR X	215/55R17			290.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKV5742M

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		1577.40	0.00	4602.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		315.48	0.00	0.00
GRAND TOTAL		1261.92	0.00	4602.50
OVERALL TOTAL		5864.42		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKV5742M

TOTAL LABOUR CHARGES	3288.00
TOTAL SPARE PARTS CHARGES	5864.42
GRAND TOTAL	9152.42 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 90010028
SURVEYED DATE	:	13/11/18 @ 1430
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	4 days

Resurvey 68 paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: