

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1204/2018/GW
Date : 23-Oct-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no: GX9049S

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

7 days - ok - jb- 11 Feb 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Eleanor Ng Kah Lian
121 Casuarina Road : 27 foch Road
#02-03
Singapore 209264
Telephone : HP +65 96365831
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SLZ 3332 T**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Jun-18
Engine No : CHZ 940584
Chassis No : WAUZZZ8V0J1066929
Mileage : 2353 KM
Date In : 20-Oct-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Oct-18
Place of Accident : 27 Foch Rd Entrance

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 3332 T

S/n	Nature of Jobs	Estimated Charges			
1	To tow and recover vehicle from scene of accident.	waived			
2	To remove and reinstall front wire harness for healights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	\$ 360.00
3	To remove and transfer rhs front door's multi-lock systeme and power window devices. Inspect for damages.	S/N	\$	280.00	\$ 280.00
4	To remove and reinstall center console and dashboard assy for door hinges renwal.	S/N	\$	3,200.00	nil
5	To dismantle front bumpe, rhs front fender, rhs front door. Inspect rhs A-pillar for further damages. To repair rhs sill panel. Renew front bumper, rhs front fender, rhs front door and rhs wing mirror assy. Reorganize crash mangaement components. reinstall all parts removed.		\$	3,000.00	\$ 1,750.00
6	To respray front bumper, rhs front fender, rhs front door, rhs wing mirror cover and rhs sill panel.		\$	3,300.00	\$ 2,350.00
SUB-TOTAL LABOUR CHARGES		:	\$	10,140.00	\$ 4,740.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 3332 T

S/n	Nature of Jobs		Estimated Charges		
		<i>c/f</i>		\$	4,740.00
7	To renew rhs front rim. To carry out wheel alignment.	S/N	\$ 280.00	\$	280.00
8	<i>Added labour charges</i>		\$ 1,200.00	\$	750.00
10	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 11,812.00	\$	5,962.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 3332 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,739.00	
2	FRONT BUMPER FIXING PARTS	\$ 161.00	
3	FRONT BUMPER GUIDE-RH	\$ 33.00	
4	FRONT BUMPER CLOSING ELEMENT	\$ 254.00	
5	FRONT ADAPTER WHEEL HOUSING LINER-RH	\$ 32.00	
6	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 164.00	
7	FRONT FENDER-RH	\$ 746.00	\$ 596.80
8	FRONT FENDER ATTACHMENT PARTS-RH	\$ 62.00	
9	FRONT FENDER UPPER BRACKET-RH	\$ 24.00	\$ 18.88
10	FRONT FENDER BRACKET-RH	\$ 34.00	\$ 26.64
11	FRONT FENDER BRACE-RH	\$ 84.00	\$ 67.04
12	FRONT FENDER CLOSING ELEMENT-RH	\$ 29.00	
13	FRONT FENDER INSULATION-RH	\$ 36.00	
14	FRONT WHEEL HOUSING LINER SEAL -RH	\$ 29.00	
15	FRONT WHEEL HOUSING LINER -RH	\$ 151.00	
16	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 77.00	
17	FRONT DOOR-RH	\$ 2,190.00	\$ 1,752.00
18	FRONT OUTER DOOR SEAL-RH	\$ 139.00	\$ 111.20
19	BONDING AGENT	\$ 43.00	
20	CLEANING SOLUTION	\$ 64.00	
SUB- SPARE PARTS CHARGES		\$ 6,091.00	\$ 2,572.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 3332 T.

S/N	Parts Description	Damaged Parts & Prices		
		S/Nett	Remark	
			\$	2,572.56
		c/f		
21	FRONT DOOR ATTACHEMENT PARTS-RH	\$ 206.00		
22	FRONT DOOR INNER SEAL-RH	\$ 139.00		
23	FRONT DOOR CATCH-RH	\$ 92.00		
24	FROTN DOOR CATAC COVER-RH	\$ 13.00		
25	FRONT DOOR UPPER HINGE HALF-RH UPPER	\$ 72.00	\$	56.88
26	FRONT DOOR UPPER HINGE HALF-RH LOWER	\$ 108.00	\$	86.00
27	FRONT DOOR LOWER HINGE HALF-RH LOWER	2 \$ 87.00		
28	FRONT EXTERIOR MIRROR MOUNTING-RH	\$ 902.00	\$	721.20
29	FRONT MIRROR CAP-RH	\$ 132.00	\$	105.60
30	FORNT MIRROR GLASS-RH	\$ 1,506.00	\$	1,204.80
31	FRONT WINDOW TRIM STRIP-RH	\$ 222.00	\$	177.60
32	FRONT WINDOW SLOT SEAL-RH	\$ 268.00	\$	214.00
33	PILLAR B TRIM	\$ 85.00		
34	CORNER TRIM-RH	\$ 40.00		
35	FRONT WINDOW REGULATOR-RH	\$ 232.00		
36	FRONT WINDOW REGULATOR MOTOR-RH	\$ 212.00		
37	FRONT DOOR CONTROL UNIT-RH	\$ 438.00		
38	CHASSIS TAG	\$ 406.00		
39	DATA PLATE FOR TYRE PRESSURE	\$ 25.00		
40	FRONT ALUMINIUMRIM-RH	\$ 659.00	\$	527.20
	SUB- SPARE PARTS CHARGES	\$ 5,844.00	\$	5,665.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 3332 T.

Material	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		c/f	\$ 5,665.84
41	RUBBER VALVE	4 \$ 12.00	
42	<i>Added parts - see attached</i>	\$ 581.00	\$ 462.64
43	SUNDRIES	\$ 800.00	\$ 19.76
	TOTAL SPARE PARTS CHARGES	\$ 13,328.00	\$ 6,148.24
	TOTAL LABOUR CHARGES	\$ 11,812.00	\$ 5,962.00
	GRAND TOTAL	\$ 25,140.00	\$ 12,110.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1204/2018/GW 30-Oct-18 Kee Siang 1 of 1 SLZ 3332 T Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>LABORS</u>			
1	To remove and reinstall center console and dashboard assy for door hinges renewal	\$ 3,200.00	<i>nil</i>
<u>PARTS</u>			
1	DOOR COVER	\$ 11.00	\$ 8.24
2	WINDOW GUIDE	\$ 365.00	\$ 291.60
3	DOOR WINDOW RH FRONT	\$ 205.00	\$ 162.80
TOTAL		\$ 3,781.00	\$ 462.64

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1204/2018/GW 29-Oct-18 Kee Siang 1 of 1 SLZ 3332 T Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>LABORS</u>			
1	To repair and respray rhs A-pillar	\$ 1,200.00	\$ 750.00
TOTAL		\$ 1,200.00	\$ 750.00

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLZ 3332 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1204/2018/MAS

25 March 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLZ 3332 T Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SLZ 3332 R**, claimant, **Ms. Elanor Ng Kah Lian @Ng Kah Lian**, please find the related document per attached.

1. A copy of the Original invoice no. 85013563 – S\$12,957.96
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLZ 3332 T

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SLZ3332T

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1204/2018/TF
11 Nov 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI

Vehicle Chassis No. : WAUZZZ8V0J1066929

Vehicle Regn No. : **SLZ3332T**

Vehicle Mileage : 2353 km

Vehicle Owner : Ms. Eleanor Ng Kah Lian

Certificate No : 1800062131

Policy Excess : Waiver

Accident Date : 20 October 2018

Place : 27 Foch Road

Repair Cost : \$ 12,957.96

WIP No. : 29128

Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


5/11

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2018 11:16		24 Oct 2018 09:18 Edit Adj Rpt	S\$12,110.24 Edit Estimates	S\$12,110.24 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ELEANOR NG KAH LIAN, ID: S6918006Z, Tel: +6596365831, Email: vertexgoal@hotmail.com		
Vehicle Reg. No.:	SLZ3332T	Date of Loss:	20/10/2018 00:00 - :59 [4 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 3335650618SG	Policy/Cover Note No.:	1800062131 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/11/2018]		
Driver/Custodian:	ELEANOR NG KAH LIAN (49 / Female) , NRIC: S6918006Z, Tel: +6596365831 Email: vertexgoal@hotmail.com		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (09/11/2018): Alert - Adj Mandate Approved (S\$12859.00) - SLZ3332T - Claim Handler: Mohd Zaway...
- AIG_SG (26/10/2018): Alert - Adj Mandate Approved (S\$11628.00) - SLZ3332T - Claim Handler: Mohd Zaway...
- AIG_SG (24/10/2018): SLZ3332T / OD / 20/10/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLZ3332T (3335650618SG)**

OD

Oct 20 2018 12:00AM

[ELEANOR NG KAH LIAN]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page			☒		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)													Thumbnail			Print		
1	20/10/18 10:08	Video - Accident [Linked Accident Report Documents]																Load MP4		
Assessment Reports															1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	24/10/18 11:18	Adjuster Immediate Advice																Load HTM		
2	05/11/18 11:25	Adjuster Immediate Advice																Load HTM		
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	24/10/18 11:22	General View																Load JPG		
2	24/10/18 11:22	Chassis Number																Load JPG		
3	24/10/18 11:22	General View																Load JPG		
4	24/10/18 11:22	General View																Load JPG		
5	24/10/18 11:22	General View																Load JPG		
6	24/10/18 11:22	General View																Load JPG		
7	24/10/18 11:22	General View																Load JPG		
8	24/10/18 11:22	General View																Load JPG		
9	24/10/18 11:22	General View																Load JPG		
10	24/10/18 11:22	General View																Load JPG		
11	24/10/18 11:22	General View																Load JPG		
12	24/10/18 11:22	General View																Load JPG		
13	24/10/18 11:22	General View																Load JPG		
14	24/10/18 11:22	General View																Load JPG		
15	24/10/18 11:22	General View																Load JPG		
16	24/10/18 11:22	General View																Load JPG		
17	24/10/18 11:22	General View																Load JPG		
18	24/10/18 11:22	General View																Load JPG		
19	24/10/18 11:22	General View																Load JPG		
20	24/10/18 11:22	General View																Load JPG		
21	24/10/18 11:22	General View																Load JPG		
22	24/10/18 11:22	General View																Load JPG		
23	24/10/18 11:22	General View																Load JPG		
24	24/10/18 11:22	General View																Load JPG		
25	24/10/18 11:22	General View																Load JPG		
26	24/10/18 11:22	General View																Load JPG		
27	05/11/18 11:18	Reinspection Photo																Load JPG		
28	05/11/18 11:18	Reinspection Photo																Load JPG		
29	05/11/18 11:18	Reinspection Photo																Load JPG		

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
30	05/11/18 11:18	Reinspection Photo	Load JPG	☒
31	05/11/18 11:18	Reinspection Photo	Load JPG	☒
32	05/11/18 11:18	Reinspection Photo	Load JPG	☒
33	05/11/18 11:18	Reinspection Photo	Load JPG	☒
34	05/11/18 11:18	Reinspection Photo	Load JPG	☒
35	05/11/18 11:18	Reinspection Photo	Load JPG	☒
36	05/11/18 11:18	Reinspection Photo	Load JPG	☒
37	05/11/18 11:18	Reinspection Photo	Load JPG	☒
38	05/11/18 11:18	Reinspection Photo	Load JPG	☒
39	05/11/18 11:18	Reinspection Photo	Load JPG	☒
40	05/11/18 11:18	Reinspection Photo	Load JPG	☒
41	05/11/18 11:18	Reinspection Photo	Load JPG	☒
42	05/11/18 11:18	Reinspection Photo	Load JPG	☒
43	05/11/18 11:18	Reinspection Photo	Load JPG	☒
44	05/11/18 11:18	Reinspection Photo	Load JPG	☒
45	05/11/18 11:18	Reinspection Photo	Load JPG	☒
46	05/11/18 11:18	Reinspection Photo	Load JPG	☒
47	05/11/18 11:18	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/10/18 11:22	Singapore Accident Statement	Load PDF	
2	24/10/18 11:22	ADDENDUM GIA REPORT	Load PDF	
3	24/10/18 11:22	Certificate of Insurance	Load PDF	
4	24/10/18 11:22	Driver's Driving License	Load PDF	
5	24/10/18 11:22	ESTIMATE	Load PDF	
6	08/04/19 16:41	WORKSHOP INVOICE	Load PDF	
7	08/04/19 16:41	DISCHARGE VOUCHER	Load PDF	
8	08/04/19 16:41	SUPPLEMENTARY	Load PDF	

Linked Accident Report Documents

Video				View View in Browser
			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/10/18 10:08	Video - Accident	Load MP4	
Assessment Reports				1 per page ☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/10/18 10:16	Accident Statement	Load HTM	
2	23/10/18 11:56	Addendum Sheet	Load JPG	☒
3	23/10/18 11:57	Accident Statement Addm. #1	Load HTM	
Photos/Images				3 per page ☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/10/18 10:15	Accident Photo	Load JPG	☒
2	20/10/18 10:15	Accident Photo	Load JPG	☒
3	20/10/18 10:15	Accident Photo	Load JPG	☒
4	20/10/18 10:15	Accident Photo	Load JPG	☒
5	20/10/18 10:15	Accident Photo	Load JPG	☒
6	20/10/18 10:15	Accident Photo	Load JPG	☒

Video			1 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
7	20/10/18 10:15	Accident Photo		Load JPG ✓
8	20/10/18 10:15	Accident Photo		Load JPG ✓
9	20/10/18 10:15	Accident Photo		Load JPG ✓
10	20/10/18 10:15	Accident Photo		Load JPG ✓
11	20/10/18 10:15	Accident Photo		Load JPG ✓
12	20/10/18 10:15	Accident Photo		Load JPG ✓
13	20/10/18 10:15	Accident Photo		Load JPG ✓
14	20/10/18 10:15	Accident Photo		Load JPG ✓
15	20/10/18 10:15	Accident Photo		Load JPG ✓

Documentation			1 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/10/18 10:16	Sketch Plan		Load JPG ✓
2	20/10/18 10:16	Sketch Plan #2		Load JPG ✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18019295/AQBS2

Date: 08/04/2019

REFERENCE

Insured/Claimant:	ELEANOR NG KAH LIAN	Policy No:	1800062131	
Date of Loss:	20/10/2018	Nature of Claim:	OD	Claim No: 3335650618SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ3332T		
Make & Model:	AUDI A3, 999cc TFSI (A)	Engine No:	CHZ940584
Reg. Date:	05/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V0J1066929
Colour:	Red	Odometer:	2354 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$125,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,209.64	6,148.24	7,061.40	53.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,012.00	5,962.00	9,050.00	60.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,221.64	12,110.24	16,111.40	57.09
+ GST 7.00/7.00% (S\$)	1,975.51	847.72	1,127.79	57.09
Nett Amount (S\$)	30,197.15	12,957.96	17,239.19	57.09

INSPECTION

Date of Assignment:	24/10/2018		
Date Inspected:	23/10/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,739.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	161.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE - RH	Not Necessary	33.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	254.00 FS	*- FS
5	1		*FRONT ADAPTER WHEEL HOUSING LINER - RH	Not Necessary	32.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	164.00 FS	*- FS
7	1		*FRONT FENDER - RH	Distorted	746.00 FS	*596.80 FS
8	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	62.00 FS	*- FS
9	1		*FRONT FENDER UPPER BRACKET - RH	Bent	24.00 FS	*18.88 FS
10	1		*FRONT FENDER BRACKET - RH	Bent	34.00 FS	*26.64 FS
11	1		*FRONT FENDER BRACE - RH	Bent	84.00 FS	*67.04 FS
12	1		*FRONT FENDER CLOSING LEMENT - RH	Not Necessary	29.00 FS	*- FS
13	1		*FRONT FENDER INSULATION - RH	Not Necessary	36.00 FS	*- FS
14	1		*FRONT WHEEL HOUSING LINER SEAL - RH	Not Necessary	29.00 FS	*- FS
15	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	151.00 FS	*- FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	77.00 FS	*- FS
17	1		*FRONT DOOR - RH	Distorted	2,190.00 FS	*1,752.00 FS
18	1		*FRONT OUTER DOOR SEAL - RH	Necessary	139.00 FS	*111.20 FS
19	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
20	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
21	1		*FRONT DOOR ATTACHMENT PARTS - RH	Not Necessary	206.00 FS	*- FS
22	1		*FRONT DOOR INNER SEAL - RH	Not Necessary	139.00 FS	*- FS
23	1		*FRONT DOOR CATCH - RH	Not Necessary	92.00 FS	*- FS
24	1		*FRONT DOOR CATCH COVER - RH	Not Necessary	13.00 FS	*- FS
25	1		*FRONT DOOR UPPER HINGE HALF - RH UPPER	Bent	72.00 FS	*56.88 FS
26	1		*FRONT DOOR UPPER HINGE HALF - RH LOWER	Bent	108.00 FS	*86.00 FS
27	2		*FRONT DOOR LOWER HINGE HALF - RH LOWER	Not Necessary	87.00 FS	*- FS
28	1		*FRONT EXTENRIOR MIRROR MOUNTING - RH	Damaged	902.00 FS	*721.20 FS
29	1		*FRONT MIRROR CAP - RH	Missing	132.00 FS	*105.60 FS
30	1		*FRONT MIRROR GLASS - RH	Cracked	1,506.00 FS	*1,204.80 FS
31	1		*FRONT WINDOW TRIM STRIP - RH	Cut	222.00 FS	*177.60 FS
32	1		*FRONT WINDOW SLOT SEAL - RH	Cut	268.00 FS	*214.00 FS
33	1		*PILLAR B TRIM	Not Necessary	85.00 FS	*- FS
34	1		*CORNER TRIM - RH	Not Necessary	40.00 FS	*- FS
35	1		*FRONT WINDOW REGULATOR - RH	Not Necessary	232.00 FS	*- FS
36	1		*FRONT WINDOW REGULATOR MOTOR - RH	Not Necessary	212.00 FS	*- FS
37	1		*FRONT DOOR CONTROL UNIT - RH	Not Necessary	438.00 FS	*- FS
38	1		*CHASSIS TAG	Not Necessary	406.00 FS	*- FS
39	1		*DATA PLATE FOR TYRE PRESSURE	Not Necessary	25.00 FS	*- FS
40	1		*FRONT ALUMINIUM RIM - RH	Cut	659.00 FS	*527.20 FS
41	4		*RUBBER VALVE	Not Necessary	12.00 FS	*- FS
42	1		*SUNDRIES	Necessary	800.00 FS	*19.76 FS
43	1		*DOOR COVER	Necessary	8.24 FS	*8.24 FS
44	1		*WINDOW GUIDE	Cut	291.60 FS	*291.60 FS
45	1		*DOOR WINDOW RH FRONT	Scratched	162.80 FS	*162.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	13,209.64	6,148.24
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT. (WAIVED)	New	0.00	0.00
2	TO REMOVED AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
3	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	New	280.00	280.00
4	TO REMOVE AND REINSTALL CENTER CONSOLE AND DASHBOARD ASSY FOR DOOR HINGES RENWAL.	New	3,200.00	0.00
5	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR. INSPECT RHS A-PILLAR FOR FURTHER DAMAGES. TO REPAIR RHS SILL PANEL. RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS WING MIRROR ASSY. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	3,000.00	1,750.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER AND RHS SILL PANEL.	New	3,300.00	2,350.00
7	TO RENEW RHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
9	TO REPAIR AND RESPRAY RHS A-PILLAR.	New	1,200.00	750.00
10	TO REMOVE AND REINSTALL CENTER CONSOLE AND DASHBOARD ASSY FOR DOOR HINGES RENEWAL. (Repeated)	New	3,200.00	0.00
Gross Labour Cost (\$\$)			15,012.00	5,962.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >