

22/03/2002

ASS. SEC. BY:

REF: CS/CT118019310/Uqd322

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CT1

Date/Time:

23/10/18 @ 3:30pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 8476 U

Insured:

GBG 82764

at Workshop m/s

Kah Motor

Tel:

9072 1766

of

15 Ubi Road 4

Policy No:

DMCV SN 1766 31706

Claim No:

8NM18D0494402

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/10/2018

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

9:51am @ 24/10/18

Person Contacted:

RubenVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLW 8476U - NA/CT118018925/24	DOA: 15/10/2018
	GBG 82764 - NA/CT118018925/24	DOA: 15/10/2018

Survey No / CUS

REF:

C7.1

ASSIGNMENT

Front: Date: Estimated Cost: 00 / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 84674 - Kahuter

at Workshop mis of insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IBAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A 39667

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLW 84674 Yr Regn: 3 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Honda

Java

9.0

1318

Colour:

pink

A/C:

Insured / Std / NI / NA

Sp. Reading:

7827

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

JHMGK380JX225710

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

15/10/18

D.O.I.

24/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

e/s Rear

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

21/2/18 L7A 39667 Conf. and final for 6563.99 with Ruben (Ref 1735.02, 217.2)

RECEIVED 12 FEB 2019

Date/Time File Pass to?

21/2/18

Date/Time File Return to?



: Preli. Report



: Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee

Transportation

Site Insp

Interview

Tech Insp

Weekend

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Insp (\$)



Weekend (\$)

2

Report Format:

Lump Sum / I.B.I. (\$)

MER-11

6563.99

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2018		23 Oct 2018 15:30 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S BM ENGINEERING WERKS PTE LTD, Co. Reg. No.: 201714594D		
Main Claimant:	KAH MOTOR CO SDN BHD		
Vehicle Reg. No.:	SLW8476U	Date of Loss:	15/10/2018 19:00 - :59
Claim Type:	TP / SNM18D04944C02	Policy/Cover Note No.:	DMCVSN1766631700 (Comprehensive)
Vehicle Reg. No. (Insured):	GBG8276H	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2018]		
Adj Asg. Remarks:	EST \$6728.16, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18004522	Page	1
	3 ANSON ROAD #16-00	Date	: 22. Oct 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SLW8476U	Engine No	: L13B11030177		
Chassis No	: JHMGK3850JX205710	Date Time	: 22. Oct 2018 2:33:21 PM		
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: KAH MOTOR CO. SDN. BHD.	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 15/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: KAH MOTOR CO. SDN.BHD						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 15/10/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: CHINA TAIPING INSURANCE						
	TP VEH: GBG8276H						
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>neu</i>	2	9.50	25	14.25	1.00	15.25
91501-T5A-003	CLIPQUARTER WINDSHIELD A <i>neu</i>	1	3.60	25	2.70	0.19	2.89
91502-T5A-003	CLIPQUARTER WINDSHIELD B <i>neu</i>	1	3.60	25	2.70	0.19	2.89
91503-T5A-003	CLIPQUARTER WINDSHIELD C <i>neu</i>	1	2.40	25	1.80	0.13	1.93
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>neu</i>	1	60.00		60.00	4.20	64.20
04636-TAR-300ZZ	PANEL SET,R.RR.OUTER <i>Body 570.50</i>	1	610.90	25	458.17	32.07	490.24
67510-T5A-N10ZZ	PANEL COMPR.RR.DOOR <i>Body 570.50</i>	1	703.40	25	527.55	36.93	564.48
67825-T5A-003	TAPER.RR.DOOR SASH <i>neu</i>	1	15.40	25	11.55	0.81	12.36
72824-T5A-J01	SUB SEALR.RR.DOOR <i>neu</i>	1	6.30	25	4.72	0.33	5.05
42700-T5S-M72	WHEEL,DISK AL 15X7 <i>R</i>	1	406.30	25	304.72	21.33	326.05
Sum Item					1388.16	97.18	1,485.34
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60
BOSUN	SUNDRIES <i>neu</i>	1	50.00	20	50.00	3.50	53.50
BOJSE	BODY JOINT SEALANT. <i>neu</i>	1	100.00	0	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	180	250.00	17.50	267.50
BG52D	REMOVE & INSTALL RR. R QTR GLASS.(N)	1	280.00		280.00	19.60	299.60

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT18004522	Page	2
Registration No	: SLW8476U	Date	: 22. Oct 2018		
Chassis No	: JHMGK3850JX205710	Customer No.	: WZC008		
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: KAH MOTOR CO. SDN. BHD.	Engine No	: L13B11030177		
Ins Policy No.	:	Date Time	: 22. Oct 2018 2:33:21 PM		
Date of Accident	: 15/10/2018	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	380.00	350	380.00	26.60	406.60
BKFE22R	CUT OFF & RENEW RR R FENDER. 260	1	2400.00	2240	2400.00	168.00	2568.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) 450	1	1600.00	1350	1600.00	112.00	1712.00
Sum Labor					5160.00	361.20	5,521.20

Survey By	<u>meerus alan</u>	Total Amount	6,728.16	470.98	7,199.14
Date & Time	<u>24/10/18 @ 12:30</u>	Total (Inclusive of GST)			<u>7,199.14</u>
Excess					
Status	<u>not adjust</u>				
Signature	<u>Alan 24/10/18 before party.</u> <u>8 dy.</u>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 22/10/2018 2:47:52 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

8299.01

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT19000284	Page	1
	3 ANSON ROAD #16-00	Date	: 16. Jan 2019		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SLW8476U	Engine No	: L13B11030177		
Chassis No	: JHMGK3850JX205710	Date Time	: 16. Jan 2019 10:58:01 AM		
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: KAH MOTOR CO. SDN. BHD.	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 15/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl'd GST
SUPPLEMENTARY PARTS & LABOUR							
04631-TAR-300ZZ	PANEL SET,R.SIDE	1	227.80	25	170.85	11.96	182.81
Sum Item					170.85	11.96	182.81
BKSP12R	CUT OFF & RENEW R SILL PANEL. STRAIGHTEN ALIGN	1	1400.00		1400.00	98.00	1498.00
Sum Labor					1400.00	98.00	1498.00

Survey By

Date & Time

Excess

Status

Signature

Total Amount 1,570.85 109.96 1,680.81

Total (Inclusive of GST) 1,680.81

Printed on 16/1/2019 11:01:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

ATTN: MARCUS CHUA

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

WD: 8 DAYS

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMGK3850JX205710
License No: SLW8476U
Mileage: 7820
Engine No: L13B11030177

Document No: SVO18069314
Printed By: JESHURUEBEN
Order Date: 22. November 2018
Order Time: 8:53:41 AM
Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71671) OWNER: KAH MOTOR CO. SDN.BHD OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 15/10/2018 SURVEYED BY: MARCUS CHUA (LKK) DATE: 24/10/2018 REF NO: TP INSURER: CHINA TAIPING INSURANCE TP VEH: GBG8276H						
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.50	25	14.25	1.00	15.25
91501-T5A-003	CLIPQUARTER WINDSHIELD A	1	3.60	25	2.70	0.19	2.89
91502-T5A-003	CLIPQUARTER WINDSHIELD B	1	3.60	25	2.70	0.19	2.89
91503-T5A-003	CLIPQUARTER WINDSHIELD C	1	2.40	25	1.80	0.13	1.93
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
04636-T5A-300ZZ	PANEL SETR.RR.OUTSIDE	1	570.50	25	427.87	29.95	457.82
67510-T5A-N10ZZ	PANEL COMPR.RR.DOOR	1	703.40	25	527.55	36.93	564.48
67825-T5A-003	TAPER.RR.DOOR SASH	1	15.40	25	11.55	0.81	12.36
72824-T5A-J01	SUB SEALR.RR.DOOR	1	6.30	25	4.72	0.33	5.05
04631-TAR-300ZZ	PANEL SET,R.SIDE	1	227.80	25	170.85	11.96	182.81
	SUM PARTS:				1,223.99	85.69	1,309.68
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BOJSE	0760 BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60
BOBC	0760 BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	EXT-YBH APPLY BODY UNDERSIDE COATING (N).	1	180.00		180.00	12.60	192.60
BG52D	EXT-YJ REMOVE & INSTALL RR. R QTR GLASS. (N)	1	280.00		280.00	19.60	299.60
BKDR22R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST & ALIGN RR R DR.(N)	1	350.00		350.00	24.50	374.50
BKFE22R	EXT-YJ CUT OFF & RENEW RR R FENDER.	1	2,240.00		2,240.00	156.80	2,396.80
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	1,350.00		1,350.00	94.50	1,444.50
BKSP12R	560.00 CUT OFF & RENEW R SILL PANEL STRAIGHTEN ALIGN SIDE FLOOR PANEL & RENEW DAMAGE PARTS.	1	560.00		560.00	39.20	599.20
	SUM LABOUR:				5,160.00	361.20	5,521.20
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	SUM EXT SERVICE:				180.00	12.60	192.60

TOTAL SGD 6,563.99 459.49 7,023.48

Total Payable (SGD)

7,023.48

OK
CONF



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMGK3850JX205710
License No: SLW8476U
Mileage: 7820
Engine No: L13B11030177

Document No: SVO18069314
Printed By: JESHURUEBEN
Order Date: 22. November 2018
Order Time: 8:53:41 AM
Service Advisor: RUEBEN THOMAS

GST Amount is calculated from individual line(s)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	16/10/2018 15:05
Date Of Accident	15/10/2018 19:55
Exact Location Of Accident	BARTLEY FLYOVER
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLW8476U
Insured/Policyholder	
Name Of Registered Owner	KAH MOTOR CO SDN BHD
Co Reg No	S60FC1380G
Email Address	JESHURUEBEN@HONDA.COM.SG
Mobile Phone No	(LOCAL) +65-90721766
Alternative Phone No	OFFICE-68465672
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ-1.3 LX (GE6) (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MC015064-R06
Cover Note Number	
Driver	
Name of Driver	HO SHU FOON GIOVANNA
NRIC No	S7921471Z
Date Of Birth	27/07/1979
Occupation	OUTDOOR
Date Of Driving Pass	04/04/2000
Driving Experience	18 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-88680680
Fax Number	
Contact Number	
EMAIL Address	FEN_SMILE@YAHOO.COM

Address	APT BLK 85B LORONG 4 TOA PAYOH #12-344
Postcode	312085
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : YAP FEE CHIN GENDER: : FEMALE
Passenger 2	NAME: : YAP WEE SOO GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG8276H
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KHAN
NRIC/Passport Number	
Contact Number	81563373
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Vehicle No

SLW 8476U

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

16/10/2018
10:30 am

Witnessed by Reporting Centre Personnel

Sketch Plan

Please continue to Annex E

Vehicle No SLW 8476U

Annex E

Describe Circumstances of the Accident

I was driving straight along the Bursley Flyover, heading towards CRE. I was driving on the extreme left lane. And suddenly a lorry GBG 8276 H came from the lane on my right and hit into my vehicle on the rear right.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (If driver is not the policyholder) / Date & Time

16/10/2015
10:30am

[Signature]

Witnessed by Reporting Centre Personnel

➤ **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Company
Owner ID:	1380G
Vehicle Details	
Vehicle No.:	SLW8476U
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	L13B11030177
Chassis No.:	JHMGK3850JX205710
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,224.00
Original Registration Date:	05 Mar 2018
First Registration Date:	05 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$5,224.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Mar 2028
PARF Rebate Amount:	\$3,918.00
Intended COE Rebate Details	
COE Expiry Date:	04 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,200.00
COE Rebate Amount:	\$35,749.00
Total Rebate Amount:	\$39,667.00

The information contained herein is correct as at 24 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Oct 2018		23 Oct 2018 15:30 Edit Adj Rpt	S\$6,563.99 Edit Estimates	S\$6,563.99 View Rpt		Pending for Survey Report Cancel Case

Main		Reference	Claim Details	Documents	Show All
-------------	--	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]	
Insured:	M/S BM ENGINEERING WERKS PTE LTD, Co. Reg. No.: 201714594D				
Main Claimant:	KAH MOTOR CO SDN BHD				
Vehicle Reg. No.:	SLW8476U	Date of Loss:	15/10/2018 19:00 - :59 [7 Months and 10 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / SNM18D04944C02	Policy/Cover Note No.:	DMCVSN1766631700 (Comprehensive)		
Vehicle Reg. No. (Insured):	GBG8276H	Policy No. (Claimant):			
		Excess:	S\$0.00		
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671				
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 01/11/2018]				
Adj Asg. Remarks:	EST \$6728.16, CASE WITH SJE.				

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS				View All	Search Tasks	Create New Task	Complete		
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW8476U (SNM18D04944C02)

[GBG8276H]

TP




































KAH MOTOR CO SDN BHD

Oct 15 2018 7:00PM




[M/S BM ENGINEERING WERKS PTE LTD]

Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<div></div>
No	Finalized On	National Assessment Centre Services (Ubi)								Thumbnail	Print
1	17/10/18 18:34	Accident Statement							<div></div>	Load HTM	
Photos/Images									3 per page		<div></div>
No	Finalized On	National Assessment Centre Services (Ubi)								Thumbnail	Print
1	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
2	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
3	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
4	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
5	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
6	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
7	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
8	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
9	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
10	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
11	17/10/18 18:32	Accident Photo [Linked Accident Report Documents]							<div></div>	Load JPG	<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	21/02/19 16:07	Chassis Number							<div></div>	Load JPG	<div></div>
2	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
3	21/02/19 16:07	Odometer Reading							<div></div>	Load JPG	<div></div>
4	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
5	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
6	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
7	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
8	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
9	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
10	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
11	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
12	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
13	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
14	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
15	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
16	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
17	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>
18	21/02/19 16:07	General View							<div></div>	Load JPG	<div></div>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
19	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
20	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
23	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
24	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
25	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
26	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
27	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
28	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
29	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
30	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
31	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
35	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
36	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
38	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/02/19 16:07	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/02/19 16:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	21/02/19 16:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	21/02/19 16:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	21/02/19 16:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	21/02/19 16:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	21/02/19 16:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	21/02/19 16:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	21/02/19 16:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/10/18 15:29	EMAIL FM KAH	 Load PDF	
2	23/10/18 15:29	REPAIR EST WITH TP GIA	 Load PDF	
3	23/10/18 15:30	OI GIA	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/10/18 18:32	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	17/10/18 18:32	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/02/19 14:14	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/10/18 18:34	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/10/18 18:32	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	17/10/18 18:32	Accident Photo	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
3	17/10/18 18:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	17/10/18 18:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	17/10/18 18:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	17/10/18 18:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	17/10/18 18:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	17/10/18 18:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	17/10/18 18:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	17/10/18 18:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	17/10/18 18:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	17/10/18 18:32	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	17/10/18 18:32	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019310/UQD3E2

Date: 22/02/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1766631700
Claimant Vehicle No :	SLW8476U	Insured Vehicle No :	GBG8276H
Date of Loss:	15/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D04944C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW8476U	Engine No:	L13B11030177
Make & Model:	HONDA JAZZ, 1.3 LX (GE6) (A)	Chassis No:	JHMGK3850JX205710
Reg. Date:	05/03/2018 (Man. Year: 2017)	Odometer:	7827 km
Colour:	Pink		
Engine Capacity:	1318 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,609.01	1,243.99	365.02	22.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,690.00	5,320.00	1,370.00	20.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,299.01	6,563.99	1,735.02	20.91
+ GST 7.00/7.00% (S\$)	580.93	459.48	121.45	20.91
Nett Amount (S\$)	8,879.94	7,023.47	1,856.47	20.91

INSPECTION

Date of Assignment:	23/10/2018		
Date Inspected:	24/10/2018	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	8.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2019)
Parts: 144	HONDA JAZZ 1.3 LX (GE6) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLW8476U)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RUBBERR QTR W/SHIELD (2PCS)	Necessary	14.25 FS	*14.25 FS
2	1		*CLIPQUARTER WINDSHIELD A	Necessary	2.70 FS	*2.70 FS
3	1		*CLIPQUARTER WINDSHIELD B	Necessary	2.70 FS	*2.70 FS
4	1		*CLIPQUARTER WINDSHIELD C	Necessary	1.80 FS	*1.80 FS
5	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
6	1		*PANEL SET, R.RR.OUTER	Badly Dented	458.17 FS	*427.87 FS
7	1		*PANEL COMPR.RR.DOOR	Badly Dented	527.55 FS	*527.55 FS
8	1		*TAPER.RR.DOOR SASH	Necessary	11.55 FS	*11.55 FS
9	1		*SUB SEALR.RR.DOOR	Necessary	4.72 FS	*4.72 FS
10	1		*WHEEL, DISK AL 15X7	Repair	304.72 FS	*- FS
11	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
12	1		*PANEL SET, R.SIDE	Dented / Bent	170.85 FS	*170.85 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	1,609.01	1,243.99
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WHEEL ALIGNMENT X4	New	180.00	180.00
2	BODY JOINT SEALANT	New	100.00	80.00
3	BODY UNDERSIDE COATING	New	100.00	100.00
4	APPLY BODY UNDERSIDE COATING	New	250.00	180.00
5	REMOVE & INSTALL RR.R QTR GLASS	New	280.00	280.00
6	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	New	380.00	350.00
7	CUT OFF & RENEW RR R FENDER	New	2,400.00	2,240.00
8	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P)	New	1,600.00	1,350.00
9	CUT OFF & RENEW R SILL PANEL. STRAIGHTEN ALIGN	New	1,400.00	560.00
Gross Labour Cost (\$\$)			6,690.00	5,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >