

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 24 Oct 2018

Preliminary Advice

Vehicle No	: SLD1338G	Accident Date	: 22/10/2018
Make	: NISSAN X-TRAIL	Policy No.	: DMPCSN3044541802
Assignment Date	: 23/10/2018	Excess	: S\$1,100.00
Date of Inspection	: 24/10/2018	Est. Duration of Repair	: 8.00
Inspection At	: AUTOLUTION INDUSTRIAL PTE LTD (UBI) 19 UBI ROAD 4 SINGAPORE 408623		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,440.86
Revised Amount	:S\$	11,945.84
Check Items (Estimated)	:S\$	4,433.42
Total	:S\$	16,379.26
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.99
COE / PARF Rebate	:S\$	56,209.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,791.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :