

ASS. REC. BY:

REF

CS/CTI18019313/Urd302

Special Instructions:

Surveyor
Merimen

Marcus

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

23/10/18 @ 4:24pm

Estimated Cost:

Bill to:

①

TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLD 1338G

Insured:

at Workshop m/s

Autolution Industrial
19 Ubi Road 4

Tel:

96450079

Policy No:

OMPESN3044541802

Claim No:

SNM18D05006

Sum Insured:

Excess:

\$1,100.00

Make of Veh:

(Client's Record)

D.O.A.

22/10/2018

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:05am @ 24/10/18

Person Contacted:

Hamzah

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLD 1338G-X

24/10/18

Revert via merimen

25/10/18

Rec approved \$16,379.26 from Alfred Toh via merimen

25/10/18

Informed Hamzah c/a ex \$1100 by email

Car No: 10/01/18

REF:

CT1/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 () TP / WS / TP RES / OD RES / EVA / INV / MV
 To Insured Vehicle No: **SLD/3386**
 at Workshop no: **Arulm**
 ()
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: **1100**
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Est. or Market Value: **\$85/-**
 I/A/C Accident Report Consistent? : Yes or No
 I/A / FR Seen: Consistent? : Yes or No
 Est. Repairs: **8** days Rep: Yes or No
 Lump Sum: **131** \$ Val: Yes or No
 CA / REV / REP / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle IN / OUT

Veh No: **SLD/3386** Yr Regn: **5 16**
 Type: **()** M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover
 Truck / Trailer or (A)
 Make: **NISSAN X-trail** Yr: **1997**
 Color: **Brown** A/C: _____ Insured / Std / NI / NA
 Seating: **546/3** T-Box: Insured / Std / NI / NA
 Engine: _____
 Chassis: **JN1JANT32Z0001849**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / R/Rim / STD A/Rim or
 Tyre Size: **F: 225/60R18**
 R: _____
 BS / **()** DUX / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **22/10/18** D.O.I: **24/10/18**
 Survey held at: _____
 Des. of Damages: **()** Front / Rear / O/S / N/S / U/C / Rooftop or
Front
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

LIA \$6209 Sol 7yrs Indr. 3/11/18 2879/

19/11/18 Car not paid by **12886.10** with **Manzab** (Ref 4554.76, 2690)

RECEIVED 20 NOV 2018

19/11/2018

Date/Time File Pass to: ☐ Prel. Report
☐ Final Report

Days Of Repair: **8**

Resurvey No. of Trip: **1**

Survey Fee

Transportation

Food

Other

Total

Remarks

Signature

Date

19/11-tyrist

Add Fee: ☐ Site Insp: \$
☐ Interview: \$
☐ Test: \$
☐ Weekend: \$

Report Format: **merimen**
 Lump Sum / I.B. / 12, 886.10

200
210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	WSI Submitted	Ins. Auth'd	Status
Main	22 Oct 2018		23 Oct 2018 16:24 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YAP YEE FARN (YE YIFAN), ID: S7716182A		
Vehicle Reg. No.:	SLD1338G	Date of Loss:	22/10/2018 08:00 - :59 [29 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D05006	Policy/Cover Note No.:	DMPCSN3044541802 (Comprehensive)
		Excess:	S\$1,100.00
Repairer:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2018]		
Driver/Custodian:	LIU WEITING (34 / Female), NRIC: S8416413E, Tel: +6591881589		
Adj. Asg. Remarks:	REVERT.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Created By
----------	----------	------	------------	---------	---------	-------------	--------------	------------	------------

No results.

Veron Chen (LKKAUTO)

From: Hamzah <hamzah_saad@tanchong.com>
Sent: Thursday, 25 October 2018 3:59 PM
To: Veron Chen (LKKAUTO); SUR
Subject: Re: SLD 1338G-DOA: 22/10/18 (CHINA TAIPING OD)

Dear Veron,

Noted with thanks.

Regards

Hamzah Sa'ad
Service Supervisor
Autolution Industrial Pte Ltd
19 Ubi Road 4
S408623
TEL: +65 67038680 DID: +65 67038690 FAX: +65 68467483
Hp: +65 96450079 Email: hamzah_saad@tanchong.com

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Thursday, October 25, 2018 3:44:49 PM
To: Hamzah; SUR
Subject: SLD 1338G-DOA: 22/10/18 (CHINA TAIPING OD)

Dear Hamzah,

As instructed by our client , please proceed to repair the **insured vehicle SLD 1338G based on surveyor's marking or which ever lower (Excess \$1100/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLD1338G (SNM18D05006)**

OD

Oct 22 2018 8:00AM

[YAP YEE FARN (YE YIFAN)]

Autolution Industrial Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **25/10/2018 15:11 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16379.26) - SLD1338G - Claim Handler: Elaine Cheong

Approved:16379.26:Please proceed to authorize repairs UP TO \$16,379.26 BEFORE EXCESS of \$1,100.00. Re-inspection of vehicle required.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Elaine Cheong	Date:	24 Oct 2018

Preliminary Advice

Vehicle No	: SLD1338G	Accident Date	: 22/10/2018
Make	: NISSAN X-TRAIL	Policy No.	: DMPCSN3044541802
Assignment Date	: 23/10/2018	Excess	: S\$1,100.00
Date of Inspection	: 24/10/2018	Est. Duration of Repair	: 8.00
Inspection At	AUTOLUTION INDUSTRIAL PTE LTD (UBI) 19 UBI ROAD 4 SINGAPORE 408623		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,440.86
Revised Amount	:S\$	11,945.84
Check Items (Estimated)	:S\$	4,433.42
Total	:S\$	16,379.26
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.99
COE / PARF Rebate	:S\$	56,209.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,791.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6182A
Vehicle Details	
Vehicle No.:	SLD1338G
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	MR20860066B
Chassis No.:	JN1JANT32Z0001849
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$22,509.00
Original Registration Date:	18 May 2016
First Registration Date:	18 May 2016
Transfer Count:	0
Actual ARF Paid:	\$23,513.00 11756
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 May 2026
PARF Rebate Amount:	\$17,634.00
Intended COE Rebate Details	
COE Expiry Date:	17 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,010.00
COE Rebate Amount:	\$38,575.00
Total Rebate Amount:	\$56,209.00

The information contained herein is correct as at 24 Oct 2018.

OK

Post FREE Ad to Sell Your Used Items!
Have preloved items cluttering around your house?
Sell it on Marketplace. Posting an advertisement is FREE!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

New 5 Years Cbe Renewal Toyota Altis 1.8i



\$2000 Downpayment Monthly
From \$568 (Unwaivable). Lowest
3.18% Pake Gv Cars Finance
GV Credit Pte Ltd. [View Ad](#)



Post an Ad Advertiser Login Ways of Selling

Browse by Category

Back (1 2) Next =

Sort by Date Posted 20 results/page

Advanced Search

23 vehicles

Nissan X-Trail

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan X-Trail	Any	Any	2016	Any	Any	Any	Available



Nissan X-Trail 2.0A Premium 7-Seater
5 Years Tan Chong Unlimited Mileage Warranty, Full Agent Servicing, Accident-Free, Ceramic Coated, 90% Loan And Trade In Available. Lowest Depreciation In The Market. Viewing By Appointment Only.

Posted: 24-Oct-2018 Tags: 2016 Nissan X-Trail, 2016 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan



Nissan X-Trail 2.0A Premium 7-Seater
Graded A by **STP**
Well Kept By 1 Carefully Owner! Fully Service And Maintained By Tan Chong Motor With Receipt To Proof. Call Us Now To Arrange An Appointment For Viewing.

Universe Motoring
Posted: 23-Oct-2018 Tags: 2016 Nissan X-Trail, 2016 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan



Nissan X-Trail 2.0A Premium 7-Seater
New Arrival! Most Valued Buy! Beautiful Red Unit With Pristine Condition! Peace Of Mind! Fully Serviced At Agent, Still Under 5 Years Warranty By Tan Chong. 100% Accident Free! Well Maintained Interior...

Posted: 22-Oct-2018 Tags: 2016 Nissan X-Trail, 2016 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan



Nissan X-Trail 2.0A 7-Seater
7 Seater SUV, Service By Tan Chong Motor, Tan Chong Motor Warranty, Beautiful Interior, Condition Almost New! Flexible Bank/In House Loan Available, Subject To Approval! Buy With A Peace Of Mind. Trad...

AL Autocar Pte Ltd
Posted: 21-Oct-2018 Tags: 2016 Nissan X-Trail, 2016 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan



Lee Sheng Auto Pte Ltd - Spray Painting
Lee Sheng Motor Works is a one-stop repair centre offering vehicle servicing, repairs, accident claims and spray painting.
[More info about this shop](#)



Nissan X-Trail 2.0A Premium 7-Seater
Come With Agent Warranty Till 2021. Full Agent Maintained From Day 1. 100% Accident Free. No Repairs Needed. Bank/In Loan With Flexible Financing Up To 90%. All Trade In Are Welcomed. Can View Anytime...

Posted: 20-Oct-2018 Tags: 2016 Nissan X-Trail, 2016 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan



Nissan X-Trail 2.0A Premium 7-Seater
1 Owner With Very Low Mileage, Servicing And Maintenance By Agent With 5 Years Warranty, Interest Rate At 1.98% With High Loan Quantum, Showroom Condition, Do Not Miss! Call Us Now!

Posted: 20-Oct-2018 Tags: 2016 Nissan X-Trail, 2016 nissan x-trail, Nissan X-Trail, nissan x-trail, Nissan, X-Trail, x-trail, Used Nissan

Compare

isan X-Trail 2.0A Premium	\$89,800	\$10,120 /yr	08-Jul-2016	1,997 cc	18,354 km	SUV	Available
---------------------------	----------	--------------	-------------	----------	-----------	-----	-----------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/10/2018 11:23
Date Of Accident	22/10/2018 08:50
Exact Location Of Accident	SLIP ROAD OF CTE TOWARDS PIE (CHANGI) AFTER ERP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD1338G
Insured/Policyholder	
Name Of Registered Owner	YAP YEE FARN (YE YIFAN)
NRIC No	S7716182A
Email Address	ALEX_YAP@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-92778183
Alternative Phone No	OTHERS-91881589

Vehicle Particulars

Manufacturer	NISSAN
Model	X-TRAIL-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3044541802
Cover Note Number	

Driver

Name of Driver	LIU WEITING
NRIC No	S8416413E
Date Of Birth	16/06/1984
Occupation	INDOOR
Date Of Driving Pass	21/05/2005
Driving Experience	13 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91881589
Fax Number	
Contact Number	
Email Address	WEITINGLIU16@GMAIL.COM

Address	82 PUNGGOL CENTRAL #09-05
Postcode	828763
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : YAP YEE FARN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA3367A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TOH CHIN TAT
NRIC/Passport Number	S7642012B
Contact Number	88222218
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB4186E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	ROHINI BIN AMIN
NRIC/Passport Number	S0063119A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLR2827G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KWA SIONG HOCK
NRIC/Passport Number	S1574802H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

22/10/16

11:50am

Driver's Signature
(If driver is not the policyholder)


Date & Time: 22/10/16

11:45am

Reporting Centre Personnel's Signature

Name: Aishah

NRIC/FIN No.: S1660822/2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

was entering into the slip road (ERP Gantry) where the traffic was clear & not congested. suddenly, the car in front stopped (SLA 3367A) and as the car is very tall, it's hard to access what ^{and why they stop down, and} caused the sudden stop, hence, had to do an emergency ~~e-brake~~ e-brake and still couldn't stop totally in time to prevent the collision.

A few minutes (12 mins or so), 2 bicycle cars appeared and 4 men came to access the accident and offered repair support etc - managed to snap a picture of their vehicle (CKK 77474).

Did a safety check with all passengers in the affected cars and no one required medical support and are well.

DECLARATION


I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 22/10/2018

11:40 AM



Driver's Signature

(If driver is not the policyholder)

Date & Time: 22/10/2018

11:40 AM



Reporting Centre Personnel's Signature

Name: Aishah

NRIC/FIN No: 2166082210

ACCIDENT INVESTIGATION P.L.C.
10 LAM ROAD #4
SINGAPORE 408023
Tel: 6733 9999 Fax: 6733 9999

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0619/18

DATE : 22-OCT-2018

CHINA TAIPIING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

S(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME : MR. YAP YEE FARN (YE YIFAN)

ADDRESS : 58 LENTOR TERRACE

S(788953)

TELEPHONE NO : 92778183

TYPE OF CLAIM : 00 OR 00 RECOVERY CLAIM

POLICY NO : DMPCSN3044541802

VEHICLE NO : SL01338G

MODEL CODE : J0RNRRZT32EWA-----

MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4x4

ENGINE NO : MR20860066B

CHASSIS NO : JN1JANT3220001849

MILEAGE : 54613 KM

DATE IN : 22/10/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 22/10/2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408523
TEL 6490 9666 FAX 6846 7483

Not Authorized
LKK

Excess \$1100

Pay.

24/10/18

Take photos before repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SL013386

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR BOTH FRT HOODLEDGE, R/F DOOR, RENEW L/F FENDER, R/F FENDER, FRONT BUMPER.	1800.00	1260
2	ZZ/002	RADIATOR SUPPORT AND BONNET.		1500
3	ZZ/003	CHARGES TO SPRAY PAINTING SAME.	1700.00	
4	ZZ/004	REMOVE AND INSTALL FRONT BUMPER TO RENEW SENSOR.	95.00	✓
5	ZZ/005	RENEW A/COND CONDENSER, VACUUM AND REFILL FREON GAS.	120.00	✓
6	ZZ/006	RENEW DAMAGED HEADLAMP AND FOCUS.	48.00	✓
7	ZZ/007	APPLY SEALANT TO BONNET.	100.00	✓
8	ZZ/008	PERFORM RUST PROOFING TO RADIATOR SUPPORT.	120.00	✓
9	ZZ/009	RENEW A/TRANSMISSION OIL COOLER.	180.00	X
10	ZZ/011	PERFORM CONSULT TEST AND RE-SET CRASH ZONE SENSOR.	180.00	2
11	ZZ/10	SUPPLY FRONT LICENCE PLATE.		
TOTAL LABOUR CHARGES			4303.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLD1338G

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	SUNRISES	NPN		1.1	70.00 X
2	FRT LICENCE PLATE	FLP		3rd	60.00 —
3	WIPER WASHER TANK	28910-4CC0A		Torn/De	201.90 X
4	A/COND CONDENSER	92100-5H00A		3rd/par	743.20 —
5	SENSOR-CRASH	KB581-3R00A		1.3	603.30 X
6	HORN ASSY	25610-4CC0A		1.3	89.60 X
7	A/TRANSMISSION OIL COOLER	21606-4B00A		1.3	240.00 X
8	RADIATOR FAN MOTOR	21481-4CE0A		1.3	1008.60 X
9	RADIATOR LOWER MNTG GUIDE	21579-48B1A		1.3	94.50 X
10	RADIATOR TOP MNTG GUIDE	21542-4CE0A		1.3	81.00 X
11	CLIP AIR GUIDE @ \$1.20 EACH	01553-05933	9.60	2	
12	GUIDE-AIR LH	21559-48B0A		De/cond	40.50 —
13	GUIDE-AIR RH	21558-48B0A		De/cond	40.50 —
14	RADIATOR ASSY	21410-48B0A		3rd/par	687.40 X
15	DUCT ASSY-AIR CLEANER	16554-48B00	66.00	De	
16	DUCT-AIR	16554-48B0A		Torn	104.80 X
17	HEADLAMP LH	26060-4CA5D	2352.00		holder cre —
18	HEADLAMP RH	26010-4CA5D	2352.00		holder cre —
19	HEADLAMP PANEL LH	64191-4CB0A	129.90	X	—
20	HEADLAMP PANEL RH	64190-4CB0A	129.90	X	—
21	BONNET LOCK	65601-4CE1C	93.20		—
22	BONNET HINGE LH	65401-4CL0A	41.80		3rd —
23	BONNET HINGE RH	65400-4CL0A	41.80		3rd —
24	BONNET	F310N-4COMA	901.90		3rd —
25	L/F FENDER ARC MOLD	63861-4CE0A	170.00	X	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLD133BG

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	R/F FENDER ARC MLDG	63860-4CE0A	170.00	X	
27	FENDER-FRONT LH	F3101-4C0MA	583.40	—	
28	FENDER-FRONT RH	F3100-4C0MA	583.40	—	
29	STAY-HOOD LOCK	62550-4CB0A	93.70	—	
30	RADIATOR SUPPORT TOP LH	62513-4CB0A	45.20	X	
31	RADIATOR SUPPORT TOP RH	62512-4CB0B	45.20	X	
32	RADIATOR SUPPORT TOP CENTRE	62511-4CE0A	233.60	—	
33	EMBLEM RAD GRILLE	62890-4B00A	59.70	—	
34	CLIP RADIATOR GRILLE @ \$1.20 EACH	01553-10501	7.20	—	
35	GRILLE-RADIATOR	62310-4CE1B	390.30	—	
36	FOG LAMP LH	26155-8994A		17	321.60 X
37	FOG LAMP RH	26150-8994A		17	321.60 X
38	FOG LAMP GARNISH LH	62257-4B00B	80.90	X	
39	FOG LAMP GARNISH RH	62256-4B00B	80.90	—	
40	FRT BUMPER STAY LH	62211-4C10A	86.60	—	
41	FRT BUMPER STAY RH	62210-4C11A	86.60	—	
42	FRT BUMPER REINFORCEMENT	62030-4C10A	453.10	—	
43	ENERGY ABSORBER FRT BUMPER	62090-4CE0A	291.60	—	
44	FRONT BUMPER LOWER CHROME MLDG	62072-4B00A	153.10	X	
45	FRONT BUMPER LOWER GRILLE	62254-4CE0A	199.50	X	
46	FRT BUMPER TOW HOOK COVER	62240-4C10A	20.30	—	
47	FRT BUMPER SIDE BRKT LH	62223-4C10A	20.90	—	
48	FRT BUMPER SIDE BRKT RH	62222-4C10A	20.90	—	
49	CLIP FRT BUMPER @ \$1.30 EACH	01553-09321	7.80	—	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL01338G

DAMAGED PARTS & PRICES					
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
50	FRONT BUMPER FASCIA	62022-4CE0H	534.70		
SUB TOTAL			10536.70	0.00	4708.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-1.00%)			2107.34	0.00	0.00
GRAND TOTAL			8429.36	0.00	4708.50
OVERALL TOTAL			13137.86		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLD1338G

TOTAL LABOUR CHARGES	4303.00
TOTAL SPARE PARTS CHARGES	13137.86
GRAND TOTAL	17440.86 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Marcus

AUTOLUTION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0619/18
DATE : 22-OCT-2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 5490 9666 FAX: 6846 7483

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR YAP YEE FAN (YE YIFAN)
ADDRESS : 5B LENTOR TERRACE
TELEPHONE NO : 51789531
: 92778183

8 days

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : DP/CSH0044541802
VEHICLE NO : SLD13386
MODEL CODE : JDMRRT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4x4
ENGINE NO : HX20B600668
CHASSIS NO : JH1JAMT3220001849
MILEAGE : 54613 KM
DATE IN : 22/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 1100.00
ESTIMATE BY : HANZAH - 96450079
ACCIDENT DATE : 22/10/2018

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLD13386

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR BOTH FRT HOODLEDGE, R/F DOOR, RENEW L/F FENDER, R/F FENDER, FRONT BUMPER,	1800.00	1260.00
2	ZZ/002	RADIATOR SUPPORT AND BRACKET.		
3	ZZ/003	CHARGES TO SPRAY PAINTING SAME.	1700.00	1500.00
4	ZZ/004	REMOVE AND INSTALL FRONT BUMPER TO RENEW SENSOR.	55.00	55.00
5	ZZ/005	RENEW A/C COND CONDENSER, VACUUM AND REFILL FREON GAS.	120.00	120.00
6	ZZ/006	RENEW DAMAGED HEADLAMP AND FOCUS.	48.00	48.00
7	ZZ/007	APPLY SEALANT TO BODINET.	100.00	100.00
8	ZZ/008	PERFORM RUST PROOFING TO RADIATOR SUPPORT.	120.00	120.00
9	ZZ/009	RENEW A/TRANSMISSION OIL COOLER.	180.00	.00
10	ZZ/011	PERFORM CONSULT TEST AND RE-SET CRASH ZONE SENSOR.	180.00	.00
11	ZZ/10	SUPPLY FRONT LICENCE PLATE.		
TOTAL LABOUR CHARGES			4303.00	3203.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLO133BG

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES	HPH			70.00 X
2	FRT LICENCE PLATE	FLP			60.00 OK
3	WIPER WASHER TANK	28910-4CC0A			201.90 OK
4	A/CORD CONDENSER	92100-5MA0A			743.20 OK
5	SENSOR-CRASH	8B581-3RA0A			603.30 X
6	HORN ASSY	25610-4CC0A			89.00 X
7	A/TRANSMISSION OIL COOLER	21606-4BA0A			240.00 X
8	RADIATOR FAN MOTOR	21481-4C10A			1008.60 X
9	RADIATOR LOWER MNTG GUIDE	21579-4BB1A			94.50 X
10	RADIATOR TOP MNTG GUIDE	21542-4CE0A			61.00 X
11	CLIP AIR GUIDE @ \$1.20 EACH	01553-05933	9.60		X
12	GUIDE-AIR LH	21559-4BB0A			40.50 OK
13	GUIDE-AIR RH	21558-4BB0A			40.50 OK
14	RADIATOR ASSY	21410-4BB0A			687.40 OK
15	DUCT ASSY-AIR CLEANER	16564-4BB0D	66.00		OK
16	DUCT-AIR	16564-4BB0A			104.80 OK
17	HEADLAMP LH	26060-4CA5D	2352.00		OK
18	HEADLAMP RH	26010-4CA5D	2352.00		OK
19	HEADLAMP PANEL LH	64191-4CB0A	129.90		X
20	HEADLAMP PANEL RH	64190-4CB0A	129.90		X
21	BOINET LOCK	65601-4C11C	93.20		OK
22	BOINET HINGE LH	65401-4CL0A	41.80		OK
23	BOINET HINGE RH	65400-4CL0A	41.80		OK
24	BOINET	F510H-4CC0A	901.90		OK
25	L/F FENDER ARC MOLD	63861-4CE0A	170.00		X

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL01336G

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	R/F FENDER ARC MLOG	63860-4CE0A	170.00		X
27	FENDER-FRONT LH	F3101-4CCYA	583.40		OK
28	FENDER-FRONT RH	F3100-4CCYA	583.40		OK
29	STAY-HOOD LOCK	62550-4CB0A	93.70		OK
30	RADIATOR SUPPORT TOP LH	62513-4CB0A	45.20		X
31	RADIATOR SUPPORT TOP RH	62512-4CB0B	45.20		X
32	RADIATOR SUPPORT TOP CENTRE	62511-4CE0A	233.60		OK
33	EMBLEM RAD GRILLE	62890-4BA0A	59.70		OK
34	CLIP RADIATOR GRILLE @ \$1.20 EACH	01553-10501	7.20		OK
35	GRILLE-RADIATOR	62310-4CE1B	390.30		OK
36	FOG LAMP LH	26155-8994A		321.60	X
37	FOG LAMP RH	26150-8994A		321.60	X
38	FOG LAMP GARNISH LH	62257-4BA0B	80.90		X
39	FOG LAMP GARNISH RH	62256-4BA0B	80.90		OK
40	FRT BUMPER STAY LH	62211-4CL0A	86.60		OK
41	FRT BUMPER STAY RH	62210-4CL1A	86.60		OK
42	FRT BUMPER REINFORCEMENT	62030-4CL0A	453.10		OK
43	ENERGY ABSORBER FRT BUMPER	62090-4CE0A	291.60		OK
44	FRONT BUMPER LOWER CHROME MLOG	62072-4BA0A	153.10		OK
45	FRONT BUMPER LOWER GRILLE	62254-4CE0A	199.50		OK
46	FRT BUMPER TOW HOOK COVER	62240-4CL0A	20.30		OK
47	FRT BUMPER SIDE BRKT LH	62221-4CL0A	20.90		OK
48	FRT BUMPER SIDE BRKT RH	62222-4CL0A	20.90		OK
49	CLIP FRT BUMPER @ \$1.30 EACH	01553-09321	7.80		OK

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLD1338G

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
50	FRONT BUMPER FASCIA	62022-4CEGH	534.70		OK
SUB TOTAL			9756.00	0.00	1878.30
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-1.00%)			1951.20	0.00	0.00
GRAND TOTAL			7804.80	0.00	1878.30
OVERALL TOTAL			9683.10		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGH NO SL01338G

NETT ITEM	9756.00
LESS 20.00%	-1951.20
NETT AMOUNT	7804.80
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	1078.30
LESS .00%	0.00
SPECIAL NETT AMOUNT	1078.30
TOTAL LABOUR CHARGES	3203.00
TOTAL SPARE PARTS CHARGES	9683.10
TOTAL CHARGES	12886.10
LESS EXCESS	1100.00
TOTAL	11786.10
ADD 7 % GST	825.03
GRAND TOTAL	12611.13

Veron Chen (LKKAUTO)

From: Hamzah <hamzah_saad@tanchong.com>
Sent: Saturday, 17 November 2018 12:53 PM
To: Marcus Chua (LKKAUTO)
Cc: SUR; Veron Chen (LKKAUTO)
Subject: Re: SLD 1338G-DOA: 22/10/18 (CHINA TAIPING OD)
Attachments: sld1338g-finalise 221018.pdf

Bro,

Attachment final repair copy.

Kindly revert for invoicing.

Regards

Hamzah Sa'ad
Service Supervisor
Autolution Industrial Pte Ltd
19 Ubi Road 4
S408623
TEL: +65 67038680 DID: +65 67038690 FAX: +65 68467483
Hp: +65 96450079 Email: hamzah_saad@tanchong.com

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Thursday, October 25, 2018 3:44:49 PM
To: Hamzah; SUR
Subject: SLD 1338G-DOA: 22/10/18 (CHINA TAIPING OD)

Dear Hamzah,

As instructed by our client , please proceed to repair the **insured vehicle SLD 1338G based on surveyor's marking or which ever lower (Excess S1100/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2018		23 Oct 2018 16:24 Edit Adj Rpt	S\$12,886.10 Edit Estimates	S\$12,886.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: YAP YEE FARN (YE YIFAN) , ID: 57716182A									
Vehicle Reg. No.: SLD1338G		Date of Loss: 22/10/2018 08:00 - :59 [29 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D05006		Policy/Cover Note No.: DMPCSN3044541802 (Comprehensive)							
		Excess: S\$1,100.00							
Repairer: Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 01/11/2018]									
Driver/Custodian: LIU WEITING (34 / Female), NRIC: S8416413E, Tel: +6591881589									
Adj Asg. Remarks: REVERT.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPIING (25/10/2018): Alert - Adj Mandate Approved (S\$16379.26) - SLD1338G - Claim Handler: Elaine Che...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD1338G (SNM18D05006)

OD

Oct 22 2018 8:00AM

[YAP YEE FARN (YE YIFAN)]

Autolution Industrial Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)						Thumbnail	Print	
1	22/10/18 18:21	Accident Statement					1	Load HTM		
2	23/10/18 14:49	Addendum Sheet					2	Load TIF		
3	23/10/18 14:50	Accident Statement Addm. #1					3	Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	24/10/18 16:41	Adjuster Immediate Advice					4	Load HTM		
Photos/Images							3 per page		☒	
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)						Thumbnail	Print	
1	22/10/18 13:12	Accident Photo [Linked Accident Report Documents]					1	Load JPG	☒	
2	22/10/18 13:12	Accident Photo [Linked Accident Report Documents]					2	Load JPG	☒	
3	22/10/18 13:12	Accident Photo [Linked Accident Report Documents]					3	Load JPG	☒	
4	22/10/18 13:12	Accident Photo [Linked Accident Report Documents]					4	Load JPG	☒	
5	22/10/18 13:12	Accident Photo [Linked Accident Report Documents]					5	Load JPG	☒	
6	22/10/18 13:12	Accident Photo [Linked Accident Report Documents]					6	Load JPG	☒	
7	22/10/18 13:12	Accident Photo [Linked Accident Report Documents]					7	Load JPG	☒	
8	22/10/18 13:12	Accident Photo [Linked Accident Report Documents]					8	Load JPG	☒	
9	22/10/18 13:13	Accident Photo [Linked Accident Report Documents]					9	Load JPG	☒	
10	22/10/18 13:13	Accident Photo [Linked Accident Report Documents]					10	Load JPG	☒	
11	22/10/18 13:13	Accident Photo [Linked Accident Report Documents]					11	Load JPG	☒	
12	22/10/18 13:13	Accident Photo [Linked Accident Report Documents]					12	Load JPG	☒	
13	22/10/18 13:13	Accident Photo [Linked Accident Report Documents]					13	Load JPG	☒	
14	22/10/18 13:13	Accident Photo [Linked Accident Report Documents]					14	Load JPG	☒	
15	22/10/18 13:13	Accident Photo [Linked Accident Report Documents]					15	Load JPG	☒	
16	22/10/18 13:13	Accident Photo [Linked Accident Report Documents]					16	Load JPG	☒	
17	22/10/18 13:14	Accident Photo [Linked Accident Report Documents]					17	Load JPG	☒	
18	22/10/18 13:14	Accident Photo [Linked Accident Report Documents]					18	Load JPG	☒	
19	22/10/18 13:14	Accident Photo [Linked Accident Report Documents]					19	Load JPG	☒	
20	22/10/18 18:19	Accident Photo [Linked Accident Report Documents]					20	Load JPG	☒	
21	22/10/18 18:19	Accident Photo [Linked Accident Report Documents]					21	Load JPG	☒	
22	22/10/18 18:19	Accident Photo [Linked Accident Report Documents]					22	Load JPG	☒	
23	22/10/18 18:19	Accident Photo [Linked Accident Report Documents]					23	Load JPG	☒	
24	22/10/18 18:19	Accident Photo					24	Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
		[Linked Accident Report Documents]		
25	22/10/18 18:19	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
26	22/10/18 18:19	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
27	22/10/18 18:19	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
28	22/10/18 18:19	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/10/18 15:07	Chassis Number	 Load JPG	☒
2	24/10/18 16:07	Odometer Reading	 Load JPG	☒
3	24/10/18 16:07	General View	 Load JPG	☒
4	24/10/18 16:07	General View	 Load JPG	☒
5	24/10/18 16:07	General View	 Load JPG	☒
6	24/10/18 16:07	General View	 Load JPG	☒
7	24/10/18 16:07	General View	 Load JPG	☒
8	24/10/18 16:07	General View	 Load JPG	☒
9	24/10/18 16:07	General View	 Load JPG	☒
10	24/10/18 16:07	General View	 Load JPG	☒
11	24/10/18 16:07	General View	 Load JPG	☒
12	24/10/18 16:07	General View	 Load JPG	☒
13	24/10/18 16:07	General View	 Load JPG	☒
14	24/10/18 16:07	General View	 Load JPG	☒
15	24/10/18 16:07	General View	 Load JPG	☒
16	24/10/18 16:07	General View	 Load JPG	☒
17	24/10/18 16:07	General View	 Load JPG	☒
18	24/10/18 16:07	General View	 Load JPG	☒
19	24/10/18 16:07	General View	 Load JPG	☒
20	24/10/18 16:07	General View	 Load JPG	☒
21	24/10/18 16:07	General View	 Load JPG	☒
22	24/10/18 16:07	General View	 Load JPG	☒
23	24/10/18 16:07	General View	 Load JPG	☒
24	24/10/18 16:07	General View	 Load JPG	☒
25	24/10/18 16:07	General View	 Load JPG	☒
26	24/10/18 16:07	General View	 Load JPG	☒
27	24/10/18 16:07	General View	 Load JPG	☒
28	24/10/18 16:07	General View	 Load JPG	☒
29	24/10/18 16:07	General View	 Load JPG	☒
30	24/10/18 16:07	General View	 Load JPG	☒
31	24/10/18 16:07	General View	 Load JPG	☒
32	24/10/18 16:07	General View	 Load JPG	☒
33	24/10/18 16:07	General View	 Load JPG	☒
34	24/10/18 16:07	General View	 Load JPG	☒
35	24/10/18 16:07	General View	 Load JPG	☒
36	24/10/18 16:07	General View	 Load JPG	☒
37	24/10/18 16:07	General View	 Load JPG	☒
38	24/10/18 16:07	General View	 Load JPG	☒
39	24/10/18 16:07	General View	 Load JPG	☒
40	24/10/18 16:07	General View	 Load JPG	☒
41	24/10/18 16:07	General View	 Load JPG	☒
42	24/10/18 16:07	General View	Load JPG	☒
43	24/10/18 16:07	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
44	24/10/18 16:07	General View	 Load JPG	☒
45	24/10/18 16:07	General View	 Load JPG	☒
46	24/10/18 16:07	General View	 Load JPG	☒
47	24/10/18 16:07	General View	 Load JPG	☒
48	24/10/18 16:07	General View	 Load JPG	☒
49	24/10/18 16:07	General View	 Load JPG	☒
50	24/10/18 16:07	General View	 Load JPG	☒
51	24/10/18 16:07	General View	 Load JPG	☒
52	24/10/18 16:07	General View	 Load JPG	☒
53	24/10/18 16:07	General View	 Load JPG	☒
54	24/10/18 16:07	General View	 Load JPG	☒
55	24/10/18 16:07	General View	 Load JPG	☒
56	24/10/18 16:07	General View	 Load JPG	☒
57	24/10/18 16:07	General View	 Load JPG	☒
58	24/10/18 16:07	General View	 Load JPG	☒
59	24/10/18 16:07	General View	 Load JPG	☒
60	24/10/18 16:07	General View	 Load JPG	☒
61	24/10/18 16:07	General View	 Load JPG	☒
62	24/10/18 16:07	General View	 Load JPG	☒
63	24/10/18 16:07	General View	 Load JPG	☒
64	24/10/18 16:07	General View	 Load JPG	☒
65	24/10/18 16:07	General View	 Load JPG	☒
66	24/10/18 16:07	General View	 Load JPG	☒
67	24/10/18 16:07	General View	 Load JPG	☒
68	24/10/18 16:07	General View	 Load JPG	☒
69	24/10/18 16:07	General View	 Load JPG	☒
70	24/10/18 16:07	General View	 Load JPG	☒
71	24/10/18 16:07	General View	 Load JPG	☒
72	24/10/18 16:07	General View	 Load JPG	☒
73	24/10/18 16:07	General View	 Load JPG	☒
74	24/10/18 16:07	General View	 Load JPG	☒
75	24/10/18 16:07	General View	 Load JPG	☒
76	24/10/18 16:07	General View	 Load JPG	☒
77	24/10/18 16:07	General View	 Load JPG	☒
78	24/10/18 16:07	General View	 Load JPG	☒
79	24/10/18 16:07	General View	 Load JPG	☒
80	24/10/18 16:07	General View	 Load JPG	☒
81	24/10/18 16:07	General View	 Load JPG	☒
82	24/10/18 16:07	General View	 Load JPG	☒
83	24/10/18 16:07	General View	 Load JPG	☒
84	24/10/18 16:07	General View	 Load JPG	☒
85	24/10/18 16:07	General View	 Load JPG	☒
86	24/10/18 16:07	General View	 Load JPG	☒
87	24/10/18 16:07	General View	 Load JPG	☒
88	24/10/18 16:07	General View	 Load JPG	☒
89	24/10/18 16:07	General View	 Load JPG	☒
90	24/10/18 16:07	General View	 Load JPG	☒
91	24/10/18 16:07	General View	 Load JPG	☒
92	24/10/18 16:07	General View	 Load JPG	☒
93	24/10/18 16:07	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
94	24/10/18 16:07	General View	 Load JPG	☒
95	24/10/18 16:07	General View	 Load JPG	☒
96	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
97	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
98	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
99	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
100	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
101	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
102	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
103	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
104	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
105	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
106	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
107	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
108	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
109	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
110	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
111	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
112	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
113	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
114	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
115	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
116	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
117	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
118	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
119	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
120	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
121	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
122	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
123	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
124	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
125	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
126	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
127	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
128	30/10/18 17:44	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/10/18 16:23	EST	 Load PDF	
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	22/10/18 14:38	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	22/10/18 14:38	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	22/10/18 14:41	IC [Linked Accident Report Documents]	 Load TIF	
4	22/10/18 14:41	IC [Linked Accident Report Documents]	 Load TIF	
5	22/10/18 14:41	CI [Linked Accident Report Documents]	 Load TIF	
6	22/10/18 18:18	IC-INSURED [Linked Accident Report Documents]	 Load TIF	
7	22/10/18 18:18	D.L-DRIVER [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 10:48	MARK ESTIMATE	 Load PDF	

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubl)	Thumbnail	Print	
1	22/10/18 18:21	Accident Statement	 Load HTM		
2	23/10/18 14:49	Addendum Sheet	 Load TIF		
3	23/10/18 14:50	Accident Statement Addm. #1	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubl)	Thumbnail	Print	
1	22/10/18 13:12	Accident Photo	 Load JPG	☒	
2	22/10/18 13:12	Accident Photo	 Load JPG	☒	
3	22/10/18 13:12	Accident Photo	 Load JPG	☒	
4	22/10/18 13:12	Accident Photo	 Load JPG	☒	
5	22/10/18 13:12	Accident Photo	 Load JPG	☒	
6	22/10/18 13:12	Accident Photo	 Load JPG	☒	
7	22/10/18 13:12	Accident Photo	 Load JPG	☒	
8	22/10/18 13:12	Accident Photo	 Load JPG	☒	
9	22/10/18 13:13	Accident Photo	 Load JPG	☒	
10	22/10/18 13:13	Accident Photo	 Load JPG	☒	
11	22/10/18 13:13	Accident Photo	 Load JPG	☒	
12	22/10/18 13:13	Accident Photo	 Load JPG	☒	
13	22/10/18 13:13	Accident Photo	 Load JPG	☒	
14	22/10/18 13:13	Accident Photo	 Load JPG	☒	
15	22/10/18 13:13	Accident Photo	 Load JPG	☒	
16	22/10/18 13:13	Accident Photo	 Load JPG	☒	
17	22/10/18 13:14	Accident Photo	 Load JPG	☒	
18	22/10/18 13:14	Accident Photo	 Load JPG	☒	
19	22/10/18 13:14	Accident Photo	 Load JPG	☒	
20	22/10/18 18:19	Accident Photo	 Load JPG	☒	
21	22/10/18 18:19	Accident Photo	 Load JPG	☒	
22	22/10/18 18:19	Accident Photo	 Load JPG	☒	
23	22/10/18 18:19	Accident Photo	 Load JPG	☒	
24	22/10/18 18:19	Accident Photo	 Load JPG	☒	
25	22/10/18 18:19	Accident Photo	 Load JPG	☒	
26	22/10/18 18:19	Accident Photo	 Load JPG	☒	
27	22/10/18 18:19	Accident Photo	 Load JPG	☒	
28	22/10/18 18:19	Accident Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Autolution Industrial Pte Ltd (Ubl)	Thumbnail	Print	
1	22/10/18 14:38	Sketch Plan	 Load TIF		
2	22/10/18 14:38	Sketch Plan #2	 Load TIF		
3	22/10/18 14:41	IC	 Load TIF		
4	22/10/18 14:41	IC	 Load TIF		
5	22/10/18 14:41	CI	 Load TIF		
6	22/10/18 18:18	IC-INSURED	 Load TIF		
7	22/10/18 18:18	D.L-DRIVER	 Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)



Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118019313/USD3E2

Date: 30/11/2018

REFERENCE

Insured/Claimant: YAP YEE FARN (YE YIFAN) Policy No: DMPCSN3044541802
Date of Loss: 22/10/2018 Nature of Claim: OD Claim No: SNM18D05006

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD1338G**
Make & Model: NISSAN X-TRAIL, 2.0 (A) Engine No: MR20860066B
Reg. Date: 18/05/2016 (Man. Year: 2016) Chassis No: JN1JANT32Z0001849
Colour: Brown Odometer: 54613 km
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$85,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,137.86	9,683.10	3,454.76	26.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,303.00	3,203.00	1,100.00	25.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,440.86	12,886.10	4,554.76	26.12
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	16,340.86	11,786.10	4,554.76	27.87
+ GST 7.00/7.00% (S\$)	1,143.86	825.03	318.83	27.87
Nett Amount (S\$)	17,484.72	12,611.13	4,873.59	27.87

INSPECTION

Date of Assignment: 23/10/2018
Date Inspected: 24/10/2018 Inspected At: Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623
Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2018)
Parts:	M1-MPV	NISSAN X-TRAIL 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1338G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	8		*CLIP AIR GUIDE	Not Necessary	9.60 FN	*- FN
2	1		*DUST ASSY-AIR CLEANER	Torn	66.00 FN	*66.00 FN
3	1		*HEADLAMP LH	Holder Cracked	2,352.00 FN	*2,352.00 FN
4	1		*HEADLAMP RH	Holder Cracked	2,352.00 FN	*2,352.00 FN
5	1		*HEADLAMP PANEL LH	Repair	129.90 FN	*- FN
6	1		*HEADLAMP PANEL RH	Repair	129.90 FN	*- FN
7	1		*BONNET LOCK	Twisted	93.20 FN	*93.20 FN
8	1		*BONNET HINGE LH	Bent	41.80 FN	*41.80 FN
9	1		*BONNET HINGE RH	Bent	41.80 FN	*41.80 FN
10	1		*BONNET	Buckled	901.90 FN	*901.90 FN
11	1		*L/F FENDER ARC MLDG	Not Necessary	170.00 FN	*- FN
12	1		*R/F FENDER ARC MLDG	Not Necessary	170.00 FN	*- FN
13	1		*FENDER-FRONT LH	Buckled	583.40 FN	*583.40 FN
14	1		*FENDER-FRONT RH	Buckled	583.40 FN	*583.40 FN
15	1		*STAY-HOOD LOCK	Twisted	93.70 FN	*93.70 FN
16	1		*RADIATOR SUPPORT TOP LH	Not Necessary	45.20 FN	*- FN
17	1		*RADIATOR SUPPORT TOP RH	Not Necessary	45.20 FN	*- FN
18	1		*RADIATOR SUPPORT TOP CENTRE	Bent	233.60 FN	*233.60 FN
19	1		*EMBLEM RAD GRILLE	Cracked	59.70 FN	*59.70 FN
20	6		*CLIP RADIATOR GRILLE	Necessary	7.20 FN	*7.20 FN
21	1		*GRILLE-RADIATOR	Cracked	390.30 FN	*390.30 FN
22	1		*FOG LAMP GARNISH LH	Not Necessary	80.90 FN	*- FN
23	1		*FOG LAMP GARNISH RH	Cut	80.90 FN	*80.90 FN
24	1		*FRT BUMPER STAY LH	Bent	86.60 FN	*86.60 FN
25	1		*FRT BUMPER STAY RH	Bent	86.60 FN	*86.60 FN
26	1		*FRT BUMPER REINFORCEMENT	Bent	453.10 FN	*453.10 FN
27	1		*ENERGY ABSORBER FRT BUMPER	Torn	291.60 FN	*291.60 FN
28	1		*FRONT BUMPER LOWER CHROME MLDG	Scratched	153.10 FN	*153.10 FN
29	1		*FRONT BUMPER LOWER GRILLE	Torn	199.50 FN	*199.50 FN
30	1		*FRT BUMPER TOW HOOK COVER	Twisted	20.30 FN	*20.30 FN
31	1		*FRT BUMPER SIDE BRKT LH	Bent	20.90 FN	*20.90 FN
32	1		*FRT BUMPER SIDE BRKT RH	Bent	20.90 FN	*20.90 FN
33	6		*CLIP FRT BUMPER	Necessary	7.80 FN	*7.80 FN
34	1		*FRONT BUMPER FASCIA	Distorted	534.70 FN	*534.70 FN
35	1		*SUNDRIES	Not Necessary	70.00 FS	*- FS
36	1		*FRT LICENCE PLATE	Bent	60.00 FS	*60.00 FS
37	1		*WIPER WASHER TANK	Torn / Deformed	201.90 FS	*201.90 FS
38	1		*A/COND CONDENSER	Bent / Punctured	743.20 FS	*743.20 FS
39	1		*SENSOR-CRASH	Not Necessary	603.30 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*HORN ASSY	Not Necessary	89.60 FS	*- FS
41	1		*A/TRANSMISSION OIL COOLER	Not Necessary	240.00 FS	*- FS
42	1		*RADIATOR FAN MOTOR	Not Necessary	1,008.60 FS	*- FS
43	1		*RADIATOR LOWER MNTG GUIDE	Not Necessary	94.50 FS	*- FS
44	1		*RADIATOR TOP MNTG GUIDE	Not Necessary	81.00 FS	*- FS
45	1		*GUIDE-AIR LH	Deformed / Twisted	40.50 FS	*40.50 FS
46	1		*GUIDE-AIR RH	Deformed / Twisted	40.50 FS	*40.50 FS
47	1		*RADIATOR ASSY	Bent / Punctured	687.40 FS	*687.40 FS
48	1		*DUCT-AIR	Torn	104.80 FS	*104.80 FS
49	1		*FOG LAMP LH	Not Necessary	321.60 FS	*- FS
50	1		*FOG LAMP RH	Not Necessary	321.60 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	15,245.20	11,634.30
- Nett Item Discount on N Items 20.00/20.00% (S\$)	2,107.34	1,951.20
Total Parts (S\$)	13,137.86	9,683.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHARGES TO SPRAY PAINTING SAME	New	1,700.00	1,500.00
2	REMOVE AND INSTALL FRONT BUMPER TO RENEW SENSOR	New	55.00	55.00
3	RENEW A/COND CONDENSER, VACUUM AND REFILL FREON GAS	New	120.00	120.00
4	RENEW DAMAGED HEADLAMP AND FOCUS	New	48.00	48.00
5	APPLY SEALANT TO BONNET	New	100.00	100.00
6	PERFORM RUST PROOFING TO RADIATOR SUPPORT	New	120.00	120.00
7	RENEW A/TRANSMISSION OIL COOLER	New	180.00	0.00
8	PERFORM CONSULT TEST AND RE-SET CRASH ZONE SENSOR	New	180.00	0.00
9	LABOUR CHARGES TO REPAIR BOTH FRT HOODLEDGE, R/F DOOR, RENEW L/F FENDER, R/F FENDER, FRONT BUMPER	New	1,800.00	1,260.00
Gross Labour Cost (S\$)			4,303.00	3,203.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >