

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z**AAD1810-230***Not Authorize
Resony B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 957Z

VF1ABL15AUC283400

RENAULT

LATITUDE

20.10.18

III**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bt/crt</i> 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>mis</i> 181.75	✓
3	1	BUMPER ABSORBER FRT	\$	<i>Bro</i> 394.68	✓
4	1	BUMPER RETAINER FRT LH	\$	<i>D.r</i> 151.41	✓
5	1	BUMPER SUPPORT FRT	\$	<i>CM</i> 123.88	✓
6	1	BUMPER RETAINER FRT RH	\$	<i>D.r</i> 150.77	✓
7	1	BUMPER SUPPORT FRT	\$	<i>CM</i> 123.88	✓
8	1	BUMPER UNDERTRAY FRT	\$	<i>CM</i> 472.83	✓
9	1	BUMPER GRILLE LOWER FRT	\$	<i>CM</i> 266.80	✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>mir</i> 207.21	✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>su</i> 207.21	X
12	1	BUMPER BEAM FRT	\$	<i>Bt</i> 914.08	✓
13	1	TOW COVER FRT	\$	<i>nd</i> 28.61	✓
14	1	RADIATOR GRILLE	\$	<i>Bro</i> 1,707.78	✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>ru</i> 225.36	✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75	✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90	✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>Bt</i> 89.79	✓
19	1	FRONT BRACE PANEL	\$	<i>Bt</i> 177.22	✓
20	1	HORN	\$	<i>su</i> 314.17	X
21	1	HORN BRACKET	\$	<i>RE</i> 40.45	X
22	1	HEADLAMP LH	\$	<i>my Bro</i> 1,184.43	✓
22	1	HEADLAMP HARNESS	\$	928.29	?
22	1	HEADLAMP RH	\$	<i>my Bro</i> 1,184.43	✓
22	1	HEADLAMP HARNESS	\$	928.29	?
22	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	X
25	1	HEADLAMP PANEL FRT RH	\$	<i>Bro</i> 152.15	✓
26	1	BONNET	\$	<i>Bt</i> 1,941.63	✓
27	1	BONNET INSULATOR	\$	<i>Reform</i> 405.73	✓
28	1	BONNET STRUT LH	\$	<i>su</i> 88.61	X

Trans-cab Auto Services Pte Ltd**AAD1810-230**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

29	1	BONNET STRUT RH	\$	PL	88.61	X
30	1	BONNET HINGE LH	\$	R	348.31	X
31	1	BONNET HINGE RH	\$	R	348.31	X
32	1	BONNET LOCK	\$	B	305.48	✓
33	1	BONNET CABLE	\$		119.19	?
34	1	BONNET CABLE COVER	\$		161.03	?
35	1	BONNET SEAL OUTER	\$	SL	92.36	X
36	1	BONNET SEAL INNER	\$	SL	157.28	X
37	1	FENDER PANEL FRT LH	\$	Bu	783.83	✓
38	1	FENDER PANEL FRT RH	\$	Bu	783.83	✓
39	1	WHEELARCH FRT LH	\$	CM	278.84	✓
40	1	WHEELARCH FRT RH	\$	CM	278.84	✓
41	1	FENDER BRACKET LOWER LH	\$	R	15.79	X
42	1	FENDER BRACKET LOWER RH	\$	R	15.79	X
43	1	FENDER INSULATOR LH	\$	SL	130.84	X
44	1	FENDER INSULATOR RH	\$	SL	130.84	X
45	1	WIPER RESERVOIR	\$	RU	348.25	✓
46	1	WIPER RESERVOIR NECK	\$		136.11	?
47	1	WIPER RESERVOIR MOTOR	\$	SL	270.06	X
48	1	AIR CLEANER LOWER	\$		271.26	?
49	1	AIR CLEANER HOSE	\$		76.14	?
55	1	ENGINE TOP COVER 2.0	\$	SL	555.12	X
56	1	ENGINE OIL SUMP	\$	SL	484.67	X
58	1	BASE BATTERY TRAY	\$	SL	363.40	X
59	1	AIR CLEANER BOX	\$		464.20	?
60	1	TURBO DUCT	\$		1,027.80	?
61	1	A/C HEATER VALVE	\$		484.50	?
63	1	SUBFRAME OUTER FRT	\$		2,652.45	?
64	1	SUBFRAME BRACKET OUTER LH	\$		92.36	?
65	1	SUBFRAME BRACKET OUTER RH	\$		92.36	?
66	1	ENGINE UNDERTRAY	\$	CM	564.98	✓
67	1	A/C CONDENSER	\$	R	2,020.37	✓
68	1	A/C CONDENSER GARNISH LH UPPER	\$		39.67	?
69	1	A/C CONDENSER GARNISH RH UPPER	\$		39.67	?
70	1	A/C CONDENSER GARNISH LH	\$		58.81	?
71	1	A/C CONDENSER GARNISH RH	\$		59.60	?
72	1	A/C PIPE CONDENSER TO COMPRESSOR	\$		208.39	?
73	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$		658.72	?
74	1	A/C PIPE COMPRESSOR	\$		334.29	?

Trans-cab Auto Services Pte Ltd**AAD1810-230**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

75	1	A/C PIPE	\$	658.72	?
76	1	A/C COMPRESSOR	\$	2,684.61	?
77	1	AIR COOLER	\$	792.60	?
78	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	?
79	1	AIR INTERCOOLER HOSE (Short)	\$	375.14	?
80	1	TRANSMISSION COOLER	\$	R ₁ 1,219.30	✓
81	1	TRANSMISSION COOLER PAD	\$	17.96	?
82	1	RADIATOR	\$	R ₁ 1,202.20	✓
83	2	RADIATOR STUD UPPER	\$	14.41	?
84	2	RADIATOR BUSH UPPER	\$	50.12	?
85	2	RADIATOR MTG LOWER	\$	S ₁ 55.85	X
86	1	RADIATOR FAN COWLING	\$	820.54	?
87	1	RADIATOR FAN MOTOR LH	\$	967.36	?
88	1	RADIATOR FAN MOTOR RH	\$	1,479.46	?
89	1	RADIATOR TANK	\$	S ₁ 324.62	X
90	1	RADIATOR HOSE UPPER	\$	240.56	?
91	1	RADIATOR HOSE LOWER	\$	491.18	?
92	1	RADIATOR TANK HOSE	\$	S ₁ 61.18	X
93	1	AUTO COMPUTER	\$	5,032.17	?
94	1	INJECTION COMPUTER	\$	4,706.30	?
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	5,154.52	?
96	1	STEERING PUMP ELECTRIC	\$	2,306.90	?
97	1	STEERING PINION RACK	\$	4,413.11	?
98	1	DOOR PANEL FRT LH	\$	R ₁ 2,844.66	✓
99	1	DOOR HINGE UPPER LH	\$	R 261.28	X
100	1	DOOR HINGE LOWER LH	\$	R 300.55	
101	1	DOOR CHECK FRT LH	\$	S ₁ 194.77	
102	1	DOOR LOCK FRT LH	\$	R 908.75	
103	1	DOOR CATCH FRT LH	\$	S ₁ 131.23	
104	1	DOOR HANDLE OUTER FRT LH	\$	S ₁ 477.76	
105	1	DOOR HANDLE COVER FRT LH	\$	S ₁ 13.22	
106	1	DOOR HANDLE MODULE FRT LH	\$	S ₁ 133.60	
107	1	DOOR REGULATOR FRT LH	\$	R 505.19	
108	1	DOOR REGULATOR MOTOR FRT LH	\$	R 796.46	
109	1	DOOR REGULATOR GUIDE FRT LH	\$	S ₁ 120.97	X
110	1	DOOR PANEL REAR LH	\$	R ₁ 2,844.66	
111	1	DOOR GUIDE REAR LH	\$	S ₁ 176.82	
112	1	DOOR HINGE UPPER LH	\$	R 274.50	
113	1	DOOR HINGE LOWER LH	\$	R 300.55	

Trans-cab Auto Services Pte Ltd**AAD1810-230**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

114	1	DOOR CHECK REAR LH	\$	N	203.06
115	1	DOOR LOCK REAR LH	\$	N	908.75
116	1	DOOR HANDLE OUTER REAR LH	\$	Sn	126.49
117	1	DOOR HANDLE CAP REAR LH	\$	Sn	35.52
118	1	DOOR HANDLE SEAL REAR LH	\$	Sn	7.89
119	1	DOOR HANDLE COVER REAR LH	\$	Sn	13.22
120	1	DOOR HANDLE MODULE REAR LH	\$	Sn	133.60
121	1	DOOR REGULATOR REAR LH	\$	N	1,135.10
122	1	DOOR REGULATOR MOTOR REAR LH	\$	N	893.75
123	1	DOOR REGULATOR NUT REAR LH	\$	Sn	12.43
124	1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	Sn	6.31
125	1	DOOR FINISHER REAR LH	\$	Sn	423.10
126	1	DOOR MOULDING REAR LH	\$	Sn	176.82
127	1	DOOR MOULDING CLIP L70Y	\$	nn	5.92
128	1	DOOR MOULDING SCREW L70Y	\$	nn	6.91
129	1	DOOR CASING REAR LH	\$	Sn	1,509.06
130	1	DOOR WATER SHIELD REAR LH	\$	Sn	30.39
131	1	DOOR CASING CLIP	\$	nn	12.63
132	1	DOOR CASING LIGHT L70Y	\$	Sn	48.74
133	1	DOOR FINISHER INNER REAR LH	\$	Sn	323.44
134	1	DOOR FINISHER BRACKET INNER REAR LH	\$	N	46.97
135	1	DOOR FINISHER BRACKET INNER REAR LH	\$	N	20.33
136	1	DOOR FINISHER BRACKET INNER REAR LH	\$	N	20.33
137	1	DOOR FINISHER BRACKET INNER REAR LH	\$	N	20.33
138	1	DOOR GRAB HANDLE REAR LH	\$	Sn	210.96
139	1	DOOR BLIND REAR LH	\$	Sn	741.80
140	1	DOOR WHEATHESTRIIP REAR LH	\$	Sn	410.66
141	1	DOOR SEAL REAR LH	\$	Sn	162.02
142	1	DOOR GLASS RUNNER SEAL REAR LH	\$	Sn	229.31
143	1	DOOR WAIST SEAL OUTER REAR LH	\$	Sn	334.69
144	1	DOOR WAIST SEAL INNER REAR LH	\$	Sn	115.64
145	1	FENDER PANEL REAR LH	\$	N	3,299.13
146	1	FENDER PANEL INNER TRIM REAR	\$	Sn	671.45
147	1	WHEELARCH REAR LH	\$	Sn	543.47
148	1	DOOR MIRROR ASSY LH	\$	Sn	1,483.40
149	1	ROCKER PANEL INNER GARNISH LH	\$	Sn	466.51
150	1	ROCKER PANEL INNER LH	\$	N	1,024.79
151	1	ROCKER PANEL CENTER LH	\$	N	990.25
152	1	DOOR HARNESS WIRE LH	\$	Sn	2,670.00

Trans-cab Auto Services Pte Ltd

AAD1810-230

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

153	1	DOOR PANEL FRONT RH	\$	<i>11</i>	2,844.66	<i>X</i>
154	1	DOOR MIRROR ASSY RH	\$	<i>12</i>	1,483.40	<i>X</i>
155	1	DOOR HARNESS WIRE RH	\$	<i>12</i>	2,670.00	<i>X</i>
156	1	DOOR PANEL REAR RH	\$	<i>11</i>	2,844.66	<i>X</i>
157	1	ROCKER PANEL INNER GARNISH RH	\$	<i>12</i>	466.51	<i>X</i>
158	1	ROCKER PANEL INNER RH	\$	<i>11</i>	1,024.79	<i>X</i>
159	1	ROCKER PANEL CENTER RH	\$	<i>12</i>	990.25	<i>✓</i>
160	1	BUMPER COVER REAR	\$	<i>11</i>	1,108.46	<i>X</i>
161	1	LOWER ARM LH L70Y	\$	<i>12</i>	685.76	<i>✓</i>
162	1	KNUCKLE ARM LH L70Y	\$	<i>12</i>	846.98	<i>✓</i>
163	1	ABSORBER FRT LH L70Y	\$		360.54	<i>?</i>
164	1	LOWER ARM RH L70Y	\$		685.76	<i>?</i>
165	1	KNUCKLE ARM RH L70Y	\$		846.98	<i>?</i>
166	1	ABSORBER FRT RH L70Y	\$		360.54	<i>?</i>
167	1	DRIVESHAFT LH	\$		1,747.45	<i>?</i>
168	1	DRIVESHAFT RH	\$		1,747.45	<i>?</i>
169	1	STABILIZER BAR FRT	\$		604.65	<i>?</i>
170	1	AIR CLEANER HOSE	\$	<i>1</i>	175.85	<i>?</i>
TOTAL			\$		116,652.76	
10%			\$		11,665.28	
			\$		104,987.48	

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>na</i>	52.00	<i>✓</i>
2	1SET	BUMPER CLIP FRT	\$	<i>na</i>	66.00	<i>✓</i>
3	1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i>	12.00	<i>X</i>
4	1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i>	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i>	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i>	10.50	
7	1	TOW COVER FRT	\$	<i>12</i>	14.50	
8	1SET	RADIATOR GRILLE SCREW	\$	<i>12</i>	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i>	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i>	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i>	20.00	<i>X</i>
12	2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i>	30.00	
13	1	Windscreen moulding	\$	<i>na</i>	120.00	
14	1	FRONT WINDSCREEN SEALANT	\$	<i>na</i>	253.80	

Trans-cab Auto Services Pte Ltd

AAD1810-230

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

15	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
16	1SET	Front licence plate with holder	\$	nn	80.00	455n
17	1	DOOR CHECK BOLT	\$	nn	22.69	X
18	1	DOOR GUIDE SCREW	\$	nn	10.85	X
19	1	DOOR HINGE BOLT	\$	nn	10.85	X
20	1	DOOR HINGE NUT RH	\$	nn	14.60	X
21	1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	✓
22	1SET	WHEELARCH CLIP FRT RH	\$	nn	30.50	✓
23	1	Front left tyre	\$		330.00	?
24	1	Front left tyre rim	\$		380.00	?
25	1	Front right tyre	\$		330.00	?
26	1	Front right tyre rim	\$		380.00	?
27	1	FRONT LH DOOR STICKER 'Trans-cab'	\$	nn	80.00	601n
28	1	FRONT LH DOOR STICKER 'Classic'	\$	nn	50.00	155n
29	1	FRONT RH DOOR STICKER 'Trans-cab'	\$	nn	80.00	X
30	1	FRONT RH DOOR STICKER 'Classic'	\$	nn	50.00	X
31	1	REAR LH DOOR STICKER '6555 3333'	\$	nn	80.00	601n
32	1	REAR RH DOOR STICKER '6555 3333'	\$	nn	80.00	X
33	1	DOOR CHECK BOLT	\$	nn	22.69	} X
34	1	DOOR CHECK NUT	\$	nn	3.75	
35	1	DOOR LOCK SCREW L70Y	\$	nn	6.12	
36	1	DOOR CATCH SCREW L70Y	\$	nn	10.06	
37	6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	
38	2	BONNET STRUT L70Y	\$	nn	88.61	
39	2	BONNET CABLE CLIP L70Y	\$	nn	6.31	}
40	2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	
TOTAL			\$		3,052.01	

TOTAL PARTS \$ 108,039.49**LABOUR**

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 9,000.00

2000

Towing Fees.

\$ 120.00

500

Trans-cab Auto Services Pte Ltd**AAD1810-230**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	9,000.00 <i>1800</i>
To rust-proofing of the affected areas.	\$	170.00 <i>1500</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>1000</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>600</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>?</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>300</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 <i>2500</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To lift-up engine with gear box and refit.	\$	440.00 <i>?</i>
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 <i>?</i>
To remove and refit air bag system and reset.	\$	<i>nn</i> 480.00 <i>X</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nn</i> 380.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00 <i>1000</i>

Trans-cab Auto Services Pte Ltd

AAD1810-230

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 957Z

To replace, refix and top up coolant for radiator	\$	170.00	501
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X
To Transfer Of Front Door Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	601
To Transfer Of Front Door Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	~ 170.00	X
To Transfer Of Rear Door Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	2401

TOTAL \$ **24,820.00****Over All Total** \$ **132,859.49****Repair Days (PART BY PART)****30 days****15 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: