

INSURANCE

INS. CASE OWNER

CC 4/III1801

annv, Feb 9

LKK
IDAC

Surveyor:

KSC

DOI:

ASSIGNMENT

netw/06

Date / Time:

netw/06

Registered in Merimen:

netw/06

Pre-assign / CCU / FTE



Insured Vehicle No.:

SH 7261H

Name of Insured:

LTP

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

netw/06

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

FONGY LUN HONG

Driver Tel No.:

(V/L- YES / NO)

Claim No.:

MU18700743

Policy No.:

W10M0615

Make / Model:

MAZDA

Place of Accident:

VISHWA AVE x AVE 6

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SMC 7187E



INSRS:
WSP:
Tel:
Liability:
RMKS:

Hui Yang



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SMC 7187E - 2 SH 7261H - 2

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):
After call ltr to OI:
Authorisation To Act:
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA:
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:
Payment Breakdown Form:
Post-Repair Photos:
Others:

7/10/06
Hui Yang

01-11-06

Check mandate for liability.

02-11-06

MANDATE APPROVE LIABILITY.

03-11-06

ISSUE VSP LIABILITY CLERK.

08-11-06

FILE PAGE TO TYPST TO POSTIVE RECORD.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

1/5

SS13,300

(8 days) Reduction:

47 %

Email

Call

FINAL SETTLEMENT

Date/Time: 21-2-09

Confirm with: MRELO

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

Repair Cost:

9/47

SS 14,231.00

1 VBI CC 00 3RD

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

765.00 (S85 x 9 days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: 4600

Total:

SS 14,996.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 21-2-09

Confirm with: MRELO

Email

Call

Payee 1:

SS 14,996.00

Name 1: HUI YANG MOTOR PTE. LTD.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

ASS. REC. BY:

REF: TH /Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

Hui Yang

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8 Pdk

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 08 days

Res.: Yes or No

Lum Sum: 1. B. / %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNC 31875Yr Regn: 06, 18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy CHRc.c. 1797Colour: Yellow

A/C: Insured / Std / NI / NA

Sp. Reading: 12038

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 24X10

2120245

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NI / S/Rim / STD / RIM orTyre Size: F: 215/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 22/10/18D.O.I. 24/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/10 File pass to Catherine45:15.300 (RED: 11,480.50 47.2)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) P. 1000

) Others

TOTAL

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

22/10/2018

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SMC3187E

1pc	rear tailgate	\$ 981.45	✓
1pc	rear tailgate outer garnish	\$ 882.20	?
1pc	rear tailgate "C-HR" emblem	\$ 83.20	—
1pc	rear tailgate "HYBRID" emblem	\$ 71.00	✓
1pc	rear tailgate "TOYOTA" logo	\$ 68.80	✓
2pcs	rear tailgate reflector @\$353.50	\$ 707.00	?
1pc	rear tailgate inner lock	\$ 374.45	?
1pc	rear tailgate inner rubber	\$ 374.85	?
2pcs	rear taillamp @\$374.50	\$ 749.00	?
2pcs	rear taillamp lower bracket @\$171.45	\$ 342.90	?
1pc	rear bumper	\$ 972.45	✓
2pcs	rear bumper side retainer @\$141.45	\$ 282.90	✓
2pcs	rear bumper reflector garnish @\$281.90	\$ 563.80	?
1pc	rear bumper diffuser	\$ 581.45	✓
1pc	rear bumper diffuser towing cover	\$ 85.85	—
8pcs	rear bumper diffuser clip @\$5.50	\$ 44.00	—
1pc	rear bumper diffuser centre cover	\$ 74.85	✓
1pc	rear bumper reinforcement	\$ 782.10	✓
1pc	rear end panel	\$ 781.45	✓
1pc	rear end panel inner garnish	\$ 378.85	?
1pc	rear floor panel	\$ 785.85	X
1pc	rear floor panel sponge	\$ 285.85	?
1pc	rear exhaust box	\$ 1,850.00	✓
1pc	rear exhaust box top cover	\$ 181.50	✓
3pcs	rear exhaust mounting @\$58.50	\$ 175.50	✓
2pcs	rear fender protector @\$258.85	\$ 517.70	?
1pc	front bonnet	\$ 972.55	✓
1pc	front bonnet inner lock	\$ 274.10	X
1pc	front centre grille base	\$ 591.45	?
1pc	front centre grille garnish	\$ 371.50	✓
1pc	front centre grille inner PCS sensor	\$ 1,481.90	?
1pc	front centre grille "TOYOTA" logo	\$ 785.50	✓
1pc	front centre grille top garnish	\$ 381.90	X
1pc	front centre grille top rubber	\$ 174.45	X
1pc	front centre grille retainer	\$ 131.25	X
2pcs	front headlamp @\$2550.50	\$ 5,101.00	?
balance c/f		\$ 23,244.55	



Not with order
Mummy Bq point
Solar

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

22/10/2018

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SMC3187E

	balance b/f		\$ 23,244.55	
1pc	front bumper	Bu \$	974.45	✓
1pc	front bumper grille	bys \$	274.45	✓
1pc	front bumper lower lid	Net/bys \$	680.00	✓
1pc	front bumper number plate garnish	Net \$	271.85	✓
1pc	front bumper reinforcement	\$	581.10	?
1pc	front bumper sponge	\$	181.90	?
			<hr/>	
			\$ 26,208.30	
	less 25%		\$ 6,552.08	
	balance c/f		<hr/>	
			\$ 19,656.23	
1pc	rear end panel outer sensor	nett \$	240.00	?
		\$	240.00	
	less 10%	\$	24.00	
		\$	<hr/>	
			\$ 216.00	
1set	parking sensor	Shen s.nett \$	280.00	200sm
	reprogram & reset PCS sensor	\$	280.00	1501
	remove & refit rear windscreen glass	\$	120.00	✓
	sealant	\$	80.00	40sm
	wiring	\$	180.00	401
	tuffkote	\$	350.00	901
	spray painting	\$	1,800.00	11001
	labour charges	\$	1,500.00	10001
	Total		<hr/>	
			\$ 24,462.23	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Print Received Message

This mail is associated with :

***SMC3187E (MCT18100743)
[SH7241H]**

TP

SKYWAY MOTOR PTE LTD
Oct 22 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 02/11/2018 11:14 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SMC3187E - Claim Handler: Zuhaidah Bte Samsuri

Approved:0.00:BOLA 28/OID NAF

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 2 November 2018 2:01 PM
To: 'hui_yang_motor@hotmail.com'
Subject: Accident Involving SMC 3187E & SH 7241H on 22/10/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: SMC 3187E
Our Ref: CC4/III18019332/Keb3

Dear Sir/Madam,

Accident Involving SMC 3187E & SH 7241H on 22/10/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	24 Oct 2018 14:43	Cim Veh Model Changed	(202021) ADIVA AD200A 200cc (M).	[A] Lau Shu Pei
2	24 Oct 2018 14:43	Cim Created	Reg No: SMC3187E. Acct Date: 2018/10/22. Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ). Workshop: Hui Yang Motor Pte Ltd (HQ)	[A] Lau Shu Pei
3	24 Oct 2018 14:43	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	24 Oct 2018 14:43	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/02	[A] Lau Shu Pei
5	24 Oct 2018 14:43	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	24 Oct 2018 14:43	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	24 Oct 2018 14:43	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei
8	25 Oct 2018 12:52	Cim Veh Model Changed	(202021) -> (205388) TOYOTA C-HR HYBRID 1.8 S CVT (A).	[A] Lau Shu Pei
9	31 Oct 2018 08:54	Cim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	31 Oct 2018 08:54	Cim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
11	01 Nov 2018 18:02	Adj Mandate Request	Cur.Reg:0.00:PODS: LIABILITY: 100% REMARK: B:28 4VEH CC OID 3RD	[A] Asher Sng Rong Yi
12	02 Nov 2018 11:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/02. Mandate Remarks: BOLA 28/OID NAF	[I] Zuhaidah Bte Samsuri
13	02 Nov 2018 11:14	Adj Mandate Set	Approved:0.00:BOLA 28/OID NAF	[I] Zuhaidah Bte Samsuri
14	17 Jan 2019 11:34	Adj Rpt Initiated		[A] Lau Shu Pei
15	17 Jan 2019 11:34	Cim Dtl Modified	Claimant's ID: -> -.	[A] Lau Shu Pei
16	17 Jan 2019 11:34	Cim Dtl Modified	JPJ Reg. Date: -> 2000/01/01.	[A] Lau Shu Pei
17	17 Jan 2019 11:34	Cim Details Notified		[A] Lau Shu Pei
18	28 Jan 2019 14:20	Cim Dtl Modified	JPJ Reg. Date: 2000/01/01 -> 2018/06/28.	[A] JOANNE LEE KHANG MIN
19	14 Feb 2019 09:13	Adj Mandate Request	Cur.Reg:14996.00:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST: \$14,231.00 + (b) LOU: \$765.00 (9days x \$85) Total: a+b = \$14,996.00 VEH MODEL: TOYOTA C-HR HYBRID 1797cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2032312	17/01/2019 11:34	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMC3187E	SH7241H	10.70

Print Received Message

This mail is associated with :

***SMC3187E (MCT18100743)**
[SH7241H]

TP

SKYWAY MOTOR PTE LTD
Oct 22 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 15/02/2019 11:31 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14996.00) - SMC3187E - Claim Handler: Zuhaidah Bte Samsuri

Approved:14996.00:BOLA 28/OID NAF

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 24 October 2018 9:38 AM
To: Hui Yang Motor; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Zuhaidah Samsuri
Subject: RE: TP Claim for SMC3187E against SH7241H / DOA: 22/10/2018
Attachments: SKM_C28718102316120.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SMC3187E and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6717 6100, Ext - 248

24.10.2018 @ 1057am
Bel veh in
Kenneth

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: 24 October, 2018 9:31 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: TP Claim for SMC3187E against SH7241H / DOA: 22/10/2018
Importance: High

Hi,

Our choice of surveyor is LKK Auto.

Thank you & Regards,
Bel
Tel: 64515752

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, October 24, 2018 9:08 AM
To: Hui Yang Motor
Subject: RE: TP Claim for SMC3187E against SH7241H / DOA: 22/10/2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

Indale International Insurance Pte Ltd

64 Cecil Street | #05 10B Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]

Sent: 23 October, 2018 4:59 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: TP Claim for SMC3187E against SH7241H / DOA: 22/10/2018

Importance: High

Dear Sir/ Mdm,

Attached follow up of GIA Report and Police Report for your perusal.

Thank you & Regards,

Marius Loh

From: Hui Yang Motor <hui_yang_motor@hotmail.com>

Sent: Tuesday, October 23, 2018 4:04 PM

To: Motor Claim - III

Subject: TP Claim for SMC3187E against SH7241H / DOA: 22/10/2018

Hi

Please refer to attached estimate and help to arrange surveyor on 24/10/2018 (Wednesday) as vehicle SMC3187E already in our workshop.

We forward you the GIA statement once ready.

Date of Accident: 22/10/2018 @ 10.20pm

Client's vehicle : SMC3187E

Your Insured vehicle : SH7241H

Thank you & Regards,
Be
Tel: 64515752

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

Ins: International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

Ins: International Insurance Pte Ltd.

Registration No. 198703792-K

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

Date: 09/11/2018

India International Insurance Pte Ltd

Motor Claims Department

64 Cecil Street

#04-00 IOB Building

Singapore 049711

**RE: ACCIDENT INVOLVING SMC3187E, SH7241H, SJR7998Z & FBJ8506D ON 22-10-2018
ALONG CROSS JUNCTION OF YISHUN AVE 6 & YISHUN AVE 7**

SETTLEMENT OF OUR CLAIM FOR SMC3187E

Lump sum repair cost as recommended by surveyor (TP0486)	\$ 14,231.00
9 days Loss of Use @ \$85.00 per day	\$ 765.00
Total	<u>\$ 14,996.00</u>

**The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

Please let us have your reply soonest possible, thank you.

Best Regards,

Marco Neo

HUI YANG MOTOR PTE LTD

DID: 64515752

Fax: 64514658

email: hui_yang_motor@hotmail.com

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, Skyway Motor Pte Ltd hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-02 Sin Ming Autocare Singapore 575721 in all my/our correspondences with any party in connection with my/our claim arising from an accident involving my/our motor vehicle registration number SML 3187E, SH7241H, SJR779KZ and other vehicles registration number BJ78506D along Cross Junction of Yishun Ave 6 & Yishun Ave 7 on 22/10/18

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd**.

A handwritten signature in black ink is written over a circular stamp. The stamp contains the text "SKYWAY MOTOR PTE LTD" around a central dot.

.....
Signature of registered owner and Company's stamp

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18100743
Claimant Ref: SMC 3187E

We/I, HUI YANG MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 14,231.00 (repair cost), S\$ 765.00 (loss of use/rental), S\$ — (search fee), vehicle no. SMC 3187E that was damaged pursuant to the accident which occurred on 22/10/2018 (date) at CROSS JUNCTION OF YISHUN AVE 5 & YISHUN AVE 7 (location) involving vehicle no. SH 7241H (insured vehicle). This is pursuant to the inspection conducted on 24/10/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SKYWAY MOTOR PTE LTD ("the third party claimant") of vehicle no. SMC 3187E to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SMC 3187E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 14,996.00 to HUI YANG MOTOR PTE LTD

Dated this 27 day of 02 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Ng Hoo E. K

NRIC:

S7932320I

Address:

—

Nationality:

—

Occupation:

Director

WITNESS:

Signature:



KSC

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

Nationality:

—

Occupation:

—

HUI YANG MOTOR PTE LTD

Bill To:

India International Insurance Pte Ltd
Motor Claims Department
64 Cecil Street
#04-00 IOB Building
Singapore 049711

TAX INVOICE

TP Claim Invoice No: TP0486
Bill Date: 09/11/2018

	Description	Amount
	Date of Accident : 22/10/2018 Owner : SKYWAY MOTOR PTE LTD Vehicle No : <u>SMC3187E</u> Make & Model : <u>TOYOTA C-HR HYBRID 1.8S</u>	
	<u>Lump Sum repair cost as recommended by surveyor</u>	\$ 13,300.00
	Sub-Total :	\$ 13,300.00
	Add 7% GST :	\$ 931.00
	Total Amount SGD :	\$ 14,231.00

Reg No.:201629438M

GST No:201629438M

HUI YANG MOTOR PTE LTD



Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax : 64514658

...CLAIM SUBFOLDER...(Pending for Survey Report)






































Direct Settlement


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2018 Edit Reg		24 Oct 2018 00:00 Edit Adj Rpt	S\$13,300.00 Edit Estimates	S\$13,300.00 View Rpt		Pending for Survey Report Cancel Case









Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -								
Main Claimant:	SKYWAY MOTOR PTE LTD , Co. Reg. No.: 199904194N								
Vehicle Reg. No.:	SMC3187E	Date of Loss:	22/10/2018 00:00 - :59 [3 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18100743	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH7241H	Policy No. (Claimant):	A28795104MCX						
		Excess:							
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (15/02/2019): Alert - Adj Mandate Approved (S\$14996.00) - SMC3187E - Claim Handler: Zuhaidah B... III_SG (02/11/2018): Alert - Adj Mandate Approved (S\$0.00) - SMC3187E - Claim Handler: Zuhaidah Bte S... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMC3187E (MCT18100743)**
[SH7241H]
TP
SKYWAY MOTOR PTE LTD
Oct 22 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
2	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
3	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
4	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
5	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
6	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
7	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
8	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
9	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
10	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
11	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
12	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
13	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
14	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
15	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
16	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
17	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
18	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
23	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
24	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
26	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
27	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
28	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
29	01/02/19 16:56	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
30	01/02/19 16:56	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
31	01/02/19 16:56	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	14/02/19 09:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/10/18 14:43	EMAIL FROM III DD 24102018	 Load PDF	
2	24/10/18 14:43	TP ESTIMATE	 Load PDF	
3	26/10/18 11:21	TP ESTIMATE- MARKED	 Load PDF	
4	28/01/19 14:21	WORKSHOP INVOICE	 Load PDF	
5	28/01/19 14:21	LOD	 Load PDF	
6	05/03/19 12:01	DISCHARGE VOUCHER	 Load PDF	
7	05/03/19 12:01	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	29/10/18 09:49	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18019332/KEB3Q2

Date: 05/03/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No: SMC3187E

Insured Vehicle No: SH7241H

Date of Loss: 22/10/2018

Nature of Claim:

TP

Claim No: MCT18100743

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC3187E

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A)

Engine No: 2ZR8438508

Reg. Date: 28/06/2018 (Man. Year: 2018)

Chassis No: ZYX102120245

Colour: Yellow

Odometer: 12038 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,720.55	14,195.89	6,524.66	31.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,230.00	2,500.00	1,730.00	40.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,950.55	16,695.89	8,254.66	33.08
Approved Total (Overridden) (S\$)		13,300.00		
(S\$)	24,950.55	13,300.00	11,650.55	46.69
+ GST 7.00/7.00% (S\$)	1,746.54	931.00	815.54	46.69
Nett Amount (S\$)	26,697.09	14,231.00	12,466.09	46.69
+ Loss of Use (9.0 x S\$85.00/day) (S\$)		765.00		
Nett Liability (S\$)		14,996.00		

INSPECTION

Date of Assignment: 24/10/2018

Date Inspected: 24/10/2018 Inspected At:

Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2019)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC3187E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	981.45 FL	*981.45 FL
2	1		*REAR TAILGATE OUTER GARNISH	Mtg Cracked	882.20 FL	*882.20 FL
3	1		*REAR TAILGATE C-HR EMBLEM	Necessary	83.20 FL	*83.20 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	71.00 FL	*71.00 FL
5	1		*REAR TAILGATE TOYOTA LOGO	Necessary	68.80 FL	*68.80 FL
6	2		*REAR TAILGATE REFLECTOR	Serviceable	707.00 FL	*- FL
7	1		*REAR TAILGATE INNER LOCK	Dented	374.45 FL	*374.45 FL
8	1		*REAR TAILGATE INNER RUBBER	Distorted / Dented	374.85 FL	*374.85 FL
9	1		*REAR TAILLAMP	O/S Cut	749.00 FL	*374.50 FL
10	2		*REAR TAILLAMP LOWER BRACKET	Repair	342.90 FL	*- FL
11	1		*REAR BUMPER	Buckled	972.45 FL	*972.45 FL
12	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	282.90 FL	*141.45 FL
13	2		*REAR BUMPER REFLECTOR GARNISH	Serviceable	563.80 FL	*- FL
14	1		*REAR BUMPER DIFFUSER	Dented / Cut	581.45 FL	*581.45 FL
15	1		*REAR BUMPER DIFFUSER TOWING COVER	Dented	85.85 FL	*85.85 FL
16	8		*REAR BUMPER DIFFUSER CLIP	Necessary	44.00 FL	*44.00 FL
17	1		*REAR BUMPER DIFFUSER CENTRE COVER	Cracked	74.85 FL	*74.85 FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	782.10 FL	*782.10 FL
19	1		*REAR END PANEL	Bent	781.45 FL	*781.45 FL
20	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	378.85 FL	*378.85 FL
21	1		*REAR FLOOR PANEL	Repair	785.85 FL	*- FL
22	1		*REAR FLOOR PANEL SPONGE	Serviceable	285.85 FL	*- FL
23	1		*REAR EXHAUST BOX	Bent	1,850.00 FL	*1,592.70 FL
24	1		*REAR EXHAUST BOX TOP COVER	Bent	181.50 FL	*181.50 FL
25	3		*REAR EXHAUST MOUNTING	Torn	175.50 FL	*175.50 FL
26	2		*REAR FENDER PROTECTOR	Serviceable	517.70 FL	*- FL
27	1		*FRONT BONNET	Bent	972.55 FL	*972.55 FL
28	1		*FRONT BONNET INNER LOCK	Repair	274.10 FL	*- FL
29	1		*FRONT CENTRE GRILLE BASE	Cracked	591.45 FL	*591.45 FL
30	1		*FRONT CENTRE GRILLE GARNISH	Cracked	371.50 FL	*371.50 FL
31	1		*FRONT CENTRE GRILLE INNER PCS SENSOR	Dented	1,481.90 FL	*1,481.90 FL
32	1		*FRONT CENTRE GRILLE TOYOTA LOGO	Cracked	785.50 FL	*785.50 FL
33	1		*FRONT CENTRE GRILLE TOP GARNISH	Serviceable	381.90 FL	*- FL
34	1		*FRONT CENTRE GRILLE TOP RUBBER	Serviceable	174.45 FL	*- FL
35	1		*FRONT CENTRE GRILLE RETAINER	Serviceable	131.25 FL	*- FL
36	1		*FRONT HEADLAMP	N/S Mtg Cracked	5,101.00 FL	*2,550.50 FL
37	1		*FRONT BUMPER	Buckled	974.45 FL	*974.45 FL
38	1		*FRONT BUMPER GRILLE	Distorted	274.45 FL	*274.45 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*FRONT BUMPER LOWER LID	Dented / Cut	680.00 FL	*680.00 FL
40	1		*FRONT BUMPER NUMBER PLATE GARNISH	Dented	271.85 FL	*271.85 FL
41	1		*FRONT BUMPER REINFORCEMENT	Repair	581.10 FL	*- FL
42	1		*FRONT BUMPER SPONGE	Serviceable	181.90 FL	*- FL
43	1		*REAR END PANEL OUTER SENSOR	Serviceable	240.00 FN	*- FN
44	1		*SET PARKING SENSOR	Shorted	280.00 FS	*200.00 FS
45	1		*SEALANT	Necessary	80.00 FS	*40.00 FS
46	1		*FRONT BUMPER LOWER REINFORCEMENT	Bent	381.10 FL	*381.10 FL
47	1		*FRONT BUMPER LOWER REINFORCEMENT RH BRACKET	Bent	98.50 FL	*98.50 FL
48	1		*FRONT BUMPER LOWER REINFORCEMENT SPONGE	Cracked	171.50 FL	*171.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	27,459.40	18,847.85
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,714.85	4,651.96
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	24.00	0.00
Total Parts (\$\$)	20,720.55	14,195.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPROGAM & RESET PCS SENSOR	New	280.00	150.00
2	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
3	WIRING	New	180.00	40.00
4	TUFFKOTE	New	350.00	90.00
5	SPRAY PAINTING	New	1,800.00	1,100.00
6	LABOUR CHARGES	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			4,230.00	2,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >