

23/10/18

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

Not Authorised

22/10/2018

Owner: SKYWAY MOTOR PTE LTD

Manny Bg pain
Solar

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SMC3187E

1pc	rear tailgate	\$ <i>As</i> 981.45 ✓
1pc	rear tailgate outer garnish	\$ 882.20 ?
1pc	rear tailgate "C-HR" emblem	\$ <i>Mc</i> 83.20 —
1pc	rear tailgate "HYBRID" emblem	\$ <i>Mc</i> 71.00 ✓
1pc	rear tailgate "TOYOTA" logo	\$ <i>Mc</i> 68.80 ✓
2pcs	rear tailgate reflector @\$353.50	\$ 707.00 ?
1pc	rear tailgate inner lock	\$ 374.45 ?
1pc	rear tailgate inner rubber	\$ 374.85 ?
2pcs	rear taillamp @\$374.50	\$ 749.00 ?
2pcs	rear taillamp lower bracket @\$171.45	\$ 342.90 ?
1pc	rear bumper	\$ <i>As</i> 972.45 ✓
2pcs	rear bumper side retainer @\$141.45	\$ <i>As/Sm</i> 282.90 ✓
2pcs	rear bumper reflector garnish @\$281.90	\$ 563.80 ?
1pc	rear bumper diffuser	\$ <i>As/Sm</i> 581.45 ✓
1pc	rear bumper diffuser towing cover	\$ <i>Mc</i> 85.85 —
8pcs	rear bumper diffuser clip @\$5.50	\$ <i>Mc</i> 44.00 —
1pc	rear bumper diffuser centre cover	\$ <i>CM</i> 74.85 —
1pc	rear bumper reinforcement	\$ <i>As</i> 782.10 —
1pc	rear end panel	\$ <i>As</i> 781.45 ✓
1pc	rear end panel inner garnish	\$ 378.85 ?
1pc	rear floor panel	\$ <i>As</i> 785.85 X
1pc	rear floor panel sponge	\$ 285.85 ?
1pc	rear exhaust box	\$ <i>As</i> 1,850.00 ✓
1pc	rear exhaust box top cover	\$ <i>As</i> 181.50 —
3pcs	rear exhaust mounting @\$58.50	\$ <i>As</i> 175.50 ✓
2pcs	rear fender protector @\$258.85	\$ 517.70 ?
1pc	front bonnet	\$ <i>As</i> 972.55 ✓
1pc	front bonnet inner lock	\$ <i>As</i> 274.10 X
1pc	front centre grille base	\$ 591.45 ?
1pc	front centre grille garnish	\$ <i>CM</i> 371.50 —
1pc	front centre grille inner PCS sensor	\$ 1,481.90 ?
1pc	front centre grille "TOYOTA" logo	\$ <i>CM</i> 785.50 ✓
1pc	front centre grille top garnish	\$ <i>SL</i> 381.90 X
1pc	front centre grille top rubber	\$ <i>SL</i> 174.45 X
1pc	front centre grille retainer	\$ <i>SL</i> 131.25 X
2pcs	front headlamp @\$2550.50	\$ 5,101.00 ?
balance c/f		\$ 23,244.55



輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

22/10/2018

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SMC3187E

	balance b/f		\$ 23,244.55	
1pc	front bumper	Bu \$	974.45	✓
1pc	front bumper grille	b.y \$	274.45	✓
1pc	front bumper lower lid	Net/buy \$	680.00	✓
1pc	front bumper number plate garnish	Net \$	271.85	✓
1pc	front bumper reinforcement	\$	581.10	?
1pc	front bumper sponge	\$	181.90	?
			<u>\$ 26,208.30</u>	
	less 25%		\$ 6,552.08	
	balance c/f		<u>\$ 19,656.23</u>	
1pc	rear end panel outer sensor	nett \$	240.00	?
			<u>\$ 240.00</u>	
	less 10%		\$ 24.00	
			<u>\$ 216.00</u>	
1set	parking sensor	Shan s.nett \$	280.00	200/ea
	reprogram & reset PCS sensor	\$	280.00	150/
	remove & refit rear windscreen glass	\$	120.00	✓
	sealant	\$	80.00	40sn
	wiring	\$	180.00	40/
	tuffkote	\$	350.00	90/
	spray painting	\$	1,800.00	1100/
	labour charges	\$	1,500.00	1000/
	Total		<u>\$ 24,462.23</u>	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: