

輝 陽 汽 車 有 限 公 司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658


Reg No. 201629438M

22/10/2018

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SMC3187E

1pc	rear tailgate	\$	981.45
1pc	rear tailgate outer garnish	\$	882.20
1pc	rear tailgate "C-HR" emblem	\$	83.20
1pc	rear tailgate "HYBRID" emblem	\$	71.00
1pc	rear tailgate "TOYOTA" logo	\$	68.80
2pcs	rear tailgate reflector @\$353.50	\$	707.00
1pc	rear tailgate inner lock	\$	374.45
1pc	rear tailgate inner rubber	\$	374.85
2pcs	rear taillamp @\$374.50	\$	749.00
2pcs	rear taillamp lower bracket @\$171.45	\$	342.90
1pc	rear bumper	\$	972.45
2pcs	rear bumper side retainer @\$141.45	\$	282.90
2pcs	rear bumper reflector garnish @\$281.90	\$	563.80
1pc	rear bumper diffuser	\$	581.45
1pc	rear bumper diffuser towing cover	\$	85.85
8pcs	rear bumper diffuser clip @\$5.50	\$	44.00
1pc	rear bumper diffuser centre cover	\$	74.85
1pc	rear bumper reinforcement	\$	782.10
1pc	rear end panel	\$	781.45
1pc	rear end panel inner garnish	\$	378.85
1pc	rear floor panel	\$	785.85
1pc	rear floor panel sponge	\$	285.85
1pc	rear exhaust box	\$	1,850.00
1pc	rear exhaust box top cover	\$	181.50
3pcs	rear exhaust mounting @\$58.50	\$	175.50
2pcs	rear fender protector @\$258.85	\$	517.70
1pc	front bonnet	\$	972.55
1pc	front bonnet inner lock	\$	274.10
1pc	front centre grille base	\$	591.45
1pc	front centre grille garnish	\$	371.50
1pc	front centre grille inner PCS sensor	\$	1,481.90
1pc	front centre grille "TOYOTA" logo	\$	785.50
1pc	front centre grille top garnish	\$	381.90
1pc	front centre grille top rubber	\$	174.45
1pc	front centre grille retainer	\$	131.25
2pcs	front headlamp @\$2550.50	\$	5,101.00
	balance c/f		\$ 23,244.55



輝 陽 汽 車 有 限 公 司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

22/10/2018

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR TOYOTA C-HR 1.8 - SMC3187E

	balance b/f		\$ 23,244.55
1pc	front bumper	\$	974.45
1pc	front bumper grille	\$	274.45
1pc	front bumper lower lid	\$	680.00
1pc	front bumper number plate garnish	\$	271.85
1pc	front bumper reinforcement	\$	581.10
1pc	front bumper sponge	\$	181.90
		\$	26,208.30
	less 25%	\$	6,552.08
	balance c/f	\$	19,656.23
1pc	rear end panel outer sensor	nett \$	240.00
		\$	240.00
	less 10%	\$	24.00
		\$	216.00
1set	parking sensor	s.nett \$	280.00
	reprogam & reset PCS sensor	\$	280.00
	remove & refit rear windscreen glass	\$	120.00
	sealant	\$	80.00
	wiring	\$	180.00
	tuffkote	\$	350.00
	spray painting	\$	1,800.00
	labour charges	\$	1,500.00
	Total	\$	24,462.23

