CYCLE & CARRIAGE AUTOMOTIVE PTE LTD



Body & Paint Centre 209 Pandan Gardens, Singapore 609339 Tel +65 6568 4501 - Fax +65 6565 1240 Company No. 197701469G

5th July 2019

Mr Khanchna (Motor Claims Department) LKK Auto Consultants Pte Ltd Blk 51 Paya Ubi Industrial Park #02-25 Ubi Avenue 1 Singapore 408933

Dear Sir,

Amended Invoice for Accident Involving Vehicles SKR7277Y and SHA7302H on 19/10/2018

Attached is the amended invoice which address to India International Insurance Pte Ltd as per requested.

Kindly process for payment to, Cycle & Carriage Automotive Pte Ltd, the soonest possible.

Appreciate your assistance.

Yours Sincerely,

Loi Ai Ting

Customer Service Advisor



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

TAX INVOICE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
India International Insurance Pte Ltd	Cust No/Name /Ms Lim Tien Phing Katherine (L			
Motor Claims Department	Reg No/Reg Date SKR7277Y / 21/09/2016			
64 Cecil Street	Date In/Mileage 08/12/2018/ 41463			
#04/05 IOB Building	Chassis/Package JMYXTGF3WGZ004432 /DC17PP			
Singapore 049711	Engine No 4B12RT9102			
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (G43)			
	Colour/Trim PO2 RED METALLIC / BK BLACK			

Terms	Date/Time Printed	CSE	Operator		WIP No	Invoice/	Credit Note N
Cash	02/05/2019/ 16:01	TLD	260 / AiTing		32168	4143363	2
	Description of Good	s / Service	8	Qty	Unit Price	Disc%	Amount
L. AND A	LL OTHER AFFECTED ARE						825.00
A CATALLAND							60.00
							840.0
		ER, AND A	LL OTHER AFFECTED				
RING AND	CHASSIS ELECTRICAL	SYSTEM					30.0
RUST PRE	VENTION ON AFFECTED	AREAS					60.00
DIAGNOST	IC CHECK USING HI-SCA	AN PRO TE	ST AND CLEAR TROUBLE	E CODE			200.00
							30.0
						COMPANY NAMED	280.0
	SIDE,RH					A STATE OF THE STATE OF	12.00
					The state of the s	500000000000000000000000000000000000000	20.00 873.00
	PER					14 ' cal ' cal ' cal ' cal '	230.00
178101	444			1.00	230.00	00.00	20010
INDIA S	HA7302H						
.10.18							
RASUL	LKK 30.10.18						
DAYS							
	Cycle & Carr	cione cal	ahratas 120 years				
				fo!			
				7% GST on			3,460.00
lenu				7 4 431 OII	3400.0		242.20
t Job				To	tal Payabl	e	3,702.20
cs Job		.00					0.00
hers		.00			Total Du	ie.	3,702.20
	DAMAGED L, AND A T TO THE ND INSTA ON REAR THE SAM RING AND RUST PRE DIAGNOST TJOB NE SET O MPR FACE BUMPER BUMPER N.RR BUM INDIA S 1.10.18 RASUL DAYS	Description of Good DAMAGED PARTS, REPLACE REAR IL, AND ALL OTHER AFFECTED ARIT TO THE SAME ND INSTALL PARKING ASSIST ON REAR END PANEL, REAR BUMPL THE SAME RING AND CHASSIS ELECTRICAL: RUST PREVENTION ON AFFECTED IN THE SAME TIJOB INE SET OF PARKING SENSOR MARY FACE SIDE, RH BUMPER IN, RR BUMPER I INDIA SHA7302H 10.18 RASUL LKK 30.10.18 DAYS Cycle & Carr Visit www.cycle 1,135 1,955 1,955 1,955 1,955 1,955 1,955 1,955	Description of Goods / Service DAMAGED PARTS, REPLACE REAR BUMPER, S L, AND ALL OTHER AFFECTED AREAS, ADJUT TO THE SAME ND INSTALL PARKING ASSIST ON REAR END PANEL, REAR BUMPER, AND A THE SAME RING AND CHASSIS ELECTRICAL SYSTEM RUST PREVENTION ON AFFECTED AREAS DIAGNOSTIC CHECK USING HI-SCAN PRO TE TJOB NE SET OF PARKING SENSOR MPR FACE SIDE,RH BUMPER N,RR BUMPER I INDIA SHA7302H 10.18 RASUL LKK 30.10.18 Cycle & Carriage cell Visit www.cyclecarriage. 1,135.00 1,955.00 1,955.00 1,000 280.00	Description of Goods / Services DAMAGED PARTS, REPLACE REAR BUMPER, SKID BUMPER, REPAIR L, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY G T TO THE SAME ND INSTALL PARKING ASSIST ON REAR END PANEL, REAR BUMPER, AND ALL OTHER AFFECTED THE SAME RING AND CHASSIS ELECTRICAL SYSTEM RUST PREVENTION ON AFFECTED AREAS DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBL TJOB NE SET OF PARKING SENSOR MPR FACE SIDE, RH BUMPER BUMPER N,RR BUMPER INDIA SHA7302H .10.18 RASUL LKK 30.10.18 DAYS Cycle & Carriage celebrates 120 years. Visit www.cyclecarriage.com/120 for more in. 1,135.00 1,955.00 0.00 280.00	Cash 02/05/2019/ 16:01 TLD 260 / AiTing Description of Goods / Services Qty DAMAGED PARTS, REPLACE REAR BUMPER, SKID BUMPER, REPAIR REAR L, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS IT TO THE SAME ND INSTALL PARKING ASSIST ON REAR END PANEL, REAR BUMPER, AND ALL OTHER AFFECTED THE SAME RING AND CHASSIS ELECTRICAL SYSTEM RUST PREVENTION ON AFFECTED AREAS DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE TJOB NE SET OF PARKING SENSOR MPR FACE SIDE,RH BUMPER 10.00 BUMPER 1.00 IN,RR BUMPER 1.00 IN,RR BUMPER 1.00 IN,RR BUMPER 1.00 INDIA SHA7302H .10.18 RASUL LKK 30.10.18 DAYS Cycle & Carriage celebrates 120 years. Visit www.cyclecarriage.com/120 for more info! 1,135.00 1,955.00 7% GST on 0.00 280.00 To	Description of Goods / Services Qty Unit Price DAMAGED PARTS, REPLACE REAR BUMPER, SKID BUMPER, REPAIR REAR L, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS IT TO THE SAME NO INSTALL PARKING ASSIST ON REAR END PANEL, REAR BUMPER, AND ALL OTHER AFFECTED THE SAME RING AND CHASSIS ELECTRICAL SYSTEM RUST PREVENTION ON AFFECTED AREAS DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE TJOB NE SET OF PARKING SENSOR MPR FACE SIDE,RH BUMPER 10.00 2.00 BUMPER 10.00 230.00 INDIA SHA7302H 1.101 RASUL LKK 30.10.18 DAYS Cycle & Carriage celebrates 120 years. Visit www.cyclecarriage.com/120 for more info! 1,135.00 7% GST on 3460.0 Tetal Payable denu 1,00 280.00 Total Payable	Description of Goods / Services