



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms Lim Tien Phing Katherine (Lin Dianping) 9 Vandar Drive Singapore 287848 Contact No Mobile: 97533023	Cust No/Name	/Ms Lim Tien Phing Katherine (Li
	Reg No/Reg Date	SKR7277Y / 21/09/201
	Date In/Mileage	/ 0
	Chassis No	JMYXTGF3WGZ004432
	Engine No	4B12RT9102
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (G43)
	Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	23/10/2018/ 15:21	QUD	247 / DonBong	32168			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								825 1650.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER, SKID BUMPER, REPAIR REAR END PANEL								
E PNT88000								60 80.00
REMOVE AND INSTALL PARKING ASSIST								
E PNT98000								840 1260.00
PAINT WORK SPRAY REAR END PANEL, REAR BUMPER AND AFFECTED PORTION								
A 54900099								30 50.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
M SUNDRY								60 80.00
PERFORM RUST PREVENTION								
A 10028901								200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
M SUNDRY								14 280.00
SUPPLY PARKING SENSOR								
M SUNDRY								30 50.00
SUNDRIES								
M					1.00	78.00	00.00	? 78.00
M					1.00	78.00	00.00	? 78.00
M					1.00	12.00	00.00	na 12.00
M					1.00	12.00	00.00	na 12.00
M					10.00	2.00	00.00	na 20.00
M					10.00	2.00	00.00	? 20.00
M					1.00	873.00	00.00	na 873.00
M					1.00	230.00	00.00	na 230.00
SURVEYOR NAME: <u>Paul</u>								
SURVEYOR SIGNATURE: <u>[Signature]</u>								
DATE: <u>30/10/18 @ 11:00 hrs</u>								
REMARKS: <u>4 days</u>								

Confirm & accepted by

Rosny by paint

Net 4,973.00
 7% GST on 4973.00 348.11
Total Payable 5,321.11

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.