



PDI TUAS

PDI TUAS

VIJAYAKUMAR PARAMESWARAN  
780 PASIR RIS STREET 71  
#07-576  
Singapore, 510780  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV031170  
Quote No. SER/QUO/1801762  
QuoteDate 22/10/18  
Salesperson Wilson Gwee Sheng  
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make               | Model Description              | Mileage              | Service Advisor   |
|--------------------|--------------------------------|----------------------|-------------------|
| Volkswagen Passeng | TiguanGP 1.4 TSI 118 DSG6 RECY | 54,204               |                   |
| License No.        | VIN                            | Initial Registration | Sales Advisor     |
| SKW5779C           | WVGZZZ5NZGW032497              | 04/11/15             | Wilson Gwee Sheng |
| Engine Code        | Labor Type                     | Engine No.           | Model Code        |
|                    | 1H                             | CTH 233471           | 5N22QY            |

| No.                        | Description                                            | Qty. | UoM     | Unit Price | Amount           |
|----------------------------|--------------------------------------------------------|------|---------|------------|------------------|
| P B&P MACP LABOUR          | LABOUR                                                 | 4    | UNIT    |            | 840 3,360.00     |
| P B&P MACP PAINT           | SPRAY PAINT                                            | 4    | UNIT    |            | 800 3,200.00     |
| P B&P DIAG                 | PROGRAMMING & CALIBRATION<br>COMPULSORY TO DO AFTER AC | 1    | Time Un |            | 480.00           |
| P B&P MECH                 | CHECK WIRE HARNESS, ECU, S<br>Nett                     | 1    | Time Un |            | 280.00           |
|                            | <b>Sum Labor</b>                                       |      |         |            | <b>7,320.00</b>  |
| P 1S0919275C GRU           | SENSOR<br>Predecessor 1S0919275C                       | 1    | Pieces  |            | 175.10           |
| P 1T0919133C 9B9           | PARKING SENSOR O RING                                  | 1    | Pieces  |            | 0.65             |
| P 5N0807305                | RR BUMPER REINFORCEMENT                                | 1    | Pieces  |            | 538.16           |
| P 5N0807393E               | BUMPER SIDE BRACKET LH<br>Use Predecessor 5N0807393B   | 1    | Pieces  |            | 38.69            |
| P 5N0807394D               | BUMPER SIDE BRACKET RH<br>Use Predecessor 5N0807394B   | 1    | Pieces  |            | 38.69            |
| P 5N0807421G GRU           | REAR BUMPER ( UPPER )                                  | 1    | Pieces  |            | 1,138.50         |
| P 5N0807521AFGRU           | REAR BUMPER ( CENTRE )                                 | 1    | Pieces  |            | 595.45           |
| P 5N0807568 2Z0            | REAR BUMPER ( LOWER )<br>Use Predecessor 5N0807568     | 1    | Pieces  |            | 558.91           |
| P 5N0919491D               | SENSOR BRACKET OUTER                                   | 1    | Pieces  |            | 17.63            |
| P 5N0919503D               | SENSOR BRACKET INNER                                   | 1    | Pieces  |            | 17.63            |
| P 5N0941071                | REVERSING LIGHT LH                                     | 1    | Pieces  |            | 87.23            |
| P 5N0941072                | REVERSING LIGHT RH                                     | 1    | Pieces  |            | 87.23            |
| P 5N0945105                | REFELCTOR REAR LH                                      | 1    | Pieces  |            | 78.22            |
| P 5N0971104AC              | SENSOR WIRE HARNESS                                    | 1    | Pieces  |            | 143.60           |
| <b>Sum carried forward</b> |                                                        |      |         |            | <b>10,835.69</b> |

Payments to:

- BBN: - Acc.-No.:



PDI TUAS

VIJAYAKUMAR PARAMESWARAN  
780 PASIR RIS STREET 71  
#07-576  
Singapore, 510780  
Singapore

PDI TUAS

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV031170  
Quote No. SER/QUO/1801762  
QuoteDate 22/10/18  
Salesperson Wilson Gwee Sheng  
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make               | Model Description              | Mileage              | Service Advisor   |
|--------------------|--------------------------------|----------------------|-------------------|
| Volkswagen Passeng | TiguanGP 1.4 TSI 118 DSG6 RECY | 54,204               |                   |
| License No.        | VIN                            | Initial Registration | Sales Advisor     |
| SKW5779C           | WVGZZZ5NZGW032497              | 04/11/15             | Wilson Gwee Sheng |
| Engine Code        | Labor Type                     | Engine No.           | Model Code        |
|                    | 1H                             | CTH 233471           | 5N22QY            |

Continued 10,835.69

Sum Item 3,515.69

Sum Labor 7,320.00  
Sum Item 3,515.69

Total SGD 10,835.69  
7% GST 10,835.69 758.50  
Total SGD Incl. GST 11,594.19

### Explanations

P = Proportionately Charged

### Payment Terms

No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*John*  
*HP 90010068*  
*3 days*  
*24/10/18 @ 1530hrs*  
*Resurvey 54 part*

Payments to:

- BBN: - Acc.-No..: