

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte Ltd (159-f&L)
 28 Leng Kee Road

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 23/10/2018

WIP No. : 34499

Veh.In/Out:

*Tel.No. : Work: 68765063

Reg.No. : SLF96933

Reg.date : 07/09/2016

Mileage : 0

Chassis No: SAJBB4AGXHCY25884

Singapore 159105

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT RH DOOR, REAR RH DOOR,	0	4500.00	0		4,500.00 S	2700
-----	---------------------------------------	---	---------	---	--	------------	------

800	REPAIR REAR RH FENDER, RH ROCKER PANEL, ETC TO PUTTY SPRAYPAINT ON FRT RH DOOR, REAR RH DOOR, REAR RH FENDER, RH ROCKER PANEL, ETC	0	4000.00	0		4,000.00 S	3200.
-----	--	---	---------	---	--	------------	-------

802	TO TRANSFER FRT RH DOOR PART	0	500.00	0		500.00 S	✓
-----	------------------------------	---	--------	---	--	----------	---

802	TO TRANSFER REAR RH DOOR PART	0	500.00	0		500.00 S	✓
-----	-------------------------------	---	--------	---	--	----------	---

0031	TO REPLACE REAR RH RIM	0	50.00	0		50.00 S	X
------	------------------------	---	-------	---	--	---------	---

419	WHEEL ALIGNMENT	0	280.00	0		280.00 S	X
-----	-----------------	---	--------	---	--	----------	---

280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00 S	✓
-----	-------------------------	---	--------	---	--	----------	---

RESETTING OF ALL ELECTRICAL MODULES

PANEL-DOOR RH	1.0 EA	1687.30				1,687.30 S	bt✓
---------------	--------	---------	--	--	--	------------	-----

PANEL-DOOR RH	1.0 EA	1960.90				1,960.90 S	bt✓
---------------	--------	---------	--	--	--	------------	-----

SEAL-DOOR	1.0 EA	230.40				230.40 S	nei✓
-----------	--------	--------	--	--	--	----------	------

SEAL-DOOR	1.0 EA	188.20				188.20 S	nei✓
-----------	--------	--------	--	--	--	----------	------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749

WP
29/10/18 @ 330

5-6 days

sure 11/11/18

sa
Resurvey before paint.

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
Wearnes Automotive Pte Ltd (159-f&L)
28 Leng Kee Road

Singapore 159105

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Wearnes Automotive P

GST Reg.No:M28920628X
Inv.No. : B&P 0 Page 2
Inv.date. : 23/10/2018
WIP No. : 34499
Veh.In/Out:
*Tel.No. : Work: 68765063
Reg.No. : SLF9693S
Reg.date. : 07/09/2016
Mileage : 0
Chassis No: SAJBB4AGXHCV25884

Op.No	Description	Mech Qty	Price	Disc%	PKg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	SOUND DEADENING PAD	2.0 EA	250.00			500.00 S	Ne ✓
	ALLOY 18" CHALICE TW	1.0 EA	1428.60			1,428.60 S	XNN

Labour Total	10,316.00
Parts Total	5,995.40
Package Total	0.00

Gross Total.	16,311.40
Net.....	16,311.40
GST @ 7.0%	1,141.80
Total.....	17,453.20
Paid.....	0.00
Please Pay..	17,453.20

GST: S=StdRated; O=OutOfScope; Z=ZeroRated